

AUTOWHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: AXA INSURANCE

DATE: 20/6/2018
VEHICLE NO: SJN3204S
MODEL: TOYOTA ALLIO
YEAR: 2009
ACCIDENT DATE: 20/6/2018
TYPE OF CLAIM: TP
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

DESCRIPTION	QTY	LIST PRICE
PARTS		
BONNET	1	\$ <i>bt</i> 845.10
FRONT GRILLE	1	\$ <i>mis</i> 356.10
FRONT GRILLE CLIPS	10	\$ <i>nei</i> 30.00
FRONT EMBLEM	1	\$ <i>nei</i> 65.40
FRONT BUMPER	1	\$ <i>de</i> 779.60
FRONT BUMPER CLIPS	10	\$ <i>ne</i> 30.00
FRONT BUMPER RETAINER	2	\$ <i>ne</i> 101.40
FRONT BUMPER BRACKET	2	\$ <i>nei</i> 155.80
FRONT BUMPER SPONGE	1	\$ <i>ave</i> 165.70
FRONT REINFORCEMENT	1	\$ <i>bt</i> 395.20
BRACE PANEL	1	\$ <i>bt</i> 95.10
SUPPORT PANEL	1	\$ <i>bul</i> 670.40
HORN	2	\$ <i>bt</i> 178.60
HEADLAMP	2	\$ <i>ave</i> 1,620.60
FOGLAMP COVER	<i>2</i> 1	\$ <i>LH-XRH-44</i> 178.40
RH FRONT FENDER	1	\$ <i>bt</i> 396.50
RH FRONT FENDER INNER PANEL	1	<i>Ry</i> RESTORE
RH FRONT FENDER INNER SHIELD	1	\$ X 197.80
RH FRONT FENDER INNER SHIELD CLIPS	10	\$ X 30.00
RH FRONT A PILLAR	1	RESTORE
RH FRONT WHEEL HOUSE	1	RESTORE
RH FRONT DOOR	1	RESTORE
LH FRONT FENDER	1	\$ <i>bt</i> 396.50
LH FRONT FENDER INNER PANEL	1	RESTORE
LH FRONT FENDER INNER SHIELD	1	\$? 197.80
LH FRONT FENDER INNER SHIELD CLIPS	10	\$? 30.00
CONDENSER	1	\$ <i>bt</i> 784.10

AUTOWHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

CONDENSER AIRGUIDE	2	\$	?	110.60
CONDENSER FAN COWLING	1	\$	?	210.40
CONDENSER FAN BLADE	1	\$	?	134.70
CONDENSER FAN MOTOR	1	\$	?	355.60
SUCTION PIPE	1	\$	?	334.30
LIQUID PIPE	1	\$	?	324.50
DISCHARGE PIPE	1	\$	?	321.30
RADIATOR	1	\$	?	799.30
RAIDATOR UPPER BUSH	2	\$	?	34.60
RADIATOR LOWER BUSH	2	\$	?	34.60
RADIATOR TOP BRACKET	2	\$	?	88.60
RADIATOR FAN COWLING	1	\$	?	210.40
RADIATOR FAN MOTOR	1	\$	?	355.60
RADIATOR FAN BLADE	1	\$	?	134.70
WIPER TANK	1	\$	X	132.70
WIPER TANK MOTOR	1	\$	X	155.30
INLET MANIFOLD	1	\$	X	781.20

TOTAL: \$ 12,218.50

DISCOUNT 25%: \$ 3,054.63

\$ 9,163.88

S/NET

FRONT NUMBER PLATE	1	\$	45.00	mis
COOLANT	1	\$	50.00	net
TOTAL:		\$	50.00	

LABOUR

LABOUR	PRICE
LABOUR FOR FACILITATE REPAIR	\$ 1600 1,800.00
TO RESPRAY AFFECTED AREAS - BONNET	\$ 200 300.00
TO RESPRAY AFFECTED AREAS - FRONT BUMPER	\$ 200 300.00
TO RESPRAY AFFECTED AREAS - RH FRONT FENDER AND INNER PANEL	\$ 200 300.00
TO RESPRAY AFFECTED AREAS - RH WHEEL HOUSE AND SUPPORT PANEL	\$ 200 300.00
TO RESPRAY AFFECTED AREAS - RH A PILLAR	\$ X 300.00
TO RESPRAY AFFECTED AREAS - RH FRONT DOOR	\$ 100 300.00
TO RESPRAY AFFECTED AREAS - LH FRONT FENDER AND INNER PANEL	\$ 200 300.00
TO CHECK AND RECONNECT ALL NECESSARY WIRING	\$ 30 100.00
TO REMOVE AND REFIT RADIATOR INCLUDING WATER PRESSURE TEST	\$ 100 150.00

AUTOWHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

TO REMOVE AND REFIT AC CONDENSER INCLUDING TOP UP GAS

SUNDARIES

RUST PROOFING

\$	100	150.00
\$	30	80.00
\$	40	100.00
TOTAL: \$		4,480.00

TOTAL: \$	13,693.88
7% GST: \$	958.57
\$	14,652.45

Tanpin 97495749
- wp'

26/6/13C '1645

hupsum

Reamy after repair

7days

sur@lkkauto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: