

1590209

INS. CASE OWNER

CC 3 / EQ11801 1282, Feb 2018

LKK: IDAC:

Surveyor: Kalvin

DOE: 20/6/18

Date / Time: 20/6/18

Registered in Merimen: ---

Pre-assign / CCU / FTE



Insured Vehicle No. : SJU 6335R
 Name of Insured : Timi JEE LEONG
 Insured Tel No. : HP: 98457745
 Excess Sec II : SS D.O.A : 17/6/18
 Is driver the owner? (YES / NO) Nature of Accident : ---

Claim No. : Dm18100152V
 Policy No. : DMP1818-00448
 Make / Model : NISSAN
 Place of Accident : TPE AFTER RPE EXIT

If NO, Driver Name / Age : ---
 Driver Tel No. : --- (VL: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO
 Insured Liability: % --- Final ? Yes / No

SUP 8190E

SJU 6335R

SJC 6691E



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS: 01



INSRS:
WSP:
Tel:
Liability:
RMKS: TP



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

25/6/18
PAKER

5-7-10 e 9:28

SJC 6691E - F
SJU 6335R - no (assignment) / or other A/B/C

OPUED 01 NO RESPONSE.

STAGE	DATE / PIC
Non-Reporting ltr (1st)	
Non-Reporting ltr (2nd)	
Non-Reporting ltr (Final)	
Notification ltr (if non-pickup)	
Call OI: <u>Answer 5.7.18</u>	
After call ltr to OI	
Documentation Check List: Handler Typist	
Notification ltr (if non-pickup)	<input type="checkbox"/>
After call ltr to OI	<input checked="" type="checkbox"/>
Authorisation To Act	<input checked="" type="checkbox"/>
Release Voucher: <u>(NO NEED)</u>	<input type="checkbox"/>
Final Repair Bill	<input checked="" type="checkbox"/>
Car Rental Invoice	<input checked="" type="checkbox"/>
Towing Invoice	<input type="checkbox"/>
LTA / GIA	<input checked="" type="checkbox"/>
Medical Bill	<input type="checkbox"/>
PIR	<input type="checkbox"/>
Mandate/Reject Instruction	<input type="checkbox"/>
LOD	<input checked="" type="checkbox"/>
Payment Breakdown Form	<input type="checkbox"/>
Post-Repair Photos	<input type="checkbox"/>
Others	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: 20/6/18 Sent By: Doe

FINALIZATION Date/Time: 26-7-18 Confirm with: ---
 Repair Cost: 45 \$S 1,050 (2 days) Reduction: 50 % Email Call

FINAL SETTLEMENT Date/Time: 23-8-18 Confirm with: GARY Email Call
 Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 28
 Repair Cost: w/651 \$S 1,235.50 3 VEH CC 01 2ND
 Loss of Rental (LOR): \$S 218.28 (2 days) x 109.14
 Loss of Use (LOU): \$S - (8 x days)
 Loss of Income (LOI): \$S 80.00 (5 x days)
 LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GLA/LTA Search: \$S 00
 Medical: \$S -
 Disbursement: \$S - (e.g. Tow/ Independent)
 Legal Cost: \$S -
 Total: \$S 1,423.78 Global Sum \$S:
 FINAL PAYMENT Date/Time: 21-8-18 Confirm with: GARY Email Call
 Payee 1: \$S 1,423.78 Name 1: PREMIER AUTOMOTIVE SERVICES PTE LTD
 Payee 2: (Strike if N.A.) \$S - Name 2: -
 Payee 3: (Strike if N.A.) \$S - Name 3: -

GARY SENT

01/05/18

Q name: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimate/Coast: _____

IT/INS / TP RES / OD RES / EVA / INV / MV

To Insp'd Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 30 % 3 Val.: Yes or No

CA / .REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHC 6691 E Yr Regn: 24 Jan, 2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Truck / Prime Mover /

Truck / Trailer or

Make: KIA optima c.c. 1.685

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 861865 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNA6M414MD5370177

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD/Rim or

Tyre Size: F: 205/65R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / BHTSU / PIR / SUMI / TOYO / YOKO or Achilles

Front R/Bal. 7 mm Rear R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 12/6/8 D.O.I. 20/6/8

Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	US: +1,050 (RED: +1,142.90 52%)

EQ
4)

Date/Time, File Pass to? : Prell. Report

1) : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Report Format: _____

Lump Sum / I.B.I: (\$) _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:	
Transportation:	
\$ + RS. \$	
Photos	
Others	
TOTAL	

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

18-Jun-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6691 E

1 pc	Rear bumper <i>Redmond</i>	\$	696.00
1 pc	Rear bumper lower cover <i>x su</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>x su</i>	\$	58.00
1 pc	Rear bumper inner sponge <i>x su</i>	\$	114.00
1 pc	Rear bumper reinforcement <i>x su</i>	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>x su</i>	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>x su</i>	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>x su</i>	\$	36.00
		\$	<u>1,861.00</u>
	Less 10%	\$	186.10
		\$	<u>164.90</u>

S/NETT

1 set	Rear bumper clips <i>see sketch</i>	\$	48.00
1 set	Reverse sensor <i>sketch</i>	\$	280.00 200
1 pc	Rear bumper top protector <i>sketch</i>	\$	80.00 50
	Sundry <i>sketch</i>	\$	50.00 x 21
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 20
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 x 27
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc.	\$	650.00 200
	To putty and spray painting on rear bumper, end panel	\$	500.00 180
	To apply rustproofing on the repaired and replaced panels	\$	120.00 x 27
		\$	<u>2,192.90</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

26/9/18
sketch L/S \$1050/200
[Signature]

Kahin UCKK
20/6/18 1000 L
2 B's
L/S
After Repair photo

LKK Auto Consultants hereby notify the Repairer of the following:

- To re-insure before other survey claiming
- To display damaged parts during repair
- Parts prices are subject to confirmation
- Third party liability is on a "Without Prejudice" basis
- No legal implications is involved
- Supplementary terms must be reviewed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC3/EQI18011282/K1eb3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 21-06-2018	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJU 6335R	Veh. Inspected	SHC 6691E
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	21/06/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	17/06/2018	Inspection Date	20/06/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/EQI18011282/K1eb3

Date: 21.06.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC6691E


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20.06.2018 at the premises of M/s Premier Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	2,192.90
Revised Estimate Amount	: S\$	1,324.40
"Check" Items Amount	: S\$	611.10
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

18-Jun-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6691 E

1 pc	Rear bumper ✓	\$	696.00
1 pc	Rear bumper lower cover ✗	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 ✓	\$	58.00
1 pc	Rear bumper inner sponge ✗	\$	114.00
1 pc	Rear bumper reinforcement .?	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 ✗	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @\$18.00 ?	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @\$18.00?	\$	36.00
		\$	1,861.00
		Less 10%	\$ 186.10
		\$	164.90

S/NETT

1 set	Rear bumper clips ✓	\$	48.00
1 set	Reverse sensor ✓	\$	280.00 200
1 pc	Rear bumper top protector ✓	\$	80.00 50
	Sundry	\$	50.00 ✗
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 20
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 ✗
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc.	\$	650.00 200
	To putty and spray painting on rear bumper, end panel ✗	\$	500.00 180
	To apply rustproofing on the repaired and replaced panels.	\$	120.00 ✗
		\$	2,192.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting.
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation.
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahin Ullah
20/6/18 1000 L
2 Rs
L/S
After Repair photo

 PREMIER TAXIS	HIRER RELIEF / SUPER RELIEF
VEHICLE NO.	STIC 6691E
CONTACT NO.	94 56 00 62
NEW MAILING ADDRESS (if any)	

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S0204523J



Name
TAN CHEW HUI

Race
CHINESE

Date of Birth
31-08-1954

Country of Birth
SINGAPORE

Sex
M




REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S0204523J**

Name:
TAN CHEW HUI

Birth Date: **31 Aug 1954**

Issue Date: **20 Jan 2003**





NRIC No. **S0204523J**



NRIC Grade: **A** Date of issue: **19-04-1992**

NET. BLK. 145 SERANGOON NORTH AVENUE 1 #03-377
SINGAPORE 250143

NRIC No: **S0204523J** Date: **12-03-1991** No: **2269304**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	PASS DATE
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	07 Feb 1977

NP 426A



Land Transport Authority

VOCATIONAL LICENCE

Licence No: **S0204523J**

Name: **TAN CHEW HUI**

Issue Date: **4/11/2013**

Please visit www.lta.gov.sg to check the status of this vocational licence



Enquire Transaction History

Transaction History Details:

Log Date/Time:	24 Jan 2013 / 10:29:33	Receipt No.:	AACCK001-AX239-130124-000010
Asset Type:	Vehicle	Transaction Amount:	\$70,810.00
Asset ID:	SHC6691E	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20130124102933799462		

Vehicle No.:	SHC6691E
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Alr-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	24 Jan 2013
Original Registration Date:	24 Jan 2013
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MD5370177
Engine No.:	D4FDCH306763
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2012
Open Market Value:	\$17,515.00
Minimum PARF Benefit:	\$6,009.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	24 Jan 2013 10:29:33
COE No.:	2013012401000869G
COE Expiry Date:	23 Jan 2021
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$60,655.00
Lifespan Expiry Date:	23 Jan 2021
Owner ID Type:	Company
Owner ID:	200304975H



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 07/09/2018

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	SJU 6335R (Insd Veh)	Your Ref. No. : DM18HO01522/FN
	SHC 6691E (TP Veh)	Our Ref. No. : CC3/EQ18011282/K1eb3q2
Date of Accident	17/6/2018	

Liability	100%	
Final Repair Cost	: \$ 1,123.50	
Loss of Income	: \$ 80.00	2 days
Rental (If any)	: \$ 218.28	2 days
Others:	: \$ 2.00	
	: \$	
	1,423.78	
Final Settlement Sum	: \$ 1,423.78	
Remarks	:	

Payment Instruction: Payee's Breakdown		
1)	PREMIER AUTOMOTIVE SERVICES PTE LTD	: \$ 1,423.78
		: \$

JOANNE LEE
LKK Auto Consultants Pte Ltd

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVE 2 #01-02
SINGAPORE 486443
TEL:65446671 FAX:62141511
CO. REG:200707743D GST REG:200707743D

Our Ref: SHC6691E/GS

WITHOUT PREJUDICE

8th August 2018

(By Email Only)

Attn: The Motor Claims Department

EQ Insurance Company Limited
5 Maxwell Road
#17-00, Tower Block
MND Complex
Singapore 069110

Dear Sir/Madam

**ACCIDENT INVOLVING SHC6691E, SJU6335R & SLP8190E ALONG TPE –
SLE ON 17.06.18**

We have been authorized by Premier Taxis Pte Ltd, the owner of Taxi vehicle number: SHC6691E, to claim against the party/parties responsible for the damages arising from the above-mentioned accident.

Our records show that you are the insurers of vehicle number: SJU6335R at the material time of the accident with the driver of our client's vehicle, Mr Tan Chew Hui

As a result of the accident caused by your Insured Driver's negligent driving and/or management of your insured's Vehicle Number: SJU6335R, our client's vehicle was damaged and we have been put to loss and damage as follows:

(1) Cost of repair	\$ 1123.50 (Incl. GST)
(2) Loss of Rental - 2Days @\$109.14per day	\$ 218.28
(3) Loss of Income – 2Days @\$100.00per day	\$ 200.00
(4) GIA Search Fee	\$ 2.00
	<u>\$ 1543.78</u>

A copy of each of the following supporting documents is enclosed:

- (1) Final Repair Bill, GIA report & sketch plan of SHC6691E
- (2) Driver's I/C and Driving Licence
- (3) Vehicle Registration card, Certificate of Insurance
- (4) Check In/Out Voucher, GIA search

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVE 2 #01-02

SINGAPORE 486443

TEL:65446671 FAX:62141511

CO. REG:200707743D GST REG:200707743D

Our Ref: SHC6691E/GS

We would appreciate if you could look into the subject matter and let us have your favorable offer within 14 days. If you are agreeable to the settlement of the above said claims, please forward us your discharge voucher as for our client's signature and payment made to "Premier Automotive Services Pte Ltd".

Please note that if we do not hear from you within the stipulated 14 days, we will have no alternative but to appoint our solicitor to act on our behalf to commence proceedings against you without further notice to you.

Yours faithfully,





Claims Department – Gary Shi

Email: gary.shi@premiertaxi.com

NB: We encourage all parties to liaise with us via email to expedite all matters

PS: Please quote our reference no when replying

c.c. Client – Premier Taxis Pte Ltd



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC3/EQI18011282/K1eb3

05 JULY 2018

TING JEE LEONG
BLK 316C PUNGGOL WAY
#08-695
SINGAPORE 823316

Dear Sir/Madam,

ACCIDENT INVOLVING SJU 6335R / SHC 6691E / OTHERS ON 17/06/2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal EQ INSURANCE COMPANY LIMITED.

Please call us if you have further queries.

Yours faithfully,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: ashersng@lkkauto.com

c.c. *EQ INSURANCE COMPANY LIMITED*
(Motor Claims Dept)

AUTHORIZATION TO ACT

I, PREMIER TAXIS PTE LTD (the third party claimant") of 23 CHANGI SOUTH AVENUE 2 #03-02 SINGAPORE 486443 (address), owner of SHC 6691E (vehicle no.) hereby authorize PREMIER AUTOMOTIVE SERVICES PTE LTD ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no SHC 6691E that was damaged pursuant to the accident which occurred on 17/06/2018 (date) along TPE - SLE (location) involving vehicle no/s SJU 6335R ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 28 (day) of Aug (month) 20 18 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)



PREMIER AUTOMOTIVE SERVICES PTE LTD
OFFICE: 23 Changi South Avenue 2 #01-02 S(486443)
TEL: 65436676 / 65436689 FAX: 62141511
CO. REG NO.: 200707743D GST. REG. NO.: 200707743D

PREMIER TAXIS PTE LTD
23 CHANGI SOUTH AVENUE 2 #03-02
SINGAPORE 486443

TAX INVOICE

DATE 8-Aug-2018
PAGE 1 OF 1

ITEM	Description	QTY	U.PRICE	AMOUNT
	FINAL REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6691 E			\$ 1,050.00
TOTAL LUMP SUM REPAIR COSTS AS RECOMMENDED BY SURVEYOR				\$ 1,050.00
GST @ 7%				\$ 73.50
GRAND TOTAL				\$ 1,123.50


for Premier Automotive Services Pte Ltd

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)



21 June 2018

To Whom It May Concern

Dear Sir/Madam

CERTIFICATION LETTER

This letter serves to inform that Tan Chew Hui of NRIC Number S0204523J is a registered driver of SHC6691E. Tan Chew Hui is paying daily rental rate of \$109.14 (inclusive of GST).

Should you require further information, please contact us at 6214 8880.

Thank you.

Yours sincerely

A handwritten signature in black ink, appearing to read "Kellie Poh".

Kellie Poh

Administration Manager

Prepared By: Hasnah

PREMIER TAXIS PTE LTD
23 Changi South Avenue 2
#03-02
Singapore 486443
Telephone: +65 6214 8880 Fax: +65 6214 0330
www.premiertaxi.com
Co. Reg. No. 200304975H



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-092422

Date of Request: 18/06/2018

Your Ref No: Online Purchase

Premier Automotive Services Pte Ltd
23 Changi South Ave 2
#01-02
Singapore 486443

Dear Sir/Madam,

Enquiry Date 18/06/2018
Enquiry By GARY SHI GUO RONG
TP Vehicle No. SJU6335R
Accident Date 17/06/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJU6335R	EQ Insurance Company Ltd	25/04/2018-24/04/2019	6223 9433

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-092422
Date of Request: 18/06/2018

Your Ref No: Online Purchase

Premier Automotive Services Pte Ltd
23 Changi South Ave 2
#01-02
Singapore 486443

Dear Sir/Madam,

Enquiry Date 18/06/2018
Enquiry By GARY SHI GUO RONG
TP Vehicle No. SJU6335R
Accident Date 17/06/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:
Date:
 GIRO Cash Cheque



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC3/EQ118011282/K1eb3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 07-09-2018	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJU 6335R	Veh. Inspected	SHC 6691E
Policy No.	DMPPHQ18-001448	Coverage (\$)	0.00
Claim No.	DM18HO01522/FN	Excess (\$)	0.00
Assign From		Assign Date	20/06/2018
2. Vehicle Particulars & Condition			
Make & Model	KIA OPTIMA	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	KNAGM414MD5370177	Colour	SILVER
Odometer	861865	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/65R16	ACHILLES	7 mm
L/H Front Tyre	205/65R16	ACHILLES	7 mm
R/H Rear Tyre	205/65R16	ACHILLES	7 mm
L/H Rear Tyre	205/65R16	ACHILLES	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/06/2018	Inspection Date	20/06/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6691E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER	SERVICEABLE	206.00	-
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	SERVICEABLE	58.00	-
1	REAR BUMPER INNER SPONGE	SERVICEABLE	114.00	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	607.00	-
2	REAR BUMPER STAY O/S & N/S	SERVICEABLE	108.00	-
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	SERVICEABLE	36.00	-
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	SERVICEABLE	36.00	-
	LESS 10% DISCOUNT		-186.10	-69.60
			1,674.90	626.40
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR BUMPER TOP PROTECTOR (SN)	NECESSARY	80.00	50.00
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			458.00	298.00
LABOUR				
	TO DISMANTLE /REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	20.00
	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDNET DAMAGED PARTS .INCLUDING KNOCK-OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE END PANEL ,ETC.		650.00	200.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER ,END PANEL.		500.00	180.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	120.00	-
			1,570.00	400.00

Report Ref No. CC3/EQ118011282/K1eb3q2



GRAND TOTAL		3,702.90	1,324.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,050.00

Report Ref No. CC3/EQ118011282/K1eb3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.