

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

18-Jun-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6691 E

1 pc	Rear bumper ✓	\$ 696.00
1 pc	Rear bumper lower cover X	\$ 206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 ✓	\$ 58.00
1 pc	Rear bumper inner sponge X	\$ 114.00
1 pc	Rear bumper reinforcement ?	\$ 607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 X	\$ 108.00
2 pcs	Rear bumper reinforcement lower bracket @\$18.00 ?	\$ 36.00
2 pcs	Rear bumper reinforcement upper bracket @\$18.00 ?	\$ 36.00
		\$ 1,861.00
Less 10%		\$ 186.10
		\$ 164.90

S/NETT

1 set	Rear bumper clips ✓	\$ 48.00
1 set	Reverse sensor ✓	\$ 280.00 200
1 pc	Rear bumper top protector ✓	\$ 80.00 50
Sundry		
To dismantle / replace reverse sensor to new bumper and reset to the same		\$ 50.00 X
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$ 120.00 20
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc.		\$ 180.00 X
To putty and spray painting on rear bumper, end panel X		\$ 500.00 180
To apply rustproofing on the repaired and replaced panels.		\$ 120.00 X
		\$ 2,192.90

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahin Ullah
20/6/18 1000 L
2 B's
L/S
After Repair