

A REC. BY:

REF:

CS / GAZ 18011283 / Uvb

Special Instruction:

SUTVA/01

ASSIGNMENT (Office)

From (Person): Kelvyna of GAL Date/Time: 21062018 11:11am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLH 878A Insured: GBF 678Pat Workshop m/s Kah motor Tel: 88465673of 15 Ubi Rd 4Policy No: _____ Claim No: CLMOMVC000003275

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 02062018

(Client's Record)

CA / REV / REP. / REV 24 HRS

29-062018 @ 10am

H.O.D. Endorsement: _____

Date/Time: 21062018 11:43am Person Contacted: Any Vehicle IN / OUT: IN

Date/Time	Action/Instruction (✓) Estimate
	SLH 878A - NA / GAZ 18010119 / 24 DLA: 02062018
	GBF 678P - X
3/7/18	Email preli revised to Kelvyna

(08/11/13) wef

REF: GAI

ASS. REC. BY:

ASSIGNMENT

From:

Date: 29/6/2018

Veh No:

SLH878A

Yr Regn:

10/16

Estimated Cost:

Type: ☒ M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

CA

To Inspect Vehicle No:

SLH878A

Make:

Honda CIVIC

c.c

1597

at Workshop m/s

Keh Motor

Colour

silver

A/C:

Insured / Std / NI / NA

of

15 Ubi Rd 4

Sp. Reading

34187

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

MRHFC5650GT000307

Claims No.

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: ☒ In order / Jammed / Leaked / Burnt or

(Client's Record)

10 am

Brake: ☒ In order / Jammed / Leaked / Burnt or

Make of Veh:

Any

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55-216

R:

(Policy Condition)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

Remark: The veh had commenced its

repair at the time of inspection.

TOYO / YOKO or

hankook

Bal. or Market Value:

Front

6

Rear

6

IDAC Accident Rpt:

Consistent?: Yes or No

R/Bal.

mm

R/Bal.

mm

GIA / PR Seen:

Consistent?: Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

4

days

Res.: Yes or No

D.O.A.

2/6/18

D.O.I.

2/7/18

Lum Sum:

%

3 Val.: Yes or No

Survey held at

CA / REV / REP. / 24 HRS

lup 2-5

Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21/7/18 contact find by 02378-57 with Any (Real 3609.51, 6090)

RECEIVED 20 JUL 2018

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

4

1)

☐

: Final Report

Resurvey No. of Trip:

1

Date/Time, File Return to?

2)

2017- typist

Add Fee:

☐

: Site Insp (\$

Survey Fee:

Transportation:

250

- 20

NAC

Photos

Others

Report Format :

TP

Lump Sum / I.B.I. (\$) 2378.57

☐

: Weekend (\$

TOTAL

230



Auto
Consultants
Pte Ltd

Company Registration No. 19960711

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564

Your Ref: PLEASE ADVISED
Our Ref: CS/GAI18011283/Uvb

Date: 3/7/2018

The Motor Claims Department
M/s: GREAT AMERICAN INSURANCE COMPANY

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SLH 878A


We thank you for your instruction on 21/6/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 2/7/2018 at the premises of M/s KAH MOTOR CO SDN BHD and have the following to report:-

Workshop Estimate Amount	: S\$5,988.08
Revised Estimate Amount	: S\$2,378.57
"Check" Items Amount	: S\$6.90
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear o/s portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 3 July 2018 11:34 AM
To: 'Ngian, Kelvyna'; SUR
Subject: RE: CLMOMVC000003275 : TP survey SLH878A (LIBERTY) & GBF678P (GAIC) DOA: 02/06/2018@13.00PM
Attachments: SLH 878A PRELI REVISED.pdf

Dear Kelvyna,

Enclosed preliminary revised of vehicle SLH 878A
Date of survey: 2/7/2018
Number of days :4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 21 June 2018 11:39 AM
To: 'Ngian, Kelvyna' <Kelvyna.Ngian@sg.gaig.com>; SUR <sur@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>
Subject: RE: CLMOMVC000003275 : TP survey SLH878A (LIBERTY) & GBF678P (GAIC) DOA: 02/06/2018@13.00PM

Dear Kelvyna,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer arrange survey on 29.06.2018.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ngian, Kelvyna [<mailto:Kelvyna.Ngian@sg.gaig.com>]
Sent: Thursday, 21 June, 2018 11:11 AM
To: SUR <sur@lkkauto.com>; Catherine Chong (LKK Auto) <admin-d@lkkauto.com>
Subject: CLMOMVC000003275 : TP survey SLH878A (LIBERTY) & GBF678P (GAIC) DOA: 02/06/2018@13.00PM

Hi team

Please conduct TP survey Friday 22/06/2018@10.30am

Thanks
Kelvyna

From: Ary Chua <arychua@honda.com.sg>
Sent: Wednesday, June 20, 2018 4:12 PM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Cc: Liew Thye Wui <twliew@honda.com.sg>
Subject: [External] RE: TPDS: SLH878A (LIBERTY) & GBF678P (GAIC) DOA: 02/06/2018@13.00PM

Hi Kelvyna
Kindly Establish this case Liability Issue?
We Choose 5. LKK Auto Consultants

Thank you.
Best Regards,
Ary Chua Wai Ngee
Bodyshop Service Advisor Kah Motor Co.Sdn.Bhd.15 Ubi Road 4 Singapore 408610
E-mail: aychua@honda.com.sg Fax: 67480770 DID:68465673 H/P:81006306

From: Ngian, Kelvyna [mailto:Kelvyna.Ngian@sg.gaig.com]
Sent: Wednesday, 20 June, 2018 3:21 PM
To: Ary Chua <arychua@honda.com.sg>
Cc: Liew Thye Wui <twliew@honda.com.sg>
Subject: RE: TPDS: SLH878A (LIBERTY) & GBF678P (GAIC) DOA: 02/06/2018@13.00PM
WITHOUT PREJUDICE
Dear Ary

We append the following list of our panel surveyors:-

1. AJAX Adjusters & Surveyors Pte Ltd
2. L.B.S. Automotive Appraisal Pte Ltd
3. Priority Services
4. RT Appraisal Pte Ltd
5. LKK Auto Consultants
6. JP KNIGHTS PTE LTD

Please advise.

Thanks
Kelvyna

From: Ary Chua <arychua@honda.com.sg>
Sent: Wednesday, June 20, 2018 2:30 PM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>; Michael.Tay@sg.gaig.com; General Claims <GeneralClaims@sg.gaig.com>
Cc: Liew Thye Wui <twliew@honda.com.sg>
Subject: [External] TPDS: SLH878A (LIBERTY) & GBF678P (GAIC) DOA: 02/06/2018@13.00PM
Hi OIC-GAIC,
Kindly Arrange for car Survey this Friday 22/06/2018@10.30am

Thank you.
Best Regards,
Ary Chua Wai Ngee
Bodyshop Service Advisor Kah Motor Co.Sdn.Bhd.15 Ubi Road 4 Singapore 408610
E-mail: aychua@honda.com.sg Fax: 67480770 DID:68465673 H/P:81006306



Catherine Chong (LKK Auto)

From: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Sent: Thursday, 21 June, 2018 11:11 AM
To: SUR; Catherine Chong (LKK Auto)
Subject: CLMOMVC000003275 : TP survey SLH878A (LIBERTY) & GBF678P (GAIC) DOA: 02/06/2018@13.00PM
Attachments: GBF678P.pdf; 2401_001.pdf; SLH878A.pdf

Hi team

Please conduct TP survey Friday 22/06/2018@10.30am

Thanks
Kelvyna

From: Ary Chua <arychua@honda.com.sg>
Sent: Wednesday, June 20, 2018 4:12 PM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Cc: Liew Thye Wui <twliew@honda.com.sg>
Subject: [External] RE: TPDS: SLH878A (LIBERTY) & GBF678P (GAIC) DOA: 02/06/2018@13.00PM

Hi Kelvyna
Kindly Establish this case Liability Issue?
We Choose 5. LKK Auto Consultants

Thank you.
Best Regards,
Ary Chua Wai Ngee
Bodyshop Service Advisor Kah Motor Co.Sdn.Bhd.15 Ubi Road 4 Singapore 408610
E-mail: arychua@honda.com.sg Fax: 67480770 DID:68465673 H/P:81006306

From: Ngian, Kelvyna [<mailto:Kelvyna.Ngian@sg.gaig.com>]
Sent: Wednesday, 20 June, 2018 3:21 PM
To: Ary Chua <arychua@honda.com.sg>
Cc: Liew Thye Wui <twliew@honda.com.sg>
Subject: RE: TPDS: SLH878A (LIBERTY) & GBF678P (GAIC) DOA: 02/06/2018@13.00PM
WITHOUT PREJUDICE
Dear Ary

We append the following list of our panel surveyors:-

1. AJAX Adjusters & Surveyors Pte Ltd
2. L.B.S. Automotive Appraisal Pte Ltd
3. Priority Services
4. RT Appraisal Pte Ltd
5. LKK Auto Consultants
6. JP KNIGHTS PTE LTD

Please advise.

Thanks
Kelvyna

From: Ary Chua <arychua@honda.com.sg>
Sent: Wednesday, June 20, 2018 2:30 PM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>; Michael.Tay@sg.gaig.com; General Claims <GeneralClaims@sg.gaig.com>

Cc: Liew Thye Wui <twliew@honda.com.sg>

Subject: [External] TPDS: SLH878A (LIBERTY) & GBF678P (GAIC) DOA: 02/06/2018@13.00PM

Hi OIC-GAIC,

Kindly Arrange for car Survey this Friday 22/06/2018@10.30am

Thank you.

Best Regards,

Ary Chua Wai Ngee

Bodyshop Service Advisor Kah Motor Co.Sdn.Bhd.15 Ubi Road 4 Singapore 408610

E-mail: arychua@honda.com.sg Fax: 67480770 DID:68465673 H/P:81006306



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Veron Chen (LKKAUTO)

From: Ary Chua <arychua@honda.com.sg>
Sent: Thursday, 19 July 2018 8:12 PM
To: Marcus Chua (LKKAUTO); SUR
Cc: Liew Thye Wui; Faeaz
Subject: 1ST Reminder: Finalise TPDS: SLH878A (LIBERTY) & GBF678P (GAIC) DOA: 02/06/2018@13.00PM
Attachments: 2914_001.pdf

Hi Marcus Chua,

Kindly Finalise TPDS: SLH878A (LIBERTY) & GBF678P (GAIC) DOA: 02/06/2018@13.00PM – 1st Reminder

Final Repair Costs (include GST)	\$2,378.57 + (\$166.49) = \$2,545.06
Repair Period* (Working Day)	04

***NOTES: The Repair Not Includes Public Holiday & Sunday.**

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thank you.

Best Regards,

Ary Chua Wai Ngee

Bodyshop Service Advisor Kah Motor Co.Sdn.Bhd.15 Ubi Road 4 Singapore 408610

E-mail: arychua@honda.com.sg Fax: 67480770 DID:68465673 H/P:81006306

From: Ary Chua

Sent: Friday, 6 July, 2018 8:44 AM

To: Marcuschua@lkkauto.com; SUR <sur@lkkauto.com>

Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>

Subject: Finalise TPDS: SLH878A (LIBERTY) & GBF678P (GAIC) DOA: 02/06/2018@13.00PM

Hi Marcus Chua,

Kindly Finalise TPDS: SLH878A (LIBERTY) & GBF678P (GAIC) DOA: 02/06/2018@13.00PM

Final Repair Costs (include GST)	\$2,378.57 + (\$166.49) = \$2,545.06
Repair Period* (Working Day)	04

***NOTES: The Repair Not Includes Public Holiday & Sunday.**

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thank you.

Best Regards,

Ary Chua Wai Ngee

Bodyshop Service Advisor Kah Motor Co.Sdn.Bhd.15 Ubi Road 4 Singapore 408610

E-mail: arychua@honda.com.sg Fax: 67480770 DID:68465673 H/P:81006306



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

 > **Back to OneMotoring****Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 0225E

Vehicle Details

Vehicle No.: SLH878A

Vehicle to be Exported: No

Intended De-registration Date: 02 Jul 2018

Vehicle Make: HONDA

Vehicle Model: CIVIC 1.6 VTI CVT

Primary Colour: Silver

Manufacturing Year: 2016

Engine No.: R16B21600434

Chassis No.: MRHFC5650GT000307

Maximum Power Output: 92.0 kW (123 bhp)

Open Market Value: \$19,491.00

Original Registration Date: 04 Oct 2016

First Registration Date: 04 Oct 2016

Transfer Count: 0

Actual ARF Paid: \$19,491.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 03 Oct 2026

PARF Rebate Amount: \$14,618.00

Intended COE Rebate Details

COE Expiry Date: 03 Oct 2026

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$53,334.00

COE Rebate Amount: \$44,014.00

Total Rebate Amount: \$58,632.00

The information contained herein is correct as at 02 Jul 2018

OK

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Owner Survey &
Rental Car 02 JUL 2018 @ 0830am
Ngiam: 68446059
Sharon Ng: 68446037
Survey & Arrange
Rental Car 29 JUN 2018 @ 10:00am : Katherine
for driver Friday Done appointment

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : GREAT AMERICAN INSURANCE
3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190
Registration No : SLH878A
Chassis No : MRHFC5650GT000307
Model : CIVIC 1.6 VTI YM2016
Owner's Name : TOH WONG LIM
Ins Policy No. : SD16V13008/VPC2/R00
Date of Accident : 4/6/2018

Document No. : SQT18002525 Page 1
Date : 20. Jun 2018
Customer No. : WZG001
Svc Advisor : ARY CHUA WAI NGEE
Engine No : R16B21600434
Date | Time : 20. Jun 2018 1:19:42 PM
Surveyor Name :
Survey Date : DID : +65 6845 5673
Authorisation Date : HP : +65 8100 6306
Email : arychua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 70713)						
	OWNER: TOH WONG LIM						
	OWNER INSURER: LIBERTY INSURANCE PTE LTD						
	ACC DATE: 04/06/2018@13.00PM						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: GREAT AMERICAN INSURANCE COMPANY						
91505-TM8-003	CLIPBUMPER <i>nel</i>	14	2.00	25	21.00	1.47	22.47
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER <i>715</i>	1	617.20	25	462.90	32.40	495.30
75722-TBA-A00	EMBLEM SETRR. <i>na</i>	1	11.50	25	8.62	0.60	9.22
75725-TEA-T01	EMBLEMRR. <i>11</i>	1	10.60	25	7.95	0.56	8.51
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER <i>11</i>	1	173.00	25	129.75	9.08	138.83
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER <i>garnish 11</i>	1	38.20	25	28.65	2.01	30.66
71503-TEA-T00	GARNISHR.RR.BUMPER SIDE <i>sized garnish</i>	1	7.60	25	5.70	0.40	6.10
71593-TEA-T01	SPACERR.RR.BUMPER SIDE <i>500</i>	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE <i>11</i>	1	11.50	25	8.62	0.60	9.22
33505-TEA-T01	REFLECTOR ASSYR.RR. <i>11</i>	1	7.00	25	5.25	0.37	5.62
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE <i>11</i>	1	2.20	25	1.65	0.12	1.77
33500-TEA-T01	TAILLIGHT ASSYR. <i>1320</i>	1	253.80	25	190.35	13.32	203.67
34150-TEX-Y01	LIGHT ASSYR.LID <i>11</i>	1	118.70	25	89.02	6.23	95.25
	Sum Item				968.08	67.76	1,035.84
BOSUN	SUNDRIES <i>nel</i>	1	100.00	20	100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	80	180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	240.00	130	240.00	16.80	256.80
BKRP22S	STRAIGHTEN ALIGN RR PANEL RR R FENDER & RENEW	1	1800.00	560	1800.00	126.00	1926.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) <i>hinge & bumper</i>	1	2700.00	900	2700.00	189.00	2889.00
	Sum Labor				5020.00	351.40	5,371.40

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : GREAT AMERICAN INSURANCE
3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Registration No : SLH878A

Chassis No : MRHFC5650GT000307

Model : CIVIC 1.6 VTI YM2016

Owner's Name : TOH WONG LIM

Ins Policy No. : SD16V13008/VPC2/R00

Date of Accident : 4/6/2018

Document No. : SQT18002525

Date : 20. Jun 2018

Customer No. : WZG001

Svc Advisor : ARY CHUA WAI NGEE

Engine No : R16B21600434

Date | Time : 20. Jun 2018 1:19:42 PM

Surveyor Name : DID : +65 6846 5673

Survey Date : HP : +65 8100 6306

Authorisation Date : Email: arychua@honda.com.sg

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Survey By	<u>marcus Hhh</u>						
Date & Time	<u>2/7/18 @ 10.40am.</u>						
Excess	<u>—</u>						
Status	<u>not approved</u>						
Signature	<u>Take ph. before repair</u>						
	<u>tel: 62563561</u>						
	<u>3dy. - 4dy.</u>						
Total Amount					5,988.08	419.16	6,407.24
Total (Inclusive of GST)							6,407.24

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 20/6/2018 2:08:23 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZG001 / GREAT AMERICAN
Chassis No: MRHFC5650GT000307
License No: SLH878A
Mileage: 34188
Engine No: R16B21600434

Document No: SVO18038284
Printed By: ARYCHUA
Order Date: 2. July 2018
Order Time: 11:03:59 AM
Service Advisor: ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 70713) OWNER: TOH WONG LIM OWNER INSURER: LIBERTY INSURANCE PTE LTD ACC DATE: 04/06/2018@13.00PM SURVEYED BY: MARCUS CHUA(LKKAUTO)02/07/2018@10.40A REF NO: TP INSURER: GREAT AMERICAN INSURANCE COMPANY						
91505-TM8-003	CLIPBUMPER	14	2.00	25	21.00	1.47	22.47
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71503-TEA-T00	GARNISHR.RR.BUMPER SIDE	1	7.60	25	5.70	0.40	6.10
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
33500-TEA-T01	TAILLIGHT ASSYR.	1	253.80	25	190.35	13.32	203.67
	SUM PARTS:				688.57	48.19	736.76
BOSUN	0672	1	20.00		20.00	1.40	21.40
	SUNDRIES						
BML02I	EXT-YJ	1	80.00		80.00	5.60	85.60
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)						
BA02R	EXT-YJ	1	130.00		130.00	9.10	139.10
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BKRP22S	EXT-YJ	1	560.00		560.00	39.20	599.20
	STRAIGHTEN ALIGN RR PANEL RR R FENDER & RENEW DAMAGE PARTS.						
BP02R	EXT-YBH	1	900.00		900.00	63.00	963.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(2P)						
	SUM LABOUR:				1,690.00	118.30	1,808.30
	TOTAL SGD				2,378.57	166.49	2,545.06

Total Payable (SGD)

2,545.06

GST Amount is calculated from individual line(s)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI18011283/Uvbn2

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 24-07-2018



Code : GAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 678P	Veh. Inspected	SLH 878A
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000003275	Excess (\$)	0.00
Assign From	KELVYNA	Assign Date	21/06/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA CIVIC (A)	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MRHFC5650GT000307	Colour	SILVER
Odometer	34187	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R16	HANKOOK	6 mm
L/H Front Tyre	215/55 R16	HANKOOK	6 mm
R/H Rear Tyre	215/55 R16	HANKOOK	6 mm
L/H Rear Tyre	215/55 R16	HANKOOK	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	02/06/2018	Inspection Date	02/07/2018
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 878A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
14	CLIPBUMPER (SN)	NECESSARY	21.00	21.00
1	FACE ASSY,RR BUMPER (SN)	DISTORTED	462.90	462.90
1	EMBLEM SETRR (SN)	NOT NECESSARY	8.62	-
1	EMBLEMRR (SN)	NOT NECESSARY	7.95	-
1	BEAM COMPRR.BUMPER (SN)	NOT NECESSARY	129.75	-
1	GARNISH,RR BUMPER LOWER (SN)	NOT NECESSARY	28.65	-
1	GARNISH,RR BUMPER SIDE (SN)	GRAZED	5.70	5.70
1	SPACERR RR BUMPER SIDE (SN)	BENT	8.62	8.62
1	SPACERL RR BUMPER SIDE (SN)	NOT NECESSARY	8.62	-
1	REFLECTOR ASSYR.RR (SN)	NOT NECESSARY	5.25	-
1	BRACKETR.RR BUMPER SIDE (SN)	NOT NECESSARY	1.65	-
1	TAILLIGHT ASSYR (SN)	BROKEN	190.35	190.35
1	LIGHT ASSYR.LID (SN)	NOT NECESSARY	89.02	-
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			1,068.08	708.57
LABOUR				
INSPECT RR LIGHTING MECHANISMS.PERFORM WATER.			180.00	80.00
REMOVE & RENEW REVERSE SENSORS-4 PCS.			240.00	130.00
STRAIGHTEN ALIGN RR PANEL RR R FENDER & RENEW DAMAGE PARTS.			1,800.00	560.00
SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.BUMPER & FENDER RH ONLY.			2,700.00	900.00
			4,920.00	1,670.00
GRAND TOTAL			5,988.08	2,378.57
RECOMMENDED COST OF REPAIRS				2,378.57

Report Ref No. CS/GAI18011283/Uvbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : GREAT AMERICAN INSURANCE
3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190
Registration No : SLH878A
Chassis No : MRHFC5650GT000307
Model : CIVIC 1.6 VTI YM2016
Owner's Name : TOH WONG LIM
Ins Policy No. : SD16V13008/VPC2/R00
Date of Accident : 4/6/2018

Document No. : SQT18002525 **Page** 2
Date : 20. Jun 2018
Customer No. : WZG001
Svc Advisor : ARY CHUA WAI NGEE
Engine No : R16B21600434
Date | Time : 20. Jun 2018 1:19:42 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Survey By							
Date & Time							
Excess							
Status							
Signature							
Total Amount					5,988.08	419.16	6,407.24
Total (Inclusive of GST)							<u>6,407.24</u>

Printed on 20/6/2018 2:07:30 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)