

ASS. REC. BY:

REF:

LPC /

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

21/6 File pass to Catherine

11 Sep @ 21501

CRAB: 41, 42A.98 (95%)

Veh No:

SHD 9851K

Yr Regn:

05, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude c.c. 1995

Colour:

M. White 1Pw

A/C: Insured / Std / NI / NA

Sp. Reading

383974

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL15AUC 277247

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: N/A / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Giti

Front

R/Bal.

P

mm

Rear

R/Bal.

7

mm

L/Bal.

P

mm

L/Bal.

7

mm

D.O.A.

13/6/18

D.O.I.

20/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Frt

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fixtures

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC3/LPC18011285/Kjb3		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 21-06-2018		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKZ 9592G	Veh. Inspected	SHD 9851K	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	21/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/06/2018	Inspection Date	18/06/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/LPC18011285/Kjb3

Date: 21.06.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD9851K


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 18.06.2018 at the premises of M/s Trans-cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	43,574.95
Revised Estimate Amount	: S\$	2,150.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
O/S Front portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9851K**AAD1806-111***Not Authored**1/1 Sep 8*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHD 9851K
VF1ABL15AUC277247
RENAULT
LATITUDE
13.6.2018
LONPAC

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Buy 1st</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75
1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68
1	BUMPER RETAINER FRT RH	\$	<i>SL</i> 150.77
1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88
1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83
1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80
1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i> 207.21
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08
1	HEADLAMP RH	\$	<i>SL</i> 1,184.43
1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15
1	FENDER PANEL FRT RH	\$	<i>R</i> 783.83 ✓
1	WHEELARCH FRT RH	\$	<i>SL</i> 278.84
1	FENDER BRACKET LOWER RH	\$	<i>SL</i> 15.79
1	FENDER INSULATOR RH	\$	<i>SL</i> 130.84
1	DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66
1	RADIATOR GRILLE	\$	<i>SL</i> 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 225.36
1	RADIATOR GRILLE FRAME	\$	<i>SL</i> 1,353.75
1	RADIATOR FAN COWLING	\$	<i>SL</i> 820.54
1	RADIATOR FAN MOTOR LH	\$	<i>SL</i> 967.36
1	RADIATOR FAN MOTOR RH	\$	<i>SL</i> 1,479.46
1	FRAME FULL SUPPORT PANEL	\$	<i>SL</i> 615.90
1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79
1	DOOR MIRROR ASSY RH	\$	<i>SL</i> 1,483.40
1	DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66
1	BONNET	\$	<i>R</i> 1,941.63
1	BONNET INSULATOR	\$	<i>SL</i> 405.73
1	BONNET STRUT LH	\$	<i>SL</i> 88.61
1	BONNET STRUT RH	\$	<i>SL</i> 88.61

Trans-cab Auto Services Pte Ltd

AAD1806-111

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9851K

1	BONNET HINGE LH	\$	R 348.31	}	X
1	BONNET HINGE RH	\$	R 348.31		
1	BONNET LOCK	\$	R 305.48		
1	BONNET CABLE	\$	S 119.19		
1	BONNET CABLE COVER	\$	S 161.03		
1	BONNET SEAL OUTER	\$	S 92.36		
1	BONNET SEAL INNER	\$	S 157.28		
1	SUBFRAME OUTER FRT	\$	S 2,652.45		
1	SUBFRAME BRACKET OUTER LH	\$	R 92.36		
1	SUBFRAME BRACKET OUTER RH	\$	R 92.36		
1	ENGINE UNDERTRAY	\$	S 564.98		
1	A/C CONDENSER	\$	S 2,020.37		
1	A/C CONDENSER GARNISH LH UPPER	\$	S 39.67		
1	A/C CONDENSER GARNISH RH UPPER	\$	S 39.67		
1	A/C CONDENSER GARNISH LH	\$	S 58.81		
1	A/C CONDENSER GARNISH RH	\$	S 59.60		
1	LOWER ARM RH	\$	S 685.76		
1	KUNCKLE ARM RH	\$	S 846.98		
1	ABSORBER FRT RH	\$	S 360.54		
1	STABILIZER BAR FRT	\$	S 604.65		
1	DRIVESHAFT RH	\$	R 1,747.45		
1	WIPER RESERVOIR	\$	S 348.25		
1	WIPER RESERVOIR NECK	\$	S 136.11		
1	WIPER RESERVOIR MOTOR	\$	S 270.06		

TOTAL \$ 35,626.53

10% \$ 3,562.65

\$ 32,063.87 91

Specical Nett

1SET	BUMPER CLIP FRT	\$	R 66.00	}	X
1	BUMPER BRACKET CLIP FRT RH	\$	R 12.00		
1	BUMPER SUPPORT CLIP FRT RH	\$	R 10.50		
1SET	BUMPER GRILLE LOWER CLIP	\$	R 69.00		
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	R 70.00		
2	FRAME FULL SUPPORT PANEL NUT	\$	S 20.00		
2	FRAME FULL SUPPORT PANEL STUD	\$	S 30.00		

Trans-cab Auto Services Pte Ltd

AAD1806-111

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9851K

1SET	WHEELARCH CLIP FRT RH	\$	<i>nn</i> 30.50 X
6	BONNET INSULATOR CLIP L70Y	\$	<i>nn</i> 7.30 X
2	BONNET STRUT L70Y	\$	<i>nn</i> 88.61 X
2	BONNET CABLE CLIP L70Y	\$	<i>nn</i> 6.31 X
2	BONNET CABLE COVER SCREW L70Y	\$	<i>nn</i> 10.85 X

TOTAL	\$	421.08
--------------	-----------	---------------

TOTAL PARTS	\$	32,484.95
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	<i>3000</i> 4,500.00
✓ Putty and spray painting of the affected portion.	\$	4,000.00 <i>4000</i>
To rust-proofing of the affected areas.	\$	170.00 <i>300</i>
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 X
To Check Electrical Lighting Concerned.	\$	<i>nn</i> 170.00 <i>150</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	<i>nn</i> 380.00 X

Trans-cab Auto Services Pte Ltd**AAD1806-111**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9851KTo replace, refix and top up coolant for radiator \$ *nn* 170.00 XTo vacuum, replace, refix and recharge Air
Intercooler \$ *nn* 170.00 X**TOTAL** \$ 11,090.00**Over All Total** \$ 43,574.95**LUMP SUM (REPAIR DAY)**~~15~~ DAYS*2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD9851K
Vehicle to be Exported:	Yes
Intended De-registration Date:	13 Jun 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C001035
Chassis No.:	VF1ABL15AUC277247
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	09 May 2014
First Registration Date:	09 May 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 May 2022
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	08 May 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$60,414.00
COE Rebate Amount:	\$29,467.00
Total Rebate Amount:	\$38,840.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 13 Jun 2018

OK

Shu Pei (LKKAUTO)

From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 22 June 2018 8:48 AM
To: Shu Pei (LKKAUTO)
Cc: MT_Claim_SG; Admin A; Joy Irene (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving SKZ9592G (OI : LPC - 18/18/18/VP05/020676) AND SHD9851K (TP : LKK REF - CC3/LPC18011285/Kjb3) on 13.06.2018
Attachments: SKZ9592G 130618.PDF

Dear Shu Pei

Please see attached for our Insured's GIA report that you have requested.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Thursday, 21 June, 2018 7:15 PM
To: GERALD POH WEE BIN; ERIC WOO JUN KIAT; ONG LI LI
Cc: MT_Claim_SG; Admin A; Joy Irene (LKKAUTO)
Subject: Direct Settlement - Accident Involving SKZ9592G (OI : LPC - TBA) AND SHD9851K (TP : LKK REF - CC3/LPC18011285/Kjb3) on 13.06.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHD 9851K at M/s Trans-cab Auto Services Pte Ltd.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP's GIA report

Our case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeit@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Friday, 28 June 2019 6:14 PM
To: ONG LI LI
Cc: MT_Claim_SG; Admin A; Vic (LKKAuto)
Subject: MANDATE REQUEST: SKZ 9592G ON 13/06/2018 (TRANS-CAB SHD 9851K)
Attachments: SURVEY REPORT.pdf; SURVEY PHOTOS.pdf; LOD.pdf; TP VIDEO.mp4

Ref: 18/18/18/VP05/020676

Dear Li Li,

This is cutting lane scenario where our insured driver hit TP whilst cutting lane.

Video link : <http://www.transcab.com.sg/Files/SHD9851K.mp4>

Liability is not in our favour.

Summary to offer to repairer M/s **TRANS-CAB AUTOS SERVICES** is as follows:

	TP CLAIMED	OUR REVISED TO OFFER
Cost of Repairs	\$ 43,574.98 (estimate)	\$ 2,300.50 GST
Loss of Rental	\$ 297.96 (\$99.32 x 3 days)	\$ 297.96 (\$99.32 x 3 days)
Loss of Income	\$ 150.00 (\$50 x 3 days)	\$ 150.00 (\$50 x 3 days)
LTA Search Fee	\$ 7.49	\$ 7.49
TOTAL	\$ 44,030.43	\$ 2,755.95

Relevant supporting claim documents attached for your perusal and reference.

For your approval.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC3/LPC18011285/Khb3s2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 17-09-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKZ 9592G	Veh. Inspected	SHD 9851K
Policy No.	Z18VP05017153	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020676	Excess (\$)	0.00
Assign From		Assign Date	20/06/2018

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC277247	Colour	METALLIC WHITE / RED
Odometer	383974	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	GITI	8 mm
L/H Front Tyre	215/60R16	GITI	8 mm
R/H Rear Tyre	215/60R16	GITI	7 mm
L/H Rear Tyre	215/60R16	GITI	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/06/2018	Inspection Date	20/06/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9851K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER FRT	BUCKLED / DENTED	1,259.42	1,259.42
1	BUMPER SPOILER FRT	SERVICEABLE	181.75	-
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT RH	SERVICEABLE	150.77	-
1	BUMPER SPOILER FRT	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	HEADLAMP RH	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	152.15	-
1	FENDER PANEL FRT RH	BENT	783.83	783.83
1	WHEELARCH FRT RH	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER RH	SERVICEABLE	15.79	-
1	FENDER INSULATOR RH	SERVICEABLE	130.84	-
1	DOOR PANEL FRT RH	TO REPAIR SEE LABOUR	2,844.66	-
1	RADIATOR GRILLE	SERVICEABLE	1,707.78	-
1	RADIATOR GRILLE BADGE 'RENAULT'	SERVICEABLE	225.36	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,353.75	-
1	RADIATOR FAN COWLING	SERVICEABLE	820.54	-
1	RADIATOR FAN MOTOR LH	SERVICEABLE	967.36	-
1	RADIATOR FAN MOTOR RH	SERVICEABLE	1,479.46	-
1	FRAME FULL SUPPORT PANEL	SERVICEABLE	615.90	-
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	-
1	DOOR MIRROR ASSY RH	SERVICEABLE	1,483.40	-
1	DOOR PANEL FRT RH	TO REPAIR SEE LABOUR	2,844.66	-

Report Ref No. CC3/LPC18011285/Khb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET	TO REPAIR SEE LABOUR	1,941.63	-
1	BONNET INSULATOR	SERVICEABLE	405.73	-
1	BONNET STRUT LH	SERVICEABLE	88.61	-
1	BONNET STRUT RH	SERVICEABLE	88.61	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET LOCK	TO REPAIR SEE LABOUR	305.48	-
1	BONNET CABLE	SERVICEABLE	119.19	-
1	BONNET CABLE COVER	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER	SERVICEABLE	92.36	-
1	BONNET SEAL INNER	SERVICEABLE	157.28	-
1	SUBFRAME OUTER FRT	SERVICEABLE	2,652.45	-
1	SUBFRAME BRACKET OUTER LH	TO REPAIR SEE LABOUR	92.36	-
1	SUBFRAME BRACKET OUTER RH	TO REPAIR SEE LABOUR	92.36	-
1	ENGINE UNDERTRAY	SERVICEABLE	564.98	-
1	A/C CONDENSER	SERVICEABLE	2,020.37	-
1	A/C CONDENSER GARNISH LH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH RH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH LH	SERVICEABLE	58.81	-
1	A/C CONDENSER GARNISH RH	SERVICEABLE	59.60	-
1	LOWER ARM RH	SERVICEABLE	685.76	-
1	KNUCKLE ARM RH	SERVICEABLE	846.98	-
1	ABSORBER FRT RH	SERVICEABLE	360.54	-
1	STABILIZER BAR FRT	SERVICEABLE	604.65	-
1	DRIVESHAFT RH	TO REPAIR SEE LABOUR	1,747.45	-
1	WIPER RESERVOIR	SERVICEABLE	348.25	-
1	WIPER RESERVOIR NECK	SERVICEABLE	136.11	-
1	WIPER RESERVOIR MOTOR	SERVICEABLE	270.06	-

Report Ref No. CC3/LPC18011285/Khb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-3,562.69	-204.33
			32,063.88	1,838.92
	SPECIAL NETT ITEMS			
1	SET BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	SERVICEABLE	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	SERVICEABLE	30.00	-
1	SET WHEELARCH CLIP FRT RH (SN)	NOT NECESSARY	30.50	-
6	BONNET INSULATOR CLIP L70Y (SN)	NOT NECESSARY	7.30	-
2	BONNET STRUT L70Y (SN)	NOT NECESSARY	88.61	-
2	BONNET CABLE CLIP L70Y (SN)	NOT NECESSARY	6.31	-
2	BONNET CABLE COVER SCREW L70Y (SN)	NOT NECESSARY	10.85	-
			421.07	66.00
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL PF PARTS, ADJUST AND REALIGN THE SAME. INCLSUIVE OF THE REPAIR OF BUMPER BEAM FRT, HEADLAMP PANEL FRT RH, DOOR PANEL FRT RH, FRAME FULL SUPPORT BRACKET, DOOR PANEL FRT RH, BONNET, BONNET HINGE LH, BONNET HINGE RH, BONNET LOCK, SUBFRAME BRACKET OUTER LH, SUBFRAME BRACKET OUTER RH AND DRIVESHAFT RH.		4,500.00	300.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,000.00	440.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE, RIM AND WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	15.00

Report Ref No. CC3/LPC18011285/Khb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF FRONT FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF BONNET FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.	NOT NECESSARY	380.00	-
	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.	NOT NECESSARY	170.00	-
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER.	NOT NECESSARY	170.00	-
			11,090.00	785.00
GRAND TOTAL			43,574.95	2,689.92
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,150.00

Report Ref No. CC3/LPC18011285/Khb3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.