

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9851K**AAD1806-111***Not withstanding**11 Sep 8*

Vehicle No.:	SHD 9851K
Chassis No.:	VF1ABL15AUC277247
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	13.6.2018
Third Party Insurer :	LONPAC

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Bu 1st</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75
1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68
1	BUMPER RETAINER FRT RH	\$	<i>SL</i> 150.77
1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88
1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83
1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80
1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i> 207.21
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08
1	HEADLAMP RH	\$	<i>SL</i> 1,184.43
1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15
1	FENDER PANEL FRT RH	\$	<i>R</i> 783.83 ✓
1	WHEELARCH FRT RH	\$	<i>SL</i> 278.84
1	FENDER BRACKET LOWER RH	\$	<i>SL</i> 15.79
1	FENDER INSULATOR RH	\$	<i>SL</i> 130.84
1	DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66
1	RADIATOR GRILLE	\$	<i>SL</i> 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 225.36
1	RADIATOR GRILLE FRAME	\$	<i>SL</i> 1,353.75
1	RADIATOR FAN COWLING	\$	<i>SL</i> 820.54
1	RADIATOR FAN MOTOR LH	\$	<i>SL</i> 967.36
1	RADIATOR FAN MOTOR RH	\$	<i>SL</i> 1,479.46
1	FRAME FULL SUPPORT PANEL	\$	<i>SL</i> 615.90
1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79
1	DOOR MIRROR ASSY RH	\$	<i>SL</i> 1,483.40
1	DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66
1	BONNET	\$	<i>R</i> 1,941.63
1	BONNET INSULATOR	\$	<i>SL</i> 405.73
1	BONNET STRUT LH	\$	<i>SL</i> 88.61
1	BONNET STRUT RH	\$	<i>SL</i> 88.61

Trans-cab Auto Services Pte Ltd**AAD1806-111**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9851K

1	BONNET HINGE LH	\$	R 348.31	}	X
1	BONNET HINGE RH	\$	R 348.31		
1	BONNET LOCK	\$	R 305.48		
1	BONNET CABLE	\$	S 119.19		
1	BONNET CABLE COVER	\$	S 161.03		
1	BONNET SEAL OUTER	\$	S 92.36		
1	BONNET SEAL INNER	\$	S 157.28		
1	SUBFRAME OUTER FRT	\$	S 2,652.45		
1	SUBFRAME BRACKET OUTER LH	\$	R 92.36		
1	SUBFRAME BRACKET OUTER RH	\$	R 92.36		
1	ENGINE UNDERTRAY	\$	S 564.98		
1	A/C CONDENSER	\$	S 2,020.37		
1	A/C CONDENSER GARNISH LH UPPER	\$	S 39.67		
1	A/C CONDENSER GARNISH RH UPPER	\$	S 39.67		
1	A/C CONDENSER GARNISH LH	\$	S 58.81		
1	A/C CONDENSER GARNISH RH	\$	S 59.60		
1	LOWER ARM RH	\$	S 685.76		
1	KUNCKLE ARM RH	\$	S 846.98		
1	ABSORBER FRT RH	\$	S 360.54		
1	STABILIZER BAR FRT	\$	S 604.65		
1	DRIVESHAFT RH	\$	R 1,747.45		
1	WIPER RESERVOIR	\$	S 348.25		
1	WIPER RESERVOIR NECK	\$	S 136.11		
1	WIPER RESERVOIR MOTOR	\$	S 270.06		

TOTAL	\$	35,626.53
10%	\$	3,562.65
	\$	32,063.87

Special Nett

1SET	BUMPER CLIP FRT	\$	R 66.00	}	X
1	BUMPER BRACKET CLIP FRT RH	\$	R 12.00		
1	BUMPER SUPPORT CLIP FRT RH	\$	R 10.50		
1SET	BUMPER GRILLE LOWER CLIP	\$	R 69.00		
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	R 70.00		
2	FRAME FULL SUPPORT PANEL NUT	\$	S 20.00		
2	FRAME FULL SUPPORT PANEL STUD	\$	S 30.00		

Trans-cab Auto Services Pte Ltd

AAD1806-111

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9851K

1SET	WHEELARCH CLIP FRT RH	\$	nn 30.50 X
6	BONNET INSULATOR CLIP L70Y	\$	nn 7.30 X
2	BONNET STRUT L70Y	\$	nn 88.61 X
2	BONNET CABLE CLIP L70Y	\$	nn 6.31 X
2	BONNET CABLE COVER SCREW L70Y	\$	nn 10.85 X

TOTAL	\$	421.08
--------------	-----------	---------------

TOTAL PARTS	\$	32,484.95
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00 ³⁰⁰¹
Putty and spray painting of the affected portion.	\$	4,000.00 ⁴⁴⁰¹
To rust-proofing of the affected areas.	\$	170.00 ³⁰¹
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To Check Electrical Lighting Concerned.	\$	nn 170.00 ¹⁵¹
To transfer of front fender fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	nn 380.00 X

Trans-cab Auto Services Pte Ltd

AAD1806-111

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9851KTo replace, refix and top up coolant for radiator \$ *nn* 170.00 *X*To vacuum, replace, refix and recharge Air
Intercooler \$ *nn* 170.00 *X***TOTAL \$ 11,090.00****Over All Total \$ 43,574.95****LUMP SUM (REPAIR DAY)**~~15 DAYS~~*2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: