

23/03/2012

ASS. REC. BY:

REF: CS/FCI18011288 / R/sd3n2 Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person): Karen Tan of FCI Date/Time: 21/06/18 @ 2:41pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLU 8863X Insured: SHA 3486L

at Workshop m/s: Mova Automotive Tel: 6272 3892

of Bk 1008, Bukit Meruh Lane 3 # 01-04

Policy No: Claim No: D18004785MPSH

Sum Insured: Excess:

Make of Veh: D.O.A. 14/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS (up) 25062018 @ after 12pm H.O.D. Endorsement:

Date/Time: 3:49pm @ 21/6/18 Person Contacted: Nitha Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SLU 8863X - X
	SHA 3486L - CS/FCI18003455 / Dvd3n2 DOA: 17/02/2018
24/06/18 @ 17:09 p.m.	revised PA to Karen via email.


Farou

REF: FCI

71ft2

ASSIGNMENT

From:
 Date: 25/06/2018
 Estimated Cost:
 OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLU 8863X
 at Workshop n/w: Mova Automotive
 of 31k 1008, Bkt Meruh Lane 3# 0104
 Insured:
 Policy No:
 Claims No:
 Sum Insured:
 (Client's Record) after 12pm
 Make of Veh:



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: days Res.: Yes or No
 Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{lup}

Date:
 Person Contacted:
 Vehicle: IN / OUT

Veh No: SLU8863X Yr Regn: 2017 / DRC
 Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Hyundai ELANTRA 1.6 cc 1591
 Colour: GREY A/C: Insured / Std / NI / NA
 Sp. Reading: 6803 T/Radio: Insured / Std / NI / NA
 Eng/No:
 C/No: KM H0841CM Ju 59 2195
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65R15
 R:
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or NEXEN
 Front:
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A: 14/06/18 D.O.I: 25/06/18
 Survey held at: Mova (AM)
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 Rear N/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
 06/09/18 Confirmed P/P \$ 1,443.20 @ 3 days with Result.
 (\$392.00 Red - 13%)

RECEIVED 12 SEP 2018

[Signature]
 6/9/2018

Date/Time: File Pass to? 12/09/18
 1) Typist
 Date/Time: File Return to?
 2)

☐ : Preli. Report
 ☒ : Final Report

Days Of Repair: 3
 Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$
 ☐ Interview (\$
 ☐ Tech. Invs (\$
 ☐ Weekend (\$

Survey Fee:
 Transportation:
 S + RS: \$
 Photos:
 Other:

Report Format :
 Lump Sum / L.B.T: (\$ 1,443.20 P/P)

110
50
50
44
254

TOTAL



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004785MFSH

Date: 27 June 2018

Our Ref: CS/FCI18011288/R1sd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLU 8863X .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 25/06/2018 at the premises of M/s Mova Automotive Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 2,135.20</u> .
Revised Estimate Amount	: <u>S\$ 1,146.00</u> .
"Check" Items Amount	: <u>S\$ 529.60</u> .
Market Value	: <u>S\$</u> .
LTA Reimbursement Value	: <u>S\$</u> .
Nett Value	: <u>S\$</u> .

Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 3 Days

Yours faithfully,
Mohammed Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	18-06-2018	Our Ref No. D18004785MFSH
Accident Date	14-06-2018	Claim Type. Third Party
Insured Vehicle	SHA3486L	Third Party Vehicle. SLU8863X
Survey Location	BLOCK 1008 BUKIT MERAH LANE 3 #01-04/06/08	
Contact Person.	NITHA	
Contact No.	62723892/ 0	Fax No. 62708314
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MOVA AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241514)



PRI Documents



Close



PRI Header Details

Claim No	D18004785MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & MOVA AU
Workshop Name	MOVA AUTOMOTIVE PTE LTD (Contact Person : NITHA)	Survey Location & Contact Details	BLOCK 1008 BUKIT MERAH LANE 3 #01-04/06/08 Mobile: 0 , Phone: 62723892 , Fax: 62708314 EmailId: NITHA@MOVA.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA3486L	TP Vehicle No	SLU8863X
PRI Recieved Date	20-06-2018 08:27:23 PM	Surveyor Appointed Date	21-06-2018 02:40:01 PM	Surveyor Accept Date	21-06-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	21-06-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 12 September 2018 11:57 AM
To: 'Jacelyn'
Cc: 'SUR'; 'Rasul (LKKAuto)'
Subject: RE: FINALIZATION: SLU8863X - HYUNDAI ELANTRA 1.6 (DOA 14.06.2018)

Hi Jacelyn,

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jacelyn [<mailto:jacelyn@movasg.com>]
Sent: Wednesday, 12 September 2018 11:59 AM
To: 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>
Cc: 'SUR' <sur@lkkauto.com>; 'Rasul (LKKAuto)' <Rasul@lkkauto.com>
Subject: RE: FINALIZATION: SLU8863X - HYUNDAI ELANTRA 1.6 (DOA 14.06.2018)

Dear Shirley,

Amount confirmed at \$1,743.20 (part by part). Thank you.

Best Regards,
Jacelyn Ooi
Estimator
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]
Sent: Wednesday, 12 September 2018 11:23 AM
To: 'Jacelyn'
Cc: 'SUR'; 'Rasul (LKKAuto)'
Subject: RE: FINALIZATION: SLU8863X - HYUNDAI ELANTRA 1.6 (DOA 14.06.2018)

Dear Jacelyn,

As spoken, enclosed herewith estimate marked.

Please re-confirm the final figure.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]
Sent: Friday, 7 September 2018 8:59 AM
To: 'Jacelyn' <jacelyn@movs.com.sg>
Cc: 'SUR' <sur@lkkauto.com>; 'Rasul (LKKAuto)' <Rasul@lkkauto.com>
Subject: RE: FINALIZATION: SLU8863X - HYUNDAI ELANTRA 1.6 (DOA 14.06.2018)

Dear Jacelyn,

Please re-confirmed final fig of \$1,743.20 (part by part) @ 3 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]
Sent: Thursday, 6 September 2018 11:07 AM
To: 'Jacelyn' <jacelyn@movs.com.sg>
Cc: 'SUR' <sur@lkkauto.com>; 'Rasul (LKKAuto)' <Rasul@lkkauto.com>
Subject: RE: FINALIZATION: SLU8863X - HYUNDAI ELANTRA 1.6 (DOA 14.06.2018)

Dear Jacelyn,

Please re-confirmed final fig of \$1,593.20 (part by part) @ 3 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jacelyn [<mailto:jacelyn@movs.com.sg>]
Sent: Tuesday, 4 September 2018 5:34 PM
To: 'Rasul (LKKAuto)' <Rasul@lkkauto.com>

Cc: 'SUR' <sur@lkkauto.com>

Subject: FW: FINALIZATION: SLU8863X - HYUNDAI ELANTRA 1.6 (DOA 14.06.2018)

Dear Rasul,

Please help to finalize the below case. Thank you

Best Regards,

Jacelyn Ooi

Estimator

Mova Automotive Pte Ltd

Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

From: Jacelyn [<mailto:jacelyn@moval.com.sg>]

Sent: Thursday, 5 July 2018 6:03 PM

To: 'Rasul (LKK Auto)'

Subject: FINALIZATION: SLU8863X - HYUNDAI ELANTRA 1.6 (DOA 14.06.2018)

Dear Rasul,

Please find the attached 'Marking Estimate', & 'After-Paint' photographs for your reference.

We propose the finalize amount at Part-By-Part \$ 1,843.20. Kindly revert.

*Remarks: Resurvey (check item & before paint) done by Taufikh on 26.06.2018.

Best Regards,

Jacelyn Ooi

Estimator

Mova Automotive Pte Ltd

Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 27 June 2018 5:09 PM
To: 'Nivitha (LKK Auto)'; 'Claim Workflow System'; ASSIGNMENTS@LKKAUTO.COM
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; "SUR"
Subject: RE: SURVEY ASSESSMENT - D18004785MFSH/1
Attachments: SLU 8863X - Preli Advise.pdf

Dear Karen,

Enclosed herewith preliminary advice of SLU 8863X.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 21 June 2018 3:52 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; "SUR" <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004785MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Thursday, 21 June 2018 2:39 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004785MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Main Office:

 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel : (65) 6476 3333
 Fax : (65) 6271 5891
 www.mova.com.sg

Workshop Dept:

 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

 Tel : (65) 6272 3892
 Fax : (65) 6270 8314

 Co. Reg: 198904033G
 GST Reg: M2-0088864-2

Estimate

20/06/2018

MS FIRST CAPITAL INSURANCE LIMITED
 36 Robinson Road
 #16-01 City House
 Singapore 068877.

Page # :- 1

Veh # :- SLU8863X

Veh Model :- HYUNDAI ELANTRA

Estimate# :- CK417590

Claim # :- 70/CK131862

ACC. Date :- 14/06/18

Terms :- C.O.D Days

Remarks :- MFG 16 Dec 2017 (2017)

Attention :- XA026

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BUMER	1 PC	479.00	479.00
2.	REAR BUMPER LOWER LID	1 PC	281.00	281.00
3.	REAR BUMPER REFLECTOR LH	1 PC	78.00	78.00
4.	REAR BUMPER SIDE RETAINER LH	1 PC	56.00	56.00
5.	REAR BUMPER SIDE RETAINER RH	1 PC	56.00	56.00
6.	REAR BUMPER REINFORCEMENT	1 PC	309.00	309.00
7.	REAR BUMPER CLIP	10 PC	3.50	35.00
LIST TOTAL S\$				1,294.00
20% DISCOUNT S\$				-258.80
				1,035.20
SPECIAL NET ITEMS :				
1.	REVERSE SENSOR	1 PC	220.00	220.00
SPECIAL NET TOTAL S\$				220.00
LABOUR :				
TO REMOVE & REPLACE REVERSE SENSOR				
TO KNOCK & STRAIGHTEN ON END PANEL. TO REMOVE				
REPLACE DAMAGED ITEMS. REALIGN CONNECTION				
TO SPRAY PAINT ON REPAIRED AREAS				
LABOUR TOTAL S\$				880.00

RASU

4p 90010068

3 days

P/P

25/06/18 @ 1415

Resurvey by paint

Consultants hence notify
 owner of the following:
 Survey before/after spray painting
 Display damaged part(s) during resurvey
 All prices are subject to confirmation
 Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 2,135.20

GST @ 7 % 149.46

AMOUNT DUE S\$ 2,284.66

 Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

* For
Record
Propose

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 100B,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0098864-2

Estimate

20/06/2018

MS FIRST CAPITAL INSURANCE LIMITED
36 Robinson Road
#16-01 City House
Singapore 068877.

Page # :- 1

Veh # :- SLU8863X

Veh Model :- HYUNDAI ELANTRA

Estimate# :- CK417590

Claim # :- 70/CK131867

ACC. Date :- 14/06/18

Terms :- C.O.D Days

Remarks :- MFB 16 Dec 2017 (2017)

Attention :- XA026

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BUMER	1 PC	479.00	479.00
2.	REAR BUMPER LOWER LID	1 PC	281.00	281.00
3.	REAR BUMPER REFLECTOR LH	1 PC	78.00	78.00
4.	REAR BUMPER SIDE RETAINER LH	1 PC	56.00	56.00
5.	REAR BUMPER SIDE RETAINER RH	1 PC	56.00	56.00
6.	REAR BUMPER REINFORCEMENT	1 PC	309.00	309.00
7.	REAR BUMPER CLIP	10 PC	3.50	35.00
LIST TOTAL S\$				1104.00
20% DISCOUNT S\$				- 220.80
				883.20
SPECIAL NET ITEMS :				
1.	REVERSE SENSOR	1 PC	220.00	220.00
SPECIAL NET TOTAL S\$				220.00
LABOUR :				
TO REMOVE & REPLACE REVERSE SENSOR				
TO KNOCK & STRAIGHTEN ON END PANEL TO REMOVE REPLACE DAMAGED ITEMS. REALIGN CONNECTION				
TO SPRAY PAINT ON REPAIRED AREAS				
LABOUR TOTAL S\$				760.00
				880.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 2,135.20

GST @ 7 % 149.46

AMOUNT DUE S\$ 2,284.66

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18011288/R1sd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 18-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3486L	Veh. Inspected	SLU 8863X	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18004785MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	21/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI ELANTRA 1.6	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KMHD841CMJU592195	Colour	GREY	
Odometer	6803	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	NEXEN	6 mm	
L/H Front Tyre	195/65 R15	NEXEN	6 mm	
R/H Rear Tyre	195/65 R15	NEXEN	6 mm	
L/H Rear Tyre	195/65 R15	NEXEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/06/2018	Inspection Date	25/06/2018	
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 8863X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	479.00	479.00
1	REAR BUMPER LOWER LID	SCRATCHED	281.00	281.00
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	78.00	-
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	56.00	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	56.00	-
1	REAR BUMPER REINFORCEMENT	BENT	309.00	309.00
10	REAR BUMPER CLIP @\$3.50	NECESSARY	35.00	35.00
	LESS 20% DISCOUNT		-258.80	-220.80
			1,035.20	883.20
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR (SN)	NOT WORKING	220.00	200.00
			220.00	200.00
	<u>LABOUR</u>			
	TO REMOVE & REPLACE REVERSE SENSOR.		80.00	60.00
	TO KNOCK & STRAIGHTEN ON END PANEL TO REMOVE		400.00	300.00
	REPLACE DAMAGED ITEMS. REALIGN CONNECTION.		400.00	300.00
	TO SPRAY PAINT ON REPAIRED AREAS.		880.00	660.00
	GRAND TOTAL		2,135.20	1,743.20
	RECOMMENDED COST OF REPAIRS			1,743.20

Report Ref No. CS/FCI18011288/R1sd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.