

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SH 3805Hat Workshop m/s Tan Lim

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen e Consistent?: Yes or NoEst. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SH 3805HYr Regn: 11/14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: Hyundai Elantra C.C. 1591Colour: yellow / black A/C: Insured / Std / Nil / NASp. Reading: 198705 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: KMHDM 41 CMEN 293993Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65u15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 13/6/18D.O.I. 21/6/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

26-6-18 L/S \$1400.xxR (\$1,756.48/56%)

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

Resurvey No. of Trip: _____

1)

☐ : Final Report

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S → RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC6/LPC18011295/Ujb3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 21-06-2018	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY (FOLLOW THROUGH INSPECTION)				
Insured Veh.	SLW 9290G	Veh. Inspected	SH 3805H	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	21/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/06/2018	Inspection Date	21/06/2018	
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933. TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC6/LPC18011295/Ujb3

Date: 22.06.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SH3805H

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21.06.2018 at the premises of M/s Tan Lim Motor Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	3,156.48
Revised Estimate Amount	: S\$	1,781.60
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Front Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Shu Pei (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 25 June 2018 9:47 AM
To: Shu Pei (LKKAUTO)
Cc: MT_Claim_SG; Joy Irene (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving SLW9290G (OI : LPC - TBA) AND SH3805H (TP : LKK REF - CC6/LPC18011295/Ujb3) on 13.06.2018
Attachments: 25062018094313.pdf

Our Ref : 18/18/18/VP05/020675

Dear Shu Pei,

Attached copy of insured's GIA report for your attention.

Please note that our insured is also claiming against the third party.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Monday, 25 June, 2018 9:36 AM
To: GERALD POH WEE BIN; ERIC WOO JUN KIAT; ONG LI LI
Cc: MT_Claim_SG; Admin A; Joy Irene (LKKAUTO)
Subject: Direct Settlement - Accident Involving SLW9290G (OI : LPC - TBA) AND SH3805H (TP : LKK REF - CC6/LPC18011295/Ujb3) on 13.06.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SH 3805H at M/s Tan Lim Motor Pte Ltd.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP's GIA report

Our case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeis@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Singapore NRIC

Owner ID:

2717H

Vehicle Details

Vehicle No.:

SH3805H

Vehicle to be Exported:

No

Intended De-registration Date:

14 Jun 2018

Vehicle Make:

HYUNDAI

Vehicle Model:

ELANTRA 1.6 AT ABS D/AB 2WD 4DR

Primary Colour:

Black

Manufacturing Year:

2014

Engine No.:

G4FGEU088055

Chassis No.:

KMHDH41CMEU293993

Maximum Power Output:

97.0 kW (130 bhp)

Open Market Value:

\$11,346.00

Original Registration Date:

12 Nov 2014

First Registration Date:

12 Nov 2014

Transfer Count:

0

Actual ARF Paid:

\$11,346.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

11 Nov 2022

PARF Rebate Amount:

\$8,509.00

Intended COE Rebate Details

COE Expiry Date:

11 Nov 2022

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$51,337.00

COE Rebate Amount:

\$28,296.00

Total Rebate Amount:**\$36,805.00****Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 14 Jun 2018

OK



Lonpac Insured's Veh No : SLW9290G
Date of Accident : 13 June 2018

TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Mr Lim Ban Hup

Date : 14 June 2018

Estimate To Repair SH3805H - Hyundai ELANTRA 1.6 AT ABS D/AB 2WD 4D
Chassis No : KMHDH41CMEU293993

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	front bumper	\$ 418.00
02	1 pc	front bumper reinforcement	\$ 515.00
03	1 pc	front bumper absorber foam	\$ 111.00
04	2 ps	front bumper side retainers @ \$17.00	\$ 34.00
05	1 pc	left front bumper spot lamp garnish	\$ 75.00
06	1 pc	front bumper lower centre air grille	\$ 146.00
07	1 pc	front bumper lower centre air grille chrome moulding	\$ 85.60
08	1 pc	radiator grille	\$ 128.00
09	1 pc	radiator grille chrome garnish	\$ 90.00
10	1 pc	radiator grille emblem badge	\$ 59.00
11	1 pc	left headlamp	\$ 859.00
			\$ 2,520.60
Less 20 %			\$ 504.12
			\$ 2,016.48
<u>SPECIAL NETT ITEMS</u>			
12	1 pc	front licence plate	\$ 80.00
			\$ 80.00
<u>LABOUR & MISC. CHARGES</u>			
01		To check electrical lighting concerned.	\$ 60.00
02		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 500.00
03		Putty and spray painting of the affected portion.	\$ 500.00
			\$ 1,060.00
Total			\$ 3,156.48

LKKA to C. plaintiffs hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No literal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Lump sum \$

20%

1,425.28

Not Adjudicated
2/5 1400
30/6/18
21/6/18

144 -
21/06/18

1,277.00

1,021.60

20

300

400

720.00

1,781.60



陳林摩打私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Lonpac Insured's Veh No : SLW9290G

Date of Accident : 13 June 2018

Not Adjudicated
Merke

2/5 th
3 day
to be photo after repair
21/6/18

Mr Lim Ban Hup

Date : 14 June 2018

144 -
21/06/18

Estimate To Repair SH3805H - Hyundai ELANTRA 1.6 AT ABS D/AB 2WD 4D

Chassis No : KMHDH41CMEU293993

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	front bumper <i>20/22</i>	\$ 418.00
02	1 pc	front bumper reinforcement <i>11</i>	\$ 515.00
03	1 pc	front bumper absorber foam <i>11</i>	\$ 111.00
04	2 ps	front bumper side retainers @ \$17.00 <i>11</i>	\$ 34.00
05	1 pc	left front bumper spot lamp garnish <i>11</i>	\$ 75.00
06	1 pc	front bumper lower centre air grille <i>11</i>	\$ 146.00
07	1 pc	front bumper lower centre air grille chrome moulding <i>11</i>	\$ 85.60
08	1 pc	radiator grille <i>11</i>	\$ 128.00
09	1 pc	radiator grille chrome garnish <i>11</i>	\$ 90.00
10	1 pc	radiator grille emblem badge <i>11</i>	\$ 59.00
11	1 pc	left headlamp <i>11</i>	\$ 859.00
			\$ 2,520.60
Less 20 %			\$ 504.12
			\$ 2,016.48
<u>SPECIAL NETT ITEMS</u>			
12	1 pc	front licence plate <i>Buy</i>	\$ 80.00
			\$ 80.00
<u>LABOUR & MISC. CHARGES</u>			
01		To check electrical lighting concerned.	\$ 60.00
02		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 500.00
03		Putty and spray painting of the affected portion.	\$ 500.00
			\$ 1,060.00
Total			\$ 3,156.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting.
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC6/LPC18011295/Ujb3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 18-10-2018	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLW 9290G	Veh. Inspected	SH 3805H
Policy No.	Z18VP05017879	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020675	Excess (\$)	0.00
Assign From		Assign Date	21/06/2018
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI ELANTRA (A)	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	KMHDH41CMEU293993	Colour	YELLOW / BLACK
Odometer	198705	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	GOODYEAR	7 mm
L/H Front Tyre	195/65 R15	GOODYEAR	7 mm
R/H Rear Tyre	195/65 R15	GOODYEAR	7 mm
L/H Rear Tyre	195/65 R15	GOODYEAR	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	13/06/2018	Inspection Date	21/06/2018
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 3805H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DENTED / DEFORMED	418.00	418.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	515.00	-
1	FRONT BUMPER ABSORBER FOAM	NOT NECESSARY	111.00	-
2	FRONT BUMPER SIDE RETAINERS @\$17.00	NOT NECESSARY	34.00	-
1	LEFT FRONT BUMPER SPOT LAMP GARNISH	NOT NECESSARY	75.00	-
1	FRONT BUMPER LOWER CENTRE AIR GRILLE	NOT NECESSARY	146.00	-
1	FRONT BUMPER LOWER CENTRE AIR GRILLE CHROME MOULDING	NOT NECESSARY	85.60	-
1	RADIATOR GRILLE	NOT NECESSARY	128.00	-
1	RADIATOR GRILLE CHROME GARNISH	NOT NECESSARY	90.00	-
1	RADIATOR GRILLE EMBLEM BADGE	NOT NECESSARY	59.00	-
1	LEFT HEADLAMP	CRACKED	859.00	859.00
	LESS 20% DISCOUNT		-504.12	-255.40
			2,016.48	1,021.60
SPECIAL NETT ITEMS				
1	FRONT LICENCE PLATE (SN)	BENT	80.00	40.00
			80.00	40.00
LABOUR				
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		60.00	20.00
	PANEL BEATING , KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS , ADJUST AND REALIGN THE SAME.		500.00	300.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		500.00	400.00
	-		-	-
	-		-	-
	-		-	-
			1,060.00	720.00
GRAND TOTAL			3,156.48	1,781.60



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,400.00
---	--	--	----------

Report Ref No. CC6/LPC18011295/Ujb3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.