



51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Date : 14 June 2018

21/06/18

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	front bumper <i>20/22</i>	\$ 418.00
02	1 pc	front bumper reinforcement <i>11</i>	\$ 515.00
03	1 pc	front bumper absorber foam <i>11</i>	\$ 111.00
04	2 ps	front bumper side retainers @ \$17.00 <i>11</i>	\$ 34.00
05	1 pc	left front bumper spot lamp garnish <i>11</i>	\$ 75.00
06	1 pc	front bumper lower centre air grille <i>11</i>	\$ 146.00
07	1 pc	front bumper lower centre air grille chrome moulding <i>11</i>	\$ 85.60
08	1 pc	radiator grille <i>11</i>	\$ 128.00
09	1 pc	radiator grille chrome garnish <i>11</i>	\$ 90.00
10	1 pc	radiator grille emblem badge <i>11</i>	\$ 59.00
11	1 pc	left headlamp <i>11</i>	\$ 859.00
			\$ 2,520.60
		Less 20 %	\$ 504.12
			\$ 2,016.48
		<u>SPECIAL NETT ITEMS</u>	
12	1 pc	front licence plate <i>Buy</i>	\$ 80.00
			\$ 80.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To check electrical lighting concerned.	\$ 60.00
02		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 500.00
03		Putty and spray painting of the affected portion.	\$ 500.00
			\$ 1,060.00
		Total	\$ 3,156.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: