



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

Not Allowed
N/S
21/6/18
who phd after
rep.

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

DATE : 19-06-2018

VEHICLE NO. : SGW3183G
ACCIDENT DATE : 02-06-2018 11:55
THIRD PARTY REF. : SHD9329C

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE SGW3183G TOYOTA WISH

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	REAR BOOT COVER <i>Body</i>	1275.00
2	1	REAR BOOT CENTRE EMBLEM <i>new</i>	68.00
3	1	REAR BOOT WINDSCREEN MOULDING <i>new</i>	148.00
4	1	REAR BOOT LOCK <i>new</i>	443.80
5	1	REAR BOOT RUBBER <i>new</i>	398.50
6	1	REAR BUMPER <i>new</i>	1162.00
7	2	REAR BUMPER SIDE RETAINER @\$58.00 <i>MS</i>	116.00
8	10	REAR BUMPER CLIP@\$5.00 <i>new</i>	50.00
9	1	REAR END PANEL <i>Body</i>	515.00
			4,176.30
LESS 25 %			1,044.08
TOTAL (A)			3,132.23
SPECIAL NETT ITEMS			
1	1	REAR WINDSCREEN GUM <i>new</i>	40.00
2	1	REAR REVERSE CAMERA <i>Daye</i>	450.00
TOTAL (C)			490.00

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	30.00
2	1	TO REMOVE/REFIT REAR WINDSCREEN GLASS	100.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : SGW3183G
ACCIDENT DATE : 02-06-2018 11:55
THIRD PARTY REF. : SHD9329C

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
3	1	TO REMOVE/REFIT REAR FENDER INNER GARNISH & ETC	120.00 80
4	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	750.00 600
5	1	SPRAYPAINTING CHARGES	680.00 650
TOTAL (D)			1,680.00
ESTIMATE TOTAL			5,302.23