

United SG Automobile Pte Ltd

"We are always in your journey"....

53 UBI AVENUE 1 #01-56 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934

Tel : 6747 4454 | Fax : 6747 7752 | Email: claims@unitedsg.com.sg

UEN No. 201729521C | GST Registered No: 2017259521C

ESTIMATION QUOTE

AXA INSURANCE PTE LTD

8 SHENTON WAY

#24-01 AXA TOWER

SINGAPORE 068811

ATTN: MOTOR CLAIMS DEPARTMENT

Vic

VEHICLE NO : SJQ7683A

MAKE MODEL : KIA CERANTO

REFERENCE : USG-201806-22

DOA : 19-Jun-18

CLAIM TYPE : TP CLAIM

PAGE 1 OF 2

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
REAR BUMPER <i>Defound</i>	1	\$ 587.34	✓
REAR BUMPER BRACKET <i>RH Best</i>	2	\$ 80.40	<i>40.20</i>
REAR BUMPER REINFORCEMENT <i>Cracked</i>	1	\$ 379.30	✓
REAR BUMPER FOAM <i>Cracked</i>	1	\$ 134.97	✓
REAR TAILLAMP <i>None</i>	2	\$ 492.10	+
BOOTLID <i>Repair</i>	1	\$ 763.94	+
BOOTLID OUTER GARNISH <i>garnish</i>	1	\$ 204.50	+
BOOTLID LAMP	2	\$ 389.30	+
BOOTLID WEATHERSTRIP	1	\$ 73.40	+
BOOTLID EMBLEM LOGO.KIA <i>garnish</i>	1	\$ 27.60	✓
BOOTLID EMBLEM - CERATO	1	\$ 26.30	✓
BOOTLID EMBLEM -EX	1	\$ 39.40	✓
BOOTLID LOCK <i>None</i>	1	\$ 243.40	+
END PANEL <i>Repair</i>	1	\$ 557.40	+
END PANEL TOP GARNISH <i>None</i>	1	\$ 74.60	+

1235.11 \$ 4,073.95
 LESS 10% \$ 407.40
 1111.59 SUBTOTAL \$ 3,666.56
 BALANCE C/F \$ 3,666.56

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 3,666.56	
REAR BUMPER CLIP <i>New</i>	1 SET	\$ 50.00	<i>30</i>
REAR REVERSE SENSOR <i>Damage</i>	1 SET	\$ 400.00	<i>200</i>
JOINT SEALANT <i>xtl new</i>	1	\$ 150.00	<i>x</i>

SUBTOTAL \$ 600.00
 BALANCE C/F \$ 4,266.56

LABOUR	S/NO	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 4,266.56	
CHECK REAR WIRING AND LIGHTNING SYSTEM	1	\$ 60.00	<i>30</i>
REMOVE AND RENEW REAR REVERSE SENSOR	2	\$ 120.00	<i>50</i>

230,

ESTIMATION QUOTE

AXA INSURANCE PTE LTD
8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811
ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SJQ7683A
MAKE MODEL : KIA CERANTO
REFERENCE : USG-201806-22
DOA : 19-Jun-18
CLAIM TYPE : TP CLAIM

PAGE 2 OF 2

LABOUR	S/NO	LIST PRICE (\$)	REMARKS
REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	3	\$ 200.00	40
REMOVE AND STRAIGHTEN REAR EXHAUST	4	\$ 150.00	X
TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	5	\$ 200.00	X
PANEL BEATING ON AFFECTED AREAS	4	\$ 800.00	400
SPRAY PAINTING ON AFFECTED AREAS	5	\$ 800.00	600
APPLY ANTI RUST ON AFFECTED AREAS	6	\$ 150.00	X
SUBTOTAL		\$ 2,480.00	

GRAND TOTAL \$ 6,746.56

1120.

total: 2461.59.
A/s: 1950 ✓
04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: