

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SLC 513D
TP/AXA

M/S : AXA INSURANCE (S) PTE LTD
 8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288 FAX: 68804739
 ATTN: Motor Claim Department

WS Ref: TP/AXA/YS
 Claim Type: Third Party
 Accident Date: 20/06/2018
 TP Veh Reg No: YP6461H

Not Authorised
Recovery B4 claim
6 days

Estimate No: ES1890684/YISHUN
Date: 21 Jun 2018
Policy No: D18MTPV01005489
Veh Reg No: SLC513D
Make/Model: MAZDA MAZDA2
 SEDAN 1.5L SP.6EAT
Chassis No: MM6DL2SAAGW196407
Engine No: P520347805
Reg. Date: 28/04/2016

Estimate Repair Cost to Vehicle No :SLC513D

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price				
1 REAR BUMPER	909.00	1 PC	909.00	?
2 RH TAILLAMP	376.40	1 PC	376.40	✓
3 REAR BUMPER RH SIDE RETAINER	21.70	1 PC	21.70	?
4 REAR BUMPER CLIPS	3.50	6 PCS	21.00	✓
5 REAR BOOT LOGO	55.40	1 PC	55.40	—
6 REAR BOOT EMBLEM (SKYACTIV)	64.30	1 PC	64.30	—
7 REAR BOOT EMBLEM (MAZDA2)	55.10	1 PC	55.10	—
8 REAR BOOT RH REFLECTOR	198.40	1 PC	198.40	—
9 REAR RH FENDER	844.00	1 PC	844.00	—
10 REAR WINDSCREEN GLASS MOULDING	49.80	1 PC	49.80	—
			2,595.10	
		Less 20%	519.02	2,076.08
Special Net				
11 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
			40.00	40.00
Labour				
12 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
13 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, REFLECTOR, TO CUT, WELD & RENEW REAR RH FENDER & REALIGN THE SAME	900.00	1 LA	900.00	800
14 REMOVE & REFIX SEAT, CARPET, TOP ROOF LINING, ETC	120.00	1 LA	120.00	✓
15 PUTTY & RESPRAY ON REAR BUMPER, BOOT, REAR RH FENDER & REAR AFFECTED AREAS	800.00	1 LA	800.00	650
16 RUSTPROOFING	30.00	1 LA	30.00	✓
			1,970.00	1,970.00
Total			S\$ 4,086.08	
Add GST @ 7%			286.03	
Total Amount Payable			S\$ 4,372.11	

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE