



ComfortDelGro Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATE**

Our Ref:

Type of Claim : TPVehicle No. : SLH9703LMake & Model : HONDA GRACE HYBRID 1.5DXYear of Manufacture : 2016Chassis No. : GM41105555Ins Company : AIG VS AXAEngine No. : LEB5255578Excess : -Policy No. : -Date of Accident : 19.06.2018Time of Accident : 16:00

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor**Repair Estimate**Case Owner : WILLIAM

Signature : \_\_\_\_\_

Parts (a) Cost / List Price Items \$ 3,754.00Plus/Less 20% \$ 750.80Total of Cost / List \$ 3,003.20(b) Nett Price Items \$ -

Less \_\_\_\_\_

Total of Nett Item \_\_\_\_\_

(c) Special Nett Items \$ 200.00Total Parts Cost (Appendix A) \$ 3,203.20Labour (Appendix B) \$ 1,950.00Total Repair Cost \$ 5,153.20Contact No  
**Frt Counter Operation**

63837103 - Patrick Tia

63837730 - Brenda Ng

63837466 - Rohani

[braddell\\_cr@sparkcarcare.com](mailto:braddell_cr@sparkcarcare.com)**Workshop Operation**

63837656 - Ngo Toh Wee

63837362 -

63838115 - William Wang

63838115 - Andrew Goh

[braddell\\_operation@sparkcarcare.com](mailto:braddell_operation@sparkcarcare.com)

*Not Authorized*  
*1.B.1*  
*Resurvey By pain*

The above total will be subjected to 7% G.S.T.

Name of Surveyor : KennethCompany : CKCSurvey conducted on : 21/6/18 at \_\_\_\_\_**Remarks By Surveyor**(a) The repair of this vehicle is not authorized / is not authorized until further notice.(b) Recommended Days of Repair : 05 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : Le Date: 21/6/18

# Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

## Spare Parts

Vehicle No : SLH9703L Case Owner : WILLIAM

Make & Model : HONDA GRACE HYBRID 1 Year Manufacture : 2016

Chassis No : GM41105555 Engine No : LEB5255578

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : TP

| S/No | Part Description                   | QTY | Cost Price    | List Price | Nett Price           | S/N | Disposition By Surveyor |
|------|------------------------------------|-----|---------------|------------|----------------------|-----|-------------------------|
| 1    | Rear bumper                        | 1   | <i>Bu</i>     | \$ 937.40  |                      |     | ✓                       |
| 2    | Rear bumper side retainer LH       | 1   | <i>Dis</i>    | \$ 13.40   |                      |     | ✓                       |
| 3    | Rear bumper side retainer RH       | 1   | <i>See</i>    | \$ 13.40   |                      |     | X                       |
| 4    | Rear bumper upper side retainer LH | 1   |               | TBA        |                      |     |                         |
| 5    | Rear bumper upper side retainer RH | 1   |               | TBA        |                      |     |                         |
| 6    | Rear bumper clips                  | 2   | <i>See</i>    | \$ 7.80    |                      |     | ✓                       |
| 7    | Reverse sensor set                 | 1   |               |            | <i>See</i> \$ 200.00 |     | ✓                       |
| 8    | Taillamp LH                        | 1   |               | \$ 395.00  |                      |     | ?                       |
| 9    | Taillamp RH                        | 1   |               | \$ 395.00  |                      |     | ?                       |
| 10   | Bootlid                            | 1   | <i>R</i>      | \$ 675.20  |                      |     | X                       |
| 11   | Bootlid badge logo                 | 1   | <i>See</i>    | \$ 27.10   |                      |     | ✓                       |
| 12   | Bootlid emblem - GRACE             | 1   | <i>See</i>    | \$ 38.90   |                      |     | ✓                       |
| 13   | Bootlid emblem - HYBRID            | 1   | <i>See</i>    | \$ 58.50   |                      |     | ✓                       |
| 14   | Bootlid lock                       | 1   | <i>R</i>      | \$ 90.30   |                      |     | X                       |
| 15   | Bootlid weatherstrip               | 1   |               | \$ 78.30   |                      |     | ?                       |
| 16   | Bootlid lamp LH                    | 1   | <i>See</i>    | \$ 306.70  |                      |     | ✓                       |
| 17   | Bootlid lamp RH                    | 1   | <i>See</i>    | \$ 306.70  |                      |     | X                       |
| 18   | Rear end panel                     | 1   | <i>Bu</i>     | \$ 323.90  |                      |     | ✓                       |
| 19   | Rear end panel inner garnish       | 1   | <i>See/Lt</i> | \$ 86.40   |                      |     | ✓                       |
| 20   | 0                                  | 0   |               |            |                      |     |                         |
| 21   | 0                                  | 0   |               |            |                      |     |                         |
| 22   | 0                                  | 0   |               |            |                      |     |                         |
| 23   | 0                                  | 0   |               |            |                      |     |                         |
| 24   | 0                                  | 0   |               |            |                      |     |                         |
| 25   | 0                                  | 0   |               |            |                      |     |                         |
| 26   | 0                                  | 0   |               |            |                      |     |                         |
| 27   | 0                                  | 0   |               |            |                      |     |                         |
| 28   | 0                                  | 0   |               |            |                      |     |                         |
| 29   | 0                                  | 0   |               |            |                      |     |                         |
| 30   | 0                                  | 0   |               |            |                      |     |                         |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax:62844284,62815767

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*