

INSURANCE

INS. CASE OWNER

Stacey

CC 1/AXA 1801 1305, A ebs

LKK  
IDAC

Surveyor:

bedwin

DOI:

ASSIGNMENT

7/6/18

Date / Time:

7/6/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

FBK 3059E

Claim No.:

S 8000 FBW / 52540

Name of Insured:

SHANMUKHAM PARAMANIKUMAR

Policy No.:

Insured Tel No.:

HP:

7/6/18

Make / Model:

Excess Sec II :S:

D.O.A.:

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(VI: YES / NO)

OI GIA REPORT: YES / NO, TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SH 2607J



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

flm  
memo



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/Time

7/6/18  
Asher

SH 2607J - ma/follow up/24 00-7/6/18  
int home  
Smartdown  
- OIR, SENT OUT 2ST LETTER

STAGE	DATE / PIC
Non-Reporting ltr (1st):	20-6-18
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	7/6/18 1-8-18
After call ltr to OI:	
Documentation Check List: Handler Typist	
Notification ltr (if non-pickup)	<input type="checkbox"/>
After call ltr to OI	<input checked="" type="checkbox"/>
Authorisation To Act:	<input checked="" type="checkbox"/>
Release Voucher:	<input checked="" type="checkbox"/>
Final Repair Bill:	<input checked="" type="checkbox"/>
Car Rental Invoice:	<input type="checkbox"/>
Towing Invoice:	<input type="checkbox"/>
LTA / GIA	<input checked="" type="checkbox"/>
Medical Bill:	<input type="checkbox"/>
PBR:	<input type="checkbox"/>
Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
LOD	<input checked="" type="checkbox"/>
Payment Breakdown Form:	<input type="checkbox"/>
Post-Repair Photos:	<input type="checkbox"/>
Others:	<input type="checkbox"/>

29.7.18 @ 2.35pm  
29.7.18 @ 3.27

OPENED OI NO RESPONSE  
OI REPAIR CALL CONFIRMED ACCIDENT. OI REAR ENDED TP  
INFORM TP CLAIM ADVISED TO SEND AND ANSWER ABOUT NOD  
12/18.  
EMAIL WSP LIABILITY CLEAR.

<b>PRELIMINARY ADVICE</b>	Date/Time:	Sent By:	Confirm with:	Confirm by: loop
<b>FINALIZATION</b>	Date/Time:	Repair Cost:	( 6 days) Reduction:	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
<b>FINAL SETTLEMENT</b>	Date/Time: 19.11.18	Final Liability:	Confirm with: durg	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Repair Cost:	\$5,400.00	Loss of Rental (LOR):	( Agreed / Assessed ) BOLA S/N No. : 27	If NO or B 28, Ass. Ltr :
Loss of Use (LOU):	\$5 - ( 8 days)	Loss of Income (LOI):	\$5,400.00 OI REAR ENDED TP	
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/>	LOR + LOU <input type="checkbox"/>	LOR + LO <input type="checkbox"/>		
GIA/LTA Search	\$51.99	Medical:		1) Claim status: Normal/Reject/Private Settle
Disbursement:	\$5 -	Legal Cost:	( e.g. Tow/ Independent )	2) Report Format: TP
<b>Total:</b>	\$5,251.99	<b>Global Sum \$5:</b>		3) Survey fee: +550
<b>FINAL PAYMENT</b>	Date/Time: 19.11.18	Payee 1:	Confirm with: durg	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Payee 2: (Strike if N.A.)	\$5	Payee 3: (Strike if N.A.)	Name 1: Sun King 33004 Phnom Penh, Vietnam	

7/1/19 SENT

Asst. REC. BY: Adrian King

REF:

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : **Yes** or **No**

GIA / PR Seen: \_\_\_\_\_ Consistent? : **Yes** or **No**

Est. Repairs: \_\_\_\_\_ days Res: **Yes** or **No**

Lump Sum: \_\_\_\_\_ % 3 Val: **Yes** or **No**

CA / REV / REP. / 24 HRS

Vehicle: **IN / OUT**

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SH 2807J • Yr Regn: 2015 / Jan

Type: M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Axio cc 1496

Colour: Black A/C: **Insured / Std / NI / NA**

Sp. Reading: 516403 T/Radio: **Insured / Std / NI / NA**

Eng/No: \_\_\_\_\_

C/No: NZE1617065453

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: **In order** / Jammed / Leaked / Burnt or

Brake: **In order** / Jammed / Leaked / Burnt or

Modi: **Nil** / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15

R: 185/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Habilead

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal: 06 mm R/Bal: 06 mm

L/Bal: 06 mm L/Bal: 06 mm

D.O.A. \_\_\_\_\_ D.O.I: 21/06/18

Survey held at Hua Meng

Des. of Damages: Frt / **Rear** / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP AXA.</u>
	<u>HS → 4,100 (2SD → 1,291.90 67%)</u>
	<u>MV: 58K</u>
	<u>PV: 33.6K</u>
	<u>Nett: 24.4K</u>

Date/Time, File Pass to/

: Prel. Report

Days Of Repair:

Date/Time, File Return to/

: Final Report

Resurvey No. of Trip:

IS

Add Fee:  Site Insp. (\$)

Report Format

Interview (\$)

Lump Sum / I.B.F. (\$)

Field Inv (\$)

Weekend (\$)

Survey Fee:

Transportation: \_\_\_\_\_

Phone: \_\_\_\_\_

Other: \_\_\_\_\_

TOTAL



## LKK Auto Consultants Pte Ltd

51 Ubi Ave.1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18011305/Aeb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 21-06-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FBK 3059E	Veh. Inspected	SH 2807J
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	21/06/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	07/06/2018	Inspection Date	21/06/2018
Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	6046J
Vehicle No.:	SH2807J
Vehicle to be Exported:	Yes
Intended De-registration Date:	21 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X A
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	1NZE456893
Chassis No.:	NZE1617065453
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$15,068.00
Original Registration Date:	09 Jan 2015
First Registration Date:	09 Jan 2015
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Jan 2023
PARF Rebate Amount:	\$3,750.00
COE Expiry Date:	08 Jan 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$52,486.00
COE Rebate Amount:	\$29,840.00
Total Rebate Amount:	\$33,590.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 21 Jun 2018

OK

# HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

NZE1617065453

## ESTIMATE

LOW BOON TIN  
BLK 180 BUKIT BATOK WEST AVE 8  
#07-197  
S 650180

TPARA  
Pshar.

Date :21.06.2018  
Vehicle no :SH 2807 J  
Make/Model :TOYOTA AXIO  
Accident date :07.06.2018

No	DESCRIPTION	Qty	Amount (\$S)
<u>List Items</u>			
1	Rear boot lid <i>Buckled</i>	1	\$ 753.3 ✓
2	Rear boot lid hinges @ \$106.40 <i>not nec</i>	2	\$ 212.8 ✓
3	Rear boot lid upper lock <i>Damaged</i>	1	\$ 103.7 ✓
4	Rear boot lid lower lock <i>not nec</i>	1	\$ 24.3 ✓
5	Rear boot lid weather strip <i>lit</i>	1	\$ 263.7 ✓
6	Rear boot lid handle <i>not nec</i>	1	\$ 230.7 ✓
7	Rear boot lid centre logo	1	\$ 64.7 ✓
8	Rear boot lid COROLLA emblem <i>not nec</i>	1	\$ 43.1 ✓
9	Rear boot lid AXIO emblem	1	\$ 46.8 ✓
10	Rear boot lid insulation <i>not nec</i>	1	\$ 218.1 ✓
11	Rear end panel <i>Dented</i>	1	\$ 662.3 ✓
12	Rear end panel inner top garnish <i>Deformed</i>	1	\$ 240.8 ✓
13	Rear bumper <i>Deformed</i>	1	\$ 477.2 ✓
14	Rear bumper side holder @ \$99.80 <i>not nec</i>	2	\$ 199.6 ✓ 70.
15	Rear bumper reflector @ \$59.50 <i>not nec</i>	2	\$ 119 ✓
16	Rear bumper clips (1set) <i>not nec</i>	1	\$ 50 <del>30</del>
17	Rear lamp @ \$413.00 <i>crushed</i>	2	\$ <del>826</del> 690.
18	Rear lamp housing @ \$157.40	2	\$ 314.8 ✓
19	Rear lamp housing bracket @ \$99.50 <i>not nec</i>	2	\$ 199 ✓
20	Rear fender inner trim @ \$346.60 <i>not nec</i>	2	\$ 693.2 ✓
21	Rear fender inner shield @ \$62.60	2	\$ 125.2 ✓
22	Rear spare tyre top board <i>Deformed</i>	1	\$ 567.4 <del>795.</del>
23	Rear spare tyre well <i>Repair</i>	1	\$ 701.6 ✓
24	Rear spare tyre well insulation @ \$424.20 <i>not nec</i>	3	\$ 1272.6 ✓
25	Rear LH fender <i>not nec</i>	1	\$ 880.1 ✓
			\$ 9290
		Less 25% Disc	\$ 2322.5
		Total	\$ 6967.5
<u>Special Nett Items</u>			
1	Rear bumper reverse sensor (1set) <i>Damaged</i>	1	\$ 380 <del>200</del>
		Total	\$ 380

3940.60  
2935.45

200

# HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

## ESTIMATE

LOW BOON TIN

BLK 180 BUKIT BATOK WEST AVE 8

#07-197

S 650180

Date :21.06.2018

Vehicle no :SH 2807 J

Make/Model :TOYOTA AXIO

Accident date :07.06.2018

No	Description	Qty	Amount (S\$)
----	-------------	-----	--------------

### Labour Cost

1	To supply rear end panel inner sealant		\$ 200 <sup>60</sup>
2	Remove & reinstall exhaust pipe		\$ 150 <sup>+</sup>
3	Remove & reinstall reverse sensor		\$ 150 <sup>50</sup>
4	Remove & reinstall boot lid inner garnish	1960	\$ 200 <sup>x</sup>
5	Remove, replace & repair consistent to the accident		\$ 1800 <sup>900</sup>
6	Respray painting		\$ 1500 <sup>900</sup>
7	Tuff kote		\$ 150 <sup>50</sup>
	Total		\$ 4150
	Grand Total		\$ 11497.5

total: 51154\$  
L/S: 4.1k.  
06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer :

Signature:

Date:



## MANDATE REQUEST FOR S8M00KBW

S8M00KBW

Type

🔔 Question

Message

Liability: Insured rear ended third party vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$4,100.00 Loss of Use: \$480.00 (8days x \$60) LTA Search: \$7.49 Total: \$4,587.49 Immediate Advice with Mandate and marked estimate uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (19/10/2018)

Reply



## Re:MANDATE REQUEST FOR S8M00KBW

Type

🔍 Question

Message

pls proceed

Reply

## CERTIFICATE OF INSURANCE

ORIGINAL

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)  
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960  
Road Transport Act, 1987 (Malaysia)  
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Type of Policy. : TAXIS  
Type of Cover. : Comprehensive  
Certificate No. : D-180089355MSH  
Vehicle No / Chassis No : SH2807J / NZE1617065453  
Name of Insured : YEO AH HEE  
Period Of Insurance : 09.01.2018 To 08.01.2019  
Insured Estimated Value : Market Value At Time Of Loss  
Financial Institution : YES MOTORING & CREDIT PTE LTD

**Excess :**

SGD1,000.00 SECTION I & II SEPARATELY EACH AND EVERY LOSS

**Authorised Driver\***

YEO AH HEE

**Persons or classes of persons entitled to drive\***

- a) Any licensed taxi driver driving on the Insured's order or with their permission.
- b) Any person provided he is in the Insured's employ and is driving on their order or with their permission.

\* Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

**Limitations as to use\***

Use as a taxi. Use for social, domestic and pleasure purposes.

**The Policy does not cover**

- (1) Use for racing, pace-making, reliability trial or speed testing.
- (2) Use whilst drawing a trailer except the towing (other than for reward of any one disabled mechanically propelled vehicle).


\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

**WE HEREBY CERTIFY** that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

First Capital Insurance Limited  
(Approved Insurers)

ITHMINAH/A0141/MZ400A 


Issued at Singapore on 19.12.2017

  
Authorised Signature

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S1260710E**  
 Name: **CHUA TIN HENG**  
 Birth Date: **03 Jul 1957**  
 Issue Date: **21 Feb 2003**

000220465P

REPUBLIC OF SINGAPORE  
 IDENTITY CARD NO. **S1260710E**



Name: **CHUA TIN HENG**  
**蔡榮偉**  
 Race: **CHINESE**  
 Date of Birth: **03-07-1957** Sex: **M**  
 Country of Birth: **SINGAPORE**



Land Transport Authority

**VOCATIONAL LICENCE**  
 Licence No : **S1260710E**  
 Name : **CHUA TIN HENG**  
 Issue Date : **6/10/2008**  
 Please visit [www.lta.gov.sg](http://www.lta.gov.sg) to check the status of this vocational licence



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE: 20 Mar 1978




1408395



LIC No: **S1260710E**

Blood Group: **A+** Date of exam: **06-11-1993**



Address: **APT BLK 14 ST. GEORGE'S ROAD #05-02 SINGAPORE 320014**

NRIC No: **S1260710E**

Date: **21-08-2003**

No: **1008162**

NP 426A

This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type	Description	Issue Date
02	TAXI VL	05/11/2004





華 明 噴 漆 廠  
**HUA MENG SPRAY PAINTING WORKSHOP**

AUTOBAY@KAKIBUKIT

1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883

Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680

Reg. No.: 254678/00M



Your Ref : FBK 3059E

Our Ref : SH 2807J

Date: 27.09.2018

Attn: Motor Claims Dept

**ACCIDENT ON 07.06.2018 INVOLVING VEHICLE SH 2807 J & FBK 3059 E ALONG  
 DESKER ROAD**

With regards to the above, we are writing on behalf of the registered owner of vehicle SH 2807 J which was involved in the above mentioned accident.

We are informed that the above accident was caused solely by the negligence of your insured vehicle FBK 3059 E. As a result of the accident, our client's vehicle was damaged and our client had instructed us to submit his claims for loss and expenses, particulars of which are follows:

1) Repair cost	\$	4,100.00
2) Loss of use-\$100 X 08days	\$	800.00
3) LTA search	\$	7.49
<b>Total</b>	<b>\$</b>	<b>4,907.49</b>

We hereby enclosed herewith the following documents for your consideration of the above claim.

- a) Final Repair Bill Of SH 2807 J
- b) GIA report
- c) LTA SEARCH
- d) Owner / Driver NRIC & Driving License

華 明 噴 漆 廠  
 HUA MENG SPRAY PAINTING WORKSHOP  
 AUTOBAY@KAKIBUKIT  
 1, Kaki Bukit Avenue 6 Blk C #01-34 SINGAPORE 417883  
 TEL: 6747 8064, 6746 5519 FAX: 6743 4896

Yours faithfully,  
**HUA MENG SPRAY PAINTING WORKSHOP**

**Asher Sng (LKKAuto)**

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Wednesday, 1 August 2018 12:48 PM  
**To:** 'SCP1981@YAHOO.CO.IN'  
**Subject:** ACCIDENT INVOLVING FBK 3059E AND SH 2807J ALONG DESKER RD ON 07/06/2018

01 AUG 2018

**SHANMUGAM PALANIKUMAR**

Dear Sir/ Mdm

**OUR REF : CC4/ASM18011305/Aeb3**  
**YOUR REF : FBK 3059E**  
**ACCIDENT INVOLVING FBK 3059E AND SH 2807J ALONG DESKER RD ON 07/06/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s HUA MENG SPRAY PAINTING WORKSHOP acting on behalf of the owner of SH 2807J against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had rear-ended the Third Party vehicle SH 2807J. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Asher  
Case Handler  
DID: 6841 6051  
FAX: 6741 4108  
Email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com)

c.c. AXA Insurance Pte Ltd (AXA)  
(Motor Claims Dept)

**AUTHORISATION TO ACT**

I/We, Yeo Ah Hee ("the third party claimant") of  
KLK180 Bukit Batok West Ave 8 #07-197, S1630180 (address),  
owner of SH2807J (vehicle no.) hereby authorise **HUA MENG SPRAY PAINTING**  
**WORKSHOP** ("the workshop") to act for me with respect to my claim for repair costs and/or  
rental and/or loss of use ("claim") for my vehicle no. SH2807J that was damaged pursuant  
to the accident which occurred on 07-06-2018 (date) along Duskin Road  
(location) involving vehicle no/s PBK3059E ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/Insurers of the other vehicle/s is concerned.

Dated this 7 (day) of 06 (month) 20 18 (year)

KH  
Signed by "the third party claimant"  
(with company stamp if applicable)

華明噴漆廠  
HUA MENG SPRAY PAINTING WORKSHOP  
AUTOBAK RAKI BUKIT  
1 KAKI BUKIT AVE 6 #01-34 SINGAPORE 41788  
TEL: 6747 4964  
Signed by "the workshop"  
(with company stamp) FAX: 6743 481



redefining / insurance

WITHOUT PREJUDICE  
TO OUR CLIENT'S PERSONAL INJURY  
CLAIM (PRESENT OR FUTURE) WHICH IS  
EXPRESSLY RESERVED

CLAIM REF : S8M00KBW  
INSURED : SHANMUGAM PALANIKUMAR

DISCHARGE VOUCHER

We/I [YEO AH HEE, NRIC NO. S0346046J] hereby agree to accept the sum of dollars [FOUR THOUSAND FIVE HUNDRED EIGHTY SEVEN AND CENTS FORTY NINE ONLY.] [S\$4,587.49] paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their insured or the driver of motor vehicle no. [FBK 3059E] as a result of an accident along [DESKER RD] on [07/06/2018] of which we/I were/was the driver/owner/hirer/passenger/rider/pillion/insurer of motor vehicle no. [SH 2807J].

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. [FBK 3059E] in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. [FBK 3059E].

Dated this 3<sup>rd</sup> day of Jan 2018

Claimant's Signature : [Signature]

NRIC no./ Company Stamp : S0346046J

Occupation/ Business : \_\_\_\_\_

Address : 180 Bukit Batok West Ave 8 #07-197, S(650180)

Telephone No. : 97678752

Witness's Name : Jinme Loh

Witness's Signature : [Signature]

Witness's NRIC No. : G7604382W



華 明 噴 漆 廠  
**HUA MENG SPRAY PAINTING WORKSHOP**

AUTOBAY@KAKIBUKIT

1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883  
Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680  
Reg. No.: 254678/00M



Your Ref : FBK 3059E

Our Ref : SH 2807J

18/9/2018

Date:.....

VEHICLE NO :SH 2807 J  
MAKE / MODEL :TOYOTA AXIO  
NAME :LOW BOON TIN  
ADDRESS :180 BUKIT BATOK WEST AVE 8  
#07-197  
S 650180

**FINAL REPAIR BILL FOR VEHICLE NO:SH 2807 J**

TO SUPPLY AND REPLACE PARTS, LABOUR CHARGES FOR  
REPAIRING, KNOCKING, WELDING AND TO RESPRAY PAINTING  
(LUMP SUM REPAIR)

\$ 4,100.00

**SINGAPORE DOLLARS: FOUR THOUSAND AND ONE HUNDRED ONLY**

> Back to OneMotoring



Land Transport Authority  
 10 Sin Ming Drive  
 Singapore 575701  
 GST Registration No. : M4-0006529-2

Print Date/Time : 11 Jun 2018 / 11:41:30

Receipt Date/Time : 11 Jun 2018 / 11:41:30

**Tax Invoice/Receipt**

Receipt No. : ITNET-00000-180611-000827

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - FBK3059E As at 07 Jun 2018/23:40:00 Insurance Co: AXA INSURANCE PTE LTD				
1	Insurance Enquiry - FBK3059E Enquiry Fee 20180611114021390105	7.00	0.49	7.49
<b>Sub-Total</b>		7.00	0.49	7.49
Result of Insurance Enquiry - GBE1671G As at 08 Jun 2018/18:10:00 Insurance Co: NTUC INCOME INS CO-OP LTD				
2	Insurance Enquiry - GBE1671G Enquiry Fee 20180611114021435986	7.00	0.49	7.49
<b>Sub-Total</b>		7.00	0.49	7.49
<b>Total Before Rounding</b>		14.00	0.98	14.98
<b>Rounding Difference</b>				0.03
<b>Total Amount Payable</b>				14.95
Paid By				
	20180611114042598	Direct Debit: eNETS Debit (Internet Banking)		14.95
<b>Total</b>				14.95
<b>Cash Change</b>				0.00
<b>Tendered Amount</b>				14.95
<b>Excess Refundable Amount</b>				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18011305/Aeb3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:STACEY NG		Date : 11-01-2019 Code : ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	FBK 3059E	Veh. Inspected	SH 2807J
Policy No.	P1617539	Coverage (\$)	0.00
Claim No.	S8M00KBW	Excess (\$)	0.00
Assign From		Assign Date	21/06/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA AXIO	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	NZE1617065453	Colour	BLACK
Odometer	516403	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	185/65 R15	HABILEAD	6 mm
L/H Front Tyre	185/65 R15	HABILEAD	6 mm
R/H Rear Tyre	185/65 R15	HABILEAD	6 mm
L/H Rear Tyre	185/65 R15	HABILEAD	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	07/06/2018	Inspection Date	21/06/2018
Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 2807J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BOOT LID (CONSISTENT)	BUCKLED	753.30	753.30
2	REAR BOOT LID HINGES @\$106.40 (CONSISTENT)	NOT NECESSARY	212.80	-
1	REAR BOOT LID UPPER LOCK (CONSISTENT)	DAMAGED	103.70	103.70
1	REAR BOOT LID LOWER LOCK (CONSISTENT)	NOT NECESSARY	24.30	-
1	REAR BOOT LID WEATHER STRIP (CONSISTENT)	CUT	263.70	263.70
1	REAR BOOT LID HANDLE (CONSISTENT)	NOT NECESSARY	230.70	-
1	REAR BOOT LID CENTRE LOGO (CONSISTENT)	NECESSARY	64.70	64.70
1	REAR BOOT LID COROLLA EMBLEM (CONSISTENT)	NECESSARY	43.10	43.10
1	REAR BOOT LID AXIO EMBLEM (CONSISTENT)	NECESSARY	46.80	46.80
1	REAR BOOT LID INSULATION (CONSISTENT)	NOT NECESSARY	218.10	-
1	REAR END PANEL (CONSISTENT)	DENTED	662.30	662.30
1	REAR END PANEL INNER TOP GARNISH (CONSISTENT)	DEFORMED	240.80	240.80
1	REAR BUMPER (CONSISTENT)	DEFORMED	477.20	477.20
2	REAR BUMPER SIDE HOLDER @\$99.80 (CONSISTENT)	NECESSARY	199.60	70.00
2	REAR BUMPER REFLECTOR @\$59.50 (CONSISTENT)	NOT NECESSARY	119.00	-
1	SET REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	50.00	30.00
2	REAR LAMP @\$413.00 (CONSISTENT)	CRACKED	826.00	690.00
2	REAR LAMP HOUSING @\$157.40 (CONSISTENT)	NOT NECESSARY	314.80	-
2	REAR LAMP HOUSING BRACKET @\$99.50 (CONSISTENT)	NOT NECESSARY	199.00	-
2	REAR FENDER INNER TRIM @\$346.60 (CONSISTENT)	NOT NECESSARY	693.20	-
2	REAR FENDER INNER SHIELD @\$62.60 (CONSISTENT)	NOT NECESSARY	125.20	-
1	REAR SPARE TYRE TOP BOARD (CONSISTENT)	DEFORMED	567.40	495.00
1	REAR SPARE TYRE WELL (CONSISTENT)	TO REPAIR SEE LABOUR	701.60	-
3	REAR SPARE TYRE WELL INSULATION @\$424.20 (CONSISTENT)	NOT NECESSARY	1,272.60	-
1	REAR LH FENDER (CONSISTENT)	NOT NECESSARY	880.10	-
	LESS 25% DISCOUNT		-2,322.50	-985.15
			6,967.50	2,955.45
<b>SPECIAL NETT ITEMS</b>				
1	SET REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT)	DAMAGED	380.00	200.00

Report Ref No. CC4/ASM18011305/Aeb3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>		380.00	200.00
	TO SUPPLY REAR END PANEL INNER SEALANT .		200.00	60.00
	REMOVE & REINSTALL EXHAUST PIPE .	NOT NECESSARY	150.00	-
	REMOVE & REINSTALL REVERSE SENSOR .		150.00	50.00
	REMOVE & REINSTALL BOOT LID INNER GARNISH .	NOT NECESSARY	200.00	-
	REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE WELL .		1,800.00	900.00
	RESPRAY PAINTING .		1,500.00	900.00
	TUFF KOTE .		150.00	50.00
			4,150.00	1,960.00
	<b>GRAND TOTAL</b>		<b>11,497.50</b>	<b>5,115.45</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,100.00</b>

Report Ref No. CC4/ASM18011305/Aeb3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.





NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 FIKKOSWE - INSURED GIA REPORT.pdf	Reports & Statement	Accident statement	NG Stacey	27 June 2018
 Non reporting letter -2807.pdf	Letters and Correspondence	Policy Holders / Insured	LKX AUTO CONSULTANTS PTE LTD (TP)	23 June 2018
 Reminder to tp w's.meg	Letters and Correspondence	Workshop	NG Stacey	19 June 2018
 LIST OF SURVEY SENT.meg	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	13 June 2018
 Email to abh.meg	Letters and Correspondence	Internal	NG Stacey	13 June 2018
 EMAIL TP PRIME	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	11 June 2018
 WORKSHOP.pdf	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	11 June 2018