

ASS. REC. BY:

REF: CS/CTI18011308/Vsd3 Special Instruction

Surveyor: Menmen ASSIGNMENT (Office)

From (Person): Sharon Han of CTI Date/Time: 21/06/2018 @ 5:34pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLH 6403 Y Insured: 8JL 2169 L

at Workshop n/s World Auto Tel: 6362 1776

of No. 1 Kranji Loop

Policy No: DMPCSN 8122911701 Claim No: SNM18D0308602/9

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 20/06/2018

(Client's Record) 22/06/2018 H.O.D. Endorsement: _____

CA / REV / REP. / REV 24 HRS 'wp' Date/Time: 5:42pm @ 21/6/18 Person Contacted: Ainee Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLH 6403 Y -- 004/2CR18001897 / Awb3 DOA: 27/01/2018</u>
	<u>8JL 2169 L - X</u>

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wp' Vehicle: IN / OUT

Date: _____ Person Contacted: _____

D.O.A. 20/6/2018 D.O.I. 22/6/2018

Survey held at World Auto

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

Sathy G, PLS see me.

(\$7,426.80 Red - 48%)

25/6

RECEIVED 27 JUL 2018

Date/Time File Pass to? : Preli. Report : Final Report

Days Of Repair: 7 Resurvey No. of Trip: 2

Date/Time File Return to?

Add Fee: : Site Insp \$: Interview \$: Tech fees \$: Weekend \$

Report Format : Lump Sum / I.B.F. \$ 8,055.20 P/P

Survey Fee:	
Transportation	
1 - 5 + 05 - 01	
1 - Photo	
1 - Other	
TOTAL	

ACCIDENT STATEMENT (2000 characters)

I (SLH6403Y) was stationary along Havelock Rd on the first lane when suddenly a car (SJL2469L) hit me from the back. No injuries involved.

Taxi Voucher No.:

DECLARATION

(We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMMAD SULHANDI BIN MOH AFFANDI



MARS Officer

Registered Owner or Driver's Signature

Job Complete Date/Time

20 June 2018 at 1:06 PM

Date/Time:

20 June 2018 at 1:06 PM

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S1485444D**

Name: **LEE YEW PONG, MELVIN**

Birth Date: **23 Aug 1961**

Issue Date: **03 Nov 2003**

100973689H




REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S1485444D**

Name: **LEE YEW PONG, MELVIN**

Race: **CHINESE**

Date of Birth: **23-08-1961**

Country of Birth: **SINGAPORE**

Sex: **M**

李耀邦





***YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE: **10 Apr 1979**

NP 428A

License No: S1485444D



001-48

NP 428A

NPIC No: **S1485444D**

Blood Group: **O+**

Date of issue: **13-06-1991**

APT BLK 132 CLARENCE LANE #09-16

SINGAPORE 140132

Date: **07-11-2002**

No: **4824179**

01485444D




WORLD AUTO PTE LTD

47, Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA INSURANCE COMPANY LIMITED
 105 CECIL STREET #18-00 & #19-00 THE OCTAGON
 069534

Attention : Motor Claim Department
 Contact : 6222 2366 Fax No. : 62247478

Estimate : ES000187

Date : 21/06/2018
 Vehicle Num. : SLH 6403Y (LCR)
 Make/Model : HONDA SHUTTLE HYBRID
 Chassis/Eng# :
 Accident Date : 20/06/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BOOT LID ✓ DMG		1,150.00 ✓
2.	1	REAR WINDSCREEN GLASS MOULDING ✓ WBC		260.00 195
3.	1	REAR BOOT HYBRID EMBLEM (SHUTTLE) ✓ NEC		100.00 88.60
4.	1	REAR BOOT SHUTTLE EMBLEM (SHUTTLE) ✓ NEC		100.00 85.40
5.	1	REAR BOOT INNER TRIM BOARD X NN		345.00 X NN
6.	1	REAR BOOT HAND GRIP COVER ✓ Deform		65.00
7.	1	REAR BOOT LOCK ASSY ✓ IM		550.00 ✓
8.	1	REAR BOOT LOCK CATCH X } NN		100.00 X }
9.	2 LH & RH	REAR BOOT ABSORBER X } NN	380.00	760.00 X } NN
10.	1	REAR NUMBER PLATE LAMP GARNISH X NN		460.00 X }
11.	1	REAR BOOT WEATHER STRIP ✓ Deform		180.00
12.	2 LH & RH	REAR BOOT REFLECTOR LAMP X NN	580.00	1,160.00 X }
13.	2 LH & RH	REAR TAIL LAMP X NN	580.00	1,160.00 X }
14.	1	REAR BUMPER ✓ DMG		1,150.00
15.	2 LH & RH	REAR BUMPER REFLECTOR GARNISH RH ✓ LH X NN	130.00	260.00 130
16.	2 LH & RH	REAR BUMPER REFLECTOR LENS X } NN	120.00	240.00 X }
17.	2 LH & RH	REAR BUMPER INNER FOAM X } NN	150.00	300.00 X }
18.	2 LH & RH	REAR BUMPER RETAINER X } NN	130.00	260.00 X }
19.	1	REAR END PANEL ✓ DT		950.00
20.	1	REAR END PANEL TOP GARNISH ✓ CRK R Δ		260.00
21.	2 LH & RH	REAR TAIL LAMP PANEL X } NN	450.00	900.00
22.	1	REAR FLOOR BOARD X NN		450.00 X NN
23.	1	REAR FLOOR PANEL R		650.00
24.	1	REAR COMPARTMENT BOX ✓ CRK		420.00
25.	1	REAR COMPARTMENT BOX BACK COVER ✓ CRK		160.00
26.	1	REAR BOOT TOOLKIT FOAM BOX ✓ Deform		120.00
27.	2 LH & RH	REAR FENDER INNER TRIM BOARD ✓ Deform CRK Δ DF	345.00	690.00
List Total S\$:				13,190.00
20.00% Discount S\$:				2,638.00
Rear Bumper Tow Cover ✓ MIS \$ 120				
Rear Antena Sensor ✓ CUT \$ 280				
				10,552.00

Sathya Sai
 22/6/2018
 98072012

- Part by Part repair
- Photo before paint
- Question mark item photo

[Signature]
 25/6/18

7 days

CONTINUE / ...

LIK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

WORLD AUTO PTE LTD

47, Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA INSURANCE COMPANY LIMITED
 105 CECIL STREET #18-00 & #19-00 THE OCTAGON
 069534

Attention : Motor Claim Department
 Contact : 6222 2366 Fax No. : 62247478

Estimate : ES000187

Date : 21/06/2018
 Vehicle Num. : SLH 6403Y (LCR)
 Make/Model : HONDA SHUTTLE HYBRID
 Chassis/Eng# :
 Accident Date : 20/06/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

SPECIAL NETT ITEMS :				
1.	1	REAR BOOT INNER TRIM BOARD CLIP ✓ NCL	50.00	30
2.	1	REAR BUMPER CLIP ✓ NCL	50.00	30
3.	1	REVERSE SENSOR ✓ DMG	280.00	260
4.	1	REAR END PANEL TOP GARNISH CLIPS ✓ NCL	50.00	30
5.	1	TOWING CHARGE ✓	60.00	
6.	1	REAR WINDSCREEN SEALANT ✓ NCL	120.00	30 50 Δ
Special Nett Total S\$:			610.00	
LABOUR :				
REMOVE & REFIT REAR WINDSCREEN GLASS			180.00	120
TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES			180.00	100 60 Δ
LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.			1,800.00	1,200 1,000 Δ
PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/ OUTER)			1,400.00	300
TO REMOVE AND INSTALL HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENTS FOR SAFETY PRECAUTIONS.			380.00	200
TO CONDUCT A STANDARD OF OPEARTING PROCEDURE POST REPAIRS DIAGNOSTIC SCAN TEST A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS.			380.00	200
Labour Total S\$:			4,320.00	

E. & O.E. Total S\$: 15,482.00

for WORLD AUTO PTE LTD

6194
 - 20%
 4955.2
 + 400
 + 2380
 7735.2
 + 320
 8055.2

∴ \$ 8055.20 @ 7 days
 confirmed



Reg No: 52977287 J

CASH SALE/WORK ORDER

迅速拖車服務

SPEEDWAY RECOVERY SERVICE

Singapore Post Centre Post Office P.O. Box 201 Singapore 914007

Tel: 6841 0080

No: M 10700

Date: 20/6/18

Name/Company World Auto

Vehicle No. SLH 0403Y Model Shuttle

From Have-lock RD

To 1 Kranji Loop

Remarks _____

- Jump Start
- Tyre Replacement
- Accident/Breakdown
- Multi/Basement
- With Load/Cargo Box
- King Dolly
- Transport Charge
- Low Body Kit
- Door Opening Service
- Crane Up/Winch Out
- Collect Doc/Key
- Repo Payment
- Trips

Time: 12:37 - 13:10 - 14:00

Amount \$ 60

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

Donci

Tow Truck

**24 HRS TOWING SERVICE
6841 0080**

www.speedwayrecovery.com
Email: speedwaytowing@gmail.com

Received By [Signature]

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Jun 2018		21 Jun 2018 17:34 Edit Adj Rpt	\$48,055.20 Edit Estimates	\$48,055.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	TAN TECK ENG, ID: -	
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K	
Vehicle Reg. No.:	SLH6403Y	Date of Loss: 20/06/2018 12:00 - :59 [19 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D03086C02/9	Policy/Cover Note No.: DMPCSN3122911701
Vehicle Reg. No. (Insured):	SJL2469L	Policy No. (Claimant): '999994927
		Excess: S\$0.00
Repairer:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop, 739535 Kranji - Tel: 63621776	
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Sharon Han - 63896]	
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sathya Sai Kathirrasen] ... [Final Rpt due 02/07/2018]	
Adj Asg. Remarks:	Please survey third party vehicle & let us have your recommendation on estimated amount required to repair the vehicle if there is NO estimate provided during pre-repair inspection. APPOINT SIMON HO AS SJE.	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*SLH6403Y (SNM18D03086C02/9)
[SJL2469L]
TP
LCRF PTE LTD
Jun 20 2018 12:00PM
[TAN TECK ENG]
World Auto Pte Ltd - Kranji

Upload Documents Upload Photos Compose New Letter			View	View in Browser <input type="button" value="v"/>
Assessment Reports			1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		Thumbnail Print
1	20/06/18 15:09	Accident Statement		Load HTM
2	21/06/18 11:53	Addendum Sheet		Load TIFF
3	21/06/18 11:53	Accident Statement Addm. #1		Load HTM
Photos/Images			3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		Thumbnail Print
1	20/06/18 15:07	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG <input checked="" type="checkbox"/>
2	20/06/18 15:07	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG <input checked="" type="checkbox"/>
3	20/06/18 15:07	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG <input checked="" type="checkbox"/>
4	20/06/18 15:07	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG <input checked="" type="checkbox"/>
5	20/06/18 15:07	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG <input checked="" type="checkbox"/>
6	20/06/18 15:07	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG <input checked="" type="checkbox"/>
7	20/06/18 15:07	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG <input checked="" type="checkbox"/>
8	20/06/18 15:07	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG <input checked="" type="checkbox"/>
9	20/06/18 15:07	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG <input checked="" type="checkbox"/>
10	20/06/18 15:07	Identification Card <small>[Linked Accident Report Documents]</small>		Load JPG <input checked="" type="checkbox"/>
11	20/06/18 15:07	Driving License <small>[Linked Accident Report Documents]</small>		Load JPG <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	25/06/18 09:41	General View		Load JPG <input checked="" type="checkbox"/>
2	25/06/18 09:41	General View		Load JPG <input checked="" type="checkbox"/>
3	25/06/18 09:41	General View		Load JPG <input checked="" type="checkbox"/>
4	25/06/18 09:41	General View		Load JPG <input checked="" type="checkbox"/>
5	25/06/18 09:41	General View		Load JPG <input checked="" type="checkbox"/>
6	25/06/18 09:41	General View		Load JPG <input checked="" type="checkbox"/>
7	25/06/18 09:41	General View		Load JPG <input checked="" type="checkbox"/>
8	25/06/18 09:41	General View		Load JPG <input checked="" type="checkbox"/>
9	25/06/18 09:41	General View		Load JPG <input checked="" type="checkbox"/>
10	25/06/18 09:41	General View		Load JPG <input checked="" type="checkbox"/>
11	25/06/18 09:41	General View		Load JPG <input checked="" type="checkbox"/>
12	25/06/18 09:41	General View		Load JPG <input checked="" type="checkbox"/>
13	25/06/18 09:41	General View		Load JPG <input checked="" type="checkbox"/>
14	25/06/18 09:41	General View		Load JPG <input checked="" type="checkbox"/>
15	25/06/18 09:41	General View		Load JPG <input checked="" type="checkbox"/>
16	25/06/18 09:41	General View		Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
17	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
18	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
19	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
20	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
21	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
22	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
23	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
24	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
25	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
26	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
27	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
28	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
29	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
30	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
31	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
32	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
33	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
34	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
35	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
36	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
37	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
38	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
39	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
40	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
41	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
42	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
43	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
44	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
45	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
46	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
47	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
48	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
49	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
50	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
51	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
52	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
53	25/06/18 09:41	Odometer Reading		<input checked="" type="checkbox"/>
54	25/06/18 09:41	Chassis Number		<input checked="" type="checkbox"/>
55	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
56	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
57	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
58	25/06/18 09:41	General View		<input checked="" type="checkbox"/>
59	27/06/18 10:39	Dismantled Parts		<input checked="" type="checkbox"/>
60	27/06/18 10:39	Dismantled Parts		<input checked="" type="checkbox"/>
61	27/06/18 10:39	Dismantled Parts		<input checked="" type="checkbox"/>
62	27/06/18 10:39	BEFORE PAINT		<input checked="" type="checkbox"/>
63	27/06/18 10:39	BEFORE PAINT		<input checked="" type="checkbox"/>
64	27/06/18 10:39	BEFORE PAINT		<input checked="" type="checkbox"/>
65	27/06/18 10:39	BEFORE PAINT		<input checked="" type="checkbox"/>
66	27/06/18 10:39	BEFORE PAINT		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
67	27/06/18 10:39	BEFORE PAINT	 Load JPG	<input checked="" type="checkbox"/>
68	27/06/18 10:39	BEFORE PAINT	 Load JPG	<input checked="" type="checkbox"/>
69	27/06/18 10:39	BEFORE PAINT	 Load JPG	<input checked="" type="checkbox"/>
70	27/06/18 10:39	BEFORE PAINT	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/06/18 17:31	TP NOTIFICATION	 Load PDF	
2	21/06/18 17:32	INSURE REPORT	 Load PDF	

No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	20/06/18 15:07	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	20/06/18 15:07	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIFF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	20/06/18 15:09	Accident Statement	 Load HTM	
2	21/06/18 11:53	Addendum Sheet	 Load TIFF	
3	21/06/18 11:53	Accident Statement Addm. #1	 Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	20/06/18 15:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	20/06/18 15:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	20/06/18 15:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	20/06/18 15:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	20/06/18 15:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	20/06/18 15:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	20/06/18 15:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	20/06/18 15:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	20/06/18 15:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	20/06/18 15:07	Identification Card	 Load JPG	<input checked="" type="checkbox"/>
11	20/06/18 15:07	Driving License	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	20/06/18 15:07	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	20/06/18 15:07	Sketch Plan #2	 Load TIFF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118011308/VSD3Q2

Date: 30/07/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3122911701
Claimant Vehicle No :	SLH6403Y	Insured Vehicle No :	SJL2469L
Date of Loss:	20/06/2018	Nature of Claim:	TP
		Claim No:	SNM18D03086C02/9

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH6403Y	Engine No:	LEB4263704
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Chassis No:	GP71043785
Reg. Date:	14/11/2016 (Man. Year: 2016)	Odometer:	64142 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Giti 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,422.00	5,615.20	5,806.80	50.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,380.00	2,440.00	1,940.00	44.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,802.00	8,055.20	7,746.80	49.02
+ GST 7.00/7.00% (S\$)	1,106.14	563.86	542.28	49.02
Nett Amount (S\$)	16,908.14	8,619.06	8,289.08	49.02

INSPECTION

Date of Assignment:	21/06/2018	Inspected At:	World Auto Pte Ltd - Kranji (HQ)
Date Inspected:	22/06/2018		No 1 Kranji Loop
			Singapore 739535
Estimated Period of Repair:	7.0 days		

Adjuster: Sathya Sai Kathirrasen

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source:	(Last Synchronised: 30 Jul 2018)
Parts:	N/A HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH6403Y)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Damaged	1,150.00 FL	*1,150.00 FL
2	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	250.00 FL	*195.00 FL
3	1		*REAR BOOT HYBRID EMBLEM (SHUTTLE)	Necessary	100.00 FL	*88.60 FL
4	1		*REAR BOOT SHUTTLE EMBLEM (SHUTTLE)	Necessary	100.00 FL	*85.40 FL
5	1		*REAR BOOT INNER TRIM BOARD	Not Necessary	345.00 FL	*- FL
6	1		*REAR BOOT HAND GRIP COVER	Deformed	65.00 FL	*65.00 FL
7	1		*REAR BOOT LOCK ASSY	Jammed	550.00 FL	*550.00 FL
8	1		*REAR BOOT LOCK CATCH	Not Necessary	100.00 FL	*- FL
9	2		*LH & RH REAR BOOT ABSORBER	Not Necessary	760.00 FL	*- FL
10	1		*REAR NUMBER PLATE LAMP GARNISH	Not Necessary	460.00 FL	*- FL
11	1		*REAR BOOT WEATHER STRIP	Deformed	180.00 FL	*180.00 FL
12	2		*LH & RH REAR BOOT REFLECTOR LAMP	Not Necessary	1,160.00 FL	*- FL
13	2		*LH & RH REAR TAIL LAMP	Not Necessary	1,160.00 FL	*- FL
14	1		*REAR BUMPER	Damaged	1,150.00 FL	*1,150.00 FL
15	1		*LH & RH REAR BUMPER REFLECTOR GARNISH	O/S Necessary/N/SNot Necessary	260.00 FL	*130.00 FL
16	2		*LH & RH REAR BUMPER REFLECTOR LENS	Not Necessary	240.00 FL	*- FL
17	2		*LH & RH REAR BUMPER INNER FOAM	Not Necessary	300.00 FL	*- FL
18	2		*LH & RH REAR BUMPER RETAINER	Not Necessary	260.00 FL	*- FL
19	1		*REAR END PANEL	Dented	950.00 FL	*950.00 FL
20	1		*REAR END PANEL TOP GARNISH	Cracked	260.00 FL	*260.00 FL
21	2		*LH & RH REAR TAILLAMP PANEL	Repair	900.00 FL	*- FL
22	1		*REAR FLOOR BOARD	Not Necessary	450.00 FL	*- FL
23	1		*REAR FLOOR PANEL	Repair	650.00 FL	*- FL
24	1		*REAR COMPARTMENT BOX	Cracked	420.00 FL	*420.00 FL
25	1		*REAR COMPARTMENT BOX BACK COVER	Cracked	160.00 FL	*160.00 FL
26	1		*REAR BOOT TOOLKIT FOAM BOX	Deformed	120.00 FL	*120.00 FL
27	2		*LH & RH REAR FENDER INNER TRIM BOARD	Deformed	690.00 FL	*690.00 FL
28	1		*REAR BUMPER TOW COVER	Missing	120.00 FL	*120.00 FL
29	1		*REAR ANTENA SENSOR	Cut	280.00 FL	*280.00 FL
30	1		*REAR BOOT INNER TRIM BOARD CLIP	Necessary	50.00 FS	*30.00 FS
31	1		*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
32	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
33	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
34	1		*REAR WINDSCREEN SEALANT	Necessary	120.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					Sub Total (S\$)	14,140.00	6,934.00
					- List Item Discount on L Items 20.00/20.00% (S\$)	2,718.00	1,318.80
					Total Parts (S\$)	11,422.00	5,615.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGE	New	60.00	60.00
2	REMOVE & REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
3	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES	New	180.00	60.00
4	LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT ,CUT/WELD ,STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS	New	1,800.00	1,000.00
5	PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)	New	1,400.00	800.00
6	TO REMOVE AND INSTALL HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENTS FOR SAFETY PRECAUTIONS	New	380.00	200.00
7	TO CONDUCT A STANDARD OF OPEARTING PROCEDURE POST REPAIRS DIAGNOSTIC SCAN TEST A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS	New	380.00	200.00
Gross Labour Cost (\$\$)			4,380.00	2,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >