

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0704/2018/PH
Date : 20-Jun-18

VehicleIN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Koh Yau Hwee Alvin
Address : Blk 10B Lorong 7 Toa Payoh
#16-211
Singapore 312010
Telephone : HP +65 90612928
Type of Claim : Own Damage claims
Policy No. : 1800008731
Vehicle No : **SLW 2489 Y**
Model Code : Audi A3 Sedan 1.0 TFSI S
Model / Year : Feb-18
Engine No : CHZ 638055
Chassis No : WAUZZZ8V5J1041735
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 18-Jun-18
Place of Accident : CTE near lamppost 401

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 2489 Y.

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓
2	To dismantle and renew front bumper, lhs front fender, headlight and bonnet. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,700.00 1250.
3	To respray front bumper, lhs front fender and bonnet.	\$ 2,200.00 1650.
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: <u>\$ 5,452.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2489 Y.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	BUMPER COVER <i>Rehd</i>	\$ 1,739.00	✓
2	GUIDE SECTION - LH <i>men</i>	\$ 33.00	X
3	GRILLE - CENTER <i>men</i>	\$ 140.00	X
4	CLOSING ELEMENT - LH/RH <i>Aben</i>	2 \$ 508.00	X
5	COVER TRIM - LH/RH <i>Aben</i>	2 \$ 280.00	X
6	FRONT BUMPER COVER TRIM-LH/RH <i>men</i>	2 \$ 280.00	X
7	RADIATOR GRILLE <i>Credid</i>	\$ 1,239.00	✓
8	CLOSING ELEMENT <i>men</i>	\$ 167.00	X
9	COVER <i>men</i>	\$ 105.00	X
10	FOAM FILLER PIECE ?	\$ 162.00	?
11	SIDE REINFORCEMENT ?	\$ 633.00	?
12	CAUTION' SIGN STICKER <i>men</i>	\$ 12.00	✓
14	FRONT FENDER - LH <i>Regr</i>	\$ 746.00	X
15	BRACKET FOR FENDER - LH <i>men</i>	\$ 34.00	X
16	BRACE - LH <i>men</i>	\$ 84.00	X
17	LED HEADLIGHT - LH <i>Credid</i>	\$ 4,888.00	✓
18	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM-LH ?	\$ 123.00	?
19	BONNET <i>Bulleled</i>	\$ 2,755.00	✓
20	ATTACHMENT PARTS FOR BONNET <i>men</i> ?	\$ 141.00	?
TOTAL SPARE PARTS		\$ 14,069.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2489 Y.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	CATCH HOOK <i>plm</i>	\$ 78.00	<i>X</i>
22	EDGE PROTECTOR <i>plm</i>	\$ 24.00	<i>✓</i>
23	CATCH HOOK <i>plm</i>	\$ 55.00	<i>X</i>
24	FRONT NUMBER PLATE <i>Best</i>	S/N \$ 25.00	<i>✓</i>
25	SUNDRIES <i>?</i>	\$ 300.00	<i>?</i>
TOTAL SPARE PARTS		:	\$ 14,551.00
TOTAL LABOUR CHARGES		:	\$ 5,452.00
GRAND TOTAL		:	\$ 20,003.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Adnan King.
: 21/06/18.

:
: *not authorised, 05 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant