

AS 200 000

REF

Q1/TPD18011340/Lc

1275.74 (2.5% 400/20)

574-575

### ASSIGNMENT (Office)

Frage (Frage): Kannallah Kamis

SPF

Date Time: 16/5/2018

Estimated Cost:

Elliott

OD / TP / WS / TP RES / OD RES / EVA / ENV / MV / CS

To inspect Vehicle No. 2B98360J

Insured

a Workshop title

Tel



Policy No. MHASPF06000000485

Claim No: TP/P/28005/2018

Sum Insured

Excess

Make of Veh.  
(Client's Record)

D.O.A. 11/5/2018

CA 1 REV 1 REP. 1 REV 24 HRS

H.C.D. Entertainment.

Date/Time:

Version: Ccs1004d

## Value-Added

Date/Time	Action/Instruction	( ) Estimate
-----------	--------------------	--------------

SSS 8360I-X

388 8360I-X  
Work involved with 10 barrel & PSP technician & driven  
on 15th Aug 2018 @ TPP

Good!

*Below: Open file*      *SBS 8360*      *5x vehicles*

---

**Rohaizal (LKKAUTO)**

**From:** Kamaliah KAMIS (SPF) <Kamaliah\_KAMIS@spf.gov.sg>  
**Sent:** Sunday, 27 May 2018 8:06 PM  
**To:** Bryan Ang (LKKAUTO); Rohaizal (LKKAUTO)  
**Cc:** SPF-TP FAIT; Muhammad Khairil KAMAL (SPF)  
**Subject:** Mechanical Inspection Report Request

Hi Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the vehicle below:

**(a) Case IAFP-IB-20180525-Mechanical Inspection of Motorcycle, FBM 30 X (TP/IP/29687/2018)**

On 19/05/2018 at about 8.46 am, the Deceased was riding motorcycle FBM 30 X along Bukit Timah Road towards Upper Bukit Timah Road on the right most lane of 3 lanes road when he lost control of the motor cycle, side swiped onto the right side metal guard rail and skidded. The Deceased suffered serious injuries and was conveyed to Tan Tock Seng Hospital via ambulance. He succumbed to his injuries on the same day at the A & E Department and passed away at 9.55 am.

**FBM 30 X** - Rider (Deceased)

IO In-Charge: SIO Farhan

**(b) Case IAFP-IB-20180525-Mechanical Inspection of Motorcycle, FBD 9969 B (TP/IP/30413/2018)**

On 23/05/2018 at about 7.32 a.m., the Deceased was found lying motionless along Tuas South Way towards Tuas Avenue 5, near LP 45, in between lanes 2 and lane 3 of the 3-lanes road while his motorcycle was found crashed into a concrete barricade. It was believed that the Deceased was riding straight along Tuas South Way towards Tuas Avenue 5 on lane 2 of the 3-lanes road when he collided into a concrete barricade on the road. The barricade was meant to seal off the road from public entry. After the collision, the Deceased was flung forward about 11 metres and landed in between lanes 2 and 3 of the 3-lanes road. Due to the accident, the Deceased was pronounced dead at 8.12 a.m. by Paramedic Yap.

**FBD 9969 B** - Rider (Deceased)

IO In-Charge: SIO Farhan

**(c) Case IAFP-IB-20180525-Mechanical Inspection of Bus, SBS 8360 J (TP/IP/28005/2018)**

On 11/05/2018 at about 9.03 a.m., the driver of SBS motor bus (SBS8360J) was stopping at a bus stop along Jalan Jurong Kechil towards PIE, behind a SMRT motor bus, which was on stationary at the bus stop. The driver claimed that he was applying brakes, however, his motor bus (SBS8360J) brakes was not functioning, resulting in a head-to-rear collision with the SMRT motor bus. Due to the accident, both drivers and passengers from both motor bus were conveyed by ambulance to NUH, NTFH and TTSH.

**SBS 8360 J** - 33 Casualties

IO In-Charge: IO Khairil

**(d) Case IAFP-IB-20180525-Mechanical Inspection of Motorcycle, JRK 2938 (TP/IP/28997/2018)**

On 16/05/2018 at about 6.15 a.m., the rider of motorcycle, JRK 2938 travelling along Penjuru Road towards End, before West Coast Road and noticed that the pedestrian (deceased) was standing on the side of the road when he was about 50 metres away, in front of Blk 54 Coffeeshop. The rider claimed he slowed down upon seeing the pedestrian (deceased) but upon reaching about half-car length away, the pedestrian (deceased) suddenly dashed across the road from rider's left to right. The rider could not brake in time and collided onto pedestrian's right side. As a result of the accident, the pedestrian (deceased) sustained head injuries and was conveyed unconscious (standby case due to traumatic arrest) to NTFGH. However on 18/05/2018 at 2pm, the pedestrian was pronounced dead.

**JRK 2938 - Rider (Slightly injured)**

**Pedestrian - Deceased**

IO In-Charge: SIO Yazid

**(e) Case IAFP-IB-20180525-Mechanical Inspection of Bus, SMB 1607 D (TP/IP/30827/2018)**

On 24/05/2018 at about 9.05 a.m., the SMRT bus, SMB 1607 D, on the single lane road of Choa Chu Kang Avenue 5 towards Choa Chu Kang Avenue 4. While travelling straight, the front right portion of his bus collided onto the Deceased, who was crossing the road from his right to left. The Deceased had just stepped down from the centre divider when the collision happened. The Deceased was conveyed in critical condition to the NUH by ambulance however he succumbed to his injuries and was pronounced dead in hospital at 10.46 a.m.

**SMB 1607 D - Driver (Not injured)**

**Pedestrian - Deceased**

IO In-Charge: SIO Shahril

2. These request has been approved by my management.
3. Thank you Sir.

Cc: FAIT Team & IO Khairil, fyip

Best regards,

**Karnaliah** Kamis (Miss)

Investigation Officer | Fatal Accident Investigation Team

Traffic Police | Singapore Police Force

DID: (65) 6547 6435 | FAX: (65) 6547 6352



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

*Callum: Open Rk*

*SBS 8360 J not done*

**Rohaizal (LKKAUTO)**

**From:** Bryan Ang (LKKAUTO)  
**Sent:** Wednesday, 16 May 2018 8:50 AM  
**To:** Muhammad Khairil KAMAL (SPF); Rohaizal (LKKAUTO)  
**Cc:** Muhammad Taufiq ANIS (SPF); Chin Loong NEO (SPF)  
**Subject:** RE: Request of Mechanical Inspection for SBS8360J

Dear IO Khairil

Below request noted.

Dear Haizal

Please carry out the needful.

Best Regards,

**Bryan Ang**

**LKK Auto Consultants Pte Ltd**

phone: 6256-3561 | email: [bryanang@lkkauto.com](mailto:bryanang@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Muhammad Khairil KAMAL (SPF) [[mailto:Muhammad\\_Khairil\\_KAMAL@spf.gov.sg](mailto:Muhammad_Khairil_KAMAL@spf.gov.sg)]  
**Sent:** Wednesday, 16 May 2018 1:59 AM  
**To:** Bryan Ang (LKKAUTO) <[bryanang@lkkauto.com](mailto:bryanang@lkkauto.com)>  
**Cc:** Muhammad Taufiq ANIS (SPF) <[Muhammad\\_Taufiq\\_ANIS@spf.gov.sg](mailto:Muhammad_Taufiq_ANIS@spf.gov.sg)>; Chin Loong NEO (SPF) <[NEO\\_Chin\\_Loong@spf.gov.sg](mailto:NEO_Chin_Loong@spf.gov.sg)>  
**Subject:** Request of Mechanical Inspection for SBS8360J

Dear Sir,

Preceding email refers.

- 2 HI has approved for the mechanical inspection to be done.
- 3 Attached is the Internal Approval for Procurement (IAFP) form.
- 4 Please assist to conduct mechanical inspection to SBS8360J. Thank you.

Regards,

Muhammad Khairil Bini Kamal  
Investigation Officer  
General Investigation Team "A"  
Traffic Police  
Singapore Police Force  
DID: (65) 6547 6131 | FAX: (65) 6547 6259



**HOME TEAM**  
TRANSFORMATION 2025  
One Home, One Team  
Building Our Future Together

**From:** Kang Bee NG (SPF)  
**Sent:** Monday, 14 May 2018 11:04 AM  
**To:** Muhammad Khairil KAMAL (SPF) <Muhammad\_Khairil\_KAMAL@spf.gov.sg>  
**Cc:** Chin Loong NEO (SPF) <NEO\_Chin\_Loong@spf.gov.sg>  
**Subject:** RE: Approval for Mechanical Inspection for SBS8360J

Approved.

Ng Kang Bee  
Head Investigation  
Traffic Police  
Singapore Police Force  
DID: (65) 6547 6199



**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

---

**From:** Muhammad Khairil KAMAL (SPF)  
**Sent:** Saturday, 12 May 2018 12:38 AM  
**To:** Kang Bee NG (SPF) <NG\_Kang\_Bee@spf.gov.sg>  
**Cc:** Chin Loong NEO (SPF) <NEO\_Chin\_Loong@spf.gov.sg>  
**Subject:** Approval for Mechanical Inspection for WC5332X

Dear Ma'am,

May I seek your approval to send one motor bus (SBS8360J) for mechanical inspection?  
Attached is the Internal Approval for Procurement (IAFP) form for your approval.

2 Briefly, this is a case of a SBS motor bus collided into a SMRT motor bus. On 11/05/2018 at about 9.03 a.m., the driver of SBS motor bus (SBS8360J) was stopping at a bus stop along Jalan Jurong Kechil towards PIE, behind a SMRT motor bus, which was stationary at the bus stop. The driver claimed that he was applying brakes, however, his motor bus (SBS8360J) brakes were not functioning, resulting in a head-to-rear collision with the SMRT motor bus. Due to the accident, both drivers and passengers from both motor buses were conveyed by ambulance to NUH, NTFH and TTSH. Total of 33 casualties.

Regards,

Muhammad Khairil Bin Kamal  
Investigation Officer  
General Investigation Team "A"  
Traffic Police  
Singapore Police Force  
DID: (65) 6547 6131 | FAX: (65) 6547 6259



**HOME TEAM**  
• TRANSFORMATION 2025 •  
*One Home, One Team*  
*Building Our Future Together*

**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

## INTERNAL APPROVAL FOR PROCUREMENT

### Part A: To be completed by Requestor

Date: 12-May-18

#### Background information to establish need for procurement:

For the investigation of a minor road traffic accident (Reference TP/IP/28005/2018), a mechanical inspection of a motor bus SBS8360J is required because of the following reason/s:

On 11 May 2018 at about 0903hrs, driver of motor bus SBS8360J was travelling along Jalan Jurong Kechil towards Pan Island Expressway and was stopping at a bus stop. Driver claimed that he was applying brakes when his motor bus brakes was not functioning, resulting in the said motor bus colliding into the rear of a motor bus. May we seek your approval for engagement of LKK Auto Consultants for this service as per TENDER NO.: HOMHQ0ETT16000362 / LETTER OF ACCEPTANCE NO. HOMHQ0ECO17000159, please.

Estimated Quantity:	1 report
Estimated Procurement Value (EPV):	(2) Motor cars and other goods vehicle (unladen weight not exceeding 2500kg) at \$550
Estimated Date Of Delivery:	6 weeks from date of request
Procurement Approach:	GeBiz E-Catalogue (Existing Contract)

#### Requested by:

SSgt Muhammad Khairil Bin Kamal  
IO GIT 'A' / TP  
14-May-18

(Name, Designation & Unit, Date)

### Part B: To be completed by Head/CO, Deputy of Branch, Chairman, Vice-Chairman, or Convenor

#### Supported by:

Supt (1A) Ng Kang Bee  
Head Investigation  
14-May-18

(Name, Designation & Unit, Date)

### Part C: To be completed by Finance Officer

Account Code: 218999

FUNDS AVAILABLE

MX15 Muhammad Taufiq Bin Anis  
Finance Officer  
14-May-18

(Name, Designation & Unit, Date)

### Part D: To be completed by Head Corporate Services

#### DECISION BY APPROVING OFFICER (AO):

(Choose from Dropdown Menu)

Supt(1A) Wendy Chio Sue Lin  
Head Corporate Services

[Click here, press Ctrl;](#)

(Name, Designation, Date)