

ESTIMATE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Vikneshvaran s/o Selvadurai	Cust No/Name FCV01515/Mr Vikneshvaran s/o Selvadurai
8 Sembawang Hills Drive	Reg No/Reg Date SJK1101J / 12/10/2017
Singapore 575887	Date In/Mileage / 0
Contact No	Chassis No VF73ABHZTHJ761274
	Engine No 10JBHD3086934
	Make/Model CIT/GC4P 1.6 BLUEHDI EAT6 INTENSIVE ML
	Colour/Trim PYM ROUGE RUBI / IXF YATAGO GREY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
FCV01515	CRDVCH	15/05/2018/ 09:07	TLC	442 / CocoLu	13487

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000				900 1200.00
TO RENEW REAR BUMPER, REPAIR TAILGATE				
E PNT98000				840 1265.00
TO SPRAY PAINT FOR REAR BUMPER, TAILGATE				
E PNT88000				80 100.00
TO REMOVE & INSTALL PARKING SENSOR				
A 54900099				50.00
TO CHECK WIRING & ELECTRICAL SYSTEM				
A 54900099				300.00
TO CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM				
M SUNDRY				20.00
Sundry				
M REAR BUMPER	1.00	858.00	0.00	858.00
M BUMPER BRACKET	1.00	258.00	0.00	258.00
M BUMPER SKIRT	1.00	313.00	0.00	313.00
M BRACKET SET	1.00	101.00	0.00	101.00
M BRACKET SET LAT	1.00	101.00	0.00	101.00
M BUMPER BRACKET	1.00	296.00	0.00	296.00
M STIFFENER LH	1.00	59.00	0.00	59.00
M LOW RR PAN FIX	1.00	167.00	0.00	167.00
M TAIL-LIGHT LH COMPLEMENTAIRE	1.00	168.00	0.00	168.00

Estimate

Rasul
Hp 9000068

4 days

25/06/18 @ 1700

Resurvey by paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirmed & accepted by
 Signature:
 Date:

Authorized signatory and company stamp

Parts	2,321.00
Labour	2,915.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	20.00
Total (w/o GST)	5,256.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.