

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 649C**AAD1806-181***Not Authorized
L1 Sup @ 3200h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF 649C

VF1ABL15AUC278383

RENAULT

LATITUDE

19.6.2018

LONPAC

PART		LIST	
1	BUMPER COVER FRT	\$	Bur 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	Sn 181.75 X
1	BUMPER ABSORBER FRT	\$	Sn 394.68 X
1	BUMPER RETAINER FRT RH	\$	D.Y 150.77 ✓
1	BUMPER SUPPORT FRT	\$	Sn 123.88 X
1	BUMPER UNDERTRAY FRT	\$	Sn 472.83 X
1	BUMPER GRILLE LOWER FRT	\$	Sn 266.80 X
1	BUMPER FOG LAMP GRILLE RH	\$	Sn 207.21 X
1	BUMPER BEAM FRT	\$	N 914.08 X
1	HEADLAMP RH	\$	Gr 1,184.43 ✓
1	HEADLAMP PANEL FRT RH	\$	N 152.15 X
1	FENDER PANEL FRT RH	\$	Bur 783.83 ✓
1	WHEELARCH FRT RH	\$	Sn 278.84
1	FENDER BRACKET LOWER RH	\$	Sn 15.79
1	FENDER INSULATOR RH	\$	Sn 130.84
1	DOOR PANEL FRT RH	\$	N 2,844.66
1	RADIATOR GRILLE	\$	Sn 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	Sn 225.36
1	RADIATOR GRILLE FRAME	\$	Sn 1,353.75
1	RADIATOR FAN COWLING	\$	Sn 820.54
1	RADIATOR FAN MOTOR LH	\$	Sn 967.36
1	RADIATOR FAN MOTOR RH	\$	Sn 1,479.46
1	FRAME FULL SUPPORT PANEL	\$	Sn 615.90
1	FRAME FULL SUPPORT BRACKET	\$	N 89.79
1	DOOR MIRROR ASSY RH	\$	Sn 1,483.40
1	DOOR PANEL FRT RH	\$	N 2,844.66
1	BONNET	\$	N 1,941.63
1	BONNET INSULATOR	\$	Sn 405.73
1	BONNET STRUT LH	\$	Sn 88.61
1	BONNET STRUT RH	\$	Sn 88.61

Trans-cab Auto Services Pte Ltd**AAD1806-181**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 649C

1	BONNET HINGE LH	\$	R	348.31	}	X
1	BONNET HINGE RH	\$	R	348.31		
1	BONNET LOCK	\$	R	305.48		
1	BONNET CABLE	\$	S	119.19		
1	BONNET CABLE COVER	\$	S	161.03		
1	BONNET SEAL OUTER	\$	S	92.36		
1	BONNET SEAL INNER	\$	S	157.28		
1	SUBFRAME OUTER FRT	\$	S	2,652.45		
1	SUBFRAME BRACKET OUTER LH	\$	S	92.36		
1	SUBFRAME BRACKET OUTER RH	\$	S	92.36		
1	ENGINE UNDERTRAY	\$	S	564.98		
1	A/C CONDENSER	\$	S	2,020.37		
1	A/C CONDENSER GARNISH LH UPPER	\$	S	39.67		
1	A/C CONDENSER GARNISH RH UPPER	\$	S	39.67		
1	A/C CONDENSER GARNISH LH	\$	S	58.81		
1	A/C CONDENSER GARNISH RH	\$	S	59.60		
1	LOWER ARM RH	\$	S	685.76		
1	KUNCKLE ARM RH	\$	S	846.98		
1	ABSORBER FRT RH	\$	S	360.54		
1	STABILIZER BAR FRT	\$	S	604.65		
1	DRIVESHAFT RH	\$	R	1,747.45		
1	WIPER RESERVOIR	\$	S	348.25		
1	WIPER RESERVOIR NECK	\$	S	136.11		
1	WIPER RESERVOIR MOTOR	\$	S	270.06		

TOTAL	\$	35,626.53
10%	\$	3,562.65
	\$	32,063.87

Specical Nett

1SET	BUMPER CLIP FRT	\$	R	66.00	✓
1	BUMPER BRACKET CLIP FRT RH	\$	R	12.00	X
1	BUMPER SUPPORT CLIP FRT RH	\$	R	10.50	X
1SET	BUMPER GRILLE LOWER CLIP	\$	R	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	R	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	R	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	R	30.00	X

Trans-cab Auto Services Pte Ltd**AAD1806-181**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 649C

1SET	WHEELARCH CLIP FRT RH	\$	<i>na</i> 30.50 X
6	BONNET INSULATOR CLIP L70Y	\$	<i>na</i> 7.30 X
2	BONNET STRUT L70Y	\$	<i>na</i> 88.61 X
2	BONNET CABLE CLIP L70Y	\$	<i>na</i> 6.31 X
2	BONNET CABLE COVER SCREW L70Y	\$	<i>na</i> 10.85 X

TOTAL	\$	421.08
--------------	-----------	---------------

TOTAL PARTS	\$	32,484.95
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00 <i>4001</i>
Putty and spray painting of the affected portion.	\$	4,000.00 <i>4401</i>
To rust-proofing of the affected areas.	\$	170.00 <i>301</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00 X
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 <i>201</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	<i>na</i> 380.00 X

Trans-cab Auto Services Pte Ltd**AAD1806-181**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 649CTo replace, refix and top up coolant for radiator \$ *~* 170.00 *X*To vacuum, replace, refix and recharge Air
Intercooler \$ *~* 170.00 *X***TOTAL \$ 11,090.00****Over All Total \$ 43,574.95****LUMP SUM (REPAIR DAY)***15 DAYS**2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: