

AUTOWORX HOUSE

C/O.176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64520715 FAX: 64529250

ESTIMATE

Not Authorised

8351.75

Aik Sun Demolition & Engineering
c/o 46 Lenton Plain
Singapore 786548

1 day

Date: 19/5/2016

QUANTITY	PARTICULARS	AMOUNT (\$)
<u>RE: ISUZU NPR85 / YM 6145 L</u>		
1 pc	rear tail gate s.nett	<i>Sm</i> 1,200.00 <i>X</i>
1 pc	rear tail gate hinge s.nett	<i>n</i> 120.00 <i>X</i>
1 pc	rear floor panel and frame s.nett	<i>n</i> 700.00 <i>X</i>
1 pc	rear tail lamp assy <i>155.00</i> s.nett	<i>can/can</i> 466.00 <i>✓</i>
1 pc	rear side gate s.nett	<i>n</i> 1,500.00 <i>X</i>
1 pc	rear side gate hinge s.nett	<i>n</i> 120.00 <i>X</i>
1 pc	"23 Pax" sticker s.nett	<i>nn</i> 20.00 <i>X</i>
1 pc	"100km/h" sticker s.nett	<i>nn</i> 20.00 <i>X</i>
1 pc	rear side gate guard s.nett	<i>Sm</i> 950.00 <i>X</i>
sub-total		5,096.00
To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.		1,000.00 <i>1000</i>
To apply putty and apray painting on affected areas.		300.00 <i>1000</i>
To check wiring system		40.00 <i>20</i>
Total		6,436.00

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Pg 1 of 1

Acknowledged by Repairer
Signature:
Date: