

F-1 AUTOCLINIC PTE LTD

Block 25 Kaki Bukit Road 4, #05-26 Synergy @ KB Singapore 417800
 HP: 96583371 TEL: (65) 67022915 FAX: 67022916

NET LINK LEASING PTE LTD
 Bk 25 Kaki Bukit Rd 4
 # 05-26 SYNERGY @KB
 Singapore 417800

FP AXA
 Vic

21st JUNE 2018

JTFHT02P100232585

Accident date: 19th JUNE 2018

Estimated repair cost for vehicle no: GBG5781K TOYOTA HIACE '17

S/n	Qty	Items	U/price	Amount
1	2	Front head lamp <i>RT Smashed</i>	\$380.40	\$760.80 <i>380.40</i>
2	2	head lamp bracket <i>not new</i>	\$92.50	\$185.00 <i>x</i>
3	1	front panel <i>distorted</i>		\$1,268.20 <i>863</i>
4	1	Front bumper <i>deformed</i>		\$634.58 <i>✓</i>
5	2	Front bumper side bracket <i>new</i>	\$38.20	\$76.40 <i>✓</i>
6	8	Front bumper clips <i>new</i>	\$12.90	\$103.20 <i>30</i>
7	1	front bumper center moulding <i>new</i>		\$188.20 <i>x</i>
8	1	front bumper number plate <i>new</i>		\$50.00 <i>x</i>
9	2	front bumper bracket <i>new</i>	\$185.00	\$370.00 <i>x</i>
10	1	Front bumper reinforcement <i>Best</i>		\$420.20 <i>✓</i>
11	2	Front bumper fog lamp <i>new</i>	\$155.20	\$310.40 <i>x</i>
12	1	Front grille <i>cracked</i>		\$454.25 <i>✓</i>
13	1	front grille logo <i>new</i>		\$42.10 <i>✓</i>
14	1	Front support panel <i>cracked</i>		\$420.10 <i>✓</i>
15	1	front support garnish <i>new</i>		\$129.20 <i>x</i>
16	1	Front Wiper Panel (Canter) <i>cracked</i>		\$380.20 <i>✓</i>
17	1	Front panel wiper arm <i>new</i>		\$161.40 <i>x</i>
18	1	Front side panel <i>distorted</i>		\$291.40 <i>✓</i>
19	1	front windscreen		\$1,105.20 <i>✓</i>
20	1	front windscreen inner seal		\$225.00 <i>x</i>
21	1	Front air cond condenser		\$1,371.80 <i>x</i>
22	2	Front horn	\$105.00	\$210.00 <i>x</i>
23	1	Front dashboard <i>cracked</i>		\$980.10 <i>✓</i>
24	1	Front radiator		\$1,528.80 <i>x</i>
25	1	Front radiator water tank		\$380.20 <i>x</i>

26	1	Radiator fan motor assy <i>new</i>	\$850.00 X
27	1	front <i>Air Cleaner Box</i>	\$: <i>649.70</i>
28	1	RH front door <i>RPS</i>	\$1,050.20 X
29	1	RH front door sticker <i>new</i>	\$30.00 ✓

5652.43
4239.32

Subtotal :- \$14,257.93

Labour charges

To Remove & refix

air-con condenser & top up gas

~~\$380.00~~ *120*

To Check Wiring System

~~\$80.00~~ *30*

Tuff kote

\$120.00 X

Wheel alignment (computer)

2090

\$150.00 X

Panel beating

~~\$1,200.00~~ *800*

Spray painting

~~\$1,200.00~~ *800*

To remove dashboard

~~300~~ *220*

Subtotal :- \$3,130.00

To remove brake pump to facilitates repairs

~~180~~ *120*

Total:- \$17,387.93

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To inspect damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No structural modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 6329.32

h/s: SK - 07 Days