

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6866 FAX NO.6366 8862
 CO/GST REG NO.201019626G
 SHC 5195C - III

ROEL

1	Front windscreen moulding	\$	NA 113.98 ✓
2	Front windscreen sealant	\$	NA 80.00 40% ✓
1	Front windscreen inner seal	\$	NA 60.00 30% ✓
2	Front tyre	\$	350.00 X
2	Front tyre rim	\$	240.00 X

TOTAL \$ 1,000.79

TOTAL PARTS \$ 44,319.13

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And renewal Of Parts, Adjust And Realign The Same	\$	3,500.00 200%
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00 180%
To Check Electrical Lighting Concerned.	\$	120.00 40%
To Reinstall Rear Bumper Parking Sensor.	\$	NA 170.00 X
Towing Fees.	\$	120.00 50%
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00 160%
To remove and renew engine and gear box mounting.	\$	NA 380.00 X
To transfer of tire, rim and on wheel balancing.	\$	NA 170.00 X
To remove and replace corporate sticker	\$	NA 330.00 X
To vacuum, replace, refix and recharge air condenser	\$	380.00 100%

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHC 5195C - III

ROEL

118	1	Power steering pump	\$	R 1,127.76 X
119	1	Power steering belt	\$	Sm 35.00 X
120	1	Power steering reservoir tank	\$	Sm 302.38 X
121	1	Power steering inlet / outlet pipe	\$	Sm 683.85 X
122	1	Power steering pump pulley	\$	Sm 208.77 X
123	1	Power steering hose - pressure	\$	Sm 60.00 X
124	1	Power steering hose - non pressure	\$	Sm 80.00 X
125	1	Crankshaft pulley	\$	Sm 323.34 X
126	1	Heater hose no. 1	\$	Sm 55.50 X
127	1	Heater hose no. 2	\$	Sm 55.50 X
128	1	Heater pipe no. 1	\$	Sm 98.20 X
129	1	Heater pipe no. 2	\$	Sm 98.20 X
130	1	Timing cover top	\$	Sm 265.00 X
131	1	Timing cover bottom	\$	Sm 78.00 X
132	1	Timing belt	\$	Sm 105.00 X
133	1	Timing belt tension bearing	\$	Sm 80.00 X
134	1	Thermostat housing	\$	Sm 145.00 X
135	1	Thermostat unit	\$	Sm 78.00 X
136	1	Thermostat temperature sensor	\$	Sm 85.00 X
137	1	Air vaccum valve	\$	Sm 70.00 X
138	1	Air vaccum valve bracket	\$	Sm 45.00 X
139	1	Front windscreen glass	\$	CMA 996.40 ✓
140	1	Front pillar inner garnish	\$	Sm 101.38 X
141	1	Front wiper blade	\$	Sm 68.82 X
142	1	Front wiper motor	\$	Sm 629.14 X
143	1	Front wiper arm	\$	Sm 78.09 X
144	1	Front wiper arm cover	\$	Sm 3.03 X
145	1	Front wiper garnish / wiper grille	\$	DIS/CM 113.38 ✓
146	1	Front wiper linkage	\$	Sm 321.56 X
147	1	Front kicking plate	\$	Sm 114.11 X
148	1	Rear kicking plate	\$	Sm 91.23 X
149	1	Front shock absorber assy LH	\$	BT 465.00 ✓
150	1	Front shock absorber top mounting LH	\$	M 132.63 ✓
151	1	Front shock absorber assy RH	\$	Sm 465.00 X
152	1	Front shock absorber top mounting RH	\$	Sm 132.63 X
153	1	Front lower arm LH	\$	DIT 517.14 ✓
154	1	Front spindle arm LH	\$	Sm 124.00 X
155	1	Front wheel bearing with hub LH	\$	Sm 268.00 X
156	1	Front strut bar LH	\$	DIT 100.79 ✓
157	1	Front strut bar bracket LH	\$	BT 231.58 ✓
158	1	Front lower arm RH	\$	Sm 517.14 X
159	1	Front spindle arm RH	\$	Sm 124.00 X

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
 SHC 5195C - III

ROEL

34	1	Front fender inner cowling LH	\$	CMA 112.20 ✓
35	1	Front fender inner wheel house panel LH	\$	R 595.72 X
36	1	Front chassis member / frame LH	\$	R 785.83 X
37	1	Support panel assy	\$	Replaced 626.30 X
38	1	Front top panel	\$	m 203.96 X
39	1	Headlamp panel LH	\$	m 107.38 X
40	1	Front fender RH	\$	R 732.83 ✓
41	1	Front fender indicator lamp RH	\$	Sm 42.06 X
42	1	Front fender inner cowling RH	\$	CMA 112.20 ✓
43	1	Front fender inner wheel house panel RH	\$	R 595.72 X
44	1	Front chassis member / frame RH	\$	R 785.83 X
45	1	Headlamp panel RH	\$	Replaced 107.38 X
46	1	Windscreen washer tank - filler neck	\$	m 80.42 ✓
47	1	Windscreen washer tank	\$	Nd 48.06 ✓
48	1	Windscreen washer tank motor	\$	Sm 204.62 X
49	1	Front fuse box - top cover	\$	m 93.01 ✓
50	1	Front fuse box lower cover	\$	CMA 191.37 ✓
51	1	Front fuse box centre junction	\$	CMA 367.17 ✓
52	1	Front fuse box centre cover	\$	CMA 22.68 ✓
53	1	Engine main harness wire	\$	R 1,151.75 X
54	1	Radiator assembly	\$	Br/Pu 1,890.20 ✓
55	1	Radiator fan blade	\$	Br 186.62 ✓
56	1	Radiator cowling	\$	CMA 184.77 ✓
57	1	Radiator top mounting bracket	\$	R 13.58 X
58	1	Radiator lower mounting bushing	\$	m 14.17 ✓
59	1	Radiator upper hose	\$	Pu 31.44 ✓
60	1	Radiator lower hose	\$	Sm 46.67 X
61	1	Radiator expansion tank	\$	Nd 150.63 ✓
62	1	Radiator overflow pipe	\$	Sm 35.00 X
63	1	Radiator grille	\$	Replaced 392.10 X
64	1	Steering column shaft	\$	Sm 385.00 X
65	1	Fan clutch	\$	Tm 642.98 ✓
66	1	Water pump	\$	Tm 316.55 ✓
67	1	Water pump pulley	\$	Sm 124.79 X
68	1	Engine main pulley (crankshaft pulley)	\$	Sm 323.34 X
69	1	Idle pump pulley	\$	Sm 15.00 X
70	1	Aircon condenser	\$	Br/Pu 1,098.16 ✓
71	1	Aircon condenser bracket	\$	R 30.00 X
72	1	Aircon condenser top mounting	\$	Sm 15.80 X
73	1	Aircon high-low power switch drier	\$	Sm 69.61 X
74	1	Aircon receiver drier	\$	Nd 143.00 ✓
75	1	Aircon hose - condenser to compressor	\$	Sm 324.59 X
				6418.46