

Asher

CRUISE AUTOCARE PTE LTD

QUOTATION

MS: AIG ASIA PACIFIC INSURANCE PTE. LTD.

TO: CLAIM DEPARTMENT

Fax: 6835 7416

Quotation No: QCA160188

Quote Date: 21-Jun-18

Contact No: 68416760

Fax No: 68413527

Veh No.	GBC1783C	Make / Model:	TOYOTA HIACE
S/N.	Description	LIST PRICE	Qty Amount
	PARTS		
1	FRONT HEADLAMP, LH	1111.10 25% \$636.00	1 \$636.00
2	FRONT BUMPER BRACKET, LH	\$143.20	1 \$143.20
3	FRONT BUMPER	833.32 \$475.10	1 \$475.10

DISCOUNT GIVEN 25 %

(\$313.58)

- SPECIAL NETT ITEM**
- 1 COMPANY REGISTRATION STICKER
 - 2 ART WORK ON SLIDING DOOR

270

\$20.00
\$500.00

1
1

\$20.00
\$500.00

- LABOUR**
- 1 LABOUR TO REMOVE DAMAGED PARTS, ALIGN AND REPLACE PARTS.
PANEL BEAT FRONT LH DOOR AND LH SLIDING DOOR
 - 2 SPRAY PAINTING ON FRONT LH DOOR AND LH SLIDING DOOR
 - 3 CHECK ELECTRICAL

830

\$400.00
\$600.00
\$50.00


LUMP SUM 20% DISCOUNT


(\$502.15)

Sub Total \$2,008.58
GST @ 7% \$140.60
Total: **\$2,149.18**

Cruise Autocare Pte Ltd.

Signature of Customer




Hp 90010068

4 days
4/8

22/06/18 @ 1055

Resurvey after repair

email: rasul@lkkauto.com

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

833.32

270.00

830.00

1933.32

20%

1546.68

45-1550

4 days

53 Ubi Avenue 1, Paya Ubi Industrial Park #03-53 Singapore 408934
TEL: 6841 6760 FAX: 6841 3527
Email: cruiseac@singnet.com.sg