

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHA 2506U

DATE 21/6/2018 16:43

MAKE :

MODEL : HYUNDAI i40

LONPAC

RIGHT WING MIRROR

T  
Fz

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Door Mirror (RH) <i>x rpr</i>			\$ 980.50
	SUB TOTAL			\$ 980.50
	LESS 20%			\$ 196.10
	DISCOUNTED TOTAL			\$ 784.40
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>250.00</del> <i>50</i>
	Spray Painting Charge			\$ <del>150.00</del> <i>50</i>
	Wiring Charge			\$ <del>50.00</del> <i>x</i>
	TOTAL LABOUR			\$ 450.00
	ESTIMATE TOTAL			\$ 1,234.40
<i>Kohli 11/14</i> <i>22/6/8 10204</i> <i>1 Py</i> <i>P/P</i> <i>After Rep p Lk</i>				
<div> LKK Auto Consultants hence notify the Repairer of the following: <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> </div> <div> Acknowledged by Repairer  Signature:  Date: </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				