

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD7076U

MAKE : HYUNDAI

MODEL : i40

Date: 21.06.2018

A15

DVA: 19.06.18

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	Rear Bumper <i>X repair</i>			\$ 603.60
1	Rear Bumper Sponge <i>X su</i>			\$ 143.40
10	Rear Bumper clips @ \$2.20 <i>X 8h</i>			\$ 22.00
1	Rear Bumper Under Cover <i>X su</i>			\$ 225.00
SUB TOTAL				\$ 994.00
LESS 20%				198.80
DISCOUNTED TOTAL				\$ 795.20
				\$ 0.00
Labour Charge				
1	Panel Beating			\$ 250.00 <i>100</i>
1	Spray Painting Charge			\$ 250.00 <i>200</i>
TOTAL LABOUR				\$ 500.00
ESTIMATE TOTAL				\$ 1,295.20

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Kalina/CCK

Page 1 of 1

21/6/18 11:00hrs

2 Bys

PP

After Repair photo

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: