



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133
T 65 6758 2222 F 65 6257 6931
E sales@scauto.com.sg
scauto.com.sg

Co. Reg. No. 199800107D

M/S	COMFORTDELGRO BUS PTE LTD 205 Braddell Rd SINGAPORE 579701
Insured	COMFORTDELGRO BUS PTE LTD
Policy	M485742

ESTIMATE Bill

GST Reg. No: 19-9800107D
Date: 21/6/2018
Our Case Ref. SC18/06/115/4CD-TP
Accident Date 4/6/2018

Damaged Vehicle No: PC5216G

S/no	Description	QTY	Price	Disc	Amount
<u>Replaced Parts</u>					
1	60 KM/HR STICKER ✓ <i>NGC</i>	1 PC	\$15.00	-	\$15.00
2	REAR BUMPER ✓ <i>CRK</i>	1 PC	\$1,880.00	-	\$1,880.00
3	REAR BUMPER STRUCTURE ?	1 PC	\$1,680.00	-	\$1,680.00
4	TAILLAMP RHS ✓ <i>SCR</i>	1 PC	\$687.21	-	\$687.21
5	REAR ENGINE COVER <i>R</i>	1 PC	\$1,980.00	-	\$1,980.00
<u>Labour Charges</u>					
1	LABOUR FOR WIRING	1	\$120.00 <i>60</i>	-	\$120.00
2	SPRAY PAINTING	1	\$2,000.00 <i>1500</i>	-	\$2,000.00
3	LABOUR FOR REAR PORTION	1	\$3,840.00 <i>2560</i>	-	\$3,840.00

Sathya Sai
22/6/2018
98072012

Sathya Sai@lkkauto.com

- Part by part repair
- Question Mark item photo
- Photo before paint

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sub Total \$ 12,202.21

Authorised Signature _____