

INS. CASE OWNER:

KC

cc 4, Asm 180 11401, / pa3<sup>52</sup>

LKK:

IDAC:

52954

Surveyor:

Kenneth

DOI:

ASSIGNMENT

26/6/18

Date/Time:

21/6/18

Registered in Merimen:

Pre-assign / CCU / FTE

SLC 2565R



Insured Vehicle No.:

Claim No.:

58m00LJQ

Name of Insured:

LI MA

Policy No.:

6833758711

Insured Tel No.:

HP:

96566883

Make / Model:

Honda Airwave

Excess Sec II :SS

D.O.A.:

20/6/18

Place of Accident:

Bukit Timah Expressway

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

WTT4590



INSRS:

WSP:

Tel:

Liability:

RMKS:

BH Auto



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

6/16  
04/1

WTT4590 - X

SLC2565R - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

24/6/18

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others: VEP

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

%

(

Agreed / Assessed)

BOLA S/N No.:

777 NTL

If NO or B 28, Ass. Lia:

Repair Cost: W/GAT

S\$

2247.00

Loss of Rental (BOR): W/GAT

S\$

720.00

(

9

days)

&gt; \$80

Loss of Use (LOU):

S\$

-

(\$

x

days)

Loss of Income (LOI):

S\$

-

(\$

x

days)

LOR only ☒ LOU only ☐

LOR + LOU

☐

LOR + LOI

☐

[Tick only one]

GIA/LTA Search

S\$

-

Medical:

S\$

-

Disbursement:

S\$

385-W (VEP)

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$

3202.20

Global Sum S\$:

3202.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$

3202-W

Name 1:

BH Auto Services Pte Ltd.

Payee 2: (Strike if N.A.)

S\$

-

Name 2:

-

Payee 3: (Strike if N.A.)

S\$

-

Name 3:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

#3000

COPY SENT

REF: ASM(GAXA)

11401 / 1403 - 10

## ASSIGNMENT

From: Date: 26 06 2018

Estimated Cost:

OD ☒ TF / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: WTT 4590

at Workshop m/s

BH Auto

of

Blk 1 Sen Ming Ind Est #01-115

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

10am - 4pm

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: RM 40k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

WTT 4590

Yr Regn:

04, 10

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda City

C.C.

1497

Colour:

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

202196

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

PMHGM2640AD100554

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size: F:

R:

185 / 60 R15

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

20/6/18

D.O.I.

26/6/18

Survey held at

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/6 File pass to Catherine

US \$ 2100 (red # 4320.36/674)

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I. (\$ )

Add Fee:

☐ Site Insp (\$ )  
☐ Interview (\$ )  
☐ Tech. Invs (\$ )  
☐ Weekend (\$ )

S+RS \$

Photos

Others

TOTAL

TOTAL



Full Report - V1  
Registration: WTT4590  
Printed: 23/06/2018 21:35

## PAGE 1 OF 5

# BH AUTO

Claim Reference: BA0904  
Assessment Number: BAC00002  
Version: BHAUTOSP/1

Full Report - V1  
Registration: WTT4590  
Printed: 23/06/2018 21:35



Primary Impact  
Secondary Impact

## Addresses

## Cost Summary

Total Labour	\$1,795.50
Total Paint/Material	\$200.42
Total Parts	\$3,869.44
Total of Additional Costs	\$555.00
Excess:	TBA
Grand Total Exc GST:	\$6,420.36
7 % GST:	\$449.43
Grand Total Inc GST:	\$6,869.79

## Repair Information

### LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR  
Price/Dent = \$45.00/HR

### Repair /

### Guide Number Repair Details

		WU	Cost Price (\$)
NO NUMBER	RUST PROOFING BODY SHELL PART	2.0	9.00
NO NUMBER	BOOTLID RUST PROOFING	1.0	4.50
8111A5)	R + R REAR BUMPER	3.0	13.50
8111A5)	RENEW REAR BUMPER	1.0	4.50
8111B8)	R + R LEFT REAR OUTER BUMPER BRACKET	2.0	9.00
8111B9)	R + R RIGHT REAR OUTER BUMPER BRACKET	2.0	9.00
7141A0	R + R LEFT REAR TAILLAMP	3.0	13.50
7411A5	R + R RIGHT REAR TAILLAMP	3.0	13.50
NO NUMBER	R + R L/R WHEELARCH SHELL	3.0	13.50
NO NUMBER	R + R R/R WHEELARCH SHELL	3.0	13.50
NO NUMBER	R + R DEFROSTER HOUSING	1.0	4.50
NO NUMBER	R + R FUEL FLAP	6.0	27.00
823104)	R + R BOOT LID	3.0	13.50
823104)	RENEW BOOTLID	9.0	40.50
	(REMOVED)		
	INCLUDES: R + R INNER TAILLAMPS, NUMBER		
	PLATE, BADGE, NUMBER PLATE LAMPS AND		
	LOCK		
832120)	R + R REAR SCREEN	10.0	45.00
8231B6	R + R BOOTLID SEAL	2.0	9.00
7141B4	R + R ADDITIONAL BRAKE LAMP	7.0	31.50
8231A9	BOOTLID STRIKER	2.0	9.00
NO NUMBER	RENEW REAR END PANEL CPL	45.0	202.50
NO NUMBER	RENEW LEFT SIDE PANEL	45.0	202.50
NO NUMBER	RENEW RIGHT SIDE PANEL	45.0	202.50
NO NUMBER	R + R SPARE WHEEL COVER	1.0	4.50
NO NUMBER	RENEW REAR FLOOR CPL	52.0	234.00

# BH AUTO

Claim Reference: BA0904

Assessment Number: BAC00002

Version: BHAUTOSP/1

Full Report - V1

Registration: WTT4590

Printed: 23/06/2018 21:35

857120	R + R L/UPPER C-PILLAR TRIM	4.0	18.00 X
857121	R + R R/UPPER C-PILLAR TRIM	4.0	18.00 X
NO NUMBER	R + R BOOT FLOOR CARPET	1.0	~ 4.50 X
8571C8	R + R L/BOOT COVER	3.0	13.50
8571C9	R + R R/BOOT COVER	3.0	13.50
7371B5	R + R REAR VEHICLE WIRING HARNESS	12.0	~ 54.00 X

## LABOUR COST

Total Work Units

278.0

Corrosion Protection

Corrosion Protection Internal Labour

0.3HRS

13.50

Sub Total

27.8HRS

\$1,251.00

Paint Labour

12.1HRS

544.50

Total Labour

39.9HRS

\$1,795.50

## PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

Guide Number	Description	WU	Cost Price (\$)
2711	REAR PANEL CPL NEW PART PAINTING	18.0	
2931	BOOTLID NEW PART PAINTING	14.0	
3481	L/R WING NEW PART PAINTING	25.0	
3482	R/R WING NEW PART PAINTING	25.0	
3900	BOOTFLOOR SURFACE PAINT	9.0	
2583	REAR BUMPER NEW PART PAINT K1R	10.0	

## LABOUR COST - PAINT

TIME(PAINT)

101.0

Preparation Main Work Metal

17.0

Preparation Comp. Work Plastic

3.0

Preparation Work Multi Layer Paint

0.0

Total Work Units (10WU/HR)

121.0

Total Paintwork Labour

12.1HRS

\$544.50

## MATERIAL COST - PAINT

New Part Painting

Cost Price

New Part Painting - Plastic K1R

\$109.96

Surface-/Blend Paint

\$41.18

Material-Const Main Work Metal

\$22.18

Material-Const Comp. Work Plastic

\$18.10

Total Excluding Pearlescent Uplift

\$9.00

Pearlescent Uplift @ 0.0%

\$200.42

Total Paint Material Cost

\$0.00

## PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
3189	1	3RD BRAKE LAMP BULB	33303S30003		0%	2.87U X
3190	1	ADD/BR/LAMP B/HOLDER	33513S50003		0%	14.20U X
3017	1	BADGE CITY	75722TM4H00		0%	30.00* ✓
3013	1	BADGE HONDA	75701TM0000		0%	25.00* ✓
3029	1	BOOT LID MOULDING	74890TM4H00		0%	68.00* X
4907	1	BOOT/TAILOUT COVER	84631TM4H01ZA		0%	195.00* X
3900	1	BOOTFLOOR	04655TM4H00ZZ		0%	503.00* X
2931	1	BOOTLID	68500TM4H00ZZ		0%	453.00* ✓
2977	1	BOOTLID LOCK	74851SNBJ12		0%	65.00* ✓
2979	1	BOOTLID LOCK CYL	74861TM0T11		0%	22.93U X
2944	1	BOOTLID SEAL	74865TM0T00		0%	75.00* X

Price Valid: 01/06/2015



# BH AUTO

Claim Reference: BA0904  
Assessment Number: BAC00002  
Version: BHAUTOSP/1

Full Report - V1  
Registration: WTT4590  
Printed: 23/06/2018 21:35

4921	1	BOOTLID TRIM M-KIT	USE SINGLE PARTS	0%	nn	0.00	
3172	2	CLIP FASTENING	91568TF0003	0%	nn	14.70U	X
4947	1	CLIP FASTENING	91507S5A003	0%	nn	1.67U	X
4945	2	CLIP FASTENING	90856SA5003	0%	nn	6.18U	X
4985	1	END PANEL TRIM	84640TM0T01ZA	0%	nn	70.00*	✓
3016	1	ENGINE BADGE	75725TM0T00	0%	nn	8.44U	X
3169	2	FASTENING STRIP	91501S70003	0%	nn	7.26U	X
3191	1	HI-LEVEL BRAKELAMP	34271SNVH01	0%	nn	0.00X	
3357	1	L/NO PL LAMP B/HOLD	34102S60003	0%	nn	25.85U	X
3355	1	L/NO PLATE LAMP BULB	33301SNA003HE	0%	nn	2.87U	X
3361	1	L/NUMBER PLATE LAMP	34101SNVH01	0%	nn	0.00X	
2953	1	L/R HINGE	68660TM0G00ZZ	0%	nn	75.00*	X
3281	1	L/R LAMP	33550TM0H01	0%	nn	225.00*	X
2619	1	L/R OUT BUMPER BRKT	71598TM0T00	0%	nn	20.00*	X
2621	1	L/R UPP BUMPER BRKT	71599TM0T00	0%	nn	10.64U	X
3165	1	L/R WINDOW SEAL	73226TM0000	0%	nn	18.28U	X
3481	1	L/R WING	04646TM2P00ZZ	0%	nn	0.00X	
3171	1	LOWER STICKER	75717TM4H01	0%	nn	0.00X	
3167	1	LWR REAR SCREEN SEAL	73227TM0000	0%	nn	22.98U	X
3015	1	MANUFACTURER BADGE	75711TM4H00	0%	nn	28.00*	X
3358	1	R/NO PL LAMP B/HOLD	34102S60003	0%	nn	25.85U	X
3356	1	R/NO PLATE LAMP BULB	33301SNA003HE	0%	nn	2.87U	X
3362	1	R/NUMBER PLATE LAMP	34101SNVH01	0%	nn	0.00X	
2954	1	R/R HINGE	68610TM0G00ZZ	0%	nn	75.00*	X
3282	1	R/R LAMP	33500TM0H01	0%	nn	225.00*	X
2620	1	R/R OUT BUMPER BRKT	71593TM0T00	0%	nn	20.00*	X
2622	1	R/R UPP BUMPER BRKT	71594TM0T00	0%	nn	10.64U	X
3166	1	R/R WINDOW SEAL	73226TM0000	0%	nn	18.28U	X
3482	1	R/R WING	04636TM4H00ZZ	0%	nn	0.00X	
3783	1	REAR AIR VENT GRILLE	75450SDET00	0%	nn	28.20U	X
2583	1	REAR BUMPER	71501TM4H20ZZ	0%	nn	463.00*	✓
9618	1	REAR HARNESS	32108TM0H00	0%	nn	248.70U	X
2973	1	REAR LOCK STRIKER	74862SE3003	0%	nn	52.00*	X
2703	1	REAR NO PLATE BACKG	KNPLO	0%	nn	5.00U	X
2702	1	REAR NUMBER PLATE	KNPL6	0%	nn	18.00U	✓
2711	1	REAR PANEL CPL	66100TM4H00ZZ	0%	nn	318.00*	✓
3151	1	REAR SCREEN	73211TM4H00	0%	nn	0.00X	
3160	1	REAR SCREEN BOND KIT	08CRCX016N0	0%	nn	30.00U	X
3170	2	REAR SCREEN CLAMPS	91536SS0J01	0%	nn	8.44U	X
3163	1	REAR SCREEN FIX SET	USE SINGLE PARTS	0%	nn	0.00X	
3168	2	REAR SCREEN SPACER	91568TF0003	0%	nn	14.70U	X
3161	1	REAR WINDOW MOULDING	73250SELT01	0%	nn	67.42U	X
2650	4	RR BUMPER CLAMP KIT	91503SZ3003	0%	nn	55.00*	✓
4979	1	SP-WHEEL WELL COVER	84521TM0T00	0%	nn	95.00*	X
3164	1	UPP REAR SCREEN SEAL	73225TM0000	0%	nn	21.60U	X
f: OEM Parts				Sub Total		3810.59	\$3,793.57
g: Original				Sundry Parts		(2 %)	\$75.87 X nn
h: Secondhand				Total Parts			\$3,869.44
p: Parallel							3886.44
x: Exchange							

THIS ASSESSMENT CONTAINS UNPRICED PARTS  
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

# BH AUTO

Claim Reference: BA0904  
Assessment Number: BAC00002  
Version: BHAUTOSP/1

Full Report - V1  
Registration: WTT4590  
Printed: 23/06/2018 21:35

*Zone 99 (Crash no. 100)*

Description		Betterment	Price
LAMP GASKET LH	SPECIALIST	0%	\$35.00
LAMP GASKET RH	SPECIALIST	0%	\$35.00
EXHAUST ASSY	SPECIALIST	0%	\$485.00
Corr Prot Internal	3 WU	0%	\$13.50
Total Extras			\$568.50

## Final Calculation

Total Parts		\$3,869.44
Labour		
Total Panel/Mechanical	279 \$1,237.50	3886.44
Total Paintwork	119.68 \$544.50	
Corr Prot Internal 3 WU	\$13.50	
Total Labour		\$1,795.50
Additional Costs		
Corr Prot Materials External	\$0.00	
Cost of Specialist	\$555.00	
Total of Additional Costs		\$555.00
Total Paint/Material Costs		\$200.42
Grand Total Excludes GST		\$6,420.36
GST @ 7 %		\$449.43
Grand Total Includes GST		\$6,869.79

## Assessment Notes

51 Ubi Avenue 1, #01-25  
Paya Ubi Industrial Park  
Singapore  
408933

Claim Reference: BA0904  
Assessment Number: BAC00002  
Version: BHAUTOSP/3  
Date Calculated: 05/12/2018 06:21

Full Report - V1  
Registration: WTT4590  
Printed: 05/12/2018 14:21

## Summary Information

### Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:	BA0904	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:	WTT4590	Actual Repair Days:	
Third Party:	True	Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

## Vehicle Details

### Vehicle

Manufacturer:	HONDA
Model:	City
Sub Model:	BASE MODEL
Model Sheet Number:	H2C 01
Registration:	WTT4590
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

### Model Specs

FROM MODEL 2009



## Vehicle Condition

### Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	23/06/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tyres - Tread Depth (MM):		

		Axles	Left Tyre	Right Tyre	
			Depth	Depth	
	LHF	0	0.0	0.0	RHF
	LHR	1	0.0	0.0	RHR
Damage Areas:					Direction of Impact:





Primary Impact  
Secondary Impact

## Addresses

## Cost Summary

Total Labour	\$751.50
Total Paint/Material	\$119.68
Total Parts	\$1,741.10
Excess:	TBA
Grand Total Exc GST:	\$2,612.28
7 % GST:	\$182.86
Grand Total Inc GST:	\$2,795.14

## Repair Information

### LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR  
Price/Dent = \$45.00/HR

### Repair /

### Guide Number Repair Details

		WU	Cost Price (\$)
NO NUMBER	RUST PROOFING BODY SHELL PART	2.0	9.00
NO NUMBER	BOOTLID RUST PROOFING	1.0	4.50
8111A5)	R + R REAR BUMPER	3.0	13.50
8111A5)	RENEW REAR BUMPER	1.0	4.50
8111B8)	R + R LEFT REAR OUTER BUMPER BRACKET	2.0	9.00
8111B9)	R + R RIGHT REAR OUTER BUMPER BRACKET	2.0	9.00
7141A0	R + R LEFT REAR TAILLAMP	3.0	13.50
7411A5	R + R RIGHT REAR TAILLAMP	3.0	13.50
823104)	R + R BOOT LID	3.0	13.50
823104)	RENEW BOOTLID	9.0	40.50
	(REMOVED)		
	INCLUDES: R + R INNER TAILLAMPS, NUMBER		
	PLATE, BADGE, NUMBER PLATE LAMPS AND		
	LOCK		
8231B6	R + R BOOTLID SEAL	2.0	9.00
8231A9	BOOTLID STRIKER	2.0	9.00
NO NUMBER	RENEW REAR END PANEL CPL	45.0	202.50
NO NUMBER	R + R BOOT FLOOR CARPET	1.0	4.50
8571C8	R + R L/BOOT COVER	3.0	13.50
8571C9	R + R R/BOOT COVER	3.0	13.50
2953	REPAIR L/R HINGE (A)	10.0*	45.00
2954	REPAIR R/R HINGE (M)	10.0*	45.00

### LABOUR COST

Total Work Units  
Corrosion Protection

105.0

**51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore**

**Claim Reference: BA0904**

**Full Report - V1**

**Assessment Number: BAC00002**

**Registration: WTT4590**

**Version: BHAUTOSP/3**

**Printed: 05/12/2018 14:21**

**Date Calculated: 05/12/2018 06:21**

Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.3HRS	13.50
<b>Sub Total</b>	<b>10.5HRS</b>	<b>\$472.50</b>
Paint Labour	6.2HRS	\$279.00
<b>Total Labour</b>	<b>16.7HRS</b>	<b>\$751.50</b>

<b>PAINT WORK</b>		<b>Time Basis 10 WU = 1 HR. Price = \$45.00/HR</b>	
<b>Guide Number</b>	<b>Description</b>	<b>WU</b>	<b>Cost Price (\$)</b>
2711	REAR PANEL CPL NEW PART PAINTING	18.0	
2931	BOOTLID NEW PART PAINTING	14.0	
2583	REAR BUMPER NEW PART PAINT K1R	10.0	
<b>LABOUR COST - PAINT</b>			
<b>TIME(PAINT)</b>			
Preparation Main Work Metal		42.0	
Preparation Comp. Work Plastic		17.0	
Preparation Work Multi Layer Paint		3.0	
Total Work Units (10WU/HR)		0.0	
Total Paintwork Labour		62.0	
		6.2HRS	\$279.00
<b>MATERIAL COST - PAINT</b>			
New Part Painting			Cost Price
New Part Painting - Plastic K1R			\$51.40
Material-Const Main Work Metal			\$41.18
Material-Const Comp. Work Plastic			\$18.10
Total Excluding Pearlescent Uplift			\$9.00
Pearlescent Uplift @ 0.0%			\$119.68
Total Paint Material Cost			\$0.00
			\$119.68

**PARTS**

				<b>Price Valid: 01/06/2015</b>	
<b>Guide No.</b>	<b>Qty</b>	<b>Description</b>	<b>Part Number</b>	<b>Supplier</b>	<b>Bet. Price (\$)</b>
3017	1	BADGE CITY	75722TM4H00		0% 30.00*
3013	1	BADGE HONDA	75701TM0000		0% 25.00*
2931	1	BOOTLID	68500TM4H00ZZ		0% 453.00*
2977	1	BOOTLID LOCK	74851SNBJ12		0% 65.00*
4985	1	END PANEL TRIM	84640TM0T01ZA		0% 70.00*
2583	1	REAR BUMPER	71501TM4H20ZZ		0% 463.00*
2711	1	REAR PANEL CPL	66100TM4H00ZZ		0% 318.00*
2650	4	RR BUMPER CLAMP KIT	91503SZ3003		0% 55.00*
1000	1	RR NUMBER PLATE	Renew		0% 35.00*
f: OEM Parts		Sub Total			\$1,514.00
g: Original		Mark Up From Cost		(15 %)	\$227.10
h: Secondhand		<b>Total Parts</b>			<b>\$1,741.10</b>
p: Parallel					
x: Exchange					

**NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER**

**Total Extras \$0.00**

**Final Calculation**

<b>Total Parts</b>	<b>\$1,741.10</b>
<b>Labour</b>	
Total Panel/Mechanical	\$459.00
Total Paintwork	\$279.00

Corr Prot Internal	3 WU	\$13.50	
<b>Total Labour</b>			<b>\$751.50</b>
<b>Additional Costs</b>			
Corr Prot Materials External		\$0.00	
<b>Total Paint/Material Costs</b>			<b>\$119.68</b>
<b>Grand Total Excludes GST</b>			<b>\$2,612.28</b>
GST @ 7 %			<b>\$182.86</b>
<b>Grand Total Includes GST</b>			<b>\$2,795.14</b>

### Assessment Notes

---

## Hsiao Tong (LKKAUTO)

---

**From:** BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>  
**Sent:** Friday, 30 November 2018 12:51 PM  
**To:** Hsiao Tong (LKKAUTO)  
**Cc:** BHAS - Bernard Kee; BHAS - Jacelyn Loh; BHAS - Ngai Kar Kit; BHAS - Chan Yun Shi; BHAS - Zhou Ya Ping  
**Subject:** FINALIZE (OUR VEHICLE - WTT4590 / YOUR VEHICLE - SLC2565R ) \*\*\* LKK REF: CC4/ASM18011401/pa3  
**Attachments:** BAC00002.AudatexMS.pdf; SKM\_C224e18113012480.pdf

Dear Hsiao Tong,

We had revised the finalize in audatex and amount is \$2100.00 B/GST lump sum.

Kindly review and confirm the amount asap.

Thank you.

Best Regards,  
Wen Zheng



**BH AUTO SERVICES PTE LTD**

BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-111/113/115/117  
SINGAPORE 575636 TEL: (65) 6559 8944 FAX: (65) 6269 2404  
CO. REG. NO.: 200917512K GST REG. NO.: 200917512K

(W) +65-6559 8945 (F) +65-6269 2404 (HP) +65 9621 2084  
(E) [wenzheng.moo@bhauto.com.sg](mailto:wenzheng.moo@bhauto.com.sg) <http://www.bhauto.com.sg>



---

**From:** Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>  
**Sent:** Tuesday, 18 September 2018 11:08 AM  
**To:** BHAS - Jacelyn Loh <jacelyn.loh@bhauto.com.sg>  
**Cc:** BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; BHAS - Anthony Lau <anthony.lau@bhauto.com.sg>; BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>; Admin A <admin-a@lkkauto.com>  
**Subject:** RE: pre repair inspection (OUR VEHICLE - WTT4590 / YOUR VEHICLE - SLC2565R ) \*\*\* LKK REF: CC4/ASM18011401/pa3

### Without Prejudice

Hi Sirs,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject to insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** BHAS - Jacelyn Loh <[jacelyn.loh@bhauto.com.sg](mailto:jacelyn.loh@bhauto.com.sg)>

**Sent:** Monday, 17 September 2018 12:07 PM

**To:** Mei Kwan (LKKAuto) <[Meikwan@lkkauto.com](mailto:Meikwan@lkkauto.com)>; Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>; Vic (LKKAuto) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Cc:** BHAS - Moo Wen Zheng <[wenzheng.moo@bhauto.com.sg](mailto:wenzheng.moo@bhauto.com.sg)>; BHAS - Anthony Lau <[anthony.lau@bhauto.com.sg](mailto:anthony.lau@bhauto.com.sg)>; BHAS - Bernard Kee <[bernard.kee@bhauto.com.sg](mailto:bernard.kee@bhauto.com.sg)>

**Subject:** RE: pre repair inspection (OUR VEHICLE - WTT4590 / YOUR VEHICLE - SLC2565R ) \*\*\*  
LKK REF: CC4/ASM18011401/pa3

Dear all,

Please kindly update me on liability states, accident happen going about 3months. Thanks

Thank You & Best Regards,

Jacelyn Loh

 **BH AUTO SERVICES PTE LTD**

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singapre:575636

(T) +65-6559 8944 /8940 (F) +65-6515 3144 / +65-6269 2404

Email: [jacelyn.loh@bhauto.com.sg](mailto:jacelyn.loh@bhauto.com.sg)

Website: <http://www.bhauto.com.sg>

---

**From:** BHAS - Jacelyn Loh

**Sent:** Wednesday, 5 September 2018 4:14 PM

**To:** 'Mei Kwan (LKKAuto)' <[Meikwan@lkkauto.com](mailto:Meikwan@lkkauto.com)>; 'Hsiao Tong (LKKAuto)' <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>; 'Vic (LKKAuto)' <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>; 'Admin A' <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Cc:** BHAS - Moo Wen Zheng <[wenzheng.moo@bhauto.com.sg](mailto:wenzheng.moo@bhauto.com.sg)>; BHAS - Anthony Lau <[anthony.lau@bhauto.com.sg](mailto:anthony.lau@bhauto.com.sg)>; BHAS - Bernard Kee <[bernard.kee@bhauto.com.sg](mailto:bernard.kee@bhauto.com.sg)>

**Subject:** RE: pre repair inspection (OUR VEHICLE - WTT4590 / YOUR VEHICLE - SLC2565R ) \*\*\*  
LKK REF: CC4/ASM18011401/pa3

**URGENT REMINDER!!!**

Dear all,

got any update on liability

Thank You & Best Regards,

Jacelyn Loh

**BH AUTO SERVICES PTE LTD**

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singapre:575636

(T) +65-6559 8944 /8940 (F) +65-6515 3144 / +65-6269 2404

Email: [Jacelyn.loh@bhauto.com.sg](mailto:Jacelyn.loh@bhauto.com.sg)

Website: <http://www.bhauto.com.sg>

---

**From:** BHAS - Jacelyn Loh

**Sent:** Thursday, 16 August 2018 5:52 PM

**To:** 'Mei Kwan (LKKAuto)' <[Meikwan@lkkauto.com](mailto:Meikwan@lkkauto.com)>; 'Hsiao Tong (LKKAuto)' <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>; 'Vic (LKKAuto)' <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>; 'Admin A' <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Cc:** BHAS - Moo Wen Zheng <[wenzheng.moo@bhauto.com.sg](mailto:wenzheng.moo@bhauto.com.sg)>; BHAS - Anthony Lau <[anthony.lau@bhauto.com.sg](mailto:anthony.lau@bhauto.com.sg)>; BHAS - Bernard Kee <[bernard.kee@bhauto.com.sg](mailto:bernard.kee@bhauto.com.sg)>

**Subject:** RE: pre repair inspection (OUR VEHICLE - WTT4590 / YOUR VEHICLE - SLC2565R ) \*\*\*  
LKK REF: CC4/ASM18011401/pa3

**URGENT REMINDER!!!**

Dear all,

Kindly advise on this liabilities status and forwards me sketch plan and statement.

Thank You & Best Regards,

Jacelyn Loh

**BH AUTO SERVICES PTE LTD**

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singapre:575636

(T) +65-6559 8944 /8940 (F) +65-6515 3144 / +65-6269 2404

Email: [Jacelyn.loh@bhauto.com.sg](mailto:Jacelyn.loh@bhauto.com.sg)

Website: <http://www.bhauto.com.sg>

---

**From:** BHAS - Jacelyn Loh

**Sent:** Friday, 3 August 2018 12:05 PM

**To:** 'Mei Kwan (LKKAuto)' <[Meikwan@lkkauto.com](mailto:Meikwan@lkkauto.com)>; 'Hsiao Tong (LKKAuto)' <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>; 'Vic (LKKAuto)' <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>; 'Admin A' <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Cc:** BHAS - Moo Wen Zheng <[wenzheng.moo@bhauto.com.sg](mailto:wenzheng.moo@bhauto.com.sg)>; BHAS - Anthony Lau <[anthony.lau@bhauto.com.sg](mailto:anthony.lau@bhauto.com.sg)>; BHAS - Bernard Kee <[bernard.kee@bhauto.com.sg](mailto:bernard.kee@bhauto.com.sg)>

**Subject:** RE: pre repair inspection (OUR VEHICLE - WTT4590 / YOUR VEHICLE - SLC2565R ) \*\*\*  
LKK REF: CC4/ASM18011401/pa3

Dear all,

Please kindly update me on liability states, accident happen going about 2months. Thanks

Thank You & Best Regards,



Jacelyn Loh

**BH AUTO SERVICES PTE LTD**

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singaopre:575636

(T) +65-6559 8944 /8940 (F) +65-6515 3144 / +65-6269 2404

Email: [Jacelyn.loh@bhauto.com.sg](mailto:Jacelyn.loh@bhauto.com.sg)

Website: <http://www.bhauto.com.sg>

---

**From:** BHAS - Jacelyn Loh

**Sent:** Tuesday, 17 July 2018 5:53 PM

**To:** 'Mei Kwan (LKKAuto)' <[Meikwan@lkkauto.com](mailto:Meikwan@lkkauto.com)>; 'Hsiao Tong (LKKAuto)' <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>;

'Vic (LKKAuto)' <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>; 'Admin A' <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Cc:** BHAS - Moo Wen Zheng <[wenzheng.moo@bhauto.com.sg](mailto:wenzheng.moo@bhauto.com.sg)>; BHAS - Anthony Lau

<[anthony.lau@bhauto.com.sg](mailto:anthony.lau@bhauto.com.sg)>; BHAS - Bernard Kee <[bernard.kee@bhauto.com.sg](mailto:bernard.kee@bhauto.com.sg)>

**Subject:** RE: pre repair inspection (OUR VEHICLE - WTT4590 / YOUR VEHICLE - SLC2565R) \*\*\*

LKK REF: CC4/ASM18011401/pa3

Dear all,

Please Kindly advise on this liabilities status. thanks

Thank You & Best Regards,

Jacelyn Loh

**BH AUTO SERVICES PTE LTD**

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singaopre:575636

(T) +65-6559 8944 /8940 (F) +65-6515 3144 / +65-6269 2404

Email: [Jacelyn.loh@bhauto.com.sg](mailto:Jacelyn.loh@bhauto.com.sg)

Website: <http://www.bhauto.com.sg>

---

**From:** BHAS - Jacelyn Loh

**Sent:** Wednesday, 4 July 2018 2:33 PM

**To:** Mei Kwan (LKKAuto) <[Meikwan@lkkauto.com](mailto:Meikwan@lkkauto.com)>; Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>;

Vic (LKKAuto) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Cc:** BHAS - Moo Wen Zheng <[wenzheng.moo@bhauto.com.sg](mailto:wenzheng.moo@bhauto.com.sg)>; BHAS - Anthony Lau

<[anthony.lau@bhauto.com.sg](mailto:anthony.lau@bhauto.com.sg)>; BHAS - Bernard Kee <[bernard.kee@bhauto.com.sg](mailto:bernard.kee@bhauto.com.sg)>

**Subject:** RE: pre repair inspection (OUR VEHICLE - WTT4590 / YOUR VEHICLE - SLC2565R) \*\*\*

LKK REF: CC4/ASM18011401/pa3

Dear sir / madam,

As your requested, please find the attached file for your perusal.

Kindly advise on this liabilities status and forwards me sketch plan and statement.

Thank You & Best Regards,

Jacelyn Loh

**BH AUTO SERVICES PTE LTD**

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singaopre:575636

(T) +65-6559 8944 /8940 (F) +65-6515 3144 / +65-6269 2404

Email: [Jacelyn.loh@bhauto.com.sg](mailto:Jacelyn.loh@bhauto.com.sg)

Website: <http://www.bhauto.com.sg>

**From:** BHAS - Janice Koh

**Sent:** Friday, 22 June 2018 5:04 PM

**To:** Mei Kwan (LKKAuto) <[Meikwan@lkkauto.com](mailto:Meikwan@lkkauto.com)>; BHAS - Jacelyn Loh <[jacelyn.loh@bhauto.com.sg](mailto:jacelyn.loh@bhauto.com.sg)>

**Cc:** BHAS - Moo Wen Zheng <[wenzheng.moo@bhauto.com.sg](mailto:wenzheng.moo@bhauto.com.sg)>; BHAS - Anthony Lau <[anthony.lau@bhauto.com.sg](mailto:anthony.lau@bhauto.com.sg)>; BHAS - Bernard Kee <[bernard.kee@bhauto.com.sg](mailto:bernard.kee@bhauto.com.sg)>; Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>; Vic (LKKAuto) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** RE: pre repair inspection (OUR VEHICLE - WTT4590 / YOUR VEHICLE - SLC2565R ) \*\*\*  
LKK REF: CC4/ASM18011401/pa3

Hi Mei Kwan,

Kindly refer to insured report which was done yesterday.

Appreciate you could advice on this liability status since it's a straight forward cases.

Thank you  
Warmest Regards,

Janice Koh

(W) 6559 8944 ext 108 (F) 6269 2404

(HP) 9159 3399

(Add) Blk 1 Sin Ming Industrial Estate Sector C #01-111-113-115-117 Singapore 575636

[janice@bhauto.com.sg](mailto:janice@bhauto.com.sg) <http://www.bhauto.com.sg>

 **BH AUTO SERVICES PTE LTD**

---

**From:** Mei Kwan (LKKAuto) [<mailto:Meikwan@lkkauto.com>]

**Sent:** Friday, June 22, 2018 04:44 PM

**To:** BHAS - Jacelyn Loh <[jacelyn.loh@bhauto.com.sg](mailto:jacelyn.loh@bhauto.com.sg)>

**Cc:** BHAS - Janice Koh <[janice.koh@bhauto.com.sg](mailto:janice.koh@bhauto.com.sg)>; BHAS - Moo Wen Zheng <[wenzheng.moo@bhauto.com.sg](mailto:wenzheng.moo@bhauto.com.sg)>; BHAS - Anthony Lau <[anthony.lau@bhauto.com.sg](mailto:anthony.lau@bhauto.com.sg)>; BHAS - Bernard Kee <[bernard.kee@bhauto.com.sg](mailto:bernard.kee@bhauto.com.sg)>; Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>; Vic (LKKAuto) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** RE: pre repair inspection (OUR VEHICLE - WTT4590 / YOUR VEHICLE - SLC2565R ) \*\*\*  
LKK REF: CC4/ASM18011401/pa3

Dear Sir / Madam,

We refer to the above matter.

Please be informed that OI has yet to report the accident and we are currently **pending verification for direct settlement**.

***Please provide us evidence i.e. video/ scene photo / estimated cost of repair.***

Please note that for liability, claim negotiation and settlement, please contact Hsiao Tong at 6742 3197.

Our respective case handler will look into the matter and revert to you in due course.

***To check availability of the case handler, you may contact the undersigned.***

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** BHAS - Jacelyn Loh [<mailto:jacelyn.loh@bhauto.com.sg>]

**Sent:** Thursday, 21 June, 2018 11:44 AM

**To:** NGUETTE Kadi <[kadidiatou.nguette@axa.com.sg](mailto:kadidiatou.nguette@axa.com.sg)>; SG AXA Insurance SM AXA SGP - Motor Survey <[motor.survey@axa.com.sg](mailto:motor.survey@axa.com.sg)>

**Cc:** BHAS - Janice Koh <[janice.koh@bhauto.com.sg](mailto:janice.koh@bhauto.com.sg)>; BHAS - Moo Wen Zheng

<[wenzheng.moo@bhauto.com.sg](mailto:wenzheng.moo@bhauto.com.sg)>; BHAS - Anthony Lau <[anthony.lau@bhauto.com.sg](mailto:anthony.lau@bhauto.com.sg)>; BHAS - Bernard Kee <[bernard.kee@bhauto.com.sg](mailto:bernard.kee@bhauto.com.sg)>

**Subject:** pre repair inspection (OUR VEHICLE - WTT4590 / YOUR VEHICLE - SLC2565R )

To: the officer in charge

Dear sir, mdm,

I would like to arrange surveyor on of the above mentioned accident vehicle.

Appreciate awaiting for your favourable reply asap. Please kindly assist.

Greatly appreciate it. Thank you and have a nice day

Thank You & Best Regards,

Jacelyn Loh

 **BH AUTO SERVICES PTE LTD**

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singaopre:575636

(T) +65-6559 8944 /8940 (F) +65-6515 3144 / +65-6269 2404

Email: [Jacelyn.loh@bhauto.com.sg](mailto:Jacelyn.loh@bhauto.com.sg)

Website: <http://www.bhauto.com.sg>

**BH AUTO**  
**Sin Ming Industrial Est**  
**Sector C**  
**Singapore 575636**

**Claim Reference: BA0904**  
**Assessment Number: BAC00002**  
**Version: BHAUTOSP/1**

**Full Report - V1**  
**Registration: WTT4590**  
**Printed: 23/06/2018 21:35**

**Summary Information**

**Claim**

Location:	Singapore (SG)	Currency:	SGD
Printed by:	BH admin	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:	BA0904	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

**Vehicle Details**

**Vehicle**

Manufacturer:	HONDA
Model:	City
Sub Model:	BASE MODEL
Model Sheet Number:	H2C 01
Registration:	WTT4590
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

**Model Specs**

FROM MODEL 2009

*Not Authorised*  
*1. B.I. / L.I. by B?*  
*6 days*

**Vehicle Condition**



**Vehicle Status**

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on	
	Inspection:	
Brakes Pedal Travel:	Date of Inspection:	23/06/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tyres - Tread Depth (MM):		

	Axes	Left Tyre	Right Tyre	
		Depth	Depth	
	LHF 0	0.0	0.0	RHF
	LHR 1	0.0	0.0	RHR
Damage Areas:				Direction of Impact:

Claim Reference: BA0904  
 Assessment Number: BAC00002  
 Version: BHAUTOSP/1

Full Report - V1  
 Registration: WTT4590  
 Printed: 23/06/2018 21:35



Primary Impact →  
 Secondary Impact →

## Addresses

## Cost Summary

Total Labour	\$1,795.50
Total Paint/Material	\$200.42
Total Parts	\$3,869.44
Total of Additional Costs	\$555.00
Excess:	TBA
Grand Total Exc GST:	\$6,420.36
7 % GST:	\$449.43
Grand Total Inc GST:	\$6,869.79

## Repair Information

### LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR  
 Price/Dent = \$45.00/HR

### Repair /

### Guide Number Repair Details

		WU	Cost Price (\$)
NO NUMBER	RUST PROOFING BODY SHELL PART	2.0	9.00
NO NUMBER	BOOTLID RUST PROOFING	1.0	4.50
8111A5)	R + R REAR BUMPER	3.0	13.50
8111A5)	RENEW REAR BUMPER	1.0	4.50
8111B8)	R + R LEFT REAR OUTER BUMPER BRACKET	2.0	9.00
8111B9)	R + R RIGHT REAR OUTER BUMPER BRACKET	2.0	9.00
7141A0	R + R LEFT REAR TAILLAMP	3.0	13.50
7411A5	R + R RIGHT REAR TAILLAMP	3.0	13.50
NO NUMBER	R + R L/R WHEELARCH SHELL	3.0	13.50
NO NUMBER	R + R R/R WHEELARCH SHELL	3.0	13.50
NO NUMBER	R + R DEFROSTER HOUSING	1.0	4.50 X
NO NUMBER	R + R FUEL FLAP	6.0	27.00 X
823104)	R + R BOOT LID	3.0	13.50
823104)	RENEW BOOTLID	9.0	40.50
	(REMOVED)		
	INCLUDES: R + R INNER TAILLAMPS, NUMBER		
	PLATE, BADGE, NUMBER PLATE LAMPS AND		
	LOCK		
832120)	R + R REAR SCREEN	10.0	45.00 X
8231B6	R + R BOOTLID SEAL	2.0	9.00
7141B4	R + R ADDITIONAL BRAKE LAMP	7.0	31.50 X
8231A9	BOOTLID STRIKER	2.0	9.00
NO NUMBER	RENEW REAR END PANEL CPL	45.0	202.50
NO NUMBER	RENEW LEFT SIDE PANEL	45.0	202.50 Y
NO NUMBER	RENEW RIGHT SIDE PANEL	45.0	202.50 X
NO NUMBER	R + R SPARE WHEEL COVER	1.0	4.50
NO NUMBER	RENEW REAR FLOOR CPL	52.0	234.00 X

# BH AUTO

Claim Reference: BA0904  
Assessment Number: BAC00002  
Version: BHAUTOSP/1

Full Report - V1  
Registration: WTT4590  
Printed: 23/06/2018 21:35

857120	R + R L/UPPER C-PILLAR TRIM	4.0	18.00
857121	R + R R/UPPER C-PILLAR TRIM	4.0	18.00
NO NUMBER	R + R BOOT FLOOR CARPET	1.0	na 4.50 X
8571C8	R + R L/BOOT COVER	3.0	13.50
8571C9	R + R R/BOOT COVER	3.0	13.50
7371B5	R + R REAR VEHICLE WIRING HARNESS	12.0	na 54.00 X
<b>LABOUR COST</b>			
	Total Work Units	278.0	
	Corrosion Protection		
	Corrosion Protection Internal Labour	0.3HRS	13.50
	Sub Total	27.8HRS	\$1,251.00
	Paint Labour	12.1HRS	544.50
	Total Labour	39.9HRS	\$1,795.50

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$45.00/HR	
Guide Number	Description	WU	Cost Price (\$)
2711	REAR PANEL CPL NEW PART PAINTING	18.0	
2931	BOOTLID NEW PART PAINTING	14.0	
3481	L/R WING NEW PART PAINTING	25.0	
3482	R/R WING NEW PART PAINTING	25.0	
3900	BOOTFLOOR SURFACE PAINT	9.0	
2583	REAR BUMPER NEW PART PAINT K1R	10.0	
<b>LABOUR COST - PAINT</b>			
	TIME(PAINT)	101.0	
	Preparation Main Work Metal	17.0	
	Preparation Comp. Work Plastic	3.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	121.0	
	Total Paintwork Labour	12.1HRS	\$544.50
<b>MATERIAL COST - PAINT</b>			
	New Part Painting		Cost Price
	New Part Painting - Plastic K1R		\$109.96
	Surface-/Blend Paint		\$41.18
	Material-Const Main Work Metal		\$22.18
	Material-Const Comp. Work Plastic		\$18.10
	Total Excluding Pearlescent Uplift		\$9.00
	Pearlescent Uplift @ 0.0%		\$200.42
	Total Paint Material Cost		\$0.00
			\$200.42

## PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
3189	1	3RD BRAKE LAMP BULB	33303S30003		0%	2.87U X
3190	1	ADD/BR/LAMP B/HOLDER	33513S50003		0%	14.20U X
3017	1	BADGE CITY	75722TM4H00		0%	na 30.00* ✓
3013	1	BADGE HONDA	75701TM0000		0%	na 25.00* ✓
3029	1	BOOT LID MOULDING	74890TM4H00		0%	na 68.00* X
4907	1	BOOT/TAILGATE COVER	84631TM4H01ZA		0%	na 195.00* ✓
3900	1	BOOTFLOOR	04655TM4H00ZZ		0%	na 503.00* X
2931	1	BOOTLID	68500TM4H00ZZ		0%	na 453.00* ✓
2977	1	BOOTLID LOCK	74851SNBJ12		0%	na 65.00* ✓
2979	1	BOOTLID LOCK CYL	74861TM0T11		0%	na 22.93U X
2944	1	BOOTLID SEAL	74865TM0T00		0%	75.00* ?

Price Valid: 01/06/2015



# BH AUTO

Claim Reference: BA0904  
Assessment Number: BAC00002  
Version: BHAUTOSP/1

Full Report - V1  
Registration: WTT4590  
Printed: 23/06/2018 21:35

4921	1	BOOTLID TRIM M-KIT	USE SINGLE PARTS	0%	0.00	
3172	2	CLIP FASTENING	91568TF0003	0%	14.70U	X
4947	1	CLIP FASTENING	91507S5A003	0%	1.67U	X
4945	2	CLIP FASTENING	90856SA5003	0%	6.18U	X
4985	1	END PANEL TRIM	84640TM0T01ZA	0%	70.00*	✓
3016	1	ENGINE BADGE	75725TM0T00	0%	8.44U	?
3169	2	FASTENING STRIP	91501S70003	0%	7.26U	?
3191	1	HI-LEVEL BRAKELAMP	34271SNVH01	0%	0.00	
3357	1	L/NO PL LAMP B/HOLD	34102S60003	0%	25.85U	?
3355	1	L/NO PLATE LAMP BULB	33301SNA003HE	0%	2.87U	X
3361	1	L/NUMBER PLATE LAMP	34101SNVH01	0%	0.00	
2953	1	L/R HINGE	68660TM0G00ZZ	0%	75.00*	X
3281	1	L/R LAMP	33550TM0H01	0%	225.00*	?
2619	1	L/R OUT BUMPER BRKT	71598TM0T00	0%	20.00*	?
2621	1	L/R UPP BUMPER BRKT	71599TM0T00	0%	10.64U	?
65	1	L/R WINDOW SEAL	73226TM0000	0%	18.28U	?
3481	1	L/R WING	04646TM2P00ZZ	0%	0.00	
3171	1	LOWER STICKER	75717TM4H01	0%	0.00	
3167	1	LWR REAR SCREEN SEAL	73227TM0000	0%	22.98U	X
3015	1	MANUFACTURER BADGE	75711TM4H00	0%	28.00*	?
3358	1	R/NO PL LAMP B/HOLD	34102S60003	0%	25.85U	?
3356	1	R/NO PLATE LAMP BULB	33301SNA003HE	0%	2.87U	X
3362	1	R/NUMBER PLATE LAMP	34101SNVH01	0%	0.00	
2954	1	R/R HINGE	68610TM0G00ZZ	0%	75.00*	X
3282	1	R/R LAMP	33500TM0H01	0%	225.00*	?
2620	1	R/R OUT BUMPER BRKT	71593TM0T00	0%	20.00*	X
2622	1	R/R UPP BUMPER BRKT	71594TM0T00	0%	10.64U	X
3166	1	R/R WINDOW SEAL	73226TM0000	0%	18.28U	X
3482	1	R/R WING	04636TM4H00ZZ	0%	0.00	
3783	1	REAR AIR VENT GRILLE	75450SDET00	0%	28.20U	X
2583	1	REAR BUMPER	71501TM4H20ZZ	0%	463.00*	✓
9618	1	REAR HARNESS	32108TM0H00	0%	248.70U	X
2973	1	REAR LOCK STRIKER	74862SE3003	0%	52.00*	X
2703	1	REAR NO PLATE BACKG	KNPL0	0%	5.00U	X
2702	1	REAR NUMBER PLATE	KNPL6	0%	18.00U	35
1	1	REAR PANEL CPL	66100TM4H00ZZ	0%	318.00*	✓
3151	1	REAR SCREEN	73211TM4H00	0%	0.00	
3160	1	REAR SCREEN BOND KIT	08CRCX016N0	0%	30.00U	X
3170	2	REAR SCREEN CLAMPS	91536SS0J01	0%	8.44U	X
3163	1	REAR SCREEN FIX SET	USE SINGLE PARTS	0%	0.00	
3168	2	REAR SCREEN SPACER	91568TF0003	0%	14.70U	X
3161	1	REAR WINDOW MOULDING	73250SELT01	0%	67.42U	X
2650	4	RR BUMPER CLAMP KIT	91503SZ3003	0%	55.00*	✓
4979	1	SP-WHEEL WELL COVER	84521TM0T00	0%	95.00*	X
3164	1	UPP REAR SCREEN SEAL	73225TM0000	0%	21.60U	X
f: OEM Parts				Sub Total	\$3,793.57	
g: Original				Sundry Parts	\$75.87	(2 %)
h: Secondhand				Total Parts	\$3,869.44	
p: Parallel						
x: Exchange						

THIS ASSESSMENT CONTAINS UNPRICED PARTS  
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

## Extras

\$1514.00 + 15% = \$1741.10

# BH AUTO

Claim Reference: BA0904  
Assessment Number: BAC00002  
Version: BHAUTOSP/1

Full Report - V1  
Registration: WTT4590  
Printed: 23/06/2018 21:35

Description	Betterment	Price
LAMP GASKET LH SPECIALIST	0%	\$35.00 ?
LAMP GASKET RH SPECIALIST		\$35.00 ?
EXHAUST ASSY SPECIALIST	0%	<i>✓</i> \$485.00 X
Corr Prot Internal 3 WU	0%	<i>✓</i> \$13.50 X
<b>Total Extras</b>		<b>\$568.50</b>

## Final Calculation

<b>Total Parts</b>	<b>\$3,869.44</b>
<b>Labour</b>	
Total Panel/Mechanical	\$1,237.50
Total Paintwork	\$544.50
Corr Prot Internal 3 WU	\$13.50
<b>Total Labour</b>	<b>\$1,795.50</b>
<b>Additional Costs</b>	
Corr Prot Materials External	\$0.00
Cost of Specialist	\$555.00
<b>Total of Additional Costs</b>	<b>\$555.00</b>
<b>Total Paint/Material Costs</b>	<b>\$200.42</b>
<b>Grand Total Excludes GST</b>	<b>\$6,420.36</b>
GST @ 7 %	\$449.43
<b>Grand Total Includes GST</b>	<b>\$6,869.79</b>

## Assessment Notes

Part: \$ 1741.10  
Panel brnt: \$ 472.50  
Spring paint: \$ 398.68  
Total: \$ 2612.28 - 20%  
= \$ 2089.82



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

22 June, 2018

**L I N A**

BLK 353 WOODLANDS AVENUE 1  
#03-753  
SINGAPORE 730353

Dear Sir,

**OUR REF : CC4/ASM18011401/pa3 / S8M00LJQ**

**YOUR REF : SLC 2565R**

**ACCIDENT INVOLVING SLC 2565R & WTT 4590 ON 20/06/2018 ALONG/AT  
BUKIT TIMAH EXPRESSWAY / BKE HEADING TOWARDS WOODLANDS**

We write to inform you that we are the appointed loss adjuster by your motor insurer, AXA insurance Pte Ltd to deal with the third party claim against your motor policy.

We refer to the above subject matter. We have received third party claim(s) against your motor insurance policy.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We highlight that this accident has not been reported to your insurer. Under the Motor Claims Framework (MCF), you are required to report any accident with the accident vehicle (whether damaged or not) within 24 hours or by the next working day after the accident. The primary purpose of this reporting is to provide your version of the accident to AXA. Omission to report the accident will result in a loss of your No Claim Discount (NCD) upon renewal of your policy, and will prejudice any claim(s) by or against you. We would appreciate it if you could urgently file a report at our approved reporting centre.

The report has to be lodged at any of AXA Premium Workshops or reporting centres (subject to your policy). For the list of AXA Premium Workshops conveniently located throughout Singapore, please refer to the back of your Certificate of Insurance or the accompanying folder, or visit <https://www.axa.com.sg/customer-care/personal/motor/owndamageaccidentreporting>.

Your full co-operation is required. Kindly submit the following when lodging the report which list is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)

- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to [chewht@lkkauto.com](mailto:chewht@lkkauto.com) or deliver it by hand to 51 Ubi Avenue 1, #01-25 Paya Ubi Ind. Park S(408933).

You should also IMMEDIATELY forward us by hand any letters or Courts Summons received from the other party involved in the accident. You should not negotiate, admit liability or offer payment to them.

We would like to bring to your attention that under Policy Condition, your insurer shall have full discretion in the process and settlement of the said third party claim subject to the merits of the case and according to the rights afforded under the policy.

Your NCD (No Claim Discount) will be reduced by 30% (20% for motorcycle/commercial vehicles) if a claim is made under your policy.

To enable us to look into the matter immediately, please let us hear from you within seven (7) days from date of this letter. In accordance with the policy conditions, your insurer reserve the right to repudiate the said claim to you should you not give proper notice to us of any occurrence which may give rise to it.

Kindly contact us at 6742 3197 if you have any further enquiries.

Yours sincerely,  
Claim Department

This is a computer generated letter and no signature is required.

CC : AXA INSURANCE PTE LTD  
Motor Claim Department




## Service Request Details

Claim

S8M00LJQ

Reference

None 

Loss Date

June 20, 2018

Request Date

June 21, 2018

Due Date

June 28, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

21062018 @ 211pm

Jacelyn veh in.

arrange survey when estimate  
done.

### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #

WTT4590

Make

TPVD

Model

Service Address

---

...

Primary Contact/Insured

---

LI NA

BLK 353 WOODLANDS AVENUE 1, #03-753, 730353, Singapore

LINA@TIB.COM.SG

Claim Handler

---

CHAN Kian Chuan

6568804269

kianchuan.chan@axa.com.sg

Additional Instructions

INSD GIA NOT REPORTED

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



## << <REQUEST FOR DS & SEEK MANDATE> - S8M00LJQ [ACCIDENT INVOLVING SLC 2565R(OI) & WTT 4590(TP) ON 20/06/2018]

Type

🔗 Question

Message

Liability: 100%. Insured rear-ended third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate up to \$3,155.07(all-in). IA with mandate had been uploaded in Smartclaims. Kindly advise if we may proceed DS and let us have your approval/instruction. Hsiao Tong - 17 Sept 2018

Reply



BH Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 CUBAVE L, #02-25 PAVANUR INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 17.09.2018

### Survey Details:

Date of loss	20.06.2018
Date of appointment	21.06.2018
Date of survey	26.06.2018
Location of survey	BH AUTO SERVICES PTE LTD

### Vehicle Details:

Claim Type:	Third party
Vehicle number	WTT 4590
Make and Model	Honda City (1497cc)
Date of registration	09.04.2010
Excess	NIL
Market Value	RM40,000.00
Parf/COE Rebate	
Nett Loss	

### Repair details:

Initial Estimate	\$ 6,420.36
------------------	-------------

### Proposed/Revised repair cost:

Parts	\$ 1,526.94
Check items (estimate)	NIL
Labour	\$ 1,190.42
Supplementary	NIL
<b>Total</b>	<b>\$ 2,717.36</b>
Lump Sum(if applicable)	

Number of days for repair	<u>6</u>
---------------------------	----------



Auto  
Consultants  
Pro Ltd

Company Registration No: 199607195R

211 BLVD L, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Date: 17.09.2018

**Remarks:**

--

**Mandate:**

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 2,907.58	
Loss of use	\$ 240.00	(8days x \$30.00)
Loss of rental	NIL	
Loss of income	NIL	
LTA/GIA search fees	\$ 7.49	
Others	NIL	
Proposed Total	\$ 3,155.07	