

ACCIDENT REPAIR ESTIMATES

Our Ref: OD / SLU4858M

Type of Claim : OD

Vehicle No. : SLU4858M

Make & Model : BLUECAR

Year of Manufacture : 2017

Chassis No. : VL4BCEB4RHT003000

Ins Company : MSIG INSURANCE
(SINGAPORE) PTE LTD

Excess : \$0.00

Date of Accident : 05/01/2018

Engine No. : 921955Q16W391425195

Policy No. : -

Time of Accident : -

Suggested Days of Repair : 10

Case Owner : BLUECAR EAST ASIA PTE LTD / BLUESG PTE LTD

Repair Estimates

Parts (a) Cost Price Items \$ 16,793.00

Plus/Less 10% \$ 1,679.30

Total of Cost / List \$ 18,472.30

(b) Nett Price Items \$ 60.00

Less 10% \$ 6.00

Total of Nett Item \$ 54.00

(c) Special Nett Items \$ 45.00

Total Parts Cost (Appendix A) \$ 18,571.30

Labour (Appendix B) \$ 4,630.00

Total Repair Cost \$ 23,201.30

Note: A/w parts price for Item No. 29 & 30 (Parts List pg 2)

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor : Tanjima 97495747

Company : LKK 62563561

Survey conducted on : 25/6/18 at

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 8 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ 2000

(e) Signature of surveyor : Tanjima

Date: 25/6/18

ESTIMATED REPAIR COST DETAILS

1

Vehicle No : SLU4858M Case Owner : BLUECAR EAST ASIA PTE LTD / BLUESG PTE LTD

Make & Model : BLUECAR Year Manufacture : 2017

Chassis No : VL4BCEB4RHT003000 Engine No : 921955Q16W391425195

Date & Time : - Supplier : -

Order By : - Type of Claim : OD

S/No	Part Description	QTY	Unit Price	Cost Price	Nett Price	S/N	Remarks
1	Front bumper <i>cm</i>	1	\$ 1,300.00	\$ 1,300.00	\$ -	\$ -	-
2	Front bumper top grille <i>bt</i>	1	\$ 22.00	\$ 22.00	\$ -	\$ -	-
3	Front bumper lower grille <i>?</i>	1	\$ 22.00	\$ 22.00	\$ -	\$ -	-
4	Front signal lamp LH <i>x</i>	1	\$ 48.00	\$ 48.00	\$ -	\$ -	-
5	Front signal lamp RH <i>x</i>	1	\$ 48.00	\$ 48.00	\$ -	\$ -	-
6	Front bumper sponge <i>cm</i>	1	\$ 45.00	\$ 45.00	\$ -	\$ -	-
7	Front bumper sponge clip <i>nr</i>	8	\$ 2.00	\$ 16.00	\$ -	\$ -	-
8	Front bumper reinforcement <i>bt</i>	1	\$ 140.00	\$ 140.00	\$ -	\$ -	-
9	Front bumper reinforcement bracket LH <i>bt</i>	1	\$ 120.00	\$ 120.00	\$ -	\$ -	-
10	Front bumper reinforcement bracket RH <i>bt</i>	1	\$ 120.00	\$ 120.00	\$ -	\$ -	-
11	Front number plate with casing <i>m.r</i>	1	\$ -	\$ -	\$ -	\$ 45.00	-
12	Headlamp assy LH <i>cm</i>	1	\$ 650.00	\$ 650.00	\$ -	\$ -	-
13	Headlamp assy RH <i>cm</i>	1	\$ 650.00	\$ 650.00	\$ -	\$ -	-
14	Headlamp adjuster LH <i>?</i>	1	\$ 65.00	\$ 65.00	\$ -	\$ -	-
15	Headlamp adjuster LH <i>?</i>	1	\$ 65.00	\$ 65.00	\$ -	\$ -	-
16	Aircon condenser <i>bt</i>	1	\$ 600.00	\$ 600.00	\$ -	\$ -	-
17	Aircon discharges hose <i>?</i>	1	\$ 125.00	\$ 125.00	\$ -	\$ -	-
18	Aircon suction hose <i>?</i>	1	\$ 125.00	\$ 125.00	\$ -	\$ -	-
19	Radiator fan motor with cowling assy <i>?</i>	1	\$ 450.00	\$ 450.00	\$ -	\$ -	-
20	Radiator fan switch <i>?</i>	1	\$ 45.00	\$ 45.00	\$ -	\$ -	-
21	Radiator assy <i>?</i>	1	\$ 450.00	\$ 450.00	\$ -	\$ -	-
22	Radiator lower hose complete set <i>?</i>	1	\$ 120.00	\$ 120.00	\$ -	\$ -	-
23	Radiator top hose <i>?</i>	1	\$ 45.00	\$ 45.00	\$ -	\$ -	-
24	Front support panel assy <i>bt</i>	1	\$ 320.00	\$ 320.00	\$ -	\$ -	-
25	Front support air guide set <i>de</i>	1	\$ 48.00	\$ 48.00	\$ -	\$ -	-
26	Heater pump <i>?</i>	1	\$ 210.00	\$ 210.00	\$ -	\$ -	-
27	Passenger warning horn <i>?</i>	1	\$ 280.00	\$ 280.00	\$ -	\$ -	-
28	Bonnet <i>bt</i>	1	\$ 1,155.00	\$ 1,155.00	\$ -	\$ -	-
29	Bonnet lock <i>bt</i>	1	\$ 45.00	\$ 45.00	\$ -	\$ -	-
30	Bonnet cable <i>?</i>	1	\$ 25.00	\$ 25.00	\$ -	\$ -	-

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL \$ 7,340.00 \$ 7,354.00 \$ - \$ 45.00

Indeco

VEHICLES & EQUIPMENT DIVISION

2

Vehicle No : SLU4858M Case Owner : BLUECAR EAST ASIA
PTE LTD / BLUESG PTE
 Make & Model : BLUECAR Year Manufacture : 2017
 Chassis No : VL4BCEB4RHT003000 Engine No : 921955Q16W391425195
 Date & Time : - Supplier : -
 Order By : - Type of Claim : OD

S/No	Part Description	QTY	Unit Price	Cost Price	Nett Price	S/N	Remarks
1	Bonnet hinge LH	1	\$ 60.00	\$ 60.00	\$ -	\$ -	-
2	Bonnet hinge RH	1	\$ 60.00	\$ 60.00	\$ -	\$ -	-
3	Bonnet stand	1	\$ 22.00	\$ 22.00	\$ -	\$ -	-
4	Bonnet stickers	1	\$ -	\$ -	\$ 60.00	\$ -	-
5	Bumper top rubber seal	1	\$ 60.00	\$ 60.00	\$ -	\$ -	-
6	Front bumper clip	10	\$ 2.00	\$ 20.00	\$ -	\$ -	-
7	Radiator lower & upper elastic damper	4	\$ 3.00	\$ 12.00	\$ -	\$ -	-
8	Radiator lower crossbeam	1	\$ 150.00	\$ 150.00	\$ -	\$ -	-
9	Front fender RH	1	\$ 800.00	\$ 800.00	\$ -	\$ -	-
10	Front fender LH	1	\$ 800.00	\$ 800.00	\$ -	\$ -	-
11	Front towing cover	1	\$ 12.00	\$ 12.00	\$ -	\$ -	-
12	Windscreen wiper tank with motor	1	\$ 85.00	\$ 85.00	\$ -	\$ -	-
13	Front windscreen	1	\$ 980.00	\$ 980.00	\$ -	\$ -	-
14	Front windscreen moulding	1	\$ 80.00	\$ 80.00	\$ -	\$ -	-
15	Sealant	1	\$ 30.00	\$ 30.00	\$ -	\$ -	-
16	Inner seal tape	1	\$ 30.00	\$ 30.00	\$ -	\$ -	-
17	IU stickers	1	\$ 5.00	\$ 5.00	\$ -	\$ -	-
18	Engine cover	1	\$ 40.00	\$ 40.00	\$ -	\$ -	-
19	Cooling water pump	1	\$ 280.00	\$ 280.00	\$ -	\$ -	-
20	Water pump for heater	1	\$ 200.00	\$ 200.00	\$ -	\$ -	-
21	Battery acid drip pan	1	\$ 38.00	\$ 38.00	\$ -	\$ -	-
22	Battery 12v	1	\$ 180.00	\$ 180.00	\$ -	\$ -	-
23	Horn	1	\$ 85.00	\$ 85.00	\$ -	\$ -	-
24	Seat belt LH	1	\$ 260.00	\$ 260.00	\$ -	\$ -	-
25	Seat belt RH	1	\$ 260.00	\$ 260.00	\$ -	\$ -	-
26	Inboard Screen cover	1	\$ 30.00	\$ 30.00	\$ -	\$ -	-
27	Steering clock spring	1	\$ 250.00	\$ 250.00	\$ -	\$ -	-
28	Repair battery pack 30kWh	1	\$ 4,000.00	\$ 4,000.00	\$ -	\$ -	-
29	Driver airbag	1	\$ -	\$ -	\$ -	\$ -	Awaiting price
30	Passenger airbag	1	\$ -	\$ -	\$ -	\$ -	Awaiting price

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL \$ 8,802.00 \$ 8,829.00 \$ 60.00 \$ -



VEHICLES & EQUIPMENT DIVISION

3

Vehicle No : SLU4858M Case Owner : BLUECAR EAST ASIA PTE LTD / BLUESG PTE LTD

Make & Model : BLUECAR Year Manufacture : 2017

Chassis No : VL4BCEB4RHT003000 Engine No : 921955Q16W391425195

Date & Time : - Supplier : -

Order By : - Type of Claim : OD

S/No	Part Description	QTY	Unit Price	Cost Price	Nett Price	S/N	Remarks
61	Airbag ECU <i>act</i>	1	\$ 450.00	\$ 450.00	\$ -	\$ -	-
62	Airbag sensor LH <i>act</i>	1	\$ 80.00	\$ 80.00	\$ -	\$ -	-
63	Airbag sensor RH <i>act</i>	1	\$ 80.00	\$ 80.00	\$ -	\$ -	-
64	0	0	\$ -	\$ -	\$ -	\$ -	-
65	0	0	\$ -	\$ -	\$ -	\$ -	-
66	0	0	\$ -	\$ -	\$ -	\$ -	-
67	0	0	\$ -	\$ -	\$ -	\$ -	-
68	0	0	\$ -	\$ -	\$ -	\$ -	-
69	0	0	\$ -	\$ -	\$ -	\$ -	-
70	0	0	\$ -	\$ -	\$ -	\$ -	-
71	0	0	\$ -	\$ -	\$ -	\$ -	-
72	0	0	\$ -	\$ -	\$ -	\$ -	-
73	0	0	\$ -	\$ -	\$ -	\$ -	-
74	0	0	\$ -	\$ -	\$ -	\$ -	-
75	0	0	\$ -	\$ -	\$ -	\$ -	-
76	0	0	\$ -	\$ -	\$ -	\$ -	-
77	0	0	\$ -	\$ -	\$ -	\$ -	-
78	0	0	\$ -	\$ -	\$ -	\$ -	-
79	0	0	\$ -	\$ -	\$ -	\$ -	-
80	0	0	\$ -	\$ -	\$ -	\$ -	-
81	0	0	\$ -	\$ -	\$ -	\$ -	-
82	0	0	\$ -	\$ -	\$ -	\$ -	-
83	0	0	\$ -	\$ -	\$ -	\$ -	-
84	0	0	\$ -	\$ -	\$ -	\$ -	-
85	0	0	\$ -	\$ -	\$ -	\$ -	-
86	0	0	\$ -	\$ -	\$ -	\$ -	-
87	0	0	\$ -	\$ -	\$ -	\$ -	-
88	0	0	\$ -	\$ -	\$ -	\$ -	-
89	0	0	\$ -	\$ -	\$ -	\$ -	-
90	0	0	\$ -	\$ -	\$ -	\$ -	-

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL \$ 610.00 \$ 610.00 \$ - \$ -

Labour

Vehicle No. : SLU4858M Case Owner
Make & Model : BLUECAR Year of Manufacture
BLUECAR EAST ASIA PTE LTD / BLUESG PTE LTD : 2017

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO PANEL BEAT, REPLACE BONNET, BUMPER, REINFORCEMENT, SUPPORT PANEL, LHF FENDER, LHF FENDER AND AFFECTED AREA	\$1,200.00	0
2	TO PUTTY AND RESPRAY ON BONNET, BUMPER, REINFORCEMENT, RHF FENDER, LHF FENDER, SUPPORT PANEL AND AFFECTED AREA	\$1,200.00	800
3	TO REMOVE AND REPLACE RADIATOR AND CONDENSER	\$150.00	120
4	TO VACUUM AND TOP UP AC GAS (R1234)	\$400.00	180 350
5	TO CHECK WIRING, AND RESET ELECTRICAL SYSTEM	\$400.00	700
6	TO TOP UP COOLANT	\$50.00	30
7	TO REMOVE AND REFIT POWER TRAIN BAY SYSTEM TO ASSIST WORK	\$400.00	250 7 plus
8	TO REMOVE AND REFIX FRT WINDSCREEN	\$150.00	120
9	TO REMOVE AND REFIX AIRBAG SYSTEM	\$400.00	300
10	TO REMOVE AND REFIX BATTERY PACK 30KWH	\$280.00	200 7 plus
TOTAL		\$4,630.00	\$0.00

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.