



1

Vehicle No : SLU4858M

Case Owner : FTE LTD / BESESOTTE LTD

Make & Model : BLUECAR

Year Manufacture : 2017

Chassis No : VL4BCEB4RHT003000

Engine No : 921955Q16W391425195

Date & Time : -

Supplier : _____

Order By : -

Type of Claim : OD

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL	\$ 7,349.00	\$ 7,354.00	\$ -	\$ 45.00
--------------	--------------------	--------------------	-------------	-----------------

Indeco

VEHICLES & EQUIPMENT DIVISION

2

Vehicle No : SLU4858M Case Owner : BLUECAR EAST ASIA
PTE LTD / BLUESG PTE
 Make & Model : BLUECAR Year Manufacture : 2017
 Chassis No : VL4BCEB4RHT003000 Engine No : 921955Q16W391425195
 Date & Time : - Supplier : -
 Order By : - Type of Claim : OD

S/No	Part Description	QTY	Unit Price	Cost Price	Nett Price	S/N	Remarks
1	Bonnet hinge LH <i>ht ? v</i>	1	\$ 60.00	\$ 60.00	\$ -	\$ -	-
2	Bonnet hinge RH <i>ht ? v</i>	1	\$ 60.00	\$ 60.00	\$ -	\$ -	-
3	Bonnet stand <i>Ry</i>	1	\$ 22.00	\$ 22.00	\$ -	\$ -	-
4	Bonnet stickers <i>acc</i>	1	\$ -	\$ -	\$ 60.00	\$ -	-
5	Bumper top rubber seal <i>aut ? v</i>	1	\$ 60.00	\$ 60.00	\$ -	\$ -	-
6	Front bumper clip <i>acc</i>	10	\$ 2.00	\$ 20.00	\$ -	\$ -	-
7	Radiator lower & upper elastic damper <i>nm ? x</i>	4	\$ 3.00	\$ 12.00	\$ -	\$ -	-
8	Radiator lower crossbeam <i>nm ? x</i>	1	\$ 150.00	\$ 150.00	\$ -	\$ -	-
9	Front fender RH <i>Ry</i>	1	\$ 800.00	\$ 800.00	\$ -	\$ -	-
10	Front fender LH <i>Ry</i>	1	\$ 800.00	\$ 800.00	\$ -	\$ -	-
11	Front towing cover <i>ms</i>	1	\$ 12.00	\$ 12.00	\$ -	\$ -	-
12	Windscreen wiper tank with motor <i>nm ? x</i>	1	\$ 85.00	\$ 85.00	\$ -	\$ -	-
13	Front windscreen <i>acc</i>	1	\$ 980.00	\$ 980.00	\$ -	\$ -	-
14	Front windscreen moulding <i>acc</i>	1	\$ 80.00	\$ 80.00	\$ -	\$ -	-
15	Sealant <i>acc</i>	1	\$ 30.00	\$ 30.00	\$ -	\$ -	-
16	Inner seal tape <i>acc</i>	1	\$ 30.00	\$ 30.00	\$ -	\$ -	-
17	IU stickers <i>acc</i>	1	\$ 5.00	\$ 5.00	\$ -	\$ -	-
18	Engine cover <i>nm ? x</i>	1	\$ 40.00	\$ 40.00	\$ -	\$ -	-
19	Cooling water pump <i>nm ? x</i>	1	\$ 280.00	\$ 280.00	\$ -	\$ -	-
20	Water pump for heater <i>nm ? x</i>	1	\$ 200.00	\$ 200.00	\$ -	\$ -	-
21	Battery acid drip pan <i>nm ? x</i>	1	\$ 38.00	\$ 38.00	\$ -	\$ -	-
22	Battery 12v <i>de ? v</i>	1	\$ 180.00	\$ 180.00	\$ -	\$ -	-
23	Horn <i>nm ? x</i>	1	\$ 85.00	\$ 85.00	\$ -	\$ -	-
24	Seat belt LH <i>nm ? x</i>	1	\$ 260.00	\$ 260.00	\$ -	\$ -	-
25	Seat belt RH <i>acc</i>	1	\$ 260.00	\$ 260.00	\$ -	\$ -	-
26	Inboard Screen cover <i>de ? v</i>	1	\$ 30.00	\$ 30.00	\$ -	\$ -	-
27	Steering clock spring <i>acc ? v</i>	1	\$ 250.00	\$ 250.00	\$ -	\$ -	-
28	Repair battery pack 30kWh <i>photo ? v</i>	1	\$ 4,000.00	\$ 4,000.00	\$ -	\$ -	-
29	Driver airbag <i>acc</i>	1	\$ -	\$ 780 -	\$ -	\$ -	Awaiting price
30	Passenger airbag <i>acc</i>	1	\$ -	\$ 700 -	\$ -	\$ -	Awaiting price

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL \$ 8,802.00 \$ 8,829.00 \$ 60.00 \$ -

Indeco

VEHICLES & EQUIPMENT DIVISION

3

Vehicle No : SLU4858M Case Owner : BLUECAR EAST ASIA PTE LTD /
BLUESG PTE LTD

Make & Model : BLUECAR Year Manufacture : 2017

Chassis No : VL4BCEB4RHT003000 Engine No : 921955Q16W391425195

Date & Time : - Supplier : -

Order By : - Type of Claim : OD

S/No	Part Description	QTY	Unit Price	Cost Price	Nett Price	S/N	Remarks
61	Airbag ECU <i>act</i>	1	\$ 450.00	\$ 450.00	\$ -	\$ -	-
62	Airbag sensor LH <i>act</i>	1	\$ 80.00	\$ 80.00	\$ -	\$ -	-
63	Airbag sensor RH <i>act</i>	1	\$ 80.00	\$ 80.00	\$ -	\$ -	-
64	0	0	\$ -	\$ -	\$ -	\$ -	-
65	0	0	\$ -	\$ -	\$ -	\$ -	-
66	0	0	\$ -	\$ -	\$ -	\$ -	-
67	0	0	\$ -	\$ -	\$ -	\$ -	-
68	0	0	\$ -	\$ -	\$ -	\$ -	-
69	0	0	\$ -	\$ -	\$ -	\$ -	-
70	0	0	\$ -	\$ -	\$ -	\$ -	-
71	0	0	\$ -	\$ -	\$ -	\$ -	-
72	0	0	\$ -	\$ -	\$ -	\$ -	-
73	0	0	\$ -	\$ -	\$ -	\$ -	-
74	0	0	\$ -	\$ -	\$ -	\$ -	-
75	0	0	\$ -	\$ -	\$ -	\$ -	-
76	0	0	\$ -	\$ -	\$ -	\$ -	-
77	0	0	\$ -	\$ -	\$ -	\$ -	-
78	0	0	\$ -	\$ -	\$ -	\$ -	-
79	0	0	\$ -	\$ -	\$ -	\$ -	-
80	0	0	\$ -	\$ -	\$ -	\$ -	-
81	0	0	\$ -	\$ -	\$ -	\$ -	-
82	0	0	\$ -	\$ -	\$ -	\$ -	-
83	0	0	\$ -	\$ -	\$ -	\$ -	-
84	0	0	\$ -	\$ -	\$ -	\$ -	-
85	0	0	\$ -	\$ -	\$ -	\$ -	-
86	0	0	\$ -	\$ -	\$ -	\$ -	-
87	0	0	\$ -	\$ -	\$ -	\$ -	-
88	0	0	\$ -	\$ -	\$ -	\$ -	-
89	0	0	\$ -	\$ -	\$ -	\$ -	-
90	0	0	\$ -	\$ -	\$ -	\$ -	-

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL \$ 610.00 \$ 610.00 \$ - \$ -



Tel: (65) 382 2736 FAX: (65) 6382 2817

BLUECAR EAST
ASIA PTE LTD /
BLUESG PTE
LTD

Case Owner	:	<u>LTD</u>
Year of Manufacture		2017

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.