

ASS. REC. BY:

REP: CS/MSG18011407/Tlv3/2

Field Instructions

Surveyor

Merimen

Protn (Person)

Kwok Woon Choo

ASSIGNMENT (Office)

MSG

Date/Time

22/6/18 @ 3.52pm

Estimated Cost

Bill to:

OD

TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLU4858M

Insured:

at Workshop m/s

Indeco Engineers

Tel:

6382 2738

of

No. 39 Defu Lane 12

Policy No:

29068237MCY

Claim No:

546367

Sum Insured

Excess

\$ 2000.00

Make of Veh:

(Client's Record)

D.O.A.

05/01/2018

CA / REV

/

REP.

/

REV 24 HRS

25/06/2018

ILLD. Endorsement

Date/Time

4.23pm 22/6/18

Person Contacted

Mr Wong

Vehicle

IN

OUT

Date/Time	Action/Instruction
	(✓) Estimate Part price for airbag to be confirmed look for fan cheng hui
	SLU4858M - X
26/6/18	Revert by merimen
27/6/18	Rece approved from Chen Haw via merimen
27/6/18	Informed cheng hui c/A ex \$ 2000/2 via email
26/12/18	Final fig \$ 22,695.80 Confirmed by email (Recd 5598.50, 2018)

Tan

REF: MSIG

ASSIGNMENT

Date: 25/06/2018

Veh No: SLU 4858M

Estimated Cost:
TP, NS/TP RES/OD RES/EVA/INV/MV

Type: Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: blue car

Colour: white

Sp Reading

Eng/Mo

C/N: VL4BLEBUR H T 0003000

Gen Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: M / S/Rim / STD A/Rim or

Tyre Size: F: 175/65 R15
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front: R/Bal: 6 mm
L/Bal: 6 mm
Rear: R/Bal: 6 mm
L/Bal: 6 mm

D.O.A: DO1 25/6/18E/730

Survey held at: Indeco

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

In Inspect Vehicle No: SLU 4858M
at Workshop no: Indeco
of: No-39 Defu Lane 12

Insured:

Policy No:

Claims No:

Sum Insured: Excess \$2,000.00

(Client's Record) Part price for airbag to be confirmed

Make of Veh: Tan Cheng Thuat

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA: REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time: Action / Instruction: New Car \$80K exclude COE

Chbe 83009115

RECEIVED 27 DEC 2018

27/12/2018

Date/Time: File Pass to: []: Prel. Report
[]: Final Report

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey For:	200
Compensation:	
2-PR: 4	
Flam:	
Other:	
	10
	210

27/12 - typist

Add Fee: [] Site Insp (\$)
[] Interview (\$)
[] Tech. Insp (\$)
[] Workshop (\$)

Report Format: merimen
Lump Sum / LB: (\$ 22,695.80

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rot	Adj Submitted	Ass Auth'd	Status
Main	06 Jan 2018		22 Jun 2018 15:52 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	BLUECAR EAST ASIA PTE LTD, Co. Reg. No.: 201617259H		
Vehicle Reg. No.:	SLU4858M	Date of Loss:	05/01/2018 00:00 - :59 [1 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 546367	Policy/Cover Note No.:	29068237MCY (Comprehensive) Coverage: 01/01/2018 - 31/12/2018
		Excess:	S\$2,000.00
Repairer:	Indeco Engineers Pte Ltd (Defu) No. 39 Defu Lane 12, 539315 Defu Lane - Tel: 6382 2738		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Kwok Woon Choo - 6643 1330]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/06/2018]		
Driver/Custodian:	LOW WEN HAO DWAYNE (19 / Male), NRIC: S9813309G		
Adj Asg. Remarks:	Car in, Survey & revert. Please contact us ASAP if you cannot attend this assignment. Part price for airbag to be confirmed.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

***SLU4858M (546367)**
OD
Jan 5 2018 12:00AM
[BLUECAR EAST ASIA PTE LTD]
Indeco Engineers Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 08/12/2018 17:51 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$22695.80) - SLU4858M - Claim Handler: Kwok Woon Choo

Approved:22695.80.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kwok Woon Choo

Date: 06 Dec 2018

Preliminary Advice

Vehicle No	: SLU4858M	Accident Date	: 05/01/2018
Make	: BLUECAR BLUECAR	Policy No.	: 29068237MCY
Assignment Date	: 22/06/2018	Excess	: S\$2,000.00
Date of Inspection	: 25/06/2018	Est. Duration of Repair	: 8.00
Inspection At	INDECO ENGINEERS PTE LTD (DEFU) NO. 39 DEFU LANE 12 SINGAPORE 539315		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,294.30	(incl.confirm check items and supplementary \$3465)
Revised Amount	:S\$	22,695.80	(incl.confirm check items and supplementary \$3465)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	22,695.80	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	105,000.00
COE / PARF Rebate	:S\$	47,224.00
Salvage Value	:S\$	
Margin for Repair	:S\$	57,776.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 27 June 2018 4:44 PM
To: 'tanch@sg.indeco.cwtlimited.com'
Cc: SUR
Subject: SLU 4858M-DOA: 5/1/2018 (MSIG OD)

Dear Cheng Huat,

As instructed by our client , please proceed to repair the insured vehicle **SLU 4858M (Excess S2000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SLU4858M (546367)**

OD

Jan 5 2018 12:00AM

[BLUECAR EAST ASIA PTE LTD]

Indeco Engineers Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 27/06/2018 16:19 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$10802.80) - SLU4858M - Claim Handler: Kwok Woon Choo

Approved:10802.80.

DOCUMENTS SUMMARY

There are no documents.

Woon Choo Kwok

From: Agnes Lee
Sent: Thursday, June 21, 2018 4:58 PM
To: Woon Choo Kwok
Subject: FW: SLU4858M - OD CLAIM (MSIG) DOA 05.01.18
Attachments: Accident Repair Estimates.pdf; BLUESG - SLU4858M - Accident on 5/1/2018

From: Tan Cheng Huat [mailto:tanch@sg.indeco.cwtlimited.com]
Sent: 21 June 2018 15:35
To: Claims <claims@sg.msig-asia.com>
Cc: Lai Bee Yin <bylai@sg.indeco.cwtlimited.com>; Wong Sin Kong <skwong@sg.indeco.cwtlimited.com>; Goh Chee Khoon <ckgoh@sg.indeco.cwtlimited.com>
Subject: SLU4858M - OD CLAIM (MSIG) DOA 05.01.18

Hi Officer-In-Charge,

We are submitting repair quotation for OD claim/repair of accident damages of **vehicle No. SLU4858M** on behalf of our client/policy holder, BLUECAR EAST ASIA PTE LTD / BLUESG PTE LTD.

Please refer to attachments on the Repair quotation & Email correspondence pertaining to the accident report.

Appreciate your arrangement for survey of the abovementioned vehicle.

Vehicle is currently parked at our following workshop and repair work will start after survey by your surveyor:

INDECO ENGINEERS PTE LTD
NO. 39, DEFU LANE 12
SINGAPORE 539139
(MAIN GATE AT BARTLEY ROAD EAST)

Thank you & Regards,

Tan Cheng Huat
Indeco Engineers Pte Ltd
Tel 63822736

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Kwok Woon Choo	Date: 26 Jun 2018

Preliminary Advice

Vehicle No	: SLU4858M	Accident Date	: 05/01/2018
Make	: BLUECAR BLUECAR	Policy No.	: 29068237MCY
Assignment Date	: 22/06/2018	Excess	: S\$2,000.00
Date of Inspection	: 25/06/2018	Est. Duration of Repair	: 8.00
Inspection At	: INDECO ENGINEERS PTE LTD (DEFU) NO. 39 DEFU LANE 12 SINGAPORE 539315		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,201.30
Revised Amount	:S\$	10,802.80
Check Items (Estimated)	:S\$	9,278.70
Total	:S\$	20,081.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	105,000.00
COE / PARF Rebate	:S\$	47,224.00
Salvage Value	:S\$	
Margin for Repair	:S\$	57,776.00

Remarks

(X) The vehicle is economical for repair.

(X) Some of the parts pending for parts prices.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kwok Woon Choo

Date: 26 Jun 2018

Preliminary Advice

Vehicle No	: SLU4858M	Accident Date	: 05/01/2018
Make	: BLUECAR BLUECAR	Policy No.	: 29068237MCY
Assignment Date	: 22/06/2018	Excess	: S\$2,000.00
Date of Inspection	: 25/06/2018	Est. Duration of Repair	: 8.00
Inspection At	: INDECO ENGINEERS PTE LTD (DEFU) NO. 39 DEFU LANE 12 SINGAPORE 539315		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,201.30
Revised Amount	:S\$	10,802.80
Check Items (Estimated)	:S\$	9,278.70
Total	:S\$	20,081.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	105,000.00
COE / PARF Rebate	:S\$	47,224.00
Salvage Value	:S\$	
Margin for Repair	:S\$	57,776.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7259H
Vehicle Details	
Vehicle No.:	SLU4858M
Vehicle to be Exported:	No
Intended De-registration Date:	22 Jun 2018
Vehicle Make:	BLUECAR
Vehicle Model:	BLUECAR
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	-
Chassis No.:	VL4BCEB4RHT003000
Maximum Power Output:	50.0 kW (67 bhp)
Open Market Value:	\$33,703.00
Original Registration Date:	04 Dec 2017
First Registration Date:	04 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$9,185.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Dec 2027
PARF Rebate Amount:	\$6,888.00
Intended COE Rebate Details	
COE Expiry Date:	03 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
PQP Paid:	\$42,698.00
COE Rebate Amount:	\$40,336.00
Total Rebate Amount:	\$47,224.00

The information contained herein is correct as at 22 Jun 2018

MV: 9105K

OK

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SLU4858M		
Vehicle Type :	R10 - Private Hire (Self-Drive) Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	EV Sharing Scheme		
Vehicle Make :	BLUECAR		
Vehicle Model :	BLUECAR		
Chassis No. :	VL4BCEB4RHT003000		
Propellant :	Electric		
Motor No. :	921955Q16W391425195		
Power Rating :	50.0 kW		
Maximum Power Output :	50.0 kW (67 bhp)		
Maximum Laden Weight :	1740 kg		
Unladen Weight :	1400 kg		
Year Of Manufacture :	2017		
Original Registration Date :	04 Dec 2017		
Lifespan Expiry Date :	-		
COE Category :	A - Car up to 1600cc & 97kW (130bhp)		
PQP Paid :	\$42,698.00		
COE Expiry Date :	03 Dec 2027		
Road Tax Expiry Date :	03 Dec 2018		
PARF Eligibility Expiry Date :	03 Dec 2027		
Inspection Due Date :	03 Dec 2020		
Intended Transfer Date :	26 Jun 2018		
CO2 Emission :	74.00 (g/km)		
CEV/VES Rebate Utilised Amount :	\$30,000.00		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
Transfer Fee :	25.00	-	25.00

Accident Report

Date of Accident	5 / 01 / 2018	Time of Accident	10:52 pm
Date of Reporting	6 / 01 / 2018	Time of Reporting	01:49 am
Location of Accident	Pan Island Expressway		
Vehicle Registration No.	SLU4858M	Company Registration No.	201617259H
Vehicle Make	Bluecar	Vehicle Model	Bluecar (A)
Registered Owner	Bluecar East Asia Pte Ltd.	Office No.	3163 7900
Vehicle Category	Private / Commercial / Motorcycle / Bus		
Name of Insurance Co.	India / QBE / Liberty / Etiga / Tokio / Lionpac / EQ / Zurich / MSIG		
Type of Coverage	Comprehensive / Third Party / Third Party, Fire & Theft		
Policy No.	MSD/VPCP/18-000001		
Type of Claim	Own Damage	Third Party	Reporting Only
Name of Driver	Low Wen Hao Dwayne		
NRIC / FIN / Passport No.	S98133096	Date of Birth	28/04/1998
Residential No.	6784 1010	Mobile No.	9630 7178
Residential Address	Blk 127, Tampines St 11, #02-438 (S521127)		
Email Address	dwaynelow21@gmail.com		
Occupation Nature	Indoor / Outdoor student	Gender	Male / Female
Licence Pass Date	01/09/2016	Years of Driving Experience	1 year 4 months
Driver Status	Owner / Non-Owner		
Relationship with Owner	BluesG		
Driver's Own Vehicle Registration No.	-		
Type of Accident			

Weather Condition Clear / Raining / Other: _____

Road Surface Condition Dry / Wet / Other: _____

Were you approached by anyone offering accident claim assistance? Yes / No

Was a police report made? Yes / No

Was any foreign vehicle involved in the accident? Yes / No

Was anybody injured during the accident? Yes / No

Was there any other vehicle or property damaged? Yes / No

Was there any video captured by your car camera? Yes / No


Number of passengers (including Driver) _____

Details of Other Vehicles	Vehicle B	Vehicle C	Vehicle D
Vehicle Registration No.	SHC8402K	SHA7675G	
Vehicle Make / Model	Hyundai i40	Hyundai i40	
Name of Driver	Koh Huen Chih		
NRIC / FIN / Passport No.	S8018964H		
Contact No.			
Name of Insurance Co.			

Details of Witnesses	Person 1	Person 2	Person 3
Name	Koh Huen Chih		
Contact No.			

Details of Injured Person	Person 1	Person 2	Person 3
Name			
Contact No.			

Driver's Declaration: I declare that the information given in this report is true and accurate to the best of my recollection and I bear full responsibility for all consequences arising out of or in connection with incomplete or inaccurate information submitted.


Signature of Driver

6/1/2018 0149AM
Date & Time



SINGAPORE POLICE FORCE



G/20180106/2007

1 of 2

POLICE REPORT (NP299)

Report No. G/20180106/2007

Police Station Of Origin
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

Date/Time Report Made 06/01/2018 01:06	Vide Report No.	Station Diary No. 16
Name Of Informant LOW WEN HAO DWAYNE	Address APT BLK 127 TAMPINES STREET 11 #02-438 SINGAPORE 521127	
ID Type / ID No. NRIC NO / S9813309G	Contact No. Home/Office Mobile 96307178	
Nationality SINGAPORE CITIZEN	Email Address	
Occupation Student	Sex Male	Age 19
	Date of Birth 28/04/1998	Race Chinese
Institution/School Name Singapore Polytechnic	Language English	
Date/Time Of Incident 05/01/2018 22:40	Location Of Incident PAN-ISLAND EXPRESSWAY SINGAPORE PIE Before Jalan Eunos Exit	

Brief details.

I am lodging this report for record purposes.

On 05/01/2018 at about 2242hrs, I was travelling along PIE towards Changi Airport. I was driving a Blue SG Rental Car Reg No: SLU4858M. Just before Eunos Exit, there were two taxis driving in front of me. The first taxi Reg no: SHA7675G make a sudden brake and stop causing the taxi in front of me Reg no: SHC8402K to brake immediately. I also steps on the brake however could not stop and avoid hitting the

Signature Of Officer Recording The Report:

G / Sr Staff Sgt MUHAMAD FAISAL BIN MOHD SALEH

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:
G / Bedok Police Divisional Investigation Branch /
Staff Sgt MUHAMMAD KHIDHIR BIN MOHAMED
HASHIM
Contact No.: 62440000

Authentication Stamp

Signature Of Informant:

Date/Time:
06/01/2018 01:06

Classification Of Case:





**SINGAPORE
POLICE FORCE**



G/20180106/2007

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. G/20180106/2007

taxi. I then came out of the car and discovered that the front bumper of my Blue SG car was badly damaged, the windscreen crack and also the air bag was deployed. The taxi rear bumper do not have any damaged. The taxi driver have two passengers and nobody informed they are injured.

I took details of the taxi driver and the vehicle Reg number and subsequently the taxi driver left the scene. I contacted Blue SG Support Hotline and was told to lodge a police report for their own follow up action and insurance claim.

Signature Of Officer Recording The Report:

G / Sr Staff Sgt MUHAMAD FAISAL BIN MOHD SALEH

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:
G / Bedok Police Divisional Investigation Branch /
Staff Sgt MUHAMMAD KHIDHIR BIN MOHAMED
HASHIM
Contact No : 62440000

Authentication Stamp

Signature Of Informant

Date/Time:
08/01/2018 01:08

Classification Of Case:



SINGAPORE
POLICE FORCE

SIGNATURE

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 9/11/18 2:00pm

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

A: SLU4858M C: SHA7675G
B: SHC8402K

SKETCH PLAN

PAN ISLAND EXPRESSWAY
ROAD SHOULDER



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I rented the Car from Bukit Botok Station and wanted to park at the Simei Charging Station. While on the expressway, I was travelling at the speed of about 85 km/h. When I was nearing Jalan Eunos exit, I was driving on the first lane. Vehicle C suddenly jammed ~~break~~ without explanation and vehicle B had no choice but to jam ~~break~~ brake as well. I was behind vehicle B and I jam brake as well but the brake wasn't fully effective for me to stop in time and I collided when the air bags got deployed and windscreen shattered but still in frame. All the drivers came out and driver B scolded driver C for braking hard for no reason. Driver C then said he will leave because vehicle B did not hit him. Driver B then exchanged details with me but left soon after because there was not a single scratch on his vehicle. After the car was towed to the empty carpark in Eunos, I then found out that the BluesG car front was made out of plastic which explained the damage to the car and leaving no scratch to the taxi made of steel. I then did the required.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 9/1/18 2:00pm

Reporting Centre Personnel's Signature
Name:
NRIC/PPN No.:

Tan Cheng Huat

From: MingHao_Peh@jltasia.com
Sent: Tuesday, 9 January, 2018 4:28 PM
To: BlueSG Claims
Cc: Maggie_Ng@jltasia.com; Tiong Say Ng
Subject: BLUESG - SLU4858M - Accident on 5/1/2018

Dear Sonya,

Please be informed that we are in receipt of the documents and have forward it to your Insurer.

Meanwhile, please send the vehicle to your workshop for assessment and inform your workshop to get in touch with MSIG motor surveyor.

Thank you.

Best Regards,

Peh Ming Hao | Executive | Claims | Jardine Lloyd Thompson Pte Ltd
Co. Registration No. 196900157N
138 Market Street | #07-01 CapitaGreen | Singapore 048946
Tel : 6333 6311 | DID : 6411 9223 | Fax : 6333 6511
MingHao_Peh@jltasia.com | www.asia.ilt.com

Follow us on [LinkedIn](#)

From: BlueSg Claims [mailto:claims@bluesg.com.sg]
Sent: Tuesday, 9 January, 2018 4:20 PM
To: Peh, Ming Hao - SGP223
Cc: Ng, Maggie - SGP255; Tiong Say Ng
Subject: RE: Accident on 5 Jan

Hello Ming Hao,

Could you kindly confirm whether you have received the email below please?

Thanks

From: Sonya Vij
Sent: Tuesday, 9 January, 2018 3:42 PM
To: 'MingHao_Peh@jltasia.com' <MingHao_Peh@jltasia.com>
Cc: Maggie_Ng@jltasia.com; Tiong Say Ng <Tiong-Say.ng@bluesg.com.sg>
Subject: RE: Accident on 5 Jan
Importance: High

Dear Ming Hao,

Please find attached the:

1. Accident report form – internal doc which contains all the relevant information for input to Merimen (including the vehicle licence plate no);
2. Sketch plan;
3. Police report; and
4. Photos.

Noted on the limit of the OD claim amount.

Do let us know if further information is required to facilitate the claim.

Regards

From: MingHao Peh<MingHao_Peh@jltasia.com>
Sent: Tuesday, 9 January, 2018 3:24 PM
To: Sonya Vij <sonya.vij@bluesg.com.sg>
Cc: Maggie Ng<Maggie_Ng@jltasia.com>
Subject: RE: Accident on 5 Jan

Dear Sonya,

We refer to your email today.

Please be informed that MSIG is still in the midst of sorting the system issue. For this case we will report to them via email.

Please assist to provide us:-

1. Car plate number
2. Circumstances of the accident
3. T/P's car plate (if any)
4. Photos of damaged vehicles

With regards to the limit under your OD cover, please be advised that it is as per declared value of the vehicle: EUR 50 000 (including the value of the battery which is EUR 38 000).

We trust the above is in order and we await your reply.

Thank you.

Best Regards,

Peh Ming Hao | Executive | Claims | Jardine Lloyd Thompson Pte Ltd
Co. Registration No. 196900157N
138 Market Street | #07-01 CapitaGreen | Singapore 048946
Tel : 6333 6311 | DID : 6411 9223 | Fax : 6333 6511
MingHao_Peh@jltasia.com | www.asia.jlt.com

Follow us on [LinkedIn](#)

From: Sonya Vij <sonya.vij@bluesg.com.sg>
Sent: Tuesday, 9 January, 2018 2:35 PM

To: Peh, Ming Hao - SGP223

Subject: Accident on 5 Jan

Hi Ming Hao,

I am trying to create a new accident report for an accident that occurred on 5 Jan 2018. As of 1 Jan 2018, the insurance has switched to MSIG however the system still indicates Zurich and I am unable to amend it – can I still submit the report?

We would also like to know, for an OD claim, what is the maximum amount that can be claimed? The accident was major with both airbags deployed and the onboard pc has been dislodged.

Kind regards,

Sonya Vij

General Counsel

Tel: +65 3163 7904

Mobile: +65 9736 5541



BlueSG Pte. Ltd., a company incorporated in Singapore with company registration no. 201617258W and having its registered office at 16 Science Park Drive, #04-01 DNV GL Technology Centre, Singapore 118227.

This email and any attachments are confidential and may contain information that is privileged. It is intended solely for the recipient to whom it is addressed. If you are not the intended recipient of this email, you must not use, copy, circulate or transmit this email, its contents or any of its attachments. If you have received this message in error, please notify the sender and immediately delete this message.

Visit us at <http://www.asia.jlt.com>

Follow us on [LinkedIn](#)

IMPORTANT NOTICE

The content of this e-mail (including any attachments) as received may not be the same as sent. If you consider that the content is material to the formation or performance of a contract or you are otherwise relying upon its accuracy, you should consider requesting a copy be sent by facsimile or normal mail. The information in this e-mail is confidential and may be legally privileged. If you are not the intended recipient, please notify the sender immediately by e-mail for any purpose or disclose any of its content to others. Opinions, conclusions and other information in this e-mail that do not relate to the official business of any JLT Group company shall be understood as neither given nor endorsed by it.

Please note we intercept and monitor incoming / outgoing e-mail and therefore you should neither expect nor intend any e-mail to be private in nature. We have checked this e-mail for viruses and other harmful components and believe but not guarantee it virus-free prior to leaving our computer system. However, you should satisfy yourself that it is free from harmful components, as we do not accept responsibility for any loss or damage it may cause to your computer systems.

ACCIDENT REPAIR ESTIMATES

Our Ref: OD / SLU4858M

Type of Claim : ODVehicle No. : SLU4858MMake & Model : BLUECARYear of Manufacture : 2017Chassis No. : VL4BCEB4RHT003000Ins Company : MSIG INSURANCE
(SINGAPORE) PTE LTDEngine No. : 921955Q16W391425195Excess : \$0.00Policy No. : -Date of Accident : 05/01/2018Time of Accident : -Suggested Days of Repair : 10Case Owner : BLUECAR EAST ASIA PTE LTD / BLUESG PTE LTD**Repair Estimates**Parts (a) Cost Price Items \$ 16,793.00Plus/Less 10% \$ 1,679.30Total of Cost / List \$ 18,472.30(b) Nett Price Items \$ 60.00Less 10% \$ 6.00Total of Nett Item \$ 54.00(c) Special Nett Items \$ 45.00Total Parts Cost (Appendix A) \$ 18,571.30Labour (Appendix B) \$ 4,630.00Total Repair Cost \$ 23,201.30 28,294.30

Note: A/w parts price for Item No. 29 & 30 (Parts List pg 2)

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor : Tan Jiah 97495747Company : LKK 62563561Survey conducted on : 25/6/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 8 day(s)(c) Resurvey : Required / Not Required(d) Excess : 2000(e) Signature of surveyor : Tan JiahDate: 25/6/18

ESTIMATED REPAIR COST DETAILS

1

Vehicle No : SLU4858M Case Owner : BLUECAR EAST ASIA PTE LTD / BLUESG PTE LTD

Make & Model : BLUECAR Year Manufacture : 2017

Chassis No : VL4BCEB4RHT003000 Engine No : 921955Q16W391425195

Date & Time : - Supplier : -

Order By : - Type of Claim : OD

S/No	Part Description	QTY	Unit Price	Cost Price	Nett Price	S/N	Remarks
1	Front bumper <i>CMA</i>	1	\$ 1,300.00	\$ 1,300.00	\$ -	\$ -	-
2	Front bumper top grille <i>bt</i>	1	\$ 22.00	\$ 22.00	\$ -	\$ -	-
3	Front bumper lower grille <i>X TM</i>	1	\$ 22.00	\$ 22.00	\$ -	\$ -	-
4	Front signal lamp LH <i>X NM</i>	1	\$ 48.00	\$ 48.00	\$ -	\$ -	-
5	Front signal lamp RH <i>X NM</i>	1	\$ 48.00	\$ 48.00	\$ -	\$ -	-
6	Front bumper sponge <i>CMA</i>	1	\$ 45.00	\$ 45.00	\$ -	\$ -	-
7	Front bumper sponge clip <i>nm</i>	8	\$ 2.00	\$ 16.00	\$ -	\$ -	-
8	Front bumper reinforcement <i>bt</i>	1	\$ 140.00	\$ 140.00	\$ -	\$ -	-
9	Front bumper reinforcement bracket LH <i>bt</i>	1	\$ 120.00	\$ 120.00	\$ -	\$ -	-
10	Front bumper reinforcement bracket RH <i>bt</i>	1	\$ 120.00	\$ 120.00	\$ -	\$ -	-
11	Front number plate with casing <i>nm</i>	1	\$ -	\$ -	\$ -	\$ 45.00	-
12	Headlamp assy LH <i>CMA</i>	1	\$ 650.00	\$ 650.00	\$ -	\$ -	-
13	Headlamp assy RH <i>CMA</i>	1	\$ 650.00	\$ 650.00	\$ -	\$ -	-
14	Headlamp adjuster LH <i>? X NM</i>	1	\$ 65.00	\$ 65.00	\$ -	\$ -	-
15	Headlamp adjuster LH <i>? X NM</i>	1	\$ 65.00	\$ 65.00	\$ -	\$ -	-
16	Aircon condenser <i>bt</i>	1	\$ 600.00	\$ 600.00	\$ -	\$ -	-
17	Aircon discharges hose <i>? bt</i>	1	\$ 125.00	\$ 125.00	\$ -	\$ -	-
18	Aircon suction hose <i>? bt</i>	1	\$ 125.00	\$ 125.00	\$ -	\$ -	-
19	Radiator fan motor with cowling assy <i>nm</i>	1	\$ 450.00	\$ 450.00	\$ -	\$ -	-
20	Radiator fan switch <i>? NM</i>	1	\$ 45.00	\$ 45.00	\$ -	\$ -	-
21	Radiator assy <i>bt</i>	1	\$ 450.00	\$ 450.00	\$ -	\$ -	-
22	Radiator lower hose complete set <i>dis</i>	1	\$ 120.00	\$ 120.00	\$ -	\$ -	-
23	Radiator top hose <i>dis</i>	1	\$ 45.00	\$ 45.00	\$ -	\$ -	-
24	Front support panel assy <i>bt</i>	1	\$ 320.00	\$ 320.00	\$ -	\$ -	-
25	Front support air guide set <i>de</i>	1	\$ 48.00	\$ 48.00	\$ -	\$ -	-
26	Heater pump <i>nm? X</i>	1	\$ 210.00	\$ 210.00	\$ -	\$ -	-
27	Passenger warning horn <i>nm? X</i>	1	\$ 280.00	\$ 280.00	\$ -	\$ -	-
28	Bonnet <i>bt</i>	1	\$ 1,155.00	\$ 1,155.00	\$ -	\$ -	-
29	Bonnet lock <i>bt</i>	1	\$ 45.00	\$ 45.00	\$ -	\$ -	-
30	Bonnet cable <i>nm X</i>	1	\$ 25.00	\$ 25.00	\$ -	\$ -	-

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL \$ 7,340.00 \$ 7,354.00 \$ - \$ 45.00

Vehicle No : SLU4858M Case Owner : BLUECAR EAST ASIA
PTE LTD / BLUESG PTE
 Make & Model : BLUECAR Year Manufacture : 2017
 Chassis No : VL4BCEB4RHT003000 Engine No : 921955Q16W391425195
 Date & Time : - Supplier : -
 Order By : - Type of Claim : OD

S/No	Part Description	QTY	Unit Price	Cost Price	Nett Price	S/N	Remarks
1	Bonnet hinge LH <i>ht ? ✓</i>	1	\$ 60.00	\$ 60.00	\$ -	\$ -	-
2	Bonnet hinge RH <i>ht ? ✓</i>	1	\$ 60.00	\$ 60.00	\$ -	\$ -	-
3	Bonnet stand <i>Ry</i>	1	\$ 22.00	\$ 22.00	\$ -	\$ -	-
4	Bonnet stickers <i>acc</i>	1	\$ -	\$ -	\$ 60.00	\$ -	-
5	Bumper top rubber seal <i>aut ? ✓</i>	1	\$ 60.00	\$ 60.00	\$ -	\$ -	-
6	Front bumper clip <i>acc</i>	10	\$ 2.00	\$ 20.00	\$ -	\$ -	-
7	Radiator lower & upper elastic damper <i>acc ? ✓</i>	4	\$ 3.00	\$ 12.00	\$ -	\$ -	-
8	Radiator lower crossbeam <i>acc ? ✓</i>	1	\$ 150.00	\$ 150.00	\$ -	\$ -	-
9	Front fender RH <i>Ry</i>	1	\$ 800.00	\$ 800.00	\$ -	\$ -	-
10	Front fender LH <i>Ry</i>	1	\$ 800.00	\$ 800.00	\$ -	\$ -	-
11	Front towing cover <i>acc ✓</i>	1	\$ 12.00	\$ 12.00	\$ -	\$ -	-
12	Windscreen wiper tank with motor <i>acc ? ✓</i>	1	\$ 85.00	\$ 85.00	\$ -	\$ -	-
13	Front windscreen <i>acc ✓</i>	1	\$ 980.00	\$ 980.00	\$ -	\$ -	-
14	Front windscreen moulding <i>acc ✓</i>	1	\$ 80.00	\$ 80.00	\$ -	\$ -	-
15	Sealant <i>acc ✓</i>	1	\$ 30.00	\$ 30.00	\$ -	\$ -	-
16	Inner seal tape <i>acc ✓</i>	1	\$ 30.00	\$ 30.00	\$ -	\$ -	-
17	IU stickers <i>acc ✓</i>	1	\$ 5.00	\$ 5.00	\$ -	\$ -	-
18	Engine cover <i>acc ? ✓</i>	1	\$ 40.00	\$ 40.00	\$ -	\$ -	-
19	Cooling water pump <i>acc ? ✓</i>	1	\$ 280.00	\$ 280.00	\$ -	\$ -	-
20	Water pump for heater <i>acc ? ✓</i>	1	\$ 200.00	\$ 200.00	\$ -	\$ -	-
21	Battery acid drip pan <i>acc ? ✓</i>	1	\$ 38.00	\$ 38.00	\$ -	\$ -	-
22	Battery 12v <i>acc ? ✓</i>	1	\$ 180.00	\$ 180.00	\$ -	\$ -	-
23	Horn <i>acc ? ✓</i>	1	\$ 85.00	\$ 85.00	\$ -	\$ -	-
24	Seat belt LH <i>acc ? ✓</i>	1	\$ 260.00	\$ 260.00	\$ -	\$ -	-
25	Seat belt RH <i>acc ✓</i>	1	\$ 260.00	\$ 260.00	\$ -	\$ -	-
26	Inboard Screen cover <i>acc ? ✓</i>	1	\$ 30.00	\$ 30.00	\$ -	\$ -	-
27	Steering clock spring <i>acc ? ✓</i>	1	\$ 250.00	\$ 250.00	\$ -	\$ -	-
28	Repair battery pack 30kWh <i>photo checked</i>	1	\$ 4,000.00	\$ 4,000.00	\$ -	\$ -	-
29	Driver airbag <i>acc ✓</i>	1	\$ -	\$ 780.00	\$ -	\$ -	Awaiting price
30	Passenger airbag <i>acc ✓</i>	1	\$ -	\$ 700.00	\$ -	\$ -	Awaiting price

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL \$ 8,802.00 \$ 8,829.00 \$ 60.00 \$ -

Indeco

VEHICLES & EQUIPMENT DIVISION

3

Vehicle No : SLU4858M Case Owner : BLUECAR EAST ASIA PTE LTD /
BLUESG PTE LTD

Make & Model : BLUECAR Year Manufacture : 2017

Chassis No : VL4BCEB4RHT003000 Engine No : 921955Q16W391425195

Date & Time : - Supplier : -

Order By : - Type of Claim : OD

S/No	Part Description	QTY	Unit Price	Cost Price	Nett Price	S/N	Remarks
61	Airbag ECU <i>net</i>	1	\$ 450.00	\$ 450.00	\$ -	\$ -	-
62	Airbag sensor LH <i>net</i>	1	\$ 80.00	\$ 80.00	\$ -	\$ -	-
63	Airbag sensor RH <i>net</i>	1	\$ 80.00	\$ 80.00	\$ -	\$ -	-
64	0	0	\$ -	\$ -	\$ -	\$ -	-
65	0	0	\$ -	\$ -	\$ -	\$ -	-
66	0	0	\$ -	\$ -	\$ -	\$ -	-
67	0	0	\$ -	\$ -	\$ -	\$ -	-
68	0	0	\$ -	\$ -	\$ -	\$ -	-
69	0	0	\$ -	\$ -	\$ -	\$ -	-
70	0	0	\$ -	\$ -	\$ -	\$ -	-
71	0	0	\$ -	\$ -	\$ -	\$ -	-
72	0	0	\$ -	\$ -	\$ -	\$ -	-
73	0	0	\$ -	\$ -	\$ -	\$ -	-
74	0	0	\$ -	\$ -	\$ -	\$ -	-
75	0	0	\$ -	\$ -	\$ -	\$ -	-
76	0	0	\$ -	\$ -	\$ -	\$ -	-
77	0	0	\$ -	\$ -	\$ -	\$ -	-
78	0	0	\$ -	\$ -	\$ -	\$ -	-
79	0	0	\$ -	\$ -	\$ -	\$ -	-
80	0	0	\$ -	\$ -	\$ -	\$ -	-
81	0	0	\$ -	\$ -	\$ -	\$ -	-
82	0	0	\$ -	\$ -	\$ -	\$ -	-
83	0	0	\$ -	\$ -	\$ -	\$ -	-
84	0	0	\$ -	\$ -	\$ -	\$ -	-
85	0	0	\$ -	\$ -	\$ -	\$ -	-
86	0	0	\$ -	\$ -	\$ -	\$ -	-
87	0	0	\$ -	\$ -	\$ -	\$ -	-
88	0	0	\$ -	\$ -	\$ -	\$ -	-
89	0	0	\$ -	\$ -	\$ -	\$ -	-
90	0	0	\$ -	\$ -	\$ -	\$ -	-

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL \$ 610.00 \$ 610.00 \$ - \$ -



Tel: (65) 382 2736 FAX: (65) 6382 2817

BLUECAR EAST
ASIA PTE LTD /
BLUESG PTE
LTD

Case Owner : LTD

Year of Manufacture 2017

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

ACCIDENT REPAIR ESTIMATES

Our Ref: OD / SLU4858M

Type of Claim : ODVehicle No. : SLU4858MMake & Model : BLUECARYear of Manufacture : 2017Chassis No. : VL4BCEB4RHT003000Ins Company : MSIG INSURANCE
(SINGAPORE) PTE LTDEngine No. : 921955Q16W391425195Excess : \$0.00Policy No. : -Date of Accident : 05/01/2018Time of Accident : -Suggested Days of Repair : 10Case Owner : BLUECAR EAST ASIA PTE LTD / BLUESG PTE LTD**Repair Estimates**Parts (a) Cost Price Items \$ 16,793.00Plus/Less 10% \$ 1,679.30Total of Cost / List \$ 18,472.30(b) Nett Price Items \$ 60.00Less 10% \$ 6.00Total of Nett Item \$ 54.00(c) Special Nett Items \$ 45.00Total Parts Cost (Appendix A) \$ 18,571.30Labour (Appendix B) \$ 4,630.00Total Repair Cost \$ 23,201.30

Note: A/w parts price for Item No. 29 & 30 (Parts List pg 2)

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Tan Fik 97495749Company : WUE 62563561Survey conducted on : 25/6/18 at -**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 8 day(s)(c) Resurvey : Required / Not Required(d) Excess : \$ 2000(e) Signature of surveyor : Tan FikDate: 25/6/18

Resurvey before print
Not Authorised
Sur @ Whan Tan

ESTIMATED REPAIR COST DETAILS

1

Vehicle No : SLU4858M Case Owner : BLUECAR EAST ASIA
PTE LTD / BLUESG PTE
LTD
 Make & Model : BLUECAR Year Manufacture : 2017
 Chassis No : VL4BCEB4RHT003000 Engine No : 921955Q16W391425195
 Date & Time : - Supplier : -
 Order By : - Type of Claim : OD

S/No	Part Description	QTY	Unit Price	Cost Price	Nett Price	S/N	Remarks
1	Front bumper <i>cr</i>	1	\$ 1,300.00	\$ 1,300.00	\$ -	\$ -	-
2	Front bumper top grille <i>bt</i>	1	\$ 22.00	\$ 22.00	\$ -	\$ -	-
3	Front bumper lower grille <i>7X</i>	1	\$ 22.00	\$ 22.00	\$ -	\$ -	-
4	Front signal lamp LH <i>x</i>	1	\$ 48.00	\$ 48.00	\$ -	\$ -	-
5	Front signal lamp RH <i>x</i>	1	\$ 48.00	\$ 48.00	\$ -	\$ -	-
6	Front bumper sponge <i>cr</i>	1	\$ 45.00	\$ 45.00	\$ -	\$ -	-
7	Front bumper sponge clip <i>nr</i>	8	\$ 2.00	\$ 16.00	\$ -	\$ -	-
8	Front bumper reinforcement <i>bt</i>	1	\$ 140.00	\$ 140.00	\$ -	\$ -	-
9	Front bumper reinforcement bracket LH <i>bt</i>	1	\$ 120.00	\$ 120.00	\$ -	\$ -	-
10	Front bumper reinforcement bracket RH <i>bt</i>	1	\$ 120.00	\$ 120.00	\$ -	\$ -	-
11	Front number plate with casing <i>mr</i>	1	\$ -	\$ -	\$ -	\$ 45.00	-
12	Headlamp assy LH <i>cr</i>	1	\$ 650.00	\$ 650.00	\$ -	\$ -	-
13	Headlamp assy RH <i>cr</i>	1	\$ 650.00	\$ 650.00	\$ -	\$ -	-
14	Headlamp adjuster LH <i>7X</i>	1	\$ 65.00	\$ 65.00	\$ -	\$ -	-
15	Headlamp adjuster LH <i>7X</i>	1	\$ 65.00	\$ 65.00	\$ -	\$ -	-
16	Aircon condenser <i>bt</i>	1	\$ 600.00	\$ 600.00	\$ -	\$ -	-
17	Aircon discharges hose <i>7 bt</i>	1	\$ 125.00	\$ 125.00	\$ -	\$ -	-
18	Aircon suction hose <i>7 M</i>	1	\$ 125.00	\$ 125.00	\$ -	\$ -	-
19	Radiator fan motor with cowling assy <i>7 cr</i>	1	\$ 450.00	\$ 450.00	\$ -	\$ -	-
20	Radiator fan switch <i>7 nr</i>	1	\$ 45.00	\$ 45.00	\$ -	\$ -	-
21	Radiator assy <i>7 RA</i>	1	\$ 450.00	\$ 450.00	\$ -	\$ -	-
22	Radiator lower hose complete set <i>7 cr</i>	1	\$ 120.00	\$ 120.00	\$ -	\$ -	-
23	Radiator top hose <i>7 tw</i>	1	\$ 45.00	\$ 45.00	\$ -	\$ -	-
24	Front support panel assy <i>bt</i>	1	\$ 320.00	\$ 320.00	\$ -	\$ -	-
25	Front support air guide set <i>de</i>	1	\$ 48.00	\$ 48.00	\$ -	\$ -	-
26	Heater pump <i>7X</i>	1	\$ 210.00	\$ 210.00	\$ -	\$ -	-
27	Passenger warning horn <i>7X</i>	1	\$ 280.00	\$ 280.00	\$ -	\$ -	-
28	Bonnet <i>bt</i>	1	\$ 1,155.00	\$ 1,155.00	\$ -	\$ -	-
29	Bonnet lock <i>bt</i>	1	\$ 45.00	\$ 45.00	\$ -	\$ -	-
30	Bonnet cable <i>7X</i>	1	\$ 25.00	\$ 25.00	\$ -	\$ -	-

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL \$ 7,340.00 \$ 7,354.00 \$ - \$ 45.00

Indeco

VEHICLES & EQUIPMENT DIVISION

2

Vehicle No : SLU4858M Case Owner : BLUECAR EAST ASIA
 Make & Model : BLUECAR Year Manufacture : 2017
 Chassis No : VL4BCEB4RHT003000 Engine No : 921955Q16W391425195
 Date & Time : - Supplier : -
 Order By : - Type of Claim : OD

S/No	Part Description	QTY	Unit Price	Cost Price	Nett Price	S/N	Remarks
1	Bonnet hinge LH	1	\$ 60.00	\$ 60.00	\$ -	\$ -	-
2	Bonnet hinge RH	1	\$ 60.00	\$ 60.00	\$ -	\$ -	-
3	Bonnet stand	1	\$ 22.00	\$ 22.00	\$ -	\$ -	-
4	Bonnet stickers	1	\$ -	\$ -	\$ 60.00	\$ -	-
5	Bumper top rubber seal	1	\$ 60.00	\$ 60.00	\$ -	\$ -	-
6	Front bumper clip	10	\$ 2.00	\$ 20.00	\$ -	\$ -	-
7	Radiator lower & upper elastic damper	4	\$ 3.00	\$ 12.00	\$ -	\$ -	-
8	Radiator lower crossbeam	1	\$ 150.00	\$ 150.00	\$ -	\$ -	-
9	Front fender RH	1	\$ 800.00	\$ 800.00	\$ -	\$ -	-
10	Front fender LH	1	\$ 800.00	\$ 800.00	\$ -	\$ -	-
11	Front towing cover	1	\$ 12.00	\$ 12.00	\$ -	\$ -	-
12	Windscreen wiper tank with motor	1	\$ 85.00	\$ 85.00	\$ -	\$ -	-
13	Front windscreen	1	\$ 980.00	\$ 980.00	\$ -	\$ -	-
14	Front windscreen moulding	1	\$ 80.00	\$ 80.00	\$ -	\$ -	-
15	Sealant	1	\$ 30.00	\$ 30.00	\$ -	\$ -	-
16	Inner seal tape	1	\$ 30.00	\$ 30.00	\$ -	\$ -	-
17	IU stickers	1	\$ 5.00	\$ 5.00	\$ -	\$ -	-
18	Engine cover	1	\$ 40.00	\$ 40.00	\$ -	\$ -	-
19	Cooling water pump	1	\$ 280.00	\$ 280.00	\$ -	\$ -	-
20	Water pump for heater	1	\$ 200.00	\$ 200.00	\$ -	\$ -	-
21	Battery acid drip pan	1	\$ 38.00	\$ 38.00	\$ -	\$ -	-
22	Battery 12v	1	\$ 180.00	\$ 180.00	\$ -	\$ -	-
23	Horn	1	\$ 85.00	\$ 85.00	\$ -	\$ -	-
24	Seat belt LH	1	\$ 260.00	\$ 260.00	\$ -	\$ -	-
25	Seat belt RH	1	\$ 260.00	\$ 260.00	\$ -	\$ -	-
26	Inboard Screen cover	1	\$ 30.00	\$ 30.00	\$ -	\$ -	-
27	Steering clock spring	1	\$ 250.00	\$ 250.00	\$ -	\$ -	-
28	Repair battery pack 30kWh	1	\$ 4,000.00	\$ 4,000.00	\$ -	\$ -	-
29	Driver airbag	1	\$ -	\$ -	\$ -	\$ -	Awaiting price
30	Passenger airbag	1	\$ -	\$ -	\$ -	\$ -	Awaiting price

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL \$ 3,802.00 \$ 8,829.00 \$ 60.00 \$ -

Indeco

VEHICLES & EQUIPMENT DIVISION

3

Vehicle No : SLU4858M Case Owner : BLUECAR EAST ASIA PTE LTD /
BLUESG PTE LTD
 Make & Model : BLUECAR Year Manufacture : 2017
 Chassis No : VL4BCEB4RHT003000 Engine No : 921955Q16W391425195
 Date & Time : - Supplier : -
 Order By : - Type of Claim : OD

S/No	Part Description	QTY	Unit Price	Cost Price	Nett Price	S/N	Remarks
61	Airbag ECU <i>act</i>	1	\$ 450.00	\$ 450.00	\$ -	\$ -	-
62	Airbag sensor LH <i>act</i>	1	\$ 80.00	\$ 80.00	\$ -	\$ -	-
63	Airbag sensor RH <i>act</i>	1	\$ 80.00	\$ 80.00	\$ -	\$ -	-
64	0	0	\$ -	\$ -	\$ -	\$ -	-
65	0	0	\$ -	\$ -	\$ -	\$ -	-
66	0	0	\$ -	\$ -	\$ -	\$ -	-
67	0	0	\$ -	\$ -	\$ -	\$ -	-
68	0	0	\$ -	\$ -	\$ -	\$ -	-
69	0	0	\$ -	\$ -	\$ -	\$ -	-
70	0	0	\$ -	\$ -	\$ -	\$ -	-
71	0	0	\$ -	\$ -	\$ -	\$ -	-
72	0	0	\$ -	\$ -	\$ -	\$ -	-
73	0	0	\$ -	\$ -	\$ -	\$ -	-
74	0	0	\$ -	\$ -	\$ -	\$ -	-
75	0	0	\$ -	\$ -	\$ -	\$ -	-
76	0	0	\$ -	\$ -	\$ -	\$ -	-
77	0	0	\$ -	\$ -	\$ -	\$ -	-
78	0	0	\$ -	\$ -	\$ -	\$ -	-
79	0	0	\$ -	\$ -	\$ -	\$ -	-
80	0	0	\$ -	\$ -	\$ -	\$ -	-
81	0	0	\$ -	\$ -	\$ -	\$ -	-
82	0	0	\$ -	\$ -	\$ -	\$ -	-
83	0	0	\$ -	\$ -	\$ -	\$ -	-
84	0	0	\$ -	\$ -	\$ -	\$ -	-
85	0	0	\$ -	\$ -	\$ -	\$ -	-
86	0	0	\$ -	\$ -	\$ -	\$ -	-
87	0	0	\$ -	\$ -	\$ -	\$ -	-
88	0	0	\$ -	\$ -	\$ -	\$ -	-
89	0	0	\$ -	\$ -	\$ -	\$ -	-
90	0	0	\$ -	\$ -	\$ -	\$ -	-

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL \$ 610.00 \$ 610.00 \$ - \$ -



Tel: (65) 382 2736 FAX: (65) 6382 2817

BLUECAR EAST
ASIA PTE LTD /
BLUESG PTE

Case Owner : LTD

Year of Manufacture 2017

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary

Supplementary 1

Vehicle No : SLU4858M Case Owner : 0

Make & Model : BLUE SG Year Manufacture : 2017

Chassis No : VL4BCEB4RHT003000 Engine No : 921955Q16W391425195

Sales Order : 0 Supplier : 0

Order By : _____ Type of Claim : OD

S/No	Part Description	QTY	Unit Price	Cost Price	Nett Item	S/N	Disposition By Surveyor
1	FRONT DASHBOARD	1	\$ 2,800.00	\$ 2,800.00	Torn		
2	FRONT WIRE HARDNESS	1			cut		Awaiting price
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ACCIDENT REPAIR ESTIMATES

Our Ref: OD / SLU4858M

Type of Claim : OD

Vehicle No. : SLU4858M

Make & Model : BLUECAR

Year of Manufacture : 2017

Chassis No. : VL4BCEB4RHT003000

Ins Company : MSIG INSURANCE
(SINGAPORE) PTE LTD

Engine No. : 921955Q16W391425195

Excess : \$0.00

Policy No. :

Date of Accident : 05/01/2018

Time of Accident :

Suggested Days of Repair : 10

Case Owner : BLUECAR EAST-ASIA PTE
LTD / BLUESG PTE LTD**Repair Estimates**

Parts (a) Cost Price Items \$ 15,793.00

Plus/Less 10% \$ 1,679.30

Total of Cost / List \$ 18,472.30

(b) Nett Price Items \$ 60.00

Less 10% \$ 6.00

Total of Nett Item \$ 54.00

(c) Special Nett Items \$ 45.00

Total Parts Cost (Appendix A) \$ 18,571.30

Labour (Appendix B) \$ 4,630.00

Total Repair Cost \$ 23,201.30

Note: A/w parts price for Item No. 29 & 30 (Parts List pg 2)

The above total will be subjected to 7% G.S.T.

a) Cost : \$ 14,738.00
Supplementary : \$ 3,150.00 17,888

+ 10% : \$ 1,788.80

total of cost : \$ 19,676.80

b) Nett Price : \$ 60.00

- 10% \$ 6.00

total of N/P \$ 54.00

c) Special Nett \$ 45.00

total part cost : \$ 19,775.80

Labour : \$ 2,930.00

Total Repair cost : \$ 22,695.80

Tan Fitch

Name of Surveyor : Tan Fitch 97495749

Company : LEE 62563561

Survey conducted on : 25/6/18 at

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 8 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ 2000

(e) Signature of surveyor : *Tan Fitch*

Date: 25/6/18

ESTIMATED REPAIR COST DETAILS

1

Vehicle No : SLU4858M Case Owner : BLUECAR EAST ASIA
PTE LTD / BLUESG PTE LTD

Make & Model : BLUECAR Year Manufacture : 2017

Chassis No : VL4BCEB4RHT003000 Engine No : 921955Q16W391425195

Date & Time : Supplier :

Order By : Type of Claim : OD

S/No	Part Description	QTY	Unit Price	Estimate Price	Nett Price	S/N	Remarks
1	Front bumper	1	\$ 1,300.00	\$ 1,300.00	\$ -	\$ -	-
2	Front bumper top grille	1	\$ 22.00	\$ 22.00	\$ -	\$ -	-
3	Front bumper lower grille	1	\$ 22.00	\$ 22.00	\$ -	\$ -	-
4	Front signal lamp LH	1	\$ 48.00	\$ 48.00	\$ -	\$ -	-
5	Front signal lamp RH	1	\$ 48.00	\$ 48.00	\$ -	\$ -	-
6	Front bumper sponge	1	\$ 45.00	\$ 45.00	\$ -	\$ -	-
7	Front bumper sponge clip	8	\$ 2.00	\$ 16.00	\$ -	\$ -	-
8	Front bumper reinforcement	1	\$ 140.00	\$ 140.00	\$ -	\$ -	-
9	Front bumper reinforcement bracket LH	1	\$ 120.00	\$ 120.00	\$ -	\$ -	-
10	Front bumper reinforcement bracket RH	1	\$ 120.00	\$ 120.00	\$ -	\$ -	-
11	Front number plate with casing	1	\$ -	\$ -	\$ -	\$ 45.00	-
12	Headlamp assy LH	1	\$ 650.00	\$ 650.00	\$ -	\$ -	-
13	Headlamp assy RH	1	\$ 650.00	\$ 650.00	\$ -	\$ -	-
14	Headlamp adjuster LH	1	\$ 85.00	\$ 85.00	\$ -	\$ -	-
15	Headlamp adjuster RH	1	\$ 85.00	\$ 85.00	\$ -	\$ -	-
16	Aircon condenser	1	\$ 600.00	\$ 600.00	\$ -	\$ -	-
17	Aircon discharges hose	1	\$ 125.00	\$ 125.00	\$ -	\$ -	-
18	Aircon suction hose	1	\$ 125.00	\$ 125.00	\$ -	\$ -	-
19	Radiator fan motor with cowl assy	1	\$ 450.00	\$ 450.00	\$ -	\$ -	-
20	Radiator fan switch	1	\$ 45.00	\$ 45.00	\$ -	\$ -	-
21	Radiator assy	1	\$ 450.00	\$ 450.00	\$ -	\$ -	-
22	Radiator lower hose complete set	1	\$ 120.00	\$ 120.00	\$ -	\$ -	-
23	Radiator top hose	1	\$ 45.00	\$ 45.00	\$ -	\$ -	-
24	Front support panel assy	1	\$ 320.00	\$ 320.00	\$ -	\$ -	-
25	Front support air guide set	1	\$ 48.00	\$ 48.00	\$ -	\$ -	-
26	Heater pump	1	\$ 210.00	\$ 210.00	\$ -	\$ -	-
27	Passenger warning horn	1	\$ 280.00	\$ 280.00	\$ -	\$ -	-
28	Bonnet	1	\$ 1,155.00	\$ 1,155.00	\$ -	\$ -	-
29	Bonnet lock	1	\$ 45.00	\$ 45.00	\$ -	\$ -	-
30	Bonnet cable	1	\$ 25.00	\$ 25.00	\$ -	\$ -	-

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL \$ 7,343.00 \$ 7,354.00 \$ - \$ 45.00

\$ 6,591.00 \$ 45.00

Indeco

VEHICLES & EQUIPMENT DIVISION

2

Vehicle No : SLU4858M Case Owner : BLUECAR EAST ASIA
 Make & Model : BLUECAR Year Manufacture : 2017
 Chassis No : VL4BCEB4RHT003000 Engine No : 921955Q16W391425195
 Date & Time : - Supplier : -
 Order By : - Type of Claim : OD

S/No	Part Description	QTY	Unit Price	Post Price	Nett Price	S/N	Remarks
1	Bonnet hinge LH	1	\$ 60.00	\$ 60.00	\$ -	\$ -	-
2	Bonnet hinge RH	1	\$ 60.00	\$ 60.00	\$ -	\$ -	-
3	Bonnet stand	1	\$ 22.00	\$ 22.00	\$ -	\$ -	-
4	Bonnet stickers	1	\$ -	\$ -	\$ 60.00	\$ -	-
5	Bumper top rubber seal	1	\$ 60.00	\$ 60.00	\$ -	\$ -	-
6	Front bumper clip	10	\$ 2.00	\$ 20.00	\$ -	\$ -	-
7	Radiator lower & upper elastic damper	4	\$ 3.00	\$ 12.00	\$ -	\$ -	-
8	Radiator lower crossbeam	1	\$ 150.00	\$ 150.00	\$ -	\$ -	-
9	Front fender RH	1	\$ 800.00	\$ 800.00	\$ -	\$ -	-
10	Front fender LH	1	\$ 800.00	\$ 800.00	\$ -	\$ -	-
11	Front towing cover	1	\$ 12.00	\$ 12.00	\$ -	\$ -	-
12	Windscreen wiper tank with motor	1	\$ 85.00	\$ 85.00	\$ -	\$ -	-
13	Front windscreen	1	\$ 980.00	\$ 980.00	\$ -	\$ -	-
14	Front windscreen moulding	1	\$ 80.00	\$ 80.00	\$ -	\$ -	-
15	Sealant	1	\$ 30.00	\$ 30.00	\$ -	\$ -	-
16	Inner seal tape	1	\$ 30.00	\$ 30.00	\$ -	\$ -	-
17	IU stickers	1	\$ 5.00	\$ 5.00	\$ -	\$ -	-
18	Engine cover	1	\$ 40.00	\$ 40.00	\$ -	\$ -	-
19	Cooling water pump	1	\$ 280.00	\$ 280.00	\$ -	\$ -	-
20	Water pump for heater	1	\$ 200.00	\$ 200.00	\$ -	\$ -	-
21	Battery acid drip pan	1	\$ 38.00	\$ 38.00	\$ -	\$ -	-
22	Battery 12v	1	\$ 180.00	\$ 180.00	\$ -	\$ -	-
23	Horn	1	\$ 85.00	\$ 85.00	\$ -	\$ -	-
24	Seat belt LH	1	\$ 260.00	\$ 260.00	\$ -	\$ -	-
25	Seat belt RH	1	\$ 260.00	\$ 260.00	\$ -	\$ -	-
26	Inboard Screen cover	1	\$ 30.00	\$ 30.00	\$ -	\$ -	-
27	Steering clock spring	1	\$ 250.00	\$ 250.00	\$ -	\$ -	-
28	Repair battery pack 30kWh	1	\$ 4,000.00	\$ 4,000.00	\$ -	\$ -	-
29	Driver airbag	1	\$ 780.00	\$ 780.00	\$ -	\$ -	Awaiting price
30	Passenger airbag	1	\$ 700.00	\$ 700.00	\$ -	\$ -	Awaiting price

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL \$ 8,829.00 \$ 8,829.00 \$ 60.00 \$ -
 \$ 7537.00 \$ 60

Indeco

VEHICLES & EQUIPMENT DIVISION

3

BLUECAR EAST ASIA PTE LTD /

Vehicle No : SLU4858M

Case Owner

: BLUESG PTE LTD

Make & Model : BLUECAR

Year Manufacture : 2017

Chassis No : VL4BCEB4RHT003000

Engine No : 921955Q16W391425195

Date & Time

Supplier

Order By

Type of Claim

: OD

S/No	Part Description	QTY	Unit Price	Cost Price	Nett Price	S/N	Remarks
61	Airbag ECU <i>alt</i>	1	\$ 450.00	\$ 450.00	\$ -	\$ -	-
62	Airbag sensor LH <i>alt</i>	1	\$ 80.00	\$ 80.00	\$ -	\$ -	-
63	Airbag sensor RH <i>alt</i>	1	\$ 80.00	\$ 80.00	\$ -	\$ -	-
64	0	0	\$ -	\$ -	\$ -	\$ -	-
65	0	0	\$ -	\$ -	\$ -	\$ -	-
66	0	0	\$ -	\$ -	\$ -	\$ -	-
67	0	0	\$ -	\$ -	\$ -	\$ -	-
68	0	0	\$ -	\$ -	\$ -	\$ -	-
69	0	0	\$ -	\$ -	\$ -	\$ -	-
70	0	0	\$ -	\$ -	\$ -	\$ -	-
71	0	0	\$ -	\$ -	\$ -	\$ -	-
72	0	0	\$ -	\$ -	\$ -	\$ -	-
73	0	0	\$ -	\$ -	\$ -	\$ -	-
74	0	0	\$ -	\$ -	\$ -	\$ -	-
75	0	0	\$ -	\$ -	\$ -	\$ -	-
76	0	0	\$ -	\$ -	\$ -	\$ -	-
77	0	0	\$ -	\$ -	\$ -	\$ -	-
78	0	0	\$ -	\$ -	\$ -	\$ -	-
79	0	0	\$ -	\$ -	\$ -	\$ -	-
80	0	0	\$ -	\$ -	\$ -	\$ -	-
81	0	0	\$ -	\$ -	\$ -	\$ -	-
82	0	0	\$ -	\$ -	\$ -	\$ -	-
83	0	0	\$ -	\$ -	\$ -	\$ -	-
84	0	0	\$ -	\$ -	\$ -	\$ -	-
85	0	0	\$ -	\$ -	\$ -	\$ -	-
86	0	0	\$ -	\$ -	\$ -	\$ -	-
87	0	0	\$ -	\$ -	\$ -	\$ -	-
88	0	0	\$ -	\$ -	\$ -	\$ -	-
89	0	0	\$ -	\$ -	\$ -	\$ -	-
90	0	0	\$ -	\$ -	\$ -	\$ -	-

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL \$ 610.00 \$ 610.00 \$ - \$ -

\$ 610.00



Tel: (65) 382 2736 FAX: (65) 6382 2817

BLUECAR EAST
ASIA PTE LTD /
BLUESG PTE
LTD

: LTD

2017

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

\$ 2950

Indeco

VEHICLES & EQUIPMENT DIVISION

No : 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

Supplementary 1

Vehicle No : SLU4858M Case Owner : 0

Make & Model : BLUE SG Year Manufacture : 2017

Chassis No : VL4BCEB4RHT003000 Engine No : 921955Q16W391425195

Sales Order : 0 Supplier : 0

Order By : _____ Type of Claim : OD

S/No	Part Description	QTY	Unit Price	Cost Price	Nett Item	S/N	Disposition By Surveyor
1	FRONT DASHBOARD	1	\$ 2,800.00	\$ 2,800.00	Done ✓		
2	FRONT WIRE HARDNESS	1		\$ 350.00	cut ✓		Awaiting price
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

\$ 3,150

Indeco

VEHICLES & EQUIPMENT DIVISION

No : 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817



3.2.12 Air-conditioning

03/02/
2012

Draining / Filling the air-conditioning system

Implementation time

Operator Accreditation

Specific equipment

3.2.12

Charging device

Equipment

An air-conditioning system charging device.

Draining:

Remove the HP/LP protective car pipe plugs.


Connect the device to the HP/LP car pipes.

Drain the air-conditioning system in accordance with the charging device recommendations.

Filling:Draw off the system to empty it in accordance with the charging device recommendations.
Fill the system in accordance with the charging device recommendations.*N.B.: Only fill with R1234yf gas (qty. at 350g)*

Disconnect the device on the HP/LP car pipes.

Fit the HP/LP protective car pipe plugs



Vehicle No : FV03000-SLU4858M

ACCIDENT EV PICTURES (AIRBAG ACTIVATED):




I. Procedure of diagnosis with result or reason of replacement:

Step 1: Emergency activated alarm









Step 2: Connected with Tablet to check ARBRE, Refer below observations



No.	Date	Driver	Actions
1	11/11/2018 11:37:27	1	Diagnose DB failed, check BCU configuration and OTCul ECU DB.
2	11/11/2018 11:38:58	2	Diagnose ECU ECU failed, read and delete the DTCs in the PMSI ECU DB.
3	11/11/2018 11:40:32	3	Diagnose isolation measurement.
4	11/11/2018 11:40:32	4	Charging plug line short circuit on 12V battery, in absence resistance base (2 A/10V) or plug failed HT battery connection ECU (see doc "check charge vehicle").
5	11/11/2018 11:40:32	5	Check external thermal on HT battery + ECU system take picture of battery HT + HT bag.
6	11/11/2018 11:40:32	6	Remove HT battery, Guarantee HT battery connection by replacement truck (See SSOE instructions).
7	11/11/2018 11:40:32	7	Preventive action at the charge +100V, Check the 12V battery in emergency power line.
8	11/11/2018 11:40:32	8	Remove HT battery, ECU system, take picture of battery HT + HT bag, ECU system, Check external short circuit in HT battery (using ECU + PMSI) and prevent external failure remove HT battery.

2. Air bag Fault code:





II. PWT Serial Number:




Sl.no: 9219550/16W39/1425195

III. Miles/Km of vehicle:

Km running: 1488

IV. Screen of PWT versions software (MAIN, AUXILIARY, INVERTER):

Main:



Auxiliary:

[illegible]


Inverter:

Category	Value
Category 1: General Information	100.00
Category 2: Specific Information	100.00
Category 3: Detailed Information	100.00
Category 4: Summary Information	100.00
Category 5: Final Information	100.00

V. DTC's showed in Main:

[illegible]


 République Française
 Ministère de l'Énergie
 Direction Générale de l'Énergie
 Service des Énergies Alternatives
 100013
 100018
 100019
 100020



Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 27 December 2018 11:37 AM
To: 'Lai Bee Yin'
Cc: 'Seah Wan Er'; Taufikh (LKKAUTO); 'Tan Cheng Huat'; SUR
Subject: RE: SLU 4858M-DOA: 5/1/2018 (MSIG OD)

Dear Bee Yin,

You may send your invoice to insurance.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 26 December 2018 3:01 PM
To: Lai Bee Yin <bylai@sg.indeco.cwtlimited.com>
Cc: Seah Wan Er <weseah@sg.indeco.cwtlimited.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; Tan Cheng Huat <tanch@sg.indeco.cwtlimited.com>
Subject: RE: SLU 4858M-DOA: 5/1/2018 (MSIG OD)

Dear Bee Yin,

Kindly hold on first. Will revert shortly.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lai Bee Yin <bylai@sg.indeco.cwtlimited.com>
Sent: Wednesday, 26 December 2018 2:05 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: Seah Wan Er <weseah@sg.indeco.cwtlimited.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>; Tan Cheng Huat <tanch@sg.indeco.cwtlimited.com>
Subject: RE: SLU 4858M-DOA: 5/1/2018 (MSIG OD)

Hi Veron,

Well noted with thanks.

Regards,
Chloe

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Wednesday, 26 December, 2018 2:03 PM
To: Lai Bee Yin <bylai@sg.indeco.cwtlimited.com>
Cc: Seah Wan Er <weseah@sg.indeco.cwtlimited.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>; Tan Cheng Huat <tanch@sg.indeco.cwtlimited.com>
Subject: RE: SLU 4858M-DOA: 5/1/2018 (MSIG OD)

Dear Bee Yin,

Confirmed amount \$22,695.80 before excess \$2000 @ 8 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lai Bee Yin <bylai@sg.indeco.cwtlimited.com>
Sent: Wednesday, 5 December 2018 3:56 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: Seah Wan Er <weseah@sg.indeco.cwtlimited.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>; Tan Cheng Huat <tanch@sg.indeco.cwtlimited.com>
Subject: RE: SLU 4858M-DOA: 5/1/2018 (MSIG OD)

Hi Veron,

Good evening,

Please find attached the Surveyed Repair Estimates for your action.

Please confirm finalised repair costs.

Thank you

Regards,
Chloe
h/p: 8300 9115

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Tuesday, 4 December, 2018 3:46 PM
To: Tan Cheng Huat <tanch@sg.indeco.cwtlimited.com>; Lai Bee Yin <bylai@sg.indeco.cwtlimited.com>
Cc: Seah Wan Er <weseah@sg.indeco.cwtlimited.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR

<sur@lkkauto.com>

Subject: RE: SLU 4858M-DOA: 5/1/2018 (MSIG OD)

Dear Chole,

Please assist to finalise the repair costs

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Thursday, 8 November 2018 12:46 PM

To: 'Tan Cheng Huat' <tanch@sg.indeco.cwtlimited.com>; Lai Bee Yin <bylai@sg.indeco.cwtlimited.com>

Cc: Seah Wan Er <weseah@sg.indeco.cwtlimited.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: SLU 4858M-DOA: 5/1/2018 (MSIG OD)

Dear Chole,

Please assist to finalise the repair costs

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Cheng Huat <tanch@sg.indeco.cwtlimited.com>

Sent: Monday, 22 October 2018 2:35 PM

To: Lai Bee Yin <bylai@sg.indeco.cwtlimited.com>

Cc: Seah Wan Er <weseah@sg.indeco.cwtlimited.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: FW: SLU 4858M-DOA: 5/1/2018 (MSIG OD)

Hi Chloe,

Please finalise the repair costs (parts & labour) with the surveyor asap and prepare the billing invoices.

Warmest Regards,

Tan Cheng Huat

Technical Officer

INDECO ENGINEERS PTE LTD

(A member of the CWT Group)

DID +65 63822736

Fax +65 63822817

www.indeco.cwtlimited.com

CONFIDENTIALITY NOTICE: This communication is meant only for the addressee(s) named above and may contain information, which is confidential and/or legally privileged. If you are not the named addressee(s), or the agent responsible for receiving and delivering this communication to the named addressee(s), this communication has been sent to you in error. If so, kindly contact us immediately for retrieval purposes. Unauthorized dissemination, distribution, copying or reliance on this communication is prohibited and may attract criminal penalties. Thank you.

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Monday, 22 October, 2018 12:38 PM
To: Tan Cheng Huat
Cc: SUR
Subject: RE: SLU 4858M-DOA: 5/1/2018 (MSIG OD)

Dear Cheng Huat,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 27 June 2018 4:44 PM
To: 'tanch@sg.indeco.cwtlimited.com' <tanch@sg.indeco.cwtlimited.com>
Cc: SUR <sur@lkkauto.com>
Subject: SLU 4858M-DOA: 5/1/2018 (MSIG OD)

Dear Cheng Huat,

As instructed by our client , please proceed to repair the insured vehicle **SLU 4858M (Excess S2000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

***Our client reserve their right not to pay if there is no valid approval obtained before repair.**

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From: Lai Bee Yin <bylai@sg.indeco.cwtlimited.com>
Sent: Wednesday, 26 December 2018 2:05 PM
To: Veron Chen (LKKAuto)
Cc: Seah Wan Er; Taufikh (LKKAuto); SUR; Tan Cheng Huat
Subject: RE: SLU 4858M-DOA: 5/1/2018 (MSIG OD)

Hi Veron,

Well noted with thanks.

Regards,
Chloe

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Wednesday, 26 December, 2018 2:03 PM
To: Lai Bee Yin <bylai@sg.indeco.cwtlimited.com>
Cc: Seah Wan Er <weseah@sg.indeco.cwtlimited.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>; Tan Cheng Huat <tanch@sg.indeco.cwtlimited.com>
Subject: RE: SLU 4858M-DOA: 5/1/2018 (MSIG OD)

Dear Bee Yin,

Confirmed amount \$22,695.80 before excess \$2000 @ 8 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lai Bee Yin <bylai@sg.indeco.cwtlimited.com>
Sent: Wednesday, 5 December 2018 3:56 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: Seah Wan Er <weseah@sg.indeco.cwtlimited.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>; Tan Cheng Huat <tanch@sg.indeco.cwtlimited.com>
Subject: RE: SLU 4858M-DOA: 5/1/2018 (MSIG OD)

Hi Veron,

Good evening,

Please find attached the Surveyed Repair Estimates for your action.

Please confirm finalised repair costs.

Thank you

Regards,
Chloe
h/p: 8300 9115

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Tuesday, 4 December, 2018 3:46 PM
To: Tan Cheng Huat <tanch@sg.indeco.cwtlimited.com>; Lai Bee Yin <bylai@sg.indeco.cwtlimited.com>
Cc: Seah Wan Er <weseah@sg.indeco.cwtlimited.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: SLU 4858M-DOA: 5/1/2018 (MSIG OD)

Dear Chole,

Please assist to finalise the repair costs

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Thursday, 8 November 2018 12:46 PM
To: 'Tan Cheng Huat' <tanch@sg.indeco.cwtlimited.com>; Lai Bee Yin <bylai@sg.indeco.cwtlimited.com>
Cc: Seah Wan Er <weseah@sg.indeco.cwtlimited.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: SLU 4858M-DOA: 5/1/2018 (MSIG OD)

Dear Chole,

Please assist to finalise the repair costs

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Cheng Huat <tanch@sg.indeco.cwtlimited.com>
Sent: Monday, 22 October 2018 2:35 PM
To: Lai Bee Yin <bylai@sg.indeco.cwtlimited.com>
Cc: Seah Wan Er <weseah@sg.indeco.cwtlimited.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: FW: SLU 4858M-DOA: 5/1/2018 (MSIG OD)

Hi Chloe,

Please finalise the repair costs (parts & labour) with the surveyor asap and prepare the billing invoices.

Warmest Regards

Tan Cheng Huat
Technical Officer
INDECO ENGINEERS PTE LTD
(A member of the CWT Group)

DID +65 63822736 | Fax +65 63822817 | www.indeco.cwtlimited.com

CONFIDENTIALITY NOTICE: This communication is meant only for the addressee(s) named above and may contain information, which is confidential and/or legally privileged. If you are not the named addressee(s), or the agent responsible for receiving and delivering this communication to the named addressee(s), this communication has been sent to you in error. If so, kindly contact us immediately for retrieval purposes. Unauthorized dissemination, distribution, copying or reliance on this communication is prohibited and may attract criminal penalties. Thank you.

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]

Sent: Monday, 22 October, 2018 12:38 PM

To: Tan Cheng Huat

Cc: SUR

Subject: RE: SLU 4858M-DOA: 5/1/2018 (MSIG OD)

Dear Cheng Huat,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Wednesday, 27 June 2018 4:44 PM

To: 'tanch@sg.indeco.cwtlimited.com' <tanch@sg.indeco.cwtlimited.com>

Cc: SUR <sur@lkkauto.com>

Subject: SLU 4858M-DOA: 5/1/2018 (MSIG OD)

Dear Cheng Huat,

As instructed by our client , please proceed to repair the insured vehicle **SLU 4858M (Excess \$2000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 26 December 2018 2:03 PM
To: 'Lai Bee Yin'
Cc: Seah Wan Er; Taufikh (LKKAuto); SUR; Tan Cheng Huat
Subject: RE: SLU 4858M-DOA: 5/1/2018 (MSIG OD)

Dear Bee Yin,

Confirmed amount \$22,695.80 before excess \$2000 @ 8 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lai Bee Yin <bylai@sg.indeco.cwtlimited.com>
Sent: Wednesday, 5 December 2018 3:56 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: Seah Wan Er <weseah@sg.indeco.cwtlimited.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>; Tan Cheng Huat <tanch@sg.indeco.cwtlimited.com>
Subject: RE: SLU 4858M-DOA: 5/1/2018 (MSIG OD)

Hi Veron,

Good evening,

Please find attached the Surveyed Repair Estimates for your action.

Please confirm finalised repair costs.

Thank you

Regards,
Chloe
h/p: 8300 9115

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Tuesday, 4 December, 2018 3:46 PM
To: Tan Cheng Huat <tanch@sg.indeco.cwtlimited.com>; Lai Bee Yin <bylai@sg.indeco.cwtlimited.com>
Cc: Seah Wan Er <weseah@sg.indeco.cwtlimited.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: SLU 4858M-DOA: 5/1/2018 (MSIG OD)

Dear Chole,

Please assist to finalise the repair costs

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Thursday, 8 November 2018 12:46 PM

To: 'Tan Cheng Huat' <tanch@sg.indeco.cwtlimited.com>; Lai Bee Yin <bylai@sg.indeco.cwtlimited.com>

Cc: Seah Wan Er <weseah@sg.indeco.cwtlimited.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: SLU 4858M-DOA: 5/1/2018 (MSIG OD)

Dear Chole,

Please assist to finalise the repair costs

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Cheng Huat <tanch@sg.indeco.cwtlimited.com>

Sent: Monday, 22 October 2018 2:35 PM

To: Lai Bee Yin <bylai@sg.indeco.cwtlimited.com>

Cc: Seah Wan Er <weseah@sg.indeco.cwtlimited.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: FW: SLU 4858M-DOA: 5/1/2018 (MSIG OD)

Hi Chloe,

Please finalise the repair costs (parts & labour) with the surveyor asap and prepare the billing invoices.

Warmest Regards

Tan Cheng Huat

Technical Officer

INDECO ENGINEERS PTE LTD

(A member of the CWT Group)

DID +65 63822736

Fax +65 63822817

www.indeco.cwtlimited.com

CONFIDENTIALITY NOTICE: This communication is meant only for the addressee(s) named above and may contain information, which is confidential and/or legally privileged. If you are not the named addressee(s), or the agent responsible for receiving and delivering this communication to the

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Monday, 22 October, 2018 12:38 PM
To: Tan Cheng Huat
Cc: SUR
Subject: RE: SLU 4858M-DOA: 5/1/2018 (MSIG OD)

Dear Cheng Huat,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 27 June 2018 4:44 PM
To: 'tanch@sg.indeco.cwtlimited.com' <tanch@sg.indeco.cwtlimited.com>
Cc: SUR <sur@lkkauto.com>
Subject: SLU 4858M-DOA: 5/1/2018 (MSIG OD)

Dear Cheng Huat,

As instructed by our client , please proceed to repair the insured vehicle **SLU 4858M (Excess S2000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Jan 2018		22 Jun 2018 15:52 Edit Adj Rpt	S\$22,695.80 Edit Estimates	S\$22,695.80 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	BLUECAR EAST ASIA PTE LTD, Co. Reg. No.: 201617259H								
Vehicle Reg. No.:	SLU4858M	Date of Loss:	05/01/2018 00:00 - :59 [1 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 546367	Policy/Cover Note No.:	29068237MCY (Comprehensive) Coverage: 01/01/2018 - 31/12/2018						
		Excess:	S\$2,000.00						
Repairer:	Indeco Engineers Pte Ltd (Defu) No. 39 Defu Lane 12, 539315 Defu Lane - Tel: 6382 2738								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Kwok Woon Choo - 6643 1330]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 22/07/2018]								
Driver/Custodian:	LOW WEN HAO DWAYNE (19 / Male), NRIC: S9813309G								
Adj Asg. Remarks:	Car in. Survey & revert. Please contact us ASAP if you cannot attend this assignment. Part price for airbag to be confirmed.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (08/12/2018): Alert - Adj Mandate Approved (S\$22695.80) - SLU4858M - Claim Handler: Kwok Woon ... - MSIG_SG (27/06/2018): Alert - Adj Mandate Approved (S\$10802.80) - SLU4858M - Claim Handler: Kwok Woon ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLU4858M (546367)
OD
Jan 5 2018 12:00AM
[BLUECAR EAST ASIA PTE LTD]
Indeco Engineers Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	26/06/18 17:14	Adjuster Immediate Advice						Load HTM		
2	06/12/18 15:02	Adjuster Immediate Advice						Load HTM		
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	26/06/18 11:19	General View						Load JPG	☒	
2	26/06/18 11:19	General View						Load JPG	☒	
3	26/06/18 11:19	General View						Load JPG	☒	
4	26/06/18 11:19	General View						Load JPG	☒	
5	26/06/18 11:19	General View						Load JPG	☒	
6	26/06/18 11:19	General View						Load JPG	☒	
7	26/06/18 11:19	General View						Load JPG	☒	
8	26/06/18 11:19	General View						Load JPG	☒	
9	26/06/18 11:19	General View						Load JPG	☒	
10	26/06/18 11:19	General View						Load JPG	☒	
11	26/06/18 11:19	General View						Load JPG	☒	
12	26/06/18 11:19	General View						Load JPG	☒	
13	26/06/18 11:19	General View						Load JPG	☒	
14	26/06/18 11:19	General View						Load JPG	☒	
15	26/06/18 11:19	General View						Load JPG	☒	
16	26/06/18 11:19	General View						Load JPG	☒	
17	26/06/18 11:19	General View						Load JPG	☒	
18	26/06/18 11:19	General View						Load JPG	☒	
19	26/06/18 11:19	General View						Load JPG	☒	
20	26/06/18 11:19	General View						Load JPG	☒	
21	26/06/18 11:19	General View						Load JPG	☒	
22	26/06/18 11:19	General View						Load JPG	☒	
23	26/06/18 11:19	General View						Load JPG	☒	
24	26/06/18 11:19	General View						Load JPG	☒	
25	26/06/18 11:19	General View						Load JPG	☒	
26	26/06/18 11:19	General View						Load JPG	☒	
27	26/06/18 11:19	General View						Load JPG	☒	
28	26/06/18 11:19	General View						Load JPG	☒	
29	26/06/18 11:19	General View						Load JPG	☒	
30	26/06/18 11:19	General View						Load JPG	☒	
31	26/06/18 11:19	General View						Load JPG	☒	
32	26/06/18 11:19	General View						Load JPG	☒	
33	26/06/18 11:19	General View						Load JPG	☒	
34	26/06/18 11:19	General View						Load JPG	☒	

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
35	26/06/18 11:19	General View	 Load JPG	☒
36	26/06/18 11:19	General View	 Load JPG	☒
37	26/06/18 11:19	General View	 Load JPG	☒
38	26/06/18 11:19	General View	 Load JPG	☒
39	26/06/18 11:19	General View	 Load JPG	☒
40	26/06/18 11:19	General View	 Load JPG	☒
41	26/06/18 11:19	General View	 Load JPG	☒
42	26/06/18 11:19	General View	 Load JPG	☒
43	26/06/18 11:19	General View	 Load JPG	☒
44	26/06/18 11:19	General View	 Load JPG	☒
45	26/06/18 11:19	General View	 Load JPG	☒
46	26/06/18 11:19	General View	 Load JPG	☒
47	26/06/18 11:19	General View	 Load JPG	☒
48	26/06/18 11:19	General View	 Load JPG	☒
49	26/06/18 11:19	General View	 Load JPG	☒
50	26/06/18 11:19	General View	 Load JPG	☒
51	26/06/18 11:19	General View	 Load JPG	☒
52	26/06/18 11:19	General View	 Load JPG	☒
53	26/06/18 11:19	General View	 Load JPG	☒
54	26/06/18 11:19	General View	 Load JPG	☒
55	26/06/18 11:19	General View	 Load JPG	☒
56	26/06/18 11:19	General View	 Load JPG	☒
57	26/06/18 11:19	General View	 Load JPG	☒
58	26/06/18 11:19	General View	 Load JPG	☒
59	26/06/18 11:19	General View	 Load JPG	☒
60	26/06/18 11:19	General View	 Load JPG	☒
61	26/06/18 11:19	General View	 Load JPG	☒
62	26/06/18 11:19	General View	 Load JPG	☒
63	26/06/18 11:19	General View	 Load JPG	☒
64	26/06/18 11:19	General View	 Load JPG	☒
65	26/06/18 11:19	General View	 Load JPG	☒
66	26/06/18 11:19	General View	 Load JPG	☒
67	26/06/18 11:19	General View	 Load JPG	☒
68	26/06/18 11:19	General View	 Load JPG	☒
69	26/06/18 11:19	General View	 Load JPG	☒
70	26/06/18 11:19	General View	 Load JPG	☒
71	26/06/18 11:19	General View	 Load JPG	☒
72	26/06/18 11:19	General View	 Load JPG	☒
73	26/06/18 11:19	General View	 Load JPG	☒
74	26/06/18 11:19	General View	 Load JPG	☒
75	26/06/18 11:19	General View	 Load JPG	☒
76	26/06/18 11:19	General View	 Load JPG	☒
77	26/06/18 11:19	General View	 Load JPG	☒
78	26/06/18 11:19	General View	 Load JPG	☒
79	26/06/18 11:19	General View	 Load JPG	☒
80	26/06/18 11:19	General View	 Load JPG	☒
81	26/06/18 11:19	General View	 Load JPG	☒
82	26/06/18 11:19	General View	 Load JPG	☒
83	26/06/18 11:19	General View	 Load JPG	☒
84	26/06/18 11:19	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
85	26/06/18 11:19	General View	 Load JPG	☒
86	26/06/18 11:19	General View	 Load JPG	☒
87	26/06/18 11:19	General View	 Load JPG	☒
88	26/06/18 11:19	General View	 Load JPG	☒
89	26/06/18 11:19	General View	 Load JPG	☒
90	26/06/18 11:19	General View	 Load JPG	☒
91	26/06/18 11:19	General View	 Load JPG	☒
92	26/06/18 11:19	General View	 Load JPG	☒
93	26/06/18 11:19	General View	 Load JPG	☒
94	26/06/18 11:19	General View	 Load JPG	☒
95	26/06/18 11:19	General View	 Load JPG	☒
96	26/06/18 11:19	General View	 Load JPG	☒
97	26/06/18 11:19	General View	 Load JPG	☒
98	26/06/18 11:19	General View	 Load JPG	☒
99	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
100	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
101	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
102	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
103	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
104	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
105	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
106	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
107	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
108	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
109	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
110	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
111	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
112	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
113	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
114	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
115	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
116	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
117	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
118	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
119	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
120	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
121	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
122	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
123	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
124	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
125	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
126	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
127	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
128	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
129	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
130	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
131	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
132	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
133	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
134	06/12/18 13:51	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
135	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
136	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
137	06/12/18 13:51	Reinspection Photo	 Load JPG	☒
138	26/12/18 14:56	Reinspection Photo	 Load JPG	☒
139	26/12/18 14:56	Reinspection Photo	 Load JPG	☒
140	26/12/18 14:56	Reinspection Photo	 Load JPG	☒
141	26/12/18 14:56	Reinspection Photo	 Load JPG	☒
142	26/12/18 14:56	Reinspection Photo	 Load JPG	☒
143	26/12/18 14:56	Reinspection Photo	 Load JPG	☒
144	26/12/18 14:56	Reinspection Photo	 Load JPG	☒
145	26/12/18 14:56	Reinspection Photo	 Load JPG	☒
146	26/12/18 14:56	Reinspection Photo	 Load JPG	☒
147	26/12/18 14:56	Reinspection Photo	 Load JPG	☒
148	26/12/18 14:56	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/06/18 10:02	TP GIA REPORT From: TP BI - Reg. No: SHCB402K, Claimant: KOH HSIEN CHIH	 Load PDF	
2	22/06/18 10:02	Insured's Accident reporting & photos From: TP BI - Reg. No: SHCB402K, Claimant: KOH HSIEN CHIH	 Load PDF	
3	22/06/18 09:11	E-MAIL FR WORKSHOP	 Load PDF	
4	22/06/18 09:13	OD ESTIMATE	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/06/18 17:15	MARK ESTIMATE	 Load PDF	
2	06/12/18 15:07	SUPPLEMENTARY	 Load PDF	
3	06/12/18 15:11	MARKING	 Load PDF	
4	03/01/19 09:58	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18011407/T1VD3E2

Date: 03/01/2019

REFERENCE

Insured/Claimant: BLUECAR EAST ASIA PTE LTD

Policy No: 29068237MCY

Date of Loss: 05/01/2018

Nature of Claim: OD

Claim No: 546367

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLU4858M

Make & Model: BLUECAR BLUECAR, (A)

Reg. Date: 04/12/2017 (Man. Year: 2017)

Colour: White

Engine Capacity: 0 cc

Market Value/New Car Price: S\$105,000.00

Sum Insured (S\$): Market Value/New Car Price

Engine No: HIDDEN

Chassis No: VL4BCEB4RHT003000

Odometer: 0 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/65 R15

Rear Tyre Size: 175/65 R15

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,664.30	19,775.80	3,888.50	16.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,630.00	2,920.00	1,710.00	36.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,294.30	22,695.80	5,598.50	19.79
- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
(S\$)	26,294.30	20,695.80	5,598.50	21.29
+ GST 7.00/7.00% (S\$)	1,840.60	1,448.71	391.89	21.29
Nett Amount (S\$)	28,134.90	22,144.51	5,990.39	21.29

INSPECTION

Date of Assignment: 22/06/2018

Date Inspected: 25/06/2018 Inspected At:

Indeco Engineers Pte Ltd (Defu)
No. 39 Defu Lane 12
Singapore 539315

Estimated Period of Repair: 8.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Jan 2019)
Parts: 144	BLUECAR BLUECAR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLU4858M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Cracked	1,300.00 F	*1,300.00 F
2	1		*FRONT BUMPER TOP GRILLE (WCP)	Bent	22.00 F	*22.00 F
3	1		*FRONT BUMPER LOWER GRILLE (WCP)	Not Necessary	22.00 F	*- F
4	1		*FRONT SIGNAL LAMP LH (WCP)	Not Necessary	48.00 F	*- F
5	1		*FRONT SIGNAL LAMP RH (WCP)	Not Necessary	48.00 F	*- F
6	1		*FRONT BUMPER SPONGE (WCP)	Cracked	45.00 F	*45.00 F
7	8		*FRONT BUMPER SPONGE CLIP (WCP)	Necessary	16.00 F	*16.00 F
8	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	140.00 F	*140.00 F
9	1		*FRONT BUMPER REINFORCEMENT BRACKET LH (WCP)	Bent	120.00 F	*120.00 F
10	1		*FRONT BUMPER REINFORCEMENT BRACKET RH (WCP)	Bent	120.00 F	*120.00 F
11	1		*FRONT NUMBER PLATE WITH CASING	Missing	45.00 FS	*45.00 FS
12	1		*HEADLAMP ASSY LH (WCP)	Cracked	650.00 F	*650.00 F
13	1		*HEADLAMP ASSY RH (WCP)	Cracked	650.00 F	*650.00 F
14	1		*HEADLAMP ADJUSTER LH (WCP)	Not Necessary	65.00 F	*- F
15	1		*HEADLAMP ADJUSTER LH (WCP)	Not Necessary	65.00 F	*- F
16	1		*AIRCON CONDENSER (WCP)	Bent	600.00 F	*600.00 F
17	1		*AIRCON SUCTION HOSE (WCP)	Bent	125.00 F	*125.00 F
18	1		*RADIATOR FAN MOTOR WITH COWLING ASSY (WCP)	Cracked	450.00 F	*450.00 F
19	1		*RADIATOR FAN SWITCH (WCP)	Distorted	45.00 F	*45.00 F
20	1		*RADIATOR ASSY (WCP)	Bent	450.00 F	*450.00 F
21	1		*SET RADIATOR LOWER HOSE COMPLETE (WCP)	Distorted	120.00 F	*120.00 F
22	1		*RADIATOR TOP HOSE (WCP)	Distorted	45.00 F	*45.00 F
23	1		*FRONT SUPPORT PANEL ASSY (WCP)	Bent	320.00 F	*320.00 F
24	1		*SET FRONT SUPPORT AIR GUIDE (WCP)	Deformed	48.00 F	*48.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
25	1		*HEATER PUMP (WCP)	Not Necessary	210.00 F	*- F
26	1		*PASSENGER WARNING HORN (WCP)	Not Necessary	280.00 F	*- F
27	1		*BONNET (WCP)	Bent	1,155.00 F	*1,155.00 F
28	1		*BONNET LOCK (WCP)	Bent	45.00 F	*45.00 F
29	1		*BONNET CABLE (WCP)	Not Necessary	25.00 F	*- F
30	1		*BONNET HINGE LH (WCP)	Bent	60.00 F	*60.00 F
31	1		*BONNET HINGE RH (WCP)	Bent	60.00 F	*60.00 F
32	1		*BONNET STAND (WCP)	Repair	22.00 F	*- F
33	1		*BONNET STICKERS	Necessary	54.00 FS	*54.00 FS
34	1		*BUMPER TOP RUBBER SEAL (WCP)	Cut	60.00 F	*60.00 F
35	10		*FRONT BUMPER CLIP (WCP)	Necessary	20.00 F	*20.00 F
36	4		*RADIATOR LOWER & UPPER ELASTIC DAMPER (WCP)	Not Necessary	12.00 F	*- F
37	1		*RADIATOR LOWER CROSSBEAM (WCP)	Not Necessary	150.00 F	*- F
38	1		*FRONT FENDER RH (WCP)	Repair	800.00 F	*- F
39	1		*FRONT FENDER LH (WCP)	Repair	800.00 F	*- F
40	1		*FRONT TOWING COVER (WCP)	Missing	12.00 F	*12.00 F
41	1		*WINDSCREEN WIPER TANK WITH MOTOR (WCP)	Not Necessary	85.00 F	*- F
42	1		*FRONT WINDSCREEN (WCP)	Cracked	980.00 F	*980.00 F
43	1		*FRONT WINDSCREEN MOULDING (WCP)	Necessary	80.00 F	*80.00 F
44	1		*SEALANT (WCP)	Necessary	30.00 F	*30.00 F
45	1		*INNER SEAL TAPE (WCP)	Necessary	30.00 F	*30.00 F
46	1		*IU STICKER (WCP)	Necessary	5.00 F	*5.00 F
47	1		*ENGINE COVER (WCP)	Not Necessary	40.00 F	*- F
48	1		*COOLING WATER PUMP (WCP)	Not Necessary	280.00 F	*- F
49	1		*WATER PUMP FOR HEATER (WCP)	Not Necessary	200.00 F	*- F
50	1		*BATTERY ACID DRIP PAN (WCP)	Not Necessary	38.00 F	*- F
51	1		*BATTERY 12V (WCP)	Deformed	180.00 F	*180.00 F
52	1		*HORN (WCP)	Not Necessary	85.00 F	*- F
53	1		*SEAT BELT LH (WCP)	Not Necessary	260.00 F	*- F
54	1		*SEAT BELT RH (WCP)	Activated	260.00 F	*260.00 F
55	1		*INBOARD SCREEN COVER (WCP)	Deformed	30.00 F	*30.00 F
56	1		*STEERING CLOCK SPRING (WCP)	Activated	250.00 F	*250.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
57	1		*REPAIR BATTERY PACK 30KWH (WCP)	Shorted	4,000.00 F	*4,000.00 F
58	1		*DRIVER AIRBAG (WCP)	Activated	780.00 F	*780.00 F
59	1		*PASSENGER AIRBAG (WCP)	Activated	700.00 F	*700.00 F
60	1		*AIRBAG ECU (WCP)	Activated	450.00 F	*450.00 F
61	1		*AIRBAG SENSOR LH (WCP)	Activated	80.00 F	*80.00 F
62	1		*AIRBAG SENSOR RH (WCP)	Activated	80.00 F	*80.00 F
63	1		*FRONT DASHBOARD (WCP)	Torn	2,800.00 F	*2,800.00 F
64	1		*FRONT WIRE HARDNESS (WCP)	Cut	350.00 F	*350.00 F
65	1		*AIRCON DIACHARGES HOSE (WCP)	Bent	125.00 F	*125.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	21,522.00	17,987.00
+ Margin on L,N Items 10.00/10.00% (S\$)	2,142.30	1,788.80
Total Parts (S\$)	23,664.30	19,775.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT, REPLACE BONNET, BUMPER, REINFORCEMENT, SUPPORT PANEL, RHF FENDER, LHF FENDER AND AFFECTED AREA	New	1,200.00	800.00
2	TO PUTTY AND RESPRAY ON BONNET, BUMPER, REINFORCEMENT, RHF FENDER, LHF FENDER, SUPPORT PANEL AND AFFECTED AREA	New	1,200.00	800.00
3	TO REMOVE AND REPLACE RADIATOR AND CONDENSER	New	150.00	120.00
4	TO VACUUM AND TOP UP AC GAS (R1234)	New	400.00	350.00
5	TO CHECK WIRING, AND RESET ELECTRICAL SYSTEM	New	400.00	200.00
6	TO TOP UP COOLANT	New	50.00	30.00
7	TO REMOVE AND REFIT POWER TRAIN BAY SYSTEM TO ASSIST WORK	New	400.00	0.00
8	TO REMOVE AND REFIX FRT WINDSCREEN	New	150.00	120.00
9	TO REMOVE AND REFIX AIRBAG SYSTEM	New	400.00	300.00
10	TO REMOVE AND REFIX BATTERY PACK 30KWH	New	280.00	200.00
Gross Labour Cost (S\$)			4,630.00	2,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >