

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 27 Jun 2018

Preliminary Advice

Insured Vehicle No	: FM2240X	Accident Date	: 19/06/2018
TP Vehicle No	: SJH7578T	Assignment Date	: 22/06/2018
Make	: PORSCHE BOXSTER	Est. Duration of Repair	: 3.00
Date of Inspection	: 25/06/2018		
Inspection At	: MR TUNING ASIA (HQ) 1010 BUKIT MERAH LANE 3 #01-119 SINGAPORE 159724		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,137.45
Revised Amount	:S\$	2,830.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,830.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.