From (Person) Charg Estimated Cost	Boon Sen	Bill to	Date/Lime: 20/6/18 @ 2.54pm
OD (TP) WS / TP RES To Inspect Vehicle No: at Workshop m/s of 176 8%	, Hui	<i>f</i> ana	Insured: GQ 424 M Tel: 645 1 5 7 52
Policy No. DMCVS Sum Insured:	N301741180	0	The state of the s
Make of Veh. (Client's Record) CA / REV / REP. / Date/Time: 4:01 pm	a 1.11a	ontacted Bell	D.O.A. [8 06] 2018 H.O.D. Endoisement Vehicle IN OUT
SKO	Struction () E 16174A-colm 24M-X	stimate 8516023056/	Gvog2 DUA: 22/11/2016
2/8 /// Red 8	2448.65 541.	enal lou	frank

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Ad) Submitted	Ins Auth'ed	Status
Main	22 Jun 2018		22 Jun 2018 14:54				New Assignment
			Assign				Cancel Case

Ma	iin		Reference		Claim	Details		Documer	nts		Show All
CLAIM SUBI	OLDER DE	TAILS	Park Land Control Control of St. 1815	The same of the sa		Marie Ma	[Created	by insurer]	The American	and the same	AND DESCRIPTION OF THE PARTY.
Insured:	YEW LIAN	ALUMIN	NIUM CONSTRUC	CTION, Co.	Reg. No.: 34:	369100X	Branch Control of Branch Street				
Main Claimant:	SKYWAY N	10TOR P	PTE LTD, Co. Re	g. No.: 1999	04194N						
Vehicle Reg. No,:	SKG617	1A			Date	of Loss:	18/06/2018	8 10:00 - :59			
Claim Type:	TP / SNM	18D030)18C02			y/Cover No.:	DMCVSN30	17411803 (Cor	mprehensi	ve)	
Vehicle Reg. No. (Insured):					y No. imant):	A 2879510	4 MCX				
					Exce		S\$0.00				
Repairer:	Hui Yang	Motor Pt	e Ltd (HQ) 176 S	Sin Ming Drive	#04-02, Sin	Ming Aut	oCare, 5757	'21 Sin Ming - 1	el: 64515	752	
Handling Insurer:	China Taip	oing Insu	urance (Singapo	re) Pte. Ltd.	(HQ) - Tel:	6389 611	1 [Handle	d by Chong B o	oon Sen]		
Claimant's Insurer:	MSIG Inst	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888									
Adjuster:	LKK Auto	Consulta	ants Pte Ltd (HQ) - Tel: 6256-	3561 [Fir	nal Rpt	due 03/07	/2018]			
Driver/Custo dian (Insured):	LEE BOON	YEW (54	/ Male), NRIC:	S1575138Z,	Tel: +65987	775515					
Adj Asg. Remarks:	EST \$4498	.65, ASSI	IGN KENNETH KOI	NG AS SJE.							
ASSOCIATE	D MAIL REG	CEIVED							View All	Compose	e Case Ma
There are no	mail for this	case.									
ALL ASSOC	IATED TAS	KS⊟		11-11-11-11-11			View All	Search Tasks	Create N	New Task	Complet
Due Date	Priority	Type	Task Group	Subject	Handler	Assign	ed By	Completed O	n Cre	eated On	Done

Your NCD will be affected due to late reporting Actual e-Filling Submission Date & Time: 20/06/2018 13:41

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	20/06/2018 12:57
Date Of Accident	18/06/2018 10:20
Exact Location Of Accident	ALONG YISHUN ST 51 ENTRY TO CONDO THE CRITERION.
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SKG6174A
Insured/Policyholder	
Name Of Registered Owner	SKYWAY MOTOR PTE LTD
Co Reg No	199904194N
Email Address	PEILIN@SKYWAY.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-63336333
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	JETTA-1.4 TSI (A)
Exact Purpose for which vehicle was being used at time of accident	A4 32
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A 28795104 MCX
Cover Note Number	
Driver	
Name of Driver	LAM CHEE MENG (LIN ZHIMING)

Name of Driver LAM CHEE MENG (LIN ZHIMING)

 NRIC No
 \$8505548H

 Date Of Birth
 22/02/1985

 Occupation
 OUTDOOR

 Date Of Driving Pass
 24/10/2011

Driving Experience 6 YEARS AND 7 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-98422986

Fax Number Contact Number

EMail Address NOEMAIL

Approximate Age

1

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKG6174A

YES

NO

BLK 429A YISHUN AVENUE 11

#03-350

761429

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

OF ATMIN

Policyholder's Signature Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature
Name: WPROS Joff

Name:

NRIC/FIN No.: 5 78 33800/

Sketch Plan #2 Pg. 1

SKETCH PLAN	The Criterion
	1 1
Web A. SKG 6174A	→ PA
Voh B-6042411	-> Yishum st 51
	←

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Promise and the real of the depth of the control of the real of th
On 18/6/18 at abount 1020Hrs, while entering condo Criterion at
19 Yishin St SI, I am at the quenny at the owner entry lane. Mr
Lee Boar to I was to come in from the Water land and out into my
Lee Boon Yew was turning in from the vistor lane and cut into my lane wasted to cut the quere from entering from the Vistor lane.
The second warred to the transfer from existing them the vision have
Therefor he bong into my Vehical SKG 6174A Right side of my front vehical

DECLARATION

I/We declare the toregoing particulars are true in every respect.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature
Name: 144716445 2541

Sketch Plan #2 Pg. 1

SKETCH PLAN	The Criterion
VAP A- SKG 6174A	
Vah B-60 424 M	-> Yishun st 51
	←
DESCRIBE CIRCUMSTANCE	ES OF THE ACCIDENT

On 18/6/18 at abount 1020Hrs. while entering Condo Criterion at 19 Yishun 51 51. I am out theo query at the owner entry lane. Mr Lop Bean Yew was turning in from the vistor lane and out into my love so and wanted to out the quere from entering from the Vistor lane. Therefore he borng into my Vehical SKG 6174A Right side of my front Vehical	
19 Yishin 51 51, I am put there queny at the owner entry lane. Mr LOP BOOM Yew was turning in from the vistor lane and cut into my lane of ord wanted to cut the quene from entering from the Vistor lane. Therefor he bung into my Vehical SKG 6174A Right side of my front vehical	On 18/6/18 at abount 1020Hrs, while entering condo Criterion at
Lee Been Yew was turning in from the vistor lone and cut into my love because he love to cut the quere from entering from the Vistor lone. Therefore he borng into my Vehical SKG 6174A Right side of my front vehical	19 Yishun ST SI, I am at their numer at the pulses entry lane Ms
Jone of wanted to cut the quere from entering from the Vistor Pane. Therefore he borng into my Vehical SKG 6174A Right Ends of My front vehical	loo Bo You les to a Conthe vite land a site of
Therefor he bang into my Vehical SKG 6174A Right side of my front vehical	because he that the first the Country to the the country the
Therefore he boung into my Vehical SKG 6174A Right side of my front Vehical	Take to aga wanted 75 cut the quere from enterine from the USTOI Take.
	Thesetos he bong into my Vehical SKG 6174A Right side of my front Vehical

DECLARATION

I/We declare the toragoing particulars are true in every respect.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature Name: MARCUS 2001

NRIC/FIN No.: 578 53800/0

辉陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add: SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

18/06/2018

Owner:

SKYWAY MOTOR PTE LTD

Not Mothers CIly 82050f.
Reany Afre Pains
30071


ESTIMATE TO REPAIR VALKSWAGEN JETTA 1.4 TSI - SKG6174A

1pc	front RH headlamp	E \$ 469.95 _
1pc	front RH handlamp lower bracket	\$ 1 37.05 X
1pc	front bumper	Bu \$ 824.83
2pc	front bumper side retainer @\$37.05	0/3 nivs 74.10 -
1pc	front bumper RH fog lamp	cm \$ 163.80 -
1pc	front bumper RH fog lamp cover	\$\$ 62.40 \$
1pc	front bumper lower grille	ns 195.00 X
1pc	front bumper reinforcement	M\$ 462.15 X
1pc	front bumper sponge	CPA\$ 819.00 ? 81.80
1pc	front centre grille	MO.50 2
1pc	front centre grille "VW" logo - come with grille	an \$ 58.50 x
		9 2 574 29

	\$	3,576.28
less 10%	S	357.63
	\$	3,218.65

wiring
spray painting
labour charges
Total

\$ 80.00	201
\$ 600.00	4001
\$ 600.00	3601
\$ 4,498.65	



- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Email: sur@lkkauto.com;assignments@lkkauto.com Tel: 6256-3561 Fax: 6844-8805

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI18011416/KRD3N2

Date:

03/08/2018

REFERENCE

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

DMCVSN3017411803

Claimant

Vehicle No:

SKG6174A

Insured Vehicle No:

Claim:

GQ424M

Date of Loss:

18/06/2018

Nature of

TP

Claim No:

SNM18D03018C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKG6174A

Make & Model:

VOLKSWAGEN JETTA, 1.4 TSI (A)

Engine No:

CAXC00194

Reg. Date:

24/09/2012 (Man. Year: 2012)

Chassis No: Odometer:

WVWZZZ16ZDM005138 147522 km

Colour: Engine Capacity: Metallic Silver

1390 cc

Market Value/New Car

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable): No Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

225/45R17

Rear Tyre Size:

225/45R17

Front Left Side:

Michelin 7 mm

Rear Left Side:

Continental 6 mm

Front Right Side:

Michelin 7 mm

Rear Right Side:

Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,218.65	1,788.33	1,430.32	44.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	780.00	500.00	39.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,498.65	2,568.33	1,930.32	42.91
Approved Total (Overridden) (S\$)		2,050.00		
(S\$)	4,498.65	2,050.00	2,448.65	54.43
+ GST 7.00/7.00% (S\$)	314.91	143.50	171.41	54.43
Nett Amount (S\$)	4,813.56	2,193.50	2,620.06	54.43

INSPECTION

Date of Assignment:

22/06/2018

Date Inspected:

26/06/2018 Inspected At:

Hui Yang Motor Pte Ltd (HQ)

176 Sin Ming Drive #04-02, Sin Ming

AutoCare

Singapore 575721

Estimated Period of Repair:

3.0 days

Adjuster: KENNETH KONG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Referen	ce		
Part Source	: MRM-SG	Version: 1.0 (Last Synchronised: 03 Aug 2018)	
Parts:	143	VOLKSWAGEN JETTA 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted	, no print-code for SKG6174A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info	: Items/values	not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH HEADLAMP	Cut	469.95 FL	*469.95 FL
2	1		*FRONT RH HEADLAMP LOWER BRACKET	Repair	37.05 FL	*-FL
3	1		*FRONT BUMPER	Buckled	824.83 FL	*824.83 FL
4	1		*FRONT BUMPER SIDE RETAINER	O/s Distorted	74.10 FL	*37.05 FL
5	1		*FRONT BUMPER RH FOG LAMP	Cracked	163.80 FL	*163.80 FL
6	1		*FRONT BUMPER RH FOG LAMP COVER	Serviceable	62.40 FL	*- FL
7	1		*FRONT BUMPER LOWER GRILLE	Serviceable	195.00 FL	*-FL
8	1		*FRONT BUMPER REINFORCEMENT	Repair	462.15 FL	*-FL
9	1		*FRONT BUMPER SPONGE	Cracked	819.00 FL	*81.90 FL
10	1		*FRONT CENTRE GRILLE	Mtg Distorted	409.50 FL	*409.50 FL
11	1		*FRONT CENTRE GRILLE VW LOGO-COME WITH GRILLE	Not Necessary	58.50 FL	*- FL
F=Fra	inchise	part. L=Li	stItemDisc	99		
				Sub Total (S\$)	3,576.28	1,987.03
			- List Item Discount on L Items	10.00/10.00% (S\$)	357.63	198.70
				Total Parts (S\$)	3,218.65	1,788.33
11			Report was unsubmitted during this pri	nt-out.		

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	WIRING	New	80.00	20.00
2	SPRAY PAINTING	New	600.00	400.00
3	LABOUR CHARGES	New	600.00	360.00
		Gross Labour Cost (S\$)	1,280.00	780.00
	Repo	rt was unsubmitted during this print-out.		

< END OF ESTIMATES >