



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SKP2122B
Date of Accident : 17 June 2018

*not approved
date
take photo After repair
25/6/18
PII # 960
2dy.*

Mr Chan Yew Kee, David

Date : 19 June 2018

*confirmed with
marcus 25/6/2018*

Estimate To Repair SFM4804G - Toyota COROLLA ALTIS 1.6 AUTO
Chassis No : MR053ZEE106115104

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	n/s rear door protector <i>R</i>	\$ 75.00 <i>x</i>
02	1 pc	n/s rear door protector moulding <i>a1</i>	\$ 27.80 <i>x</i>
		Less 25 %	\$ 102.80
			\$ 25.70
			\$ 77.10
<u>SPECIAL NETT ITEMS</u>			
03	1 pc	n/s rear wheel rim <i>n</i>	\$ 400.00 <i>x</i>
			\$ 400.00
<u>LABOUR & MISC. CHARGES</u>			
01		To check steering geometry and computer wheel alignment.	\$ 120.00 <i>60</i>
02		To transfer of n/s rear wheel tyre, rim and on wheel balancing.	\$ 50.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 450.00 <i>300</i>
04		Putty and spray painting of the affected portion.	\$ 800.00 <i>600</i>
			\$ 1,420.00 <i>960</i>
		Total	\$ 1,897.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Thiru party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: