

7/23/2007

ASS. REC. BY:

REF: es/MSG18011464 / Rlvds²

Special Instruction:

Surveyor
Merimen

ASSIGNMENT (Office)

From (Person): Catherine Thra of MS16 Date/Time: 25/6/18 @ 8:58am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKB 4449Y Insured: SLB 5226E

at Workshop m/s Performance Motor Tel: 6319 0174

of 303 Alexander Road

Policy No: A28886828 MTR Claim No: 561680

Sum Insured: Excess:

Make of Veh: D.O.A. 18/06/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS (up) 29.062018 H.O.D. Endorsement:

Date/Time: 1002am @ 25/6/18 Person Contacted: caroline Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate trans.
	SKB 4449Y - X
	SLB 5226 E - X
27/1/18	Send preli. revised via merimen
6/8/18	Final fig \$10,542.40 (Red 451115, 3070 confirmed by email

(08/11/13) wef
ASS. REC. BY: *Robur*

REF: MSIG

4823C

ASSIGNMENT

From: Date: 29/6/2018

Estimated Cost:

OP / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKB 4449Y

at Workshop m/s

of

Performance
303 Alexandra Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Gary

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS *1 up*

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKB 4449Y Yr Regn: 2011 / MY

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 6403 3.0AT C.C. 2979

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 73181 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBALW720X0C582654

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/35R19

R: . .

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *Pirelli*

Front

Rear

R/Bal. *6* mm R/Bal. *6* mm

L/Bal. *6* mm L/Bal. *6* mm

D.O.A. *18/06/18* D.O.I. *29/06/18*

Survey held at *PERFORMANCE*

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: 6

1)

☐

: Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2) *48 - typist*

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

☐ S + RS, SI

Photos

Others

TOTAL

Report Format : *merimen*

Lump Sum / I.B.I. (\$) *10,542.40*

200
10

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Inc Auth'd	Status
Main	18 Jun 2018		25 Jun 2018 08:58 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	RIVERVIEW AUTO SERVICES PTE LTD, Co. Reg. No.: 200800062E		
Main Claimant:	LAI YUK NYEN, ID: S1764823C		
Vehicle Reg. No.:	SKB4449Y	Date of Loss:	18/06/2018 11:00 - :59 [84 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 561680	Policy/Cover Note No.:	A28886828MTR (Third Party Only) Coverage: 04/02/2018 - 03/02/2019
Vehicle Reg. No. (Insured):	SLB5226E	Policy No. (Claimant):	
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 26/06/2018]		
Driver/Custodian (Insured):	CHAN YEW FOO (), NRIC: S7165348Z, Tel: +6596451308		
Adj Asg. Remarks:	on WP. Liability clear: 100%. tp agree with SJE - assign LKK auto consultants pte ltd.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 02 Jul 2018

Preliminary Advice

Insured Vehicle No	: SLB5226E	Accident Date	: 18/06/2018
TP Vehicle No	: SKB4449Y	Assignment Date	: 25/06/2018
Make	: BMW 640i	Est. Duration of Repair	: 6.00
Date of Inspection	: 29/06/2018		
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,559.70
Revised Amount	:S\$	8,650.45
Check Items (Estimated)	:S\$	3,685.25
Total	:S\$	12,335.70

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

MSIG

Insurance (Singapore) Pte. Ltd.
Way, # 21-01, SGX Centre 2, Singapore 068907
27 7888; Fax +65 6927 7800
200412212G GST Reg. No. 20-0412212G

MOTOR TRADE INSURANCE**RENEWAL CERTIFICATE**

Policy Number	Period of Insurance	Place of Issue
A 28886828 MTR	04/02/2018 to 03/02/2019	SINGAPORE
Name and Address of Insured		Date of Issue
Riverview Auto Services Pte Ltd 10 Ang Mo Kio Industrial Park 2A #04-07/16 AMK Autopoint Singapore 568047		05/02/2018
		Account Number
		1A0102
Premium	GST	Total Due
SGD1,420.00	SGD99.40	SGD1,519.40

RISK NUMBER 1**COMMERCIAL VEHICLE - TP****BUSINESS**

Motor Workshop

SCOPE OF COVER Third Party**INTEREST INSURED**

ITEM 0001
REGISTRATION NO. -
MAKE/MODEL Trade Plate
ENGINE NUMBER -
CHASSIS NUMBER -
YEAR OF MFG -
CAPACITY -
SEATING CAPACITY -

NO CLAIM DISCOUNT NIL
EXCESS SGD1,000
WINDSCREEN NIL
ANNUAL PREMIUM SGD1,420.00

AUTHORISED DRIVERS

Chan Yew Foo

PAID
02 FEB 2018

LIMITATION AS TO USE

BY:.....

Use only for Motor Trade purposes.
The Policy does not cover use for hire or reward racing pace-making
reliability trial or speed-testing.
N.B. Use solely for "Breakdown" purposes is not deemed to be use
for hire or reward.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/06/2018 15:42
Date Of Accident	18/06/2018 11:25
Exact Location Of Accident	MARYMOUNT ROAD BEFORE AMK AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKB4449Y
Insured/Policyholder	
Name Of Registered Owner	LAI YUK NYEN
NRIC No	S1764823C
Email Address	LAIYUKNYEN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96655290
Alternative Phone No	OFFICE-96655290

Vehicle Particulars

Manufacturer	BMW
Model	640
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B27121576SMP
Cover Note Number	

Driver

Name of Driver	LAI YUK NYEN
NRIC No	S1764823C
Date Of Birth	31/10/1966
Occupation	INDOOR
Date Of Driving Pass	08/02/1986
Driving Experience	32 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96655290
Fax Number	
Contact Number	OFFICE-96655290
EMail Address	LAIYUKNYEN@GMAIL.COM

Address	24 MARGOLIOUTH ROAD
Postcode	258550
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	A28886828MTR
Vehicle Make/Model/Colour	RIVERVIEW AUTO SERVICES PTE LTD
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	96690725 - KELVIN
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers or the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my Workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or ascribed to by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively, the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/ law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that exist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulatory, law or court orders;


Policyholder's Signature
Date & Time: 13/6/18
12.50 am

Driver's Signature
(If not, please not the authorised driver)
Date & Time:

Reporting Centre Personnel's Signature
Name:
Date/Time:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 18/6/18 around 11.25am, I was driving along Marymount Road towards the junction of Ang Mo Kio Ave 1. I was driving on the middle lane of the Road (3 lane Road). The front vehicle slowed down as a ~~bus~~ vehicle was filtering to the slow lane. I slowed down too and was hit at the behind by vehicle SLB 5226 E. It was drizzling at the time of the accident. I am claiming against Rivermen Auto Services Pte Ltd at 10 Ang Mo Kio Industrial Park 2A #04-07/16 Ark Autopoint. Under Policy no A 28386328 MTR. (MS16)

DECLARATION

I/We declare the foregoing particulars to be true in every respect

Policyholder's Signature
Date & Time: 18/6/18
12.50 pm

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name
Initials / No.:

GARY P. LITTON
Performance Analyst
333 Ang Mo Kio Road
Room 0407/16 Ark Autopoint
Singapore
18/6/18

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

18 JUN 2018

ESTIMATE

Estimate No. : b1 47340
Date Estimated : 18/06/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Lai Yuk Nyen
24 Margoliouth Road

Singapore 258550

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKB4449Y	C582654	30/05/2011	640iA-C	0

DESCRIPTION

To replace rear bumper and remove and install rear right fender and attachment include knocking cause by the accident

Painting rear bumper, tail panel, right rear fender.

To check electrical wiring systems and lightings at the rear section for proper function.

To replace rear exhaust silencer including alignment system and conduct checks for leak.

Sundries.

VALUE

✓ 2550 3,400.00

✓ 2399 2,666.00

✓ 150 177.00

✓ 451 531.00

rec ✓ ? 150.00

Total Labour 1: 6,924.00

DESCRIPTION

EXHAUST RUBBER RING
EXHAUST TRIM CHROME
Bracket
RR RH SILENCER
RR BUMPER CARRIER
RR BUMPER ADAPTER
GUIDE CENTER REAR
GUIDE BOTTOM CENTER
MOUNT REAR LH
MOUNT REAR RH
RR BUMPER (PDC)
RR BUMPER TOW HOOK COVER (PRIMED)
RR BUMPER RH HEAT INSULATOR
RR BUMPER RH REFLECTOR
REAR LIGHT IN THE SIDE PANEL RH
DECOUPLING RING PDC TORQUE CONVERTE
BUMPER PDC SENSOR (A76 TIEFSEEBLAU)

QTY PRIC

1 19.25
1 130.55
1 41.85
1 1,201.80
1 770.50
1 68.75
1 72.00
1 51.30
1 142.55
1 142.55
1 1,732.90
1 50.65
1 33.55
1 35.20
1 646.90
2 5.05
2 368.80

VALUE

✓ 19.25
✓ 130.55
✓ 41.85
✓ 1,201.80
✓ 770.50
✓ 68.75
✓ 72.00
✓ 51.30
✓ 142.55
✓ 142.55
✓ 1,732.90
✓ 50.65
✓ 33.55
✓ 35.20
✓ 646.90
✓ 20.20
✓ 1,475.20

Total Parts : 6,635.70

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 47340
Date Estimated : 18/06/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKB4449Y	C582654	30/05/2011	640iA-C	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD C / Uninsured Loss / Other

Regn No. _____ Date _____

Date/TIME 29/06/18 @ 1140

Surveyor's Name RASUL

Surveyor's Tel 90010068

Authorized Date _____

RESURVEY FOR 30 DAYS ONLY

Surveyor's E-mail _____

No. of Working Days Recommended 6 days

[Signature]
27/18

15,053.55

Labour 1	:	6,924.00
Parts	:	6,635.70
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	949.18
Grand Total	:	14,508.88

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401509W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 47340
Date Estimated : 18/06/2018
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Lai Yuk Nyen
24 Margoliouth Road

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 258550

REGN NO	CHASSI S NO	REGN DATE	MODEL	M LEAGE
SKB4449Y	C582654	30/05/2011	640iA-C	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments include making good the tail end panel, rear RH fender and knocking out dents caused by the accident	2550.00		2,550.00	
To spray paint rear bumper, tail end panel and rear RH fender	2399.00		2,399.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
To replace rear exhaust silencer include alignment and conducting checks for leak	451.00		451.00	
Sundries	150.00		150.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# RR SILENCER CLAMPING BUSH *	60.60	1.00		60.60
# RR SILENCER CLAMPING BUSH *	60.60	3.00		181.80
EXHAUST TRIM CHROME	130.55	1.00		130.55
# CENTRE MUFFLER *	1,251.45	1.00		1,251.45
RR RH SILENCER	1,201.80	1.00		1,201.80
GUIDE CENTER REAR	72.00	1.00		72.00
MOUNT REAR RH	142.55	1.00		142.55
RR BUMPER (PDC)	1,732.90	1.00		1,732.90
RR BUMPER RH HEAT INSULATOR	33.55	1.00		33.55
RR BUMPER RH REFLECTOR	35.20	1.00		35.20

SUPPLEMENTARY ITEMS

Total Labour :	5,700.00
Total Parts :	4,842.40
Total Labour & Parts :	10,542.40
Deduction for Excess :	
Total Repair Costs less Excess:	10,542.40
GST @7%:	737.97
Grand Total :	11,280.37

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 47340
Date Estimated : 18/06/2018
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Lai Yuk Nyen
24 Margoliouth Road

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 258550

REGN. NO	CHASSIS NO	REGN. DATE	MODEL	MILEAGE
SKB4449Y	C582654	30/05/2011	640iA-C	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# RR SILENCER CLAMPING BUSH *	60.60	1.00		60.60 <i>Net</i>
# RR SILENCER CLAMPING BUSH *	60.60	3.00		181.80 <i>Net</i>
# CENTRE MUFFLER *	1,251.45	1.00		1,251.45 <i>7A</i>

Total Labour :	
Total Parts :	1,493.85
Total Labour & Parts :	1,493.85

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 6 August 2018 9:55 AM
To: 'PBSP'; Rasul (LKKAUTO); SUR
Subject: RE: FINAL REPORT / SKB4449Y

Dear Caroline,

WITHOUT PREJUDICE

Confirmed \$10,542.40 before GST

Repair days: 6 days

Kindly send Final invoice and all supporting documents to MSIG

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Friday, 3 August 2018 4:51 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: FINAL REPORT / SKB4449Y

Dear Rasul

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 5,700.00
Total Parts : 4,842.40
Total Labour & Parts : 10,542.40

Repair days: 6

Thank you.

Regards,
Caroline

C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jun 2018		25 Jun 2018 08:58 Edit Adj Rpt	S\$10,542.40 Edit Estimates	S\$10,542.40 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	RIVERVIEW AUTO SERVICES PTE LTD, Co. Reg. No.: 200800062E		
Main Claimant:	LAI YUK NYEN, ID: S1764823C		
Vehicle Reg. No.:	SKB4449Y	Date of Loss:	18/06/2018 11:00 - :59 [84 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 561680	Policy/Cover Note No.:	A28886828MTR (Third Party Only) Coverage: 04/02/2018 - 03/02/2019
Vehicle Reg. No. (Insured):	SLB5226E	Policy No. (Claimant):	
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 25/07/2018]		
Driver/Custodian (Insured):	CHAN YEW FOO (), NRIC: S7165348Z, Tel: +6596451308		
Adj Asg. Remarks:	on WP, Liability clear: 100%, tp agree with SJE - assign LKK auto consultants pte ltd.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKB4449Y (561680)**
[SLB5226E]
TP
LAI YUK NYEN
Jun 18 2018 11:00AM
[RIVERVIEW AUTO SERVICES PTE LTD]
Performance Motors Limited

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/06/18 09:15	Accident Statement From: SC - Reg. No: TPSLB5226E, Claimant: RIVERVIEW AUTO SERVICES PTE LTD	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/07/18 14:04	Adjuster Immediate Advice	Load HTM	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/07/18 13:55	General View	Load JPG	☒
2	02/07/18 13:55	General View	Load JPG	☒
3	02/07/18 13:55	General View	Load JPG	☒
4	02/07/18 13:55	General View	Load JPG	☒
5	02/07/18 13:55	General View	Load JPG	☒
6	02/07/18 13:55	General View	Load JPG	☒
7	02/07/18 13:55	General View	Load JPG	☒
8	02/07/18 13:55	General View	Load JPG	☒
9	02/07/18 13:55	General View	Load JPG	☒
10	02/07/18 13:55	General View	Load JPG	☒
11	02/07/18 13:55	General View	Load JPG	☒
12	02/07/18 13:55	General View	Load JPG	☒
13	02/07/18 13:55	General View	Load JPG	☒
14	02/07/18 13:55	General View	Load JPG	☒
15	02/07/18 13:55	General View	Load JPG	☒
16	02/07/18 13:55	General View	Load JPG	☒
17	02/07/18 13:55	General View	Load JPG	☒
18	02/07/18 13:55	General View	Load JPG	☒
19	02/07/18 13:55	General View	Load JPG	☒
20	02/07/18 13:55	General View	Load JPG	☒
21	02/07/18 13:55	General View	Load JPG	☒
22	02/07/18 13:55	General View	Load JPG	☒
23	02/07/18 13:55	General View	Load JPG	☒
24	02/07/18 13:55	General View	Load JPG	☒
25	02/07/18 13:55	General View	Load JPG	☒
26	02/07/18 13:55	General View	Load JPG	☒
27	02/07/18 13:55	General View	Load JPG	☒
28	02/07/18 13:55	General View	Load JPG	☒
29	02/07/18 13:55	General View	Load JPG	☒
30	02/07/18 13:55	General View	Load JPG	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
31	02/07/18 13:55	General View	 Load JPG	✓
32	06/08/18 09:44	Reinspection Photo	 Load JPG	✓
33	06/08/18 09:44	Reinspection Photo	 Load JPG	✓
34	06/08/18 09:44	Reinspection Photo	 Load JPG	✓
35	06/08/18 09:44	Reinspection Photo	 Load JPG	✓
36	06/08/18 09:44	Reinspection Photo	 Load JPG	✓
37	06/08/18 09:44	Reinspection Photo	 Load JPG	✓
38	06/08/18 09:44	Reinspection Photo	 Load JPG	✓
39	06/08/18 09:44	Reinspection Photo	 Load JPG	✓
40	06/08/18 09:44	Reinspection Photo	 Load JPG	✓
41	06/08/18 09:44	Reinspection Photo	 Load JPG	✓
42	06/08/18 09:44	Reinspection Photo	 Load JPG	✓
43	06/08/18 09:44	Reinspection Photo	 Load JPG	✓
44	06/08/18 09:44	Reinspection Photo	 Load JPG	✓
45	06/08/18 09:44	Reinspection Photo	 Load JPG	✓
46	06/08/18 09:44	Reinspection Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/08/18 12:10	SUPPLEMENTARY	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18011464/R1VD3S2

Date: 14/08/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28886828MTR

Claimant Vehicle No : SKB4449Y

Insured Vehicle No : SLB5226E

Date of Loss: 18/06/2018

Nature of Claim: TP

Claim No: 561680

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKB4449Y

Make & Model: BMW 640I, 3.0 (A)

Reg. Date: 30/05/2011 (Man. Year: 2011)

Colour: Blue

Engine Capacity: 2979 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 14307752N55B30A

Chassis No: WBALW720X0C582654

Odometer: 73181 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/35R19

Rear Tyre Size: 225/35R19

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,279.55	4,992.40	3,287.15	39.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,774.00	5,550.00	1,224.00	18.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,053.55	10,542.40	4,511.15	29.97
+ GST 7.00/7.00% (S\$)	1,053.75	737.97	315.78	29.97
Nett Amount (S\$)	16,107.30	11,280.37	4,826.93	29.97

INSPECTION

Date of Assignment: 25/06/2018

Date Inspected: 29/06/2018 Inspected At:

Performance Motors Limited (Alexandra)

303 Alexandra Road, Sime Darby Performance Centre
Singapore 159941

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Aug 2018)
Parts:	143	BMW 640I 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB4449Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EXHAUST RUBBER RING	Not Necessary	19.25 FS	*- FS
2	1		*EXHAUST TRIM CHROME	Bent	130.55 FS	*130.55 FS
3	1		*BRACKET	Not Necessary	41.85 FS	*- FS
4	1		*RR RH SILENCER	Bent	1,201.80 FS	*1,201.80 FS
5	1		*RR BUMPER CARRIER	Serviceable	770.50 FS	*- FS
6	1		*RR BUMPER ADAPTER	Serviceable	68.75 FS	*- FS
7	1		*GUIDE CENTER REAR	Cracked	72.00 FS	*72.00 FS
8	1		*GUIDE BOTTOM CENTER	Serviceable	51.30 FS	*- FS
9	1		*MOUNT REAR LH	Serviceable	142.55 FS	*- FS
10	1		*MOUNT REAR RH	Cracked	142.55 FS	*142.55 FS
11	1		*RR BUMPER (PDC)	Deformed	1,732.90 FS	*1,732.90 FS
12	1		*RR BUMPER TOW HOOK COVER (PRIMED)	Serviceable	50.65 FS	*- FS
13	1		*RR BUMPER RH HEAT INSULATOR	Bent	33.55 FS	*33.55 FS
14	1		*RR BUMPER RH REFLECTOR	Broken	35.20 FS	*35.20 FS
15	1		*REAR LIGHT IN THE SIDE PANEL RH	Serviceable	646.90 FS	*- FS
16	4		*DECOUPLING RING PDC TORQUE CONVERTE	Serviceable	20.20 FS	*- FS
17	4		*BUMPER PDC SENSOR (A76 TIEFSEEBLAU)	Serviceable	1,475.20 FS	*- FS
18	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
19	1		*RR SILENCER CLAMPING BUSH	Necessary	60.60 FS	*60.60 FS
20	3		*RR SILENCER CLAMPING BUSH	Necessary	181.80 FS	*181.80 FS
21	1		*CENTRE MUFFLER	Bent	1,251.45 FS	*1,251.45 FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	8,279.55 4,992.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER AND REMOVE AND INSTALL REAR RIGHT FENDER AND ATTACHMENT INCLUDE KNOCKING CAUSE BY THE ACCIDENT.	New	3,400.00	2,550.00
2	PAINTING REAR BUMPER, TAIL PANEL, RIGHT REAR FENDER.	New	2,666.00	2,399.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION.	New	177.00	150.00
4	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK.	New	531.00	451.00
Gross Labour Cost (\$\$)			6,774.00	5,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >