

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 02 Jul 2018

Preliminary Advice

Insured Vehicle No : SLB5226E
 TP Vehicle No : SKB4449Y Accident Date : 18/06/2018
 Make : BMW 640I Assignment Date : 25/06/2018
 Date of Inspection : 29/06/2018 Est. Duration of Repair : 6.00
 Inspection At : PERFORMANCE MOTORS LIMITED (ALEXANDRA)
 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE
 SINGAPORE 159941

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,559.70
Revised Amount	:S\$	8,650.45
Check Items (Estimated)	:S\$	3,685.25
Total	:S\$	12,335.70

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.