



AH CHANG MOTOR SERVICE CENTRE

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047
 Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre
 Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

SJD1878M Honda Jazz

Kenner
 96910663

Not Not hand
 L1 Sing & 2500
 Assembly After Paint

5 days

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy 568.90	Bu \$ 623.70 ✓
2	2	Rear bumper bracket	\$ n 85.40 X
3	2	Rear bumper retainer	old \$ 92.80 ✓
4	1	Rear tailgate assy 762.20	Bu \$ 962.80 ✓
5	2	Rear tailgate rubber stopper	Sn \$ 36.20 X
6	2	Rear tailgate hinges	n \$ 78.90 X
7	1	Rear tailgate weatherstrip	Sn \$ 138.10 508sn
8	1	Rear tailgate lock mechanism	n \$ 105.20 ✓
9	1	Rear tailgate lock catch	n \$ 66.70 X
10	1	Rear tailgate outer garnish	Sn \$ 176.30 X
11	2	Rear tailgate no plate lamp	Sn \$ 120.60 X
12	2	Rear tailgate damper	Sn \$ 268.20 X
13	1	Rear tailgate inner trim board	Sn \$ 276.20 X
14	1	Rear tailgate inner trim board handle	Sn \$ 86.30 X
15	1	Rear tailgate center logo	Sn \$ 68.80 X
16	1	Rear tailgate 'jazz' emblem	n \$ 66.40 ✓
17	1	Rear tailgate third brake lamp	Sn \$ 350.10 X
18	1	Rear left taillamp	Sn \$ 468.30 X
19	1	Rear right taillamp 343.10	ms \$ 468.30 ✓
20	1	Rear wiper arm	Sn \$ 108.60 X
21	1	Rear wiper blade	Sn \$ 112.60 X
22	1	Rear wiper motor	Sn \$ 498.40 X
23	1	Rear wiper spray nozzle	Sn \$ 99.80 X
24	1	Rear right fender	n \$ 1,283.20 X
25	1	Rear right fender inner side garnish	Sn \$ 332.10 X
26	1	Rear end lower panel	n \$ 498.60 X
27	1	Rear end lower panel top garnish	Sn \$ 123.60 X
28	1	Rear spare tyre top cover	Sn \$ 212.20 X
29	1	Rear spare tyre lock holder	n \$ 176.80 X
30	1	Rear right quarter glass	n \$ 989.80 X
31	1	Rear tool tray	Sn \$ 181.30 X
32	1	Rear car jack	n \$ 216.20 X
33	1	Rear exhaust muffler assy	n \$ 982.30 X
34	2	Rear exhaust muffler rubber mounting	Sn \$ 66.40 X
			\$ 10,421.20
Less 20%			\$ 2,084.24
			\$ 8,336.96




AH CHANG MOTOR SERVICE CENTRE

Bldg 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047
 Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre
 Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

SJD1878M Honda Jazz

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	10	Rear bumper clips	<i>nn</i> \$ 50.00 X
2	8	Rear tailgate inner trim board clips	<i>nn</i> \$ 30.00 X
3	4	Rear tailgate outer garnish clips	<i>nn</i> \$ 20.00 X
4	8	Rear right fender inner side garnish clips	<i>nn</i> \$ 30.00 X
5	4	Rear end lower panel top garnish clips	<i>nn</i> \$ 20.00 X
6	1	Rear end lower panel sealant	<i>nn</i> \$ 120.00 X
7	1	Rear right fender sealant	<i>nn</i> \$ 80.00 X
8	1	Rear right quarter glass sealant	<i>nn</i> \$ 60.00 X
9	1	Rear windscreen glass sealant	\$ 80.00 <i>405A</i>
10	2	Rear bumper reverse sensor	<i>shon</i> \$ 250.00 <i>2005A</i>
11	1	Rear no plate with garnish	<i>nn</i> \$ 80.00 X
			<u>\$ 820.00</u>
Total parts			\$ 9,156.96



AH CHANG MOTOR SERVICE CENTRE

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047
Email: acm.chang@outlook.com / FB: www.facebook.com/AcmServiceCentre
Tel / Fax: (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

SJD1878M Honda Jazz

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affeted area and replace rear damaged parts.	\$ 1,400.00 <i>500</i>
2	To putty and spray painting rear portion.	\$ 1,400.00 <i>600</i>
3	To check rear lighting and wiring.	\$ 50.00 <i>20</i>
4	To remove and install rear tailgate lock mechanism.	\$ 80.00 <i>50</i>
5	To remove and install rear exhaust muffler assy.	<i>nn</i> \$ 100.00 <i>X</i>
6	To remove and install rear seat, inner garnish and trim to facilitate the repair.	\$ 180.00 <i>60</i>
7	To apply anti rust proofing to rear affected area.	\$ 120.00 <i>30</i>
8	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00 <i>120</i>
9	To remove and install rear right quarter glass.	<i>nn</i> \$ 80.00 <i>X</i>
10	To remove and install rear fuel tank to facilitate the repair.	<i>nn</i> \$ 180.00 <i>X</i>
11	To remove and install rear bumper reverse sensor.	\$ 80.00 <i>50</i>
12	Towing service.	<i>nn</i> \$ 100.00 <i>X</i>
Total labour :		\$ 3,910.00

Total parts : \$ 9,156.96

Total labour : \$ 3,910.00

Total repair cost : \$ 13,066.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: