

ASS. REC. BY:

REF: CS1AIG18011475 / Kvd3n2 Special Instruction:

Surveyor

Maimun

ASSIGNMENT (Office)

From (Person): Chen Yoke Shi of AIG Date/Time: 25/6/18 @ 10:03am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJD 1878 M Insured: SJR 7514 A

at Workshop in/iz Ah Chang Motor Tel: 6483 5434

of B1k 10, AMK Ind. Park 2A #03-16

Policy No: 2100150557 Claim No: 2840678987 SG

Sum Insured: Excess:

Make of Veh: D.O.A. 20/06/2018
(Client's Record) 26/06/2018 @ after 10am

CA / REV / REP. / REV 24 HRS up)

H.O.D. Endorsement:

Date/Time: 10:10am @ 25/6/18 Person Contacted: Diana Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJD 1878 M - CS1AWA150190711 H/vbd1 DOA: 07/11/2015
	SJR 7514 A - CS1AIG10008545/Gg DOA: 29/01/2010
5/10/18	1/Ly, 8250d confirmed by email (Red 10,566-96, 80b)

REF: AIG

ASSIGNMENT

STD 1878M

03 08

From

Date: 26/06/2018

Veh No.

Yr Regn

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No.

STD 1878M

at Workshop m/s

Ah Chang Motor

of BIK 10, AMK Ind. Park 2A #03-16

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date:

Person Contacted:

Vehicle: IN / OUT

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Jazz

cc

1339

Colour:

White

A/C:

Insured / Std / NI / NA

Sp Reading

150674

T/Radio:

Insured / Std / NI / NA

Eng/No:

JHMGD 18508S 208194

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/55R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

20/6/18

D.O.I.

20/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/6 File pass to Catherine

RECEIVED 8 OCT 2018

Date/Time, File Pass to:



Preli. Report

1)



Final Report

Date/Time, File Return to:

2)

s/10 - typist

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

Transportation

S + RS - SI

Photos

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Weekend (\$

Report Format:

merimen

Lump Sum / I.B.F. (\$

2500/-

250
20

270

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Jun 2018 Edit Reg		27 Jun 2018 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	SUMESH KUMAR ARORA, ID: S7081560E		
Main Claimant:	LOW KIM YEW JEFFREY, ID: S1658121F		
Vehicle Reg. No.:	SJD1878M	Date of Loss:	20/06/2018 08:00 - :59
Claim Type:	TP / 2840678987SG	Policy/Cover Note No.:	2100150557
Vehicle Reg. No. (Insured):	SJR7514A	Policy No. (Claimant):	
		Excess:	
Repairer:	Ah Chang Motor Service Centre (HQ) 10 ANG MO KIO INDUSTRIAL PARK 2A, ANG MO KIO POINT #03-16, 568047 Ang Mo Kio - Tel: 64835434		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 06/07/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (28/06/2018): No OI GIA Report (SJR7514A VS SJD1878M)

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

- Pre repair inspection request - SJD1878M VS SJR7514A (OI) DOA: 20/06/2018

From: Chan, Yoke Shi
To: ASSIGNMENTS@LKKAUTO.COM, admin-a@lkkauto.com
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene; Mithoosingh, Aashweenjeetkaur; A
Sent: 25/6/2018 10:03:21 AM
Attachments: 80563 (Notice of Accident).pdf

Hi,

Please refer to the enclosed request from **Cheonghoh Law Corporation**.

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Thank you.

Regards,

Yoke Shi @ Ashley
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]

Sent: Monday, June 25, 2018 9:57 AM

To: Chan, Yoke Shi

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina

Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJR7514A (AIG) AND SJD1878M ON 20/06/2018 (Our ref: LCH.my/AMK10-80563.18)

URGENT

Dear Sirs

We refer to the above matter and your e-mail of even date below.

We hereby confirm our client nominates **LKK Auto Consultants Pte Ltd** to conduct the pre-repair survey ("PRS") of the damages to our client's vehicle no. SJD 1878 M and appointed as the Single Joint Expert.

Kindly do the needful.

Thank you.

Regards,
Jennifer (for Melody)
Cheonghoh Law Corporation
Blk 53 Chin Swee Road #03-05
Singapore 160053
Tel: 63378700
Fax: 63373700

On 25 Jun 2018, at 09:21, Chan, Yoke Shi <yokeshi.chan@aig.com> wrote:

Dear Jennifer,

Please confirm that you are nominating LKK Auto Consultants Pte Ltd named in the list of surveyors to conduct the pre-repair survey and appointed as the "Single Joint Expert".
Thank you.

Regards,

Yoke Shi @ Ashley
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]

Sent: Saturday, June 23, 2018 10:20 AM

To: Chan, Yoke Shi

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairidina

Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJR7514A (AIG) AND SJD1878M ON 20/06/2018 (Our ref: LCH.my/AMK10-80563.18)

URGENT

Dear Sirs

We refer to the above matter and your e-mail of dated 22 June 2018 below.

Our client hereby nominates **LKK Auto Consultants Pte Ltd** as listed in your aforesaid e-mail for the pre-repair survey ("PRS") of the damages to our client's vehicle no. SJD 1878 M.

Please be informed that our client's vehicle is currently laying at our client's workshop, Ah Chang Motor Service Centre, Blk 10 Ang Mo Kio Industrial Park 2A, Ang Mo Kio Point #03-16 Singapore 568047. Kindly proceed to do the needful and you may contact the person in charge Mr Ng/Diana at 64835434 before your surveyor attend at the said workshop.

Regards,

Jennifer (for Melody)

Cheonghoh Law Corporation

Blk 53 Chin Swee Road #03-05

Singapore 160053

Tel: 63378700

Fax: 63373700

On 22 Jun 2018, at 12:25, Chan, Yoke Shi <yokeshi.chan@aig.com> wrote:

Without Prejudice

Your Reference : LCH.my/AMK10-80563.18

Our Reference : SJR7514A

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/customer's vehicle jointly with your client's/customer's motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (867191-D)

Mensara Worldwide, Level 12, 196 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

From: Cheong Hoh Lee [<mailto:mail@mail@cheonghoh.sg>]

Sent: Friday, June 22, 2018 12:07 PM

To: Supramaniam, Darshene

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi; Chin, Lee-Ying

Subject: Re: Notice of Accident - Traffic accident involving SJD 1878 M and SJR 7514 A (your insured) on 20 June 2018 at/along Bukit Timah towards
Duaran Road after Whitley Flyover; Our ref: [LCH.my/AMK10-80563.18](#)

Dear Sir/ Madam,

Please see attached Notice of Accident for your attention and reply.

Regards,

Melody

Cheonghoh Law Corporation
Blk 53 Chin Swee Road #03-05
Singapore 160053
Tel: 6337 8700
Fax: 6337 3700

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

<80563 (Notice of Accident).pdf>

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 5 October 2018 12:31 PM
To: ACM Chang; SUR
Subject: RE: SJD 1878M - DOA : 20/6/2018 (AIG TP)

Dear Chang,

Noted with thanks.

Kindly send Final invoice and all supporting documents to AIG

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ACM Chang <acm.chang@outlook.com>
Sent: Friday, 5 October 2018 11:06 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: SJD 1878M - DOA : 20/6/2018 (AIG TP)

Dear Veron

We confirm your Offer Lump Sum \$2500 @ 5 working days.

Please proceed.

Thank you

Chang

9111 7978

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Friday, October 5, 2018 10:47 AM
To: acm.chang@outlook.com; SUR
Subject: SJD 1878M-DOA: 20/6/2018 (AIG TP)

Dear Sir/Madam,

WITHOUT PREJUDICE

Offer Lump Sum \$2500 @ 5 working days.

Kindly check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8121F
Vehicle Details	
Vehicle No.:	SJD1878M
Vehicle to be Exported:	No
Intended De-registration Date:	13 Jul 2018
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.4A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	L13A55000204
Chassis No.:	JHMGD18508S208194
Maximum Power Output:	60.0 kW (80 bhp)
Open Market Value:	\$14,465.00
Original Registration Date:	13 Mar 2008
First Registration Date:	13 Mar 2008
Transfer Count:	1
Actual ARF Paid:	\$15,912.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Mar 2028
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$39,274.00
COE Rebate Amount:	\$37,944.00
Total Rebate Amount:	\$37,944.00

The information contained herein is correct as at 13 Jul 2018

OK



AH CHANG MOTOR SERVICE CENTRE

Bldg 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047
 Email: acm.chang@outlook.com / FB: www.facebook.com/AcmServiceCentre
 Tel / Fax: (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

Kenrick
96910663

Not Not hand
11 Sep 8 2500
Assembly After Paint

5 days

SJD1878M Honda Jazz

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy <i>568.90</i>	<i>Br</i> \$ 623.70 ✓
2	2	Rear bumper bracket	\$ 85.40 X
3	2	Rear bumper retainer	<i>old</i> \$ 92.80 ✓
4	1	Rear tailgate assy <i>762.20</i>	<i>R</i> \$ 962.80 ✓
5	2	Rear tailgate rubber stopper	<i>Sn</i> \$ 36.20 X
6	2	Rear tailgate hinges	<i>R</i> \$ 78.90 X
7	1	Rear tailgate weatherstrip	<i>LS</i> \$ 138.10 <i>508sn</i>
8	1	Rear tailgate lock mechanism	<i>nd</i> \$ 105.20 ✓
9	1	Rear tailgate lock catch	<i>R</i> \$ 66.70 X
10	1	Rear tailgate outer garnish	<i>Sn</i> \$ 176.30 X
11	2	Rear tailgate no plate lamp	<i>Sn</i> \$ 120.60 X
12	2	Rear tailgate damper	<i>Sn</i> \$ 268.20 X
13	1	Rear tailgate inner trim board	<i>Sn</i> \$ 276.20 X
14	1	Rear tailgate inner trim board handle	<i>Sn</i> \$ 86.30 X
15	1	Rear tailgate center logo	<i>Sn</i> \$ 68.80 X
16	1	Rear tailgate 'jazz' emblem	<i>Sn</i> \$ 66.40 ✓
17	1	Rear tailgate third brake lamp	<i>Sn</i> \$ 350.10 X
18	1	Rear left taillamp	<i>Sn</i> \$ 468.30 X
19	1	Rear right taillamp <i>393.10</i>	<i>MS</i> \$ 468.30 ✓
20	1	Rear wiper arm	<i>Sn</i> \$ 108.60 X
21	1	Rear wiper blade	<i>Sn</i> \$ 112.60 X
22	1	Rear wiper motor	<i>Sn</i> \$ 498.40 X
23	1	Rear wiper spray nozzle	<i>Sn</i> \$ 99.80 X
24	1	Rear right fender	<i>R</i> \$ 1,283.20 X
25	1	Rear right fender inner side garnish	<i>Sn</i> \$ 332.10 X
26	1	Rear end lower panel	<i>R</i> \$ 498.60 X
27	1	Rear end lower panel top garnish	<i>Sn</i> \$ 123.60 X
28	1	Rear spare tyre top cover	<i>Sn</i> \$ 212.20 X
29	1	Rear spare tyre lock holder	<i>R</i> \$ 176.80 X
30	1	Rear right quarter glass	<i>MS</i> \$ 989.80 X
31	1	Rear tool tray	<i>Sn</i> \$ 181.30 X
32	1	Rear car jack	<i>R</i> \$ 216.20 X
33	1	Rear exhaust muffler assy	<i>R</i> \$ 982.30 X
34	2	Rear exhaust muffler rubber mounting	<i>Sn</i> \$ 66.40 X
			\$ 10,421.20
Less 20%			\$ 2,084.24
			<u>\$ 8,336.96</u>



AH CHANG MOTOR SERVICE CENTRE

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047
 Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre
 Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

SJD1878M Honda Jazz

			Estimated Parts Price	
No	Qty	Parts Description		
<u>Special Nett Items</u>				
1	10	Rear bumper clips	NN \$	50.00 X
2	8	Rear tailgate inner trim board clips	NN \$	30.00 X
3	4	Rear tailgate outer garnish clips	NN \$	20.00 X
4	8	Rear right fender inner side garnish clips	NN \$	30.00 X
5	4	Rear end lower panel top garnish clips	NN \$	20.00 X
6	1	Rear end lower panel sealant	NN \$	120.00 X
7	1	Rear right fender sealant	NN \$	80.00 X
8	1	Rear right quarter glass sealant	NN \$	60.00 X
9	1	Rear windscreen glass sealant	rel \$	80.00 405N
10	2	Rear bumper reverse sensor	shen \$	250.00 2005N
11	1	Rear no plate with garnish	sw \$	80.00 X
			<hr/>	
			\$ 820.00	
Total parts			\$ 9,156.96	



AH CHANG MOTOR SERVICE CENTRE

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047
Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre
Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

SJD1878M Honda Jazz

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,400.00 <i>50d</i>
2	To putty and spray painting rear portion.	\$ 1,400.00 <i>60d</i>
3	To check rear lighting and wiring.	\$ 50.00 <i>20d</i>
4	To remove and install rear tailgate lock mechanism.	\$ 80.00 <i>5d</i>
5	To remove and install rear exhaust muffler assy.	<i>~</i> \$ 100.00 <i>X</i>
6	To remove and install rear seat, inner garnish and trim to facilitate the repair.	\$ 180.00 <i>60d</i>
7	To apply anti rust proofing to rear affected area.	\$ 120.00 <i>30d</i>
8	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00 <i>120d</i>
9	To remove and install rear right quarter glass.	<i>~</i> \$ 80.00 <i>X</i>
10	To remove and install rear fuel tank to facilitate the repair.	<i>~</i> \$ 180.00 <i>X</i>
11	To remove and install rear bumper reverse sensor.	\$ 80.00 <i>5d</i>
12	Towing service.	<i>~</i> \$ 100.00 <i>X</i>
Total labour :		\$ 3,910.00

Total parts : \$ 9,156.96

Total labour : \$ 3,910.00

Total repair cost : \$ 13,066.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18011475/KVD3N2

Date: 10/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100150557
Claimant Vehicle No: SJD1878M Insured Vehicle No: SJR7514A
Date of Loss: 20/06/2018 Nature of Claim: TP Claim No: 2840678987SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJD1878M Engine No: L13A55000204
Make & Model: HONDA JAZZ, 1.4 (A) Chassis No: JHMGD18508S208194
Reg. Date: 13/03/2008 (Man. Year: 2008) Odometer: 150674 km
Colour: White
Engine Capacity: 1339 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55R15 Rear Tyre Size: 185/55R15
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,156.96	1,822.81	7,334.15	80.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,910.00	1,430.00	2,480.00	63.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,066.96	3,252.81	9,814.15	75.11
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	13,066.96	2,500.00	10,566.96	80.87
+ GST 7.00/7.00% (S\$)	914.69	175.00	739.69	80.87
Nett Amount (S\$)	13,981.65	2,675.00	11,306.65	80.87

INSPECTION

Date of Assignment: 25/06/2018
Date Inspected: 26/06/2018 Inspected At: Ah Chang Motor Service Centre (HQ)
10 ANG MO KIO INDUSTRIAL PARK
2A, ANG MO KIO POINT #03-16
Singapore 568047
Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER ASSY	Buckled	623.70 FL	*568.90 FL
2	2	*REAR BUMPER BRACKET	Repair	85.40 FL	*- FL
3	1	*REAR BUMPER RETAINER	O/s Distorted	92.80 FL	*46.40 FL
4	1	*REAR TAILGATE ASSY	Bent	962.80 FL	*762.20 FL
5	2	*REAR TAILGATE RUBBER STOPPER	Serviceable	36.20 FL	*- FL
6	2	*REAR TAILGATE HINGES	Repair	78.90 FL	*- FL
7	1	*REAR TAILGATE LOCK MECHANISM	Dented	105.20 FL	*105.20 FL
8	1	*REAR TAILGATE LOCK CATCH	Repair	66.70 FL	*- FL
9	1	*REAR TAILGATE OUTER GARNISH	Serviceable	176.30 FL	*- FL
10	2	*REAR TAILGATE NO PLATE LAMP	Serviceable	120.60 FL	*- FL
11	2	*REAR TAILGATE DAMPER	Serviceable	268.20 FL	*- FL
12	1	*REAR TAILGATE INNER TRIM BOARD	Serviceable	276.20 FL	*- FL
13	1	*REAR TAILGATE INNER TRIM BOARD HANDLE	Serviceable	86.30 FL	*- FL
14	1	*REAR TAILGATE CENTER LOGO	Serviceable	68.80 FL	*- FL
15	1	*REAR TAILGATE JAZZ EMBLEM	Necessary	66.40 FL	*66.40 FL
16	1	*REAR TAILGATE THIRD BRAKE LAMP	Serviceable	350.10 FL	*- FL
17	1	*REAR LEFT TAILLAMP	Serviceable	468.30 FL	*- FL
18	1	*REAR RIGHT TAILLAMP	Mtg Cracked	468.30 FL	*343.10 FL
19	1	*REAR WIPER ARM	Serviceable	108.60 FL	*- FL
20	1	*REAR WIPER BLADE	Serviceable	112.60 FL	*- FL
21	1	*REAR WIPER MOTOR	Serviceable	498.40 FL	*- FL
22	1	*REAR WIPER SPRAY NOZZLE	Serviceable	99.80 FL	*- FL
23	1	*REAR RIGHT FENDER	Repair	1,283.20 FL	*- FL
24	1	*REAR RIGHT FENDER INNER SIDE GARNISH	Serviceable	332.10 FL	*- FL
25	1	*REAR END LOWER PANEL	Repair	498.60 FL	*- FL
26	1	*REAR END LOWER PANEL TOP GARNISH	Serviceable	123.60 FL	*- FL
27	1	*REAR SPARE TYRE TOP COVER	Serviceable	212.20 FL	*- FL
28	1	*REAR SPARE TYRE LOCK HOLDER	Repair	176.80 FL	*- FL
29	1	*REAR RIGHT QUARTER GLASS	Not Necessary	989.80 FL	*- FL
30	1	*REAR TOOL TRAY	Serviceable	181.30 FL	*- FL
31	1	*REAR CAR JACK	Repair	216.20 FL	*- FL
32	1	*REAR EXHAUST MUFFLER ASSY	Repair	982.30 FL	*- FL
33	2	*REAR EXHAUST MUFFLER RUBBER MOUNTING	Serviceable	66.40 FL	*- FL
34	10	*REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
35	8	*REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	30.00 FS	*- FS
36	4	*REAR TAILGATE OUTER GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
37	8	*REAR RIGHT FENDER INNER SIDE GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
38	4	*REAR END LOWER PANEL TOP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
39	1	*REAR END LOWER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
40	1	*REAR RIGHT FENDER SEALANT	Not Necessary	80.00 FS	*- FS
41	1	*REAR RIGHT QUARTER GLASS SEALANT	Not Necessary	60.00 FS	*- FS
42	1	*REAR WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
43	2	*REAR BUMPER REVERSES ENSOR	Shorted	250.00 FS	*200.00 FS
44	1	*REAR NO PLATE WITH GARNISH	Serviceable	80.00 FS	*- FS
45	1	*REAR TAILGATE WEATHERSTRIP (50%)	Cut	110.48 FS	*69.05 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 11,213.58 2,201.25
 - List Item Discount on L Items 20.00/20.00% (\$\$) 2,056.62 378.44

Total Parts (\$\$) 9,156.96 1,822.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS	New	1,400.00	500.00
2	TO PUTTY AND SPRAY PAINTING REAR PORTION	New	1,400.00	600.00
3	TO CHECK REAR LIGHTING AND WIRING	New	50.00	20.00
4	TO REMOVE AND INSTALL REAR TAILGATE LOCK MECHANISM	New	80.00	50.00
5	TO REMOVE AND INSTALL REAR EXHAUST MUFFLER ASSY	New	100.00	-
6	TO REMOVE AND INSTALL REAR SEAT,INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	180.00	60.00
7	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	New	120.00	30.00
8	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR	New	140.00	120.00
9	TO REMOVE AND INSTALL REAR RIGHT QUARTER GLASS	New	80.00	-
10	TO REMOVE AND INSTALL REAR FUEL TANK TO FACILITATE THE REPAIR	New	180.00	-
11	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	80.00	50.00
12	TOWING SERVICE	New	100.00	-
Gross Labour Cost (\$\$)			3,910.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >