

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 26 Jun 2018

Preliminary Advice

Vehicle No	: GBC4983Y	Accident Date	: 30/05/2018
Make	: SSANGYONG ACTYON SPORTS	Policy No.	: M492427
Assignment Date	: 26/06/2018	Excess	: S\$0.00
Date of Inspection	: 26/06/2018	Est. Duration of Repair	: 4 days
Inspection At	: Sin Ming Autocare BFG Pte Ltd (HQ) 176, Sin Ming Drive #02-05, Sin Ming Autocare Complex Singapore 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,312.00
Revised Amount	:S\$	1,262.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,262.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	40,000.00
COE / PARF Rebate	:S\$	24,469.00
Salvage Value	:S\$	
Margin for Repair	:S\$	15,531.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Pending parts prices (supplementary) .