

Surveyor:

aws

ASSIGNMENT (Office)

From (Person):

Suzene Ler

of

FCI

Date/Time: 25/6/18 @ 2.29pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGR 4219H

Insured:

SHC 8949A

at Workshop m/s:

Fastech Auto

Tel:

67465405

of

Ikaki Bukit Ave 6 # 01-46

Policy No:

Claim No:

D18004985MPSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/06/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

3.55pm @ 26/6/18

Person Contacted:

Nancy

Vehicle (IN/OUT)

Date/Time	Action/Instruction	Estimate
	SGR 4219H - CO/INC 13010541/Rlvk3	DA: 20712
	SHC 8949A - X	
27/6/18	Informed FCI pending workshop est by email	
23/7/18	Email preli revised to FCI	

08/11/13 Wef

ASS. REC. BY: MORIS

REF:

F01

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGR 4219H

at Workshop m/s FF

of \_\_\_\_\_

Insured: SMC 89594

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 24500

ID No Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GLA / PR Seen: 2 Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

3.1.1.2022

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SGR 4219H Yr Regn: 207

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: mazda 35PHB C.C. 1598

Colour: Red/Black A/C: Insured / Std / NI / NA

Sp. Reading: 147571 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JM6BK106270335728

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 215/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or hankook

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 23/6/18

Survey held at \_\_\_\_\_

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 25/6/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27A 18229 3yrs 7mth. net 7k. net 6271 hyper need to spray

21/7/18 L/S & 5800 contact with Alu. (Red 9140.20, 619)

Note: MV: \$24,500 (EST) LTA: \$18,229 NV: \$6271

RECEIVED 23 JUL 2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 23/7 - typist

Report Format: CWS

Lump Sum / I.B.I.: (\$ 5800 1/2)

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

Photos 337

Others 24/18

TOTAL

4x15: 60

170+60

50

50+50

103

483



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18004985MFSH

Our ref: CS/FCI18011486/Uvb

DATE: 23/7/2018

The Motor Claims Department  
M/s FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

**INITIAL INSPECTION REPORT OF VEHICLE NO. SGR 4219H**


We thank for your instruction on 25/6/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 25/6/2018 at the premises of M/s FASTECH AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$14,940.20
Revised Estimate Amount	: S\$5,800.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

**Description of Damage:**

The vehicle sustained damages at the rear portion.



Comments/Present Status:  
Damages Consistent

Yours faithfully,

MARCUS CHUA  
Licensed Appraiser

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	25-06-2018	<b>Our Ref No.</b> D18004985MFSH
<b>Accident Date</b>	23-06-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHC8949A	<b>Third Party Vehicle.</b> SGR4219H
<b>Survey Location</b>	1 KAKI BUKIT AVENUE 6 #01-46/48/50AUTOBAY	
<b>Contact Person.</b>	NANCY LAM	
<b>Contact No.</b>	67465405/ 0	<b>Fax No.</b> 67458520
<b>Survey Type</b>	WITHOUT PREJUDICE: NO EST. PROVIDED	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	FASTECH AUTO PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	SERENE	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

**Veron Chen (LKKAUTO)**

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Monday, 23 July 2018 11:10 AM  
**To:** 'Claim Workflow System'  
**Cc:** 'SERENELER@MSFIRSTCAPITAL.COM.SG'; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18004985MFSH/1, SGR 4219H  
**Attachments:** SGR 4219H HPRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SGR 4219H  
Date of survey: 25/6/2018  
Number of days :6 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Wednesday, 27 June 2018 8:39 AM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>  
**Cc:** SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18004985MFSH/1, SGR 4219H

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SGR 4219H on 25/6/2018 .

We are pending estimate from repairer.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Tuesday, 26 June 2018 3:55 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18004985MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

**Sent:** Tuesday, 26 June 2018 2:29 PM

**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)

**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [SERENELER@MSFIRSTCAPITAL.COM.SG](mailto:SERENELER@MSFIRSTCAPITAL.COM.SG)

**Subject:** PRI: SURVEY ASSESSMENT - D18004985MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

**PS:** This is a system generated mail. Please do not reply to this mail.

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Wednesday, 27 June 2018 8:39 AM  
**To:** 'Claim Workflow System'  
**Cc:** SERENELER@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18004985MFSH/1, SGR 4219H

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SGR 4219H on 25/6/2018 .

We are pending estimate from repairer.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Tuesday, 26 June 2018 3:55 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18004985MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Tuesday, 26 June 2018 2:29 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [SERENELER@MSFIRSTCAPITAL.COM.SG](mailto:SERENELER@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18004985MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



**SELL YOUR CAR BY BIDDING**  
**HIGHEST SELLING PRICE GUARANTEED!**  
**OR GET \$100 CASH!**



Mazda 3 Price Range Depreciation > 10 year Vehicle Type Submit


Advanced Search

Home » Used Cars » Hua Yang Credit Pte Ltd » Mazda 3 1.6A SP Luxury (COE till 02/2022)

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Tyres



Mazda 3 1.6A SP Luxury (COE till 02/2022)

Overview Financial Accessories Similar Research Photos Map

PREMIUM AD



HUA YANG CREDIT PTE LTD



Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$26,800	?
Depreciation	\$7,280 /yr	?
Reg Date	28-Feb-2007 (3yrs 8mths 2days COE left)	?
Manufactured	2007	?
Mileage	-	?
Transmission	Auto	?
Engine Cap	1,598 cc	?
Road Tax	\$816 /yr	?
Power	79.0 kW (105 bhp) View specs of the Mazda 3 Sedan (2004-2009)	?
Curb Weight	1,235 kg	?
Features	Powered By 1.6L 4 Cylinder DOHC 16 Values Engine, 4 Speed Auto Transmission With Tiptronic, Knock Down Rear Seats, Immobilizer Remote Key, Airbags.	?
Accessories	Original Leather Upholstery, Upgraded Sports Rim, Upgraded Mazda Touch Screen System, Reverse Sensors, Solar Film Etc.	?
Description	Hari Raya Special. New Paintwork! Very Well Taken Care Off! Owner's Reluctant Sale! 100% Finance Available, Lowest Interest Rates With Fast Approval! Same Day Delivery! Buy With A Peace Of Mind From An ISO Certified Company With More Than 30 Years Of Experiences! New Road Tax, Inspection Cleared! 2 x Free In House Servicing Provided! Make An Appt With Dominic Now For A No Obligation Discussion!	?
COE	\$25,197	?
OMV	\$15,209	?
ARF	\$11,611	?
Dereg Value	\$18,542 as of today (change)	?
No. of Owners	3	?
Type of Veh	Mid-Sized Sedan	?
Category	COE Car, Premium Ad Car	?
Availability	Available	?



Location Map

Seller Information

Company	Hua Yang Credit Pte Ltd * dealer's pricelist * 166 vehs sold   145 vehs available
Address	61 Ubi Avenue 2 #03-14 Search cars nearby this location
Location	Automobile Megamart
Office No	64545111
Contact Person(s)	Dominic Tan Edison 94230390 82698288

Compare

PREMIUM AD

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 3260D

### Vehicle Details

Vehicle No.: SGR4219H

Vehicle to be Exported: No

Intended De-registration Date: 25 Jun 2018

Vehicle Make: MAZDA

Vehicle Model: MAZDA3 SP HB

Primary Colour: Red

Manufacturing Year: 2006

Engine No.: Z6527590

Chassis No.: JM6BK106270335728

Maximum Power Output: 79.0 kW (105 bhp)

Open Market Value: \$14,999.00

Original Registration Date: 08 Feb 2007

First Registration Date: 08 Feb 2007

Transfer Count: 1

Actual ARF Paid: \$16,499.00

### Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 31 Jan 2022

COE Category: A - Car (1600cc & below)

COE Period(Years): 5

PQP Paid: \$25,323.00

COE Rebate Amount: \$18,229.00

**Total Rebate Amount: \$18,229.00**

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 25 Jun 2018

OK

VEHICLE NO:SGR 4219H

Date:

Not Adult  
N/A  
2/5 45800  
6/7.

QTY	PARTICULAR	AMOUNT
1 PCS	TAILGATE	\$1,408.30
2 PCS	TAILGATE REFLECTORS @\$231.60	\$463.20
1 PCS	TAILGATE INNER LOCK	\$221.80
1 PCS	TAILGATE WEATHERSTRIP	\$97.70
1 PCS	TAILGATE INNER TRIM BOARD	\$295.30
1 SET	TAILGATE INNER TRIM BOARD CLIPS	\$50.00
2 PCS	TAILLAMPS @\$794.9	\$1,589.80
1 PCS	REAR BUMPER SPORT	\$1,500.00
1 PCS	REAR BUMPER REINFORCEMENT	\$374.50
2 PCS	REAR BUMPER SIDE RETAINERS @\$37.60	\$75.20
2 PCS	REAR BUMPER LAMPS @\$115.00	\$230.00
1 PCS	REAR END PANEL	\$357.00
1 PCS	REAR END PANEL TOP GARNISH	\$212.50
1 PCS	REAR FLOOR PANEL	\$1,120.30
1 PCS	REAR FLOOR PANEL TOOLS TRAY	\$341.10
1 PCS	REAR FENDER O/S	\$762.90
1 PCS	REAR FENDER INNER TRIM O/S	\$262.50
1 PCS	REAR WINDSCREEN MOULDING	\$66.80
1 SET	REAR LICENCE PLATE LAMP	\$280.20
1 PCS	REAR EXHAUST	\$971.10
		\$10,680.20
	S.NETT	
1 SET	REAR BUMPER REVERSE SENSOR	\$280.00
1 PCS	REAR BUMPER WIRE MESH	\$100.00
1 PCS	REAR LICENCE PLATE	\$40.00
1 PCS	REAR END PANEL SEALANT	\$50.00
1 PCS	REAR WINDSCREEN SEALANT	\$50.00
1 SET	REAR BUMPER REFLECTOR 'LED'	\$280.00
	LABOUR CHARGES:	
	TO CHECK WIRING	\$80.00
	TO DISMENTLE & REPLACING REVERSE SENSOR	\$80.00
	TO DISMENTLE & REFIX REAR WINDSCREEN	\$150.00

TO DISMENTLE & REFIX PETROL TANK	11	\$100.00	X
TO DISMENTLE & REFIX SEAT,CUSHION UPHOLSTERY		\$150.00	80
TO DISMENTLE & REFIX TAILGATE COMPONENTS		\$100.00	60
TO SPRAY RUST PROOFING		\$100.00	60
LABOUR FOR PANEL BEATING & REPLACING PARTS		\$1,200.00	800
TO PUTTY & SPRAY PAINTING		\$1,500.00	1000

TOTAL	\$14,940.20
-------	-------------

7259.04

5807




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18011486/Uvbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 24-07-2018		
		Code : FCI2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 8949A	Veh. Inspected	SGR 4219H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18004985MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	25/06/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MAZDA 3 SP HB (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	JM6BK106270335728	Colour	RED / BLACK	
Odometer	147571	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	HANKOOK	6 mm	
L/H Front Tyre	215/45 R17	HANKOOK	6 mm	
R/H Rear Tyre	215/45 R17	HANKOOK	6 mm	
L/H Rear Tyre	215/45 R17	HANKOOK	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	23/06/2018	Inspection Date	25/06/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
<b>5a. Remarks</b>				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGR 4219H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	TAILGATE	BADLY DENTED	1,408.30	1,099.60
2	TAILGATE REFLECTORS @\$231.60	NOT NECESSARY	463.20	-
1	TAILGATE INNER LOCK	SHORTED	221.80	221.80
1	TAILGATE WEATHERSTRIP	TWISTED	97.70	97.70
1	TAILGATE INNER TRIM BOARD	DEFORMED / CRACKED	295.30	295.30
1	SET TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	50.00	50.00
2	TAILLAMPS @\$794.90	O/S CRACKED	1,589.80	794.90
1	REAR BUMPER REINFORCEMENT	DISTORTED	374.50	374.50
2	REAR BUMPER SIDE RETAINERS @\$37.60	O/S BENT	75.20	37.60
2	REAR BUMPER LAMPS @\$115.00	NOT NECESSARY	230.00	-
1	REAR END PANEL	BADLY DENTED	357.00	357.00
1	REAR END PANEL TOP GARNISH	TWISTED	212.50	212.50
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,120.30	-
1	REAR FLOOR PANEL TOOLS TRAY	TWISTED	341.10	341.10
1	REAR FENDER O/S	TO REPAIR SEE LABOUR	762.90	-
1	REAR FENDER INNER TRIM O/S	DEFORMED / TORN	262.50	262.50
1	REAR WINDSCREEN MOULDING	NECESSARY	66.80	66.80
1	SET REAR LICENCE PLATE LAMP	NOT NECESSARY	280.20	-
1	REAR EXHAUST	NOT NECESSARY	971.10	-
	LESS 20% DISCOUNT		-	-842.26
			9,180.20	3,369.04
<b>SPECIAL NETT ITEMS</b>				
1	REAR BUMPER SPORT (SN)	DISTORTED	1,500.00	1,100.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR BUMPER WIRE MESH (SN)	BENT	100.00	80.00
1	REAR LICENCE PLATE (SN)	CRACKED	40.00	20.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00

Report Ref No. CS/FCI18011486/Uvbn2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR BUMPER REFLECTOR "LED" (SN)	BROKEN	280.00	200.00
			2,300.00	1,690.00
	<b>LABOUR</b>			
	TO CHECK WIRING.		80.00	30.00
	TO DISMENTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO DISMENTLE & REFIX REAR WINDSCREEN.		150.00	120.00
	TO DISMENTLE & PETROL TANK.	NOT NECESSARY	100.00	-
	TO DISMENTLE & REFIX SEAT,CUSHION UPHOLSTERY.		150.00	80.00
	TO DISMENTLE & REFIX TAILGATE COMPONENTS.		100.00	60.00
	TO SPRAY RUST PROOFING.		100.00	60.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL AND REAR FENDER O/S.		1,200.00	800.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,000.00
			3,460.00	2,200.00
GRAND TOTAL			14,940.20	7,259.04

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,800.00
--	--	--	----------

Report Ref No. CS/FCI18011486/Uvbn2

MARKET VALUE: \$24,500.00 (EST)-LTA REIMBURSEMENT VALUE: \$18,229.00=NETT VALUE: \$6,271.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.