

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 734P**AAD1806-217***Not Authored
11 Sep @ 4750h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF 734P

VF1ABL15AUC281206

RENAULT

LATITUDE

22.6.2018

AXA**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46	—
2	1 BUMPER LOWER REAR	\$	<i>Di Mo</i> 768.84	—
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47	X
4	1 BUMPR BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97	X
5	1 BUMPR RETAINER RH REAR	\$	<i>Sn</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61	X
7	1 BUMPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	X
8	1 BUMPR RETAINER LH REAR	\$	<i>Sn</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$	<i>CM</i> 43.61	✓
10	1 BUMPER BEAM REAR	\$	<i>Bu</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>Bu</i> 225.95	✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	X
13	1 BOOT REAR	\$	<i>R</i> 2,872.68	} X
14	1 BOOT FINISHER	\$	<i>Sn</i> 470.06	
15	1 BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05	
16	1 BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35	
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35	
18	1 BOOT BADGE 'RENAULT'	\$	<i>na</i> 225.36	
19	1 BOOT BADGE	\$	<i>na</i> 225.36	
20	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08	
21	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08	
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1 BOOT INNER TRIM	\$	<i>Sn</i> 586.45	
25	1 BOOT SWITCH	\$	<i>Sn</i> 168.13	
26	1 BOOT LOCK	\$	<i>R</i> 202.67	
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	
28	2 LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52	
29	2 BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81	

Trans-cab Auto Services Pte Ltd**AAD1806-217**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 734P

30	1 DOOR PANEL REAR LH	\$	<i>R</i> 2,844.66	}	<i>X</i>
31	1 FENDER PANEL INNER TRIM REAR LH	\$	<i>Sn</i> 671.45		
32	1 FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13		
33	1 WHEELARCH REAR LH	\$	<i>Sn</i> 543.47		
34	1 FENDER PANEL INNER TRIM REAR RH	\$	<i>Sn</i> 671.45		
35	1 FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13		
36	1 WHEELARCH REAR RH	\$	<i>Sn</i> 543.47		
37	1 TAILLAMP RH	\$	<i>Sn</i> 552.55		
38	1 TAILLAMP PANEL RH	\$	<i>R</i> 986.70		
39	1 TAILLAMP LH	\$	<i>Sn</i> 552.55		
40	1 TAILLAMP PANEL LH	\$	<i>R</i> 986.70		
41	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77 ✓		
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sn</i> 404.56 <i>X</i>		
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>R</i> 2,189.88 <i>X</i>		
44	1 SPARE WHEEL PANEL TRIM	\$	<i>Sn</i> 612.21 <i>X</i>		
45	1 EXHAUST REAR	\$	<i>R</i> 7,489.05 <i>X</i>		
46	1 EXHAUST CAP REAR	\$	<i>R</i> 230.49 <i>X</i>		
47	1 FUEL FLAP L70Y	\$	<i>Sn</i> 343.57 <i>X</i>		
48	1 CHASSIS PANEL REAR LH	\$	<i>R</i> 3,766.43 <i>X</i>		
TOTAL		\$	42,823.60		
10%		\$	4,282.36		
		\$	38,541.24		

Special Nett

1	1SET PARKING AID	\$	<i>Shan</i> 700.00 <i>600.00</i>
2	1SET REAR BUMPER CLIP	\$	<i>na</i> 66.00 —
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00 —
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00 <i>X</i>
5	1SET BUMPR RETAINER RH CLIP RR	\$	<i>na</i> 20.00 <i>X</i>
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00 <i>X</i>
7	1SET BUMPR RETAINER CLIP LH RR	\$	<i>na</i> 20.00 <i>X</i>
8	1SET BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00 <i>X</i>
9	1SET BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00 ✓
10	1 EXHAUST MOUNTING REAR	\$	<i>Sn</i> 17.82 <i>X</i>
11	1SET BOOT FINISHER CLIP	\$	<i>na</i> 24.20 <i>X</i>
12	1 BOOT STICKER "Trans-cab"	\$	<i>na</i> 30.00 <i>X</i>
13	1 BOOT STICKER "6555-3333"	\$	<i>na</i> 30.00 <i>X</i>

Trans-cab Auto Services Pte Ltd

AAD1806-217

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 734P

14	1 BOOT INNER TRIM CLIP	\$	na	45.00	}	X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00		
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00		
17	1 FENDER INNER TRIM CLIP LH	\$	na	28.00		
18	1 FENDER INNER TRIM CLIP LH	\$	na	28.00		
19	1 TAILLAMP CLIP RH	\$	na	5.00		
20	1 TAILLAMP CLIP LH	\$	na	5.00		
21	2 REAR WINDSCREEN SELANT	\$	na	80.00		
22	1 WINDSCREEN MOULDING	\$	na	100.00		
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00		
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sm	385.00	}	
25	1 SPARE TYRE	\$	sm	330.00		

TOTAL \$ 2,225.02**TOTAL PARTS \$ 40,766.26****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	6001
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	na 170.00	X
To repair and realign rear exhaust pipe.	\$	na 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na 170.00	X

Trans-cab Auto Services Pte Ltd

AAD1806-217

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 734P

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	1020 170.00 601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	1020 170.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	↪ 380.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	↪ 380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	↪ 170.00 X
To check steering geometry and computer wheel alignment	\$	↪ 220.00 X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	↪ 380.00 X

TOTAL \$ 12,540.00**Over All Total \$ 53,306.26****(LUMP SUM)****Repair Days**~~20 DAYS~~

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: