

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA7078E

MAKE : HYUNDAI

MODEL : SONATA

Date : .2018 22 June

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	Front Bumper			\$ 538.80
1	Front Bumper Top Bracket - LH ?			\$ 22.40
1	Front Bumper Side Bracket - LH			\$ 14.30
1	Front Bumper Protector - LH <i>x repair</i>			\$ 29.20
10	Front Bumper clips		\$2.20	\$ 22.00
1	Headlamp - LH			\$ 797.90
1	Front Fender - LH			\$ 593.00
1	Front Fender Shield - LH <i>X</i>			\$ 86.00
1	Front Fender Retainer - LH ?			\$ 9.20
1	Headlamp Support Panel ?			\$ 1,023.00
1	Front Wheel Cover - LH			\$ 145.00
1	Front Suspension Lower Arm - LH ?			\$ 685.20
1	Front Wheel Bearing & Hub - LH ?			\$ 258.50
1	Front Absorber - LH ?			\$ 203.70
1	Front Absorber Mounting - LH ?			\$ 72.00
1	Steering Tie Rod End - LH ?			\$ 66.50
1	Front Steel Rim - LH			\$ 284.70

SUB TOTAL

\$ 4,851.40

LESS 20%

970.28

DISCOUNTED TOTAL

\$ 3,881.12

1 Front Tyre - RH *X*

207.00 **Nett**

\$ 207.00

Labour Charge

1 Panel Beating
1 Spray Painting Charge
1 Wiring Charge
1 Tuff Kote
1 Remove/refix Front Undercarriage
1 Front Wheel Alignment
1 Remove/refix AC system and top up AC Gas

Kalir 1004
25/6/8 1305L
3 hrs.
L/S
After Repair

\$ 600.00 *400*

\$ 500.00 *400*

\$ 50.00 *20*

\$ 80.00 *20*

\$ 200.00

\$ 120.00 *60*

\$ 120.00 *X*

TOTAL LABOUR

\$ 1,670.00

ESTIMATE TOTAL

\$ 5,758.12

Larry Ng

Kalir 1004
25/6/8 1305L
3 hrs.
L/S
After Repair

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.