

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 9660T

DATE 21/6/2018 14:42

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille — <i>cr</i>			\$ 1,480.00
	Front Bumper Cover — <i>ent</i>			\$ 1,052.20
	Front Bumper Sponge <i>Xsu</i>			\$ 142.20
	Front Bumper Reinforcement <i>Xsu</i>			\$ 526.10
	Front Bumper Grille (RH) <i>Xsu</i>			\$ 285.50
	Front Bumper Bracket Top (LH/RH) <i>Xsu</i>		\$ 22.40	\$ 44.80
	Front Bumper Bracket (LH/RH) <i>Xsu</i>		\$ 24.60	\$ 49.20
	Headlamp (RH) — <i>cl</i>			\$ 1,388.00
	SUB TOTAL			\$ 4,968.00
	LESS 20%			\$ 993.60
	DISCOUNTED TOTAL			\$ 3,974.40
	Front Number Plate — <i>7/2018</i>			\$ 25.00 Nett
	Front No Plate Trim Cover — <i>2018</i>			\$ 30.00 Nett
				\$ 55.00
	Labour Charge			200
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 250.00
				200
	TOTAL LABOUR			\$ 600.00
	ESTIMATE TOTAL			\$ 4,629.40

*Kahr 11/11/18**22/6/18 1040L**2 Pm**P/P**Before Put p/h*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.