

MOTOR SPORT PTE LTD

Blk 3007 Ubi Road 1 #01-446 Singapore 408701

Tel: 67496717/8

Fax: 67416719

CR No. 199002311D

GST No. M2-0093053-3

Our Ref: 220620188/MS

Date: 22 June 2018

INDIA INT'L INSURANCE

64 Cecil St. #04/#05/#06-02

IOB Building

Singapore 049711

To: Motor Vehicle Claim Dept.

ACCIDENT INVOLVED WITH FBK5432Y AND SHA2344U

We will requested by our client FBK5432Y to claim against vehicle SHA2344U which you are the insurer.

The damages is as below:-

1	HANDLE BAR	best	\$	94.00	PC	—
2	RH BRAKE LEVER	scr/scr	\$	54.00	PC	—
3	RH BAR END	scr	\$	18.00	PC	—
4	RH MIRROR	scr	\$	54.00	PC	—
5	RH FRONT COVER	cut	\$	136.00	PC	—
6	RH SIDE SKIRT	cut	\$	112.00	PC	—
7	RH SIDE SKIRT EMBLEM	scr	\$	6.00	PC	—
8	RH SIDE SKIRT REAR	cut	\$	78.00	PC	—
9	RH LEGSHIELD	cut	\$	96.00	PC	—
10	RH FRONT FOOT REST	cut	\$	47.00	PC	—
11	HEADLAMP COMPLETE	scr	\$	562.00	PC	—
12	STEERING STEM	best	\$	174.00	PC	2 change
13	STEERING CONE SET	scr	\$	154.00	PC	2 change
14	LH FRONT COVER	cut	\$	136.00	PC	—
15	LH FRONT COVER LH SIDE SLIP	cut	\$	38.00	PC	—
16	LH SIDE SKIRT	cut	\$	112.00	PC	—
17	LH SIDE SKIRT EMBLEM	scr	\$	6.00	PC	—
18	LH SIGNAL LAMP FRONT	scr/mis	\$	141.00	PC	—
19	LH SIDE SKIRT REAR	cut	\$	73.00	PC	—
20	LH COMPARTMENT COMPLETE	cut	\$	141.00	PC	—
21	LH FOOT REST	cut	\$	47.00	PC	—
22	LH PILLION FOOTREST	cut	\$	48.00	PC	X cancel
23	FRONT COVER GRILL	cut	\$	67.00	PC	—
24	FRONT COVER GRILL BOTTOM	cut	\$	19.00	PC	—
25	FRONT COVER GRILL CENTRE COVER	cut	\$	23.00	PC	—
26	FRONT FENDER	scr	\$	100.00	PC	—
27	FRONT FENDER LH COVER	scr	\$	36.00	PC	—
28	RH FORK COMPLETE	scr/mis	\$	271.00	PC	2 change
29	LH FORK COMPLETE	scr/mis	\$	271.00	PC	2 change
30	METER COVER	cut	\$	45.00	PC	2 change
31	HEADLAMP BRACKET	best	\$	136.00	PC	2 change

3247

MOTOR SPORT PTE LTD

Blk 3007 Ubi Road 1 #01-446 Singapore 408701

Tel: 67496717/8

Fax: 67416719

CR No. 199002311D

GST No. M2-0093053-3

32 RADIATOR COMPLETE *put*
33 COOLANT *rec*
34 EXHAUST COVER *scr*
35 TOPBOX *cut*
36 SPRAY PAINTING
37 TOWING TO WORKSHOP AND REPORTING CENTER
38 LABOR CHARGE

\$	190.00	PC	✓
\$	18.00	BOT	✓ S.W
\$	102.00	PC	✓
\$	550.00	PC	480 S.W
\$	320.00	SET	300
\$	70.00	2 TRIP	✓
\$	250.00		240
TOTAL		\$	4,795.00

We attach the Singapore Accident Statement and Police Report for your reference.

We would appreciate that you assign a surveyor to our designated address above soonest.

Thank you

Yours faithfully,



Herbert Teh
Manager
Mobile: 96638118

P. 3877
102
P-3879.30
S.N - 498
14687-610
4687.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MOTOR SPORT PTE LTD

Blk 3007 Ubi Road 1 #01-446 Singapore 408701

Tel: 67496717/8

Fax: 67416719

CR No. 199002311D

GST No. M2-0093053-3

Our Ref: 280620188/MS

Date: 28 June 2018

INDIA INT'L INSURANCE

64 Cecil St. #04/#05/#06-02

IOB Building

Singapore 049711

To: Motor Vehicle Claim Dept.

ACCIDENT INVOLVED WITH FBK5432Y AND SHA2344U

ADDITIONAL PARTS CLAIMS

1	FRONT BRAKE DISC	<i>Set</i>	\$	223.00	PC	<i>—</i>
2	FRONT WHEEL SHAFT	<i>Set</i>	\$	34.00	PC	<i>—</i>
3	CLIP MUDGUARD \$3 X 7 PCS	<i>ner</i>	\$	21.00	PC	<i>—</i>
4	RUBBER PACKING PROTECTOR \$3 X 5 PCS	<i>ner</i>	\$	15.00		<i>—</i>
5	CLIP NUT MUDGUARD \$3 X 3 PCS	<i>ner</i>	\$	9.00		<i>—</i>
6	FRONT COVER CENTER LH	<i>one</i>	\$	136.00		<i>—</i>
TOTAL			\$	<u>438.00</u>		

Thank you

Yours faithfully,



Herbert Teh

Manager

Mobile: 96638118