

EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY REG. NO. : 53105453E

Vehicle Number : SJK 632A

Date : 25.06.2018

Vehicle Model : HONDA CIVIC

Chassis : JHMF16306S210332

Accident Date : 22.06.2018

TP Ins. AXA

Original Reg Date : 21.07.2006 (31.05.2021)

ESTIMATE

1	1 pc	Boot Lid Assy	BT		690.50	✓
2	1 pc	Boot Lid Badge	Nuc		52.20	✓
3	1 pc	Boot Lid Emblem 1.8	Nuc		48.00	✓
4	1 pc	Boot Lid Emblem I VTEC	Nuc		48.00	✓
5	1 pc	Boot Lid Emblem CIVIC	Nuc		52.00	✓
6	2 pcs	Boot Lid Number Plate Lamps	HN	52.00	104.00	X
7	2 pcs	Boot Lid Lamps	N/S mounting bracket of S/N	232.00	464.00	✓
8	2 set	Boot Lid Lamp Inner Sealer	SVL	30.00	60.00	X
9	2 set	Boot Lid Lamp Clips	SVL	25.00	50.00	X
10	1 pc	Boot Lid Stopper 'Long'	SVL	22.00	44.00	X
11	1 pc	Boot Lid Inner Lock	BT		194.00	✓
12	1 pc	Boot Lid Lock Catch	Nuc		36.20	X
13	1 pc	Boot Lid Weatherstrip	Nuc		159.50	✓
14	2 pcs	Boot Lid Hinges	HN	56.20	112.40	X
15	1 pc	Rear Bumper Assy	distorted		689.20	✓
16	2 pcs	Rear Bumper Side Retainers	SVL	38.00	76.00	X
17	1 set	Rear Bumper Clips	Nuc		50.00	✓
18	1 pc	Rear Bumper Lower Arch Garnish	crack		58.00	✓
19	2 pcs	Taillamps Assy	crack mounting	339.20	678.40	✓
20	2 pcs	Taillamp Inner Sealer	SVL	30.00	60.00	X
21	2 set	Taillamp Clips	SVL	25.00	50.00	X
22	1 pc	Taillamp Lower Retainer	SVL	42.00	84.00	X
23	1 pc	End Panel Assy	Dented		465.00	✓
24	1 pc	End Panel Top Trim	deformed		119.60	✓
25	1 pc	End Panel Top Trim Cover	SVL		36.00	X
26	1 set	End Panel Top Trim Clips	Nuc		30.00	✓
27	1 pc	Spare Tyre Panel Top Board	HN		321.80	X
28	2 pcs	Rear Fender Inner Trims	SVL o/s N/S deformed	236.00	472.00	✓
29	2 set	Rear Fender Inner Trim Clips	SVL o/s N/S deformed	30.00	60.00	✓

C/F

5,364.80

EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY REG. NO. : 53105453E

Vehicle No : SJK 632A

B/F

5,364.80

1	1 pc	Rear Exhaust Silencer <i>En 15t</i>		593.00	<i>7 L</i>
2	2 pcs	Rear Exhaust Mountings <i>SV2</i>	38.00	76.00	<i>X</i>
3	1 pc	Rear Exhaust Gasket <i>SV2</i>		46.20	<i>X</i>
4	1 pc	Rear Exhaust Heat Plate <i>SV2</i>		92.60	<i>X</i>
				6,172.60	
				Less 20% <i>75</i>	
				1,543.15	
				4,629.45	

Special Nett

1	1 pc	Rear Number Plate with Holder <i>15t</i>		70.00	<i>40/-</i>
2	2 pcs	Rear Exhaust Chrome Pipe <i>2 15t</i>	140.00	<i>200/-</i> 280.00	<i>2 L</i>
3	1 pc	Body Panel Joint Sealant <i>new</i>		120.00	<i>✓</i>
4	1 set	Reverse Sensor <i>Down</i>		250.00	<i>220/-</i>

Labour charge

Panel Beating		1,000.00	<i>800/-</i>
Spray painting		1,000.00	<i>800/-</i>
Check Wiring		50.00	<i>30/-</i>
Anti rust		100.00	<i>40/-</i>
Remove and install carpet and seat.		120.00	<i>80/-</i>
Remove and install rear exhaust silencer.		120.00	<i>60/-</i>
Remove and install rear reverse sensor.		90.00	<i>40/-</i>

\$ 7,829.45

26/06/2018 @ 1030am

NA Antars

2/3mm

5 days

2KK Antars

EM-1 Auto Consultants hence notify the following:

- To return car after **spray painting**
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____