

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909
TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Estimate No: **EST1800188**
Date: 22 Jun 2018
Veh Reg No: **SKL4150E**
Make/Model: TOYOTA VIOS E
GRADE AUTO
Chasis No: MR2BT9F34010472147
Reg. Date: 08/11/2013
Your Ref No: GBD6523Z

Claim Type: Third Party
Accident Date: 21/06/2018
TP Veh Reg No: GBD6523Z

Xiao Tony

Estimate Repair Cost to Vehicle No :SKL4150E

Quantity	Description	List Price	Amount
		SS	SS
List Price			
1	1 PC REAR RIGHT FENDER <i>Distorted</i>	1459.20	863.20 ✓
2	1 PC REAR RIGHT TAIL LAMP <i>mm</i>	1094.40	357.90 ✗
3	1 PC REAR BUMPER <i>distorted</i>		482.10 ✓
4	1 PC REAR BUMPER SIDE RETAINER <i>mm</i>		113.90 ✓
		1,817.10	
	Less 25%	454.28	1,362.84
Special Net			
5	1 SET REAR RIGHT STICKERS <i>mm</i>	445	190.00 ✓
6	1 SET REAR BUMPER STICKER		195.00 ✓
7	1 PC REAR WINDSCREEN SEALANT <i>mm</i>		60.00 <i>30</i>
8	1 PC REAR WINDSCREEN INNER SEAL <i>mm</i>		60.00 <i>30</i>
		505.00	505.00
Labour			
9	1 TO CHECK WIRING	1180	50.00 <i>30</i>
10	1 TO SPRAY PAINTING DAMAGED PORTION, INCLUDING SUPPLY OF PAINT MATERIALS		1,000.00 <i>400</i>
11	1 REMOVE AND REFIT SEAT CUSHION		200.00 <i>60</i>
12	1 REMOVE AND REFIT WINDSCREEN		120.00 <i>100</i>
		1,370.00	1,370.00

Panel Beating

800 600

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 21/06/2018
TP Veh Reg No: GBD6523Z

Estimate No: EST1800188
Date: 22 Jun 2018

Veh Reg No: SKL4150E
Make/Model: TOYOTA VIOS E
GRADE AUTO
Chasis No: MR2BT9F34010472147
Reg. Date: 08/11/2013
Your Ref No: GBD6523Z

Estimate Repair Cost to Vehicle No :SKL4150E

Quantity	Description	List Price S\$	Amount S\$
		Total	S\$ 3,237.84
		Add GST @ 7%	226.65
		Total Amount Payable	S\$ 3,464.49

TOTAL: SINGAPORE DOLLAR THREE THOUSAND FOUR HUNDRED SIXTY FOUR AND CENTS FORTY NINE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

Adrian hy total: 272940
22/06/18 4/5 2150

05 days 2150

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: