

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

25-Jun-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8643 L

1 pc	Front bumper <i>x repair</i>	\$	531.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00 <i>x</i>	\$	32.00
1 pc	Front bumper emblem @ \$44.00 <i>✓</i>	\$	44.00
1 pc	Front n/s wheel cover <i>x</i>	\$	116.00
1 pc	Front n/s fender <i>x repair</i>	\$	384.00
1 pc	Front n/s fender inner shield <i>x</i>	\$	120.00
		\$	1,227.00
Less 10%		\$	122.70
		\$	1,104.30

### S/NETT

1 set	Front bumper clips <i>x</i>	\$	48.00
1 set	Front n/s fender inner shield clips <i>x</i>	\$	28.00

### Sundry

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$ ~~50.00~~ *x*

\$ ~~180.00~~ *x*

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.

\$ ~~500.00~~ *200*

To putty and spray painting on front bumper, front n/s fender

\$ ~~550.00~~ *360*

To apply rustproofing on the repaired and replaced panels.

\$ ~~120.00~~ *x*

\$ 2,580.30

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.

*Kah 16/10/18*  
*25/6/18 1315hr.*  
*2 Apr.*  
*L/S*  
*After Repair*



LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: