



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLL1445M
Make & Model : TOYOTA, HARRIER PREMIUM 2.0
CVT, ZSU600088883
Year of Manufacture : 2016

Estimation No. : E18060048
DOA : 22/06/2018

No	Description	Qty	U/P	Amt
Section: List Items				
1	Front grille assy / <i>le</i>	1.00	598.10	598.10
2	Front grille logo / <i>le</i>	1.00	120.00	120.00
3	Head lamp (LH) <i>X NN</i>	1.00	2,116.70	2,116.70
4	Head lamp (RH) <i>X CFA</i>	1.00	2,116.70	2,116.70
5	Front bumper / <i>le</i>	1.00	1,582.30	1,582.30
6	Front bumper retainer (LH) <i>X</i>	1.00	99.50	99.50
7	Front bumper retainer (RH) <i>X</i>	1.00	99.50	99.50
8	Front bumper bracket (LH) <i>X</i>	1.00	84.80	84.80
9	Front bumper bracket (RH) <i>X</i>	1.00	84.80	84.80
10	Front bumper reinforcement <i>X</i>	1.00	609.70	609.70
11	Front bumper sponge <i>X CFA</i>	1.00	332.70	332.70
12	Front bumper lower grille <i>X CFA</i>	1.00	194.60	194.60
13	Front bumper towing cap <i>X</i>	1.00	79.60	79.60
14	Front bumper fog lamp (LH) <i>X</i>	1.00	392.30	392.30
15	Front bumper fog lamp (RH) <i>X</i>	1.00	392.30	392.30
16	Front bumper fog lamp garnish (LH) <i>X</i>	1.00	140.00	140.00
17	Front bumper fog lamp garnish (RH) <i>X</i>	1.00	140.00	140.00
18	Front bumper fog lamp chrome piece (LH) <i>X</i>	1.00	0.00	0.00
19	Front bumper fog lamp chrome piece (RH) <i>X</i>	1.00	0.00	0.00
20	Front bumper lower garnish <i>X</i>	1.00	1,891.20	1,891.20
21	Front bumper undercover <i>X</i>	1.00	301.70	301.70
22	Support panel <i>X</i>	1.00	2,136.70	2,136.70
23	Support panel top garnish <i>X le</i>	1.00	546.00	546.00
24	Support panel side panel (LH) <i>X</i>	1.00	260.30	260.30

Continue on next page...

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLL1445M
Make & Model : TOYOTA, HARRIER PREMIUM 2.0
CVT, ZSU600088883
Year of Manufacture : 2016

Estimation No. : E18060048
DOA : 22/06/2018

No	Description	Qty	U/P	Amt
25	Support panel side panel (RH) X	1.00	260.30	260.30
26	Condenser X	1.00	1,895.40	1,895.40
27	Radiator X	1.00	1,860.30	1,860.30
28	Radiator side bracket (LH) X	1.00	180.00	180.00
29	Radiator side bracket (RH) X	1.00	180.00	180.00
30	Tailgate - Blue	1.00	3,659.50	3,659.50
31	Tailgate absorber (LH) X	1.00	312.70	312.70
32	Tailgate absorber (RH) X	1.00	312.70	312.70
33	Tailgate logo / MC	1.00	84.50	84.50
34	Tailgate emblem - Harrier - MC	1.00	81.00	81.00
35	Tailgate top panel X	1.00	0.00	0.00
36	Tailgate outer handle X	1.00	261.20	261.20
37	Tailgate lock X	1.00	981.00	981.00
38	Tailgate weather strip - Twi	1.00	499.20	499.20
39	Tailgate lamp (LH) X	1.00	483.40	483.40
40	Tailgate lamp (RH) X	1.00	483.40	483.40
41	Tailgate inner trim (LH) X	1.00	610.35	610.35
42	Tailgate inner trim (RH) X	1.00	610.35	610.35
43	Rear bumper - Re	1.00	1,895.30	1,895.30
44	Rear bumper retainer (LH) = } Re	1.00	133.60	133.60
45	Rear bumper retainer (RH) = } Re	1.00	133.60	133.60
46	Rear bumper bracket (LH) X	1.00	123.70	123.70
47	Rear bumper bracket (RH) X	1.00	123.70	123.70
48	Rear bumper reinforcement X	1.00	825.20	825.20
49	Rear bumper sponge 2 - CMA	1.00	141.20	141.20

Continue on next page...

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLL1445M
Make & Model : TOYOTA, HARRIER PREMIUM 2.0
CVT, ZSU600088883
Year of Manufacture : 2016

Estimation No. : E18060048
DOA : 22/06/2018

No	Description	Qty	U/P	Amt
50	Rear bumper reflector (LH) X - CMA	1.00	131.70	131.70
51	Rear bumper reflector (RH) - CMA	1.00	131.70	131.70
52	Rear bumper lower garnish - RE	1.00	682.70	682.70
53	Tail lamp (LH) X NN	1.00	691.20	691.20
54	Tail lamp (RH) X - CMA	1.00	691.20	691.20
55	Rear fender (LH) - repair X	1.00	1,311.20	1,311.20
56	Rear fender (RH) - repair X	1.00	1,311.20	1,311.20
57	Rear fender inner trim (LH) X	1.00	961.10	961.10
58	Rear fender inner trim (RH) X - RE	1.00	961.10	961.10
59	Rear end panel X - BUC	1.00	966.70	966.70
60	Rear end panel top garnish X - RE	1.00	423.10	423.10
61	Exhaust pipe X repair	1.00	1,317.60	1,317.60
62	Exhaust pipe heat shield X	1.00	0.00	0.00
63	Exhaust pipe mounting X	2.00	112.60	225.20
64	Exhaust pipe gasket X	1.00	96.30	96.30

Spare tyre panel - DIS.
" " Board - RE X5
" " sponge - CMA.
Tailgate Inner Trim - RE.

Amt S\$ 40,353.10
Discount (0.00%) S\$ 0.00
Subtotal S\$ 40,353.10

Section: Special Nett Items

65	Front grille clips - REC.	1.00	50.00	50.00	20
66	Head lamp clips (LH) X NN	1.00	30.00	30.00	X
67	Head lamp clips (RH) X NN	1.00	30.00	30.00	X
68	Front bumper clips - REC.	1.00	50.00	50.00	40
69	Front bumper undercover clips X NN	1.00	50.00	50.00	X

Tail lamp bracket RH - CMA

Continue on next page...

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLL1445M
Make & Model : TOYOTA, HARRIER PREMIUM 2.0
 CVT, ZSU600088883
Year of Manufacture : 2016

Estimation No. : E18060048
DOA : 22/06/2018

No	Description	Qty	U/P	Amt	
70	Tailgate inner trim clips / MC	1.00	50.00	50.00	20
71	Rear number plate X NN	1.00	50.00	50.00	X
72	Rear bumper clips / MC	1.00	50.00	50.00	40
73	Rear bumper reverse sensor - DM	1.00	350.00	350.00	200
74	Tail lamp clips (LH) X NN	1.00	30.00	30.00	X
75	Tail lamp clips (RH) X NN	1.00	30.00	30.00	X
76	Rear fender inner trim clip (LH) X NN	1.00	50.00	50.00	X
77	Rear fender inner trim clip (RH) X NN	1.00	50.00	50.00	X
78	Rear end panel top garnish clips / MC	1.00	50.00	50.00	20
79	Rear end panel top garnish sealant X NN	1.00	80.00	80.00	X

Amt S\$ 1,000.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 1,000.00

Section: Labour Items

80	To R&R front accident affected areas	1.00	800.00	800.00	200
81	To putty & respray front accident affected areas	1.00	800.00	800.00	200
82	To rust proof front accident affected areas	1.00	60.00	60.00	X NN
83	To R&R aircon condensor & refill gas	1.00	200.00	200.00	X NN
84	To check wiring layout & head lamp focus	1.00	80.00	80.00	30
85	To check, diagnose & reset any fault codes	1.00	350.00	350.00	X
86	To R&R rear accident affected areas	1.00	1,250.00	1,250.00	600 800
87	To putty & respray rear accident affected areas	1.00	1,250.00	1,250.00	600 800
88	To rust proof rear accident affected areas	1.00	80.00	80.00	60
89	To R&R tailgate mechanism	1.00	200.00	200.00	60
90	To R&R rear luggage compartment	1.00	80.00	80.00	60.

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLL1445M
Make & Model : TOYOTA, HARRIER PREMIUM 2.0
CVT, ZSU600088883
Year of Manufacture : 2016

Estimation No. : E18060048
DOA : 22/06/2018

No	Description	Qty	U/P	Amt
91	To R&R rear bumper reverse sensor & check function	1.00	80.00	80.00
92	To check wiring layout of tail lamp	1.00	200.00	200.00
93	To R&R exhaust pipe assy	1.00	80.00	80.00
94	To check for water / oil seepage	1.00	150.00	150.00
95	To do wheel alignment - after	1.00	0.00	0.00

Amt S\$ 5,660.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 5,660.00

9 Days.

Lump Sum Repair.

After repair photos.

Gino Giar - 8288 0282

26/6/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

List Items Subtotal S\$ 40,353.10

Special Nett Items Subtotal S\$ 1,000.00

Labour Items Subtotal S\$ 5,660.00

Total S\$ 47,013.10