

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 195E**AAD1806-204***Not Authored
Resurvey B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 195E

VF1ABL15AUC282270

RENAULT

LATITUDE

21.6.2018

EQ**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>BH/CM</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>DIS/CM</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>DIS</i> 113.47	✓
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>SN</i> 135.97	X
5	1 BUMEP R RETAINER RH REAR	\$	<i>SN</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>SN GR</i> 43.61	X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>SN</i> 135.97	X
8	1 BUMEP R RETAINER LH REAR	\$	<i>SN</i> 44.99	✓
9	1 BUMPER REFLECTOR LH	\$	<i>SN</i> 43.61	X
10	1 BUMPER BEAM REAR	\$	<i>B</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>B</i> 225.95	✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>B</i> 225.95	✓
13	1 BOOT REAR	\$	<i>B</i> 2,872.68	✓
14	1 BOOT FINISHER	\$	<i>SN</i> 470.06	X
15	1 BOOT WHEATERSTRIP	\$	<i>DIS/MD</i> 323.05	✓
16	1 BOOT REFLECTOR LAMP LH	\$	<i>CM</i> 493.35	✓
17	1 BOOT REFLECTOR LAMP RH	\$	<i>CM</i> 493.35	✓
18	1 BOOT BADGE 'RENAULT'	\$	<i>R</i> 225.36	✓
19	1 BOOT BADGE	\$	<i>R</i> 225.36	✓
20	1 BOOT STRUT LH	\$	<i>SN</i> 276.08	} X
21	1 BOOT STRUT RH	\$	<i>SN</i> 276.08	
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1 BOOT INNER TRIM	\$	<i>SN</i> 586.45	
25	1 BOOT SWITCH	\$	<i>SN</i> 168.13	
26	1 BOOT LOCK	\$	<i>R</i> 202.67	
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	
28	2 LICENCE PLATE LAMP	\$	<i>SN</i> 50.52	
29	2 BOOT RUBBER PLUG	\$	<i>SN</i> 221.81	

Trans-cab Auto Services Pte Ltd**AAD1806-204**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 195E

30	1 DOOR PANEL REAR LH	\$	R	2,844.66	X
31	1 FENDER PANEL INNER TRIM REAR LH	\$	SL	671.45	X
32	1 FENDER PANEL REAR LH	\$	R	3,299.13	X
33	1 WHEELARCH REAR LH	\$	SL	543.47	X
34	1 FENDER PANEL INNER TRIM REAR RH	\$	SL	671.45	X
35	1 FENDER PANEL REAR RH	\$	R	3,299.13	X
36	1 WHEELARCH REAR RH	\$	SL	543.47	X
37	1 TAILLAMP RH	\$	CM	552.55	✓
38	1 TAILLAMP PANEL RH	\$	R	986.70	X
39	1 TAILLAMP LH	\$	CM	552.55	✓
40	1 TAILLAMP PANEL LH	\$	R	986.70	X
41	1 OUTER PANEL REAR (End Panel)	\$	R	1,471.77	✓
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	SL	404.56	X
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X
44	1 SPARE WHEEL PANEL TRIM	\$	SL	612.21	X
45	1 EXHAUST REAR	\$	R	7,489.05	X
46	1 EXHAUST CAP REAR	\$	R	230.49	X
47	1 FUEL FLAP L70Y	\$	SL	343.57	X
48	1 BUMPER COVER FRT	\$	Bu	1,259.42	✓
49	1 BUMPER SPOILER FRT	\$	SL	181.75	X
50	1 BUMPER ABSORBER FRT	\$		394.68	?
51	1 BUMPER RETAINER FRT LH	\$	D.I	151.41	✓
52	1 BUMPER SUPPORT FRT	\$	SL	123.88	X
53	1 BUMPER RETAINER FRT RH	\$	D.I	150.77	✓
54	1 BUMPER SUPPORT FRT	\$	SL	123.88	X
55	1 BUMPER UNDERTRAY FRT	\$	SL	472.83	X
56	1 BUMPER GRILLE LOWER FRT	\$	SL	266.80	X
57	1 BUMPER FOG LAMP GRILLE LH	\$	SL	207.21	X
58	1 BUMPER FOG LAMP GRILLE RH	\$	SL	207.21	X
59	1 BUMPER BEAM FRT	\$		914.08	?
60	1 TOW COVER FRT	\$	SL	28.61	X
61	1 RADIATOR GRILLE	\$	CM	1,707.78	✓
62	1 RADIATOR GRILLE BADGE 'RENAULT'	\$	R	225.36	X
63	1 RADIATOR GRILLE FRAME	\$	CM	1,353.75	X
64	1 FRAME FULL SUPPORT PANEL	\$	CM	615.90	X
65	1 FRAME FULL SUPPORT BRACKET	\$	R	89.79	X
66	1 FRONT BRACE PANEL	\$	R	177.22	X
67	1 HORN	\$	SL	314.17	X
68	1 HORN BRACKET	\$	R	40.45	X

Trans-cab Auto Services Pte Ltd**AAD1806-204**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 195E

69	1 HEADLAMP LH	\$	<i>CMA</i> 1,184.43	✓
70	1 HEADLAMP RH	\$	<i>CMA</i> 1,184.43	✓
71	1 HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15	X
72	1 HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15	X
73	1 BONNET	\$	<i>B</i> 1,941.63	✓
74	1 BONNET INSULATOR	\$	<i>SL</i> 405.73	X
75	1 BONNET STRUT LH	\$	<i>SL</i> 88.61	X
76	1 BONNET STRUT RH	\$	<i>SL</i> 88.61	X
77	1 BONNET HINGE LH	\$	<i>R</i> 348.31	X
78	1 BONNET HINGE RH	\$	<i>R</i> 348.31	X
79	1 BONNET LOCK	\$	<i>D17</i> 305.48	✓
80	1 BONNET CABLE	\$	<i>SL</i> 119.19	}
81	1 BONNET CABLE COVER	\$	<i>SL</i> 161.03	
82	1 BONNET SEAL OUTER	\$	<i>SL</i> 92.36	
83	1 BONNET SEAL INNER	\$	<i>SL</i> 157.28	
84	1 FENDER PANEL FRT LH	\$	<i>R</i> 783.83	
85	1 WHEELARCH FRT LH	\$	<i>SL</i> 278.84	
86	1 FENDER BRACKET LOWER LH	\$	<i>SL</i> 15.79	
87	1 FENDER INSULATOR LH	\$	<i>SL</i> 130.84	
88	1 FENDER INSULATOR RH	\$	<i>SL</i> 130.84	
89	1 AIR CLEANER LOWER	\$	<i>SL</i> 271.26	
90	1 AIR CLEANER HOSE	\$	<i>SL</i> 76.14	}
91	1 BASE BATTERY TRAY	\$	<i>SL</i> 363.40	
92	1 AIR CLEANER BOX	\$	<i>SL</i> 464.20	
93	1 TURBO DUCT	\$	<i>SL</i> 1,027.80	
94	1 A/C HEATER VALVE	\$	<i>SL</i> 484.50	
95	1 SUBFRAME OUTER FRT	\$	<i>SL</i> 2,652.45	
96	1 SUBFRAME BRACKET OUTER LH	\$	<i>SL</i> 92.36	
97	1 ENGINE UNDERTRAY	\$	<i>SL</i> 564.98	
98	1 A/C CONDENSER	\$	<i>B</i> 2,020.37	
99	1 A/C CONDENSER GARNISH LH UPPER	\$	<i>SL</i> 39.67	}
100	1 A/C CONDENSER GARNISH RH UPPER	\$	<i>SL</i> 39.67	
101	1 A/C CONDENSER GARNISH LH	\$	<i>SL</i> 58.81	
102	1 A/C CONDENSER GARNISH RH	\$	<i>SL</i> 59.60	
103	1 A/C PIPE CONDENSER TO COMPRESSOR	\$	<i>SL</i> 208.39	
104	1 A/C PIPE CONDENSER TO EXPENSION VALVE	\$	<i>SL</i> 658.72	
105	1 A/C PIPE COMPRESSOR	\$	<i>SL</i> 334.29	
106	1 A/C PIPE	\$	<i>SL</i> 658.72	

Trans-cab Auto Services Pte Ltd**AAD1806-204**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 195E

107	1 A/C COMPRESSOR	\$	Sin 2,684.61	}
108	1 AIR COOLER	\$	Sin 792.60	
109	1 AIR INTERCOOLER HOSE (LONG)	\$	Sin 1,014.13	
110	1 AIR INTERCOOLER HOSE (Short)	\$	Sin 375.14	
111	1 TRANSMISSION COOLER	\$	Sin 1,219.30	
112	1 TRANSMISSION COOLER PAD	\$	Sin 17.96	
113	1 RADIATOR	\$	Sin 1,202.20	
114	2 RADIATOR STUD UPPER	\$	Sin 14.41	
115	2 RADIATOR BUSH UPPER	\$	Sin 50.12	
116	2 RADIATOR MTG LOWER	\$	Sin 55.85	
117	1 RADIATOR FAN COWLING	\$	Sin 820.54	
118	1 RADIATOR FAN MOTOR LH	\$	Sin 967.36	
119	1 RADIATOR FAN MOTOR RH	\$	Sin 1,479.46	
120	1 RADIATOR TANK	\$	Sin 324.62	
121	1 RADIATOR HOSE UPPER	\$	Sin 240.56	
122	1 RADIATOR HOSE LOWER	\$	Sin 491.18	
123	1 RADIATOR TANK HOSE	\$	Sin 61.18	
124	1 AUTO COMPUTER	\$	Sin 5,032.17	
125	1 INJECTION COMPUTER	\$	Sin 4,706.30	
126	1 RHD HYDRAULIC POWER(ROCK&PINION)	\$	Sin 5,154.52	}
127	1 STEERING PUMP ELECTRIC L70Y	\$	Sin 2,306.90	
128	1 STEERING PINION RACK L70Y	\$	Sin 4,413.11	

TOTAL	\$	99,633.49
10%	\$	9,963.35
	\$	89,670.15

Specical Nett

1 1SET PARKING AID	\$	Short 700.00 600.00
2 1SET REAR BUMPER CLIP	\$	na 66.00 —
3 1SET BUMPER BRACKET CTR CLIP	\$	na 33.00 —
4 1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na 10.00 X
5 1SET BUMPR RETAINER RH CLIP RR	\$	na 20.00 X
6 1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na 10.00 X
7 1SET BUMPR RETAINER CLIP LH RR	\$	na 20.00 X
8 1SET BUMPER LOWER REAR RIVET	\$	na 22.00 X
9 1SET BUMPER LOWER REAR CLIP	\$	na 66.00 ✓

Trans-cab Auto Services Pte Ltd**AAD1806-204**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 195E

10	1 EXHAUST MOUNTING REAR	\$	Sn	17.82	X
11	1SET BOOT FINISHER CLIP	\$	nn	24.20	X
12	1 BOOT STICKER "Trans-cab"	\$	nn	30.00	✓
13	1 BOOT STICKER "6555-3333"	\$	nn	30.00	✓
14	1 BOOT INNER TRIM CLIP	\$	nn	45.00	X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	X
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00	X
17	1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	X
18	1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	X
19	1 TAILLAMP CLIP RH	\$	nn	5.00	✓
20	1 TAILLAMP CLIP LH	\$	nn	5.00	✓
21	2 REAR WINDSCREEN SELANT	\$	nn	80.00	X
22	1 WINDSCREEN MOULDING	\$	nn	100.00	X
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	X
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn	385.00	X
25	1 SPARE TYRE	\$	Sn	330.00	X
26	1SET RADIATOR GRILLE FRAME CLIP	\$	nn	52.00	✓
27	1SET BUMPER CLIP FRT	\$	nn	66.00	✓
28	1 BUMPER BRACKET CLIP FRT LH	\$	nn	12.00	} X
29	1 BUMPER SUPPORT CLIP FRT LH	\$	nn	10.50	
30	1 BUMPER BRACKET CLIP FRT RH	\$	nn	12.00	
31	1 BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50	
32	1 TOW COVER FRT	\$	Sn	14.50	
33	1SET RADIATOR GRILLE SCREW	\$	nn	16.00	
34	1SET BUMPER GRILLE LOWER CLIP	\$	nn	69.00	
35	1SET FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	
36	2 FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	
37	2 FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	
38	1 Windscreen moulding	\$	nn	100.00	
39	1SET Front licence plate with holder	\$	Bz	80.00	45mm

TOTAL \$ 2,787.52**TOTAL PARTS \$ 92,457.67****LABOUR**

Putty And Spray Painting Of The Affected Portion. \$ 9,000.00 1100/

Trans-cab Auto Services Pte Ltd**AAD1806-204**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 195E

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	1100/
To Rust-Proofing Of The Affected Areas.	\$	170.00	90/
To reinstall rear bumper parking sensor.	\$	170.00	60/
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	60/
To repair and realign rear exhaust pipe.	\$	na 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 60/
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	na 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	na 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	na 170.00	X
To check steering geometry and computer wheel alignment	\$	na 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	na 380.00	X
Towing Fees.	\$	120.00	50/

Trans-cab Auto Services Pte Ltd**AAD1806-204**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 195E

To apply paint protection system (PPS) maintain and enhancement	\$	<i>nn</i>	380.00	<i>X</i>
To rust-proofing of the affected areas.	\$	<i>Pyment</i>	170.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>7</i>	380.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i>	220.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i>	170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>401</i>
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>nn</i>	380.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i>	380.00	<i>X</i>
To lift-up engine with gear box and refit.	\$	<i>nn</i>	440.00	<i>X</i>
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	<i>nn</i>	440.00	<i>X</i>
To remove and refit air bag system and reset.	\$	<i>nn</i>	480.00	<i>X</i>
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	<i>nn</i>	380.00	<i>X</i>
To vacuum, replace, refix and recharge air condenser	\$		380.00	<i>1001</i>
To replace, refix and top up coolant for radiator	\$		170.00	<i>501</i>

Trans-cab Auto Services Pte Ltd

AAD1806-204

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 195E

To vacuum, replace, refix and recharge Air
Intercooler

\$ 170.00 *501*

To Transfer Of Fender Fittings, Attachments And
Perform Water Seepage Test.

\$ *~* 170.00 *X*

TOTAL \$ 24,220.00

Over All Total \$ 116,677.67

(LUMP SUM)**Repair Days****30 DAYS***8 days*

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer**Signature:****Date:**