

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 47404
Date Estimated : 22/06/2018
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Ng Boon Phiang
33 Jurong West Street 41
#11-60

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 649413

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SDD8484R	DX54017	13/06/2013	520iA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments include making good the boot lid, tail end panel and knocking out dents caused by the accident	2550.00		2,550.00	
To spray paint rear bumper, boot lid and tail end panel	2537.00		2,537.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
Sundries (A)	80.00		80.00	nec ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RR BUMPER BOTTOM CENTRE GUIDE	58.95	1.00		58.95
RR BUMPER CARRIER	714.25	1.00		714.25
RR BUMPER PANEL PRIMED (PDC)	1,467.20	1.00		1,467.20
RR BUMPER ADAPTER	48.00	1.00		48.00
EMBLEM GROMMET	0.80	2.00		1.60
BMW EMBLEM	69.50	1.00		69.50
# PLUG *	1.05	5.00		5.25
# REAR RIGHT COVERING * }	84.20	1.00		84.20
# PLUG BLACK D=5MM *	0.90	7.00		6.30

SUPPLEMENTARY ITEMS

Total Labour :	5,317.00
Total Parts :	2,455.25
Total Labour & Parts :	7,772.25
Deduction for Excess :	
Total Repair Costs less Excess:	7,772.25
GST @7%:	544.06
Grand Total :	8,316.31