

ASS. REC. BY:

REF: CS/MSG18011525 / Agd3 / Special Instructions

Surgery
Mentman

Adrian

ASSIGNMENT (Office)

From (Person):

Monica cheng

of

MSIG

Date/Time:

25/6/18 @ 4:33pm

Estimated Cost:

Bill to:

OD (IP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 18 22K

Insured:

GBA 7118 U

at Workshop to/s

SW WerkZ

Tel:

9271 2214

of

Blk 25 Kaki Blk + Rd 4 #03-67

Policy No:

28809641MKF

Claim No:

56 2141

Sum Insured:

Excess:

Make of Veh:

D.O.A.

22/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

4:58pm @ 25/6/18

Person Contacted:

Chris

Vehicle:

IN / OUT

Date/Time

Action/Instruction

(✓) Estimate

SLB 1822K - X

GBA 7118U - X

26/6/18 @

3:30pm informed Monica Cheng, we are pending estimate from rapier

17/10/18 @

10:35am revised to Monica Cheng via Mentman.

US 81890, 14 days (led to 3118397, 62%)

ADJ. REC. BY: Adrian King

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLB1822K Yr Regn: 2016 March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel c.c. 1496

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 37133 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: R21110593

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: 215/60R16

BS: PUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal: 06 mm R/Bal: 06 mm

L/Bal: 06 mm L/Bal: 06 mm

D.O.A. _____ D.O.I. 25/06/18

Survey held at S.W.

Des. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP MS/G

MV: 751C
PV: 44K
Nett: 31K

RECEIVED 10 OCT 2018

Date/Time, File Pass to?

☐ : Preli. Report

11/10/18 tp/MS/G

☐ : Final Report

Date/Time, File Return to?

21

Days Of Repair: 14

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech Invs (\$)

☐ Weekend (\$)

Report Format: WCR-TP

Lump Sum / 18900

66423

Survey Fee: 360

Transportation: _____

S + RS: 360

Photos: _____

Liberty: _____

(TOTAL)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Jun 2018		25 Jun 2018 16:33 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Indeco Engineers (Pte) Ltd, Co. Reg. No.: 198304130G		
Main Claimant:	LOUISE KAM CHIA HUI(GAN JIAHUI), ID: S8116642J		
Vehicle Reg. No.:	SLB1822K	Date of Loss:	22/06/2018 17:00 - :59 [26 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 562141	Policy/Cover Note No.:	28809641MKF (Third Party Only) Coverage: 01/09/2017 - 31/08/2018
Vehicle Reg. No. (Insured):	GBA7118U	Policy No. (Claimant):	
		Excess:	
Repairer:	Sw Werkz Pte Ltd (HQ) BLK 25 KAKI BUKIT ROAD 4, #03-67/68 SYNERGY @ KAKI BUKIT, 417800 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 26/06/2018]		
Adj Asg. Remarks:	on WP. SJE Agree Please appoint LKK and contact Chris Chan Pick Yuen @ 92712214 Liability (Non-reporting)		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 17 Oct 2018

Preliminary Advice

Insured Vehicle No	: GBA7118U	Accident Date	: 22/06/2018
TP Vehicle No	: SLB1822K	Assignment Date	: 25/06/2018
Make	: HONDA ACCORD	Est. Duration of Repair	: 14
Date of Inspection	: 25/06/2018		
Inspection At	: SW WERKZ PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	50,083.97
Revised Amount	:S\$	23,684.10
Check Items (Estimated)	:S\$	0.00
Total	:S\$	23,684.10

Lump Sum Repair	:S\$	18,900.00
-----------------	------	-----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Tuesday, 26 June 2018 3:20 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE SLB 1822K (YOUR REF: 562141)

This mail is associated with :

***SLB1822K (562141)**

[GBA7118U]

TP

LOUISE KAM CHIA HUI(GAN JIAHUI)

Jun 22 2018 5:00PM

[Indeco Engineers (Pte) Ltd]

Sw Werkz Pte Ltd

Dear Monica,

Please be informed that we have inspected the vehicle SLB 1822K on 25/06/2018.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6642J
Vehicle Details	
Vehicle No.:	SLB1822K
Vehicle to be Exported:	Yes
Intended De-registration Date:	25 Jun 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	L15B4030997
Chassis No.:	RU11110993
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$20,266.00
Original Registration Date:	30 Mar 2016
First Registration Date:	30 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$10,373.00
Intended PARF Rebate Particulars	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Mar 2026
PARF Rebate Amount:	\$7,779.00
Intended COE Rebate Particulars	
COE Expiry Date:	29 Mar 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,651.00
COE Rebate Amount:	\$36,204.00
Total Rebate Amount:	\$43,983.00

The information contained herein is correct as at 25 Jun 2018

OK



Confirm Cheapest "S" Model Vezel 1.5A, Super Low Mileage Done 50050km, Totally Like Brand New, See To Believe. 1 Owner, New Pearl White Paintwork, Road Tax Till Jan 19. 100% Accident Free. Call Now!

Lake View Credit Pte Ltd

Posted: 24-Jun-2018 Tags: 2016 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda



☐ Honda Vezel 1.5A X

\$78,800

\$9,750 /yr

25-Jan-2016

1,496 cc

-

SUV

Available

Evaluated By VICOM, Free 6 Months Maintenance And 1 Grooming, Roomy Interior, Free 1 Year Servicing, Non Grab Or Private Hire Car...

Yong Lee Seng Motor

Posted: 26-May-2018 Tags: 2016 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda



☐ Honda Vezel 1.5A X

\$72,800

\$8,980 /yr

01-Feb-2016

1,496 cc

-

SUV

Available

Low Drive Away, Monthly At \$800+, Well Maintained By 1 Owner, Car Serviced Regularly, 4 New Bridgestone Tyres, Great Fuel Efficiency, Huge Boot Space, Test Drive To Evaluate The Condition, View By App...

Posted: 25-May-2018 Tags: 2016 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda



Best car deals without the hassle of paperwork!

We have over a thousand consignment cars available for sale at highly attractive prices. All without the need to do paperwork. Pick out your favourite car today.

Find out more!



☐ Honda Vezel 1.5A X

\$72,000

\$8,820 /yr

02-Feb-2016

1,496 cc

\$1,500 /mo

SUV

Available

Regularly Serviced, Used By Homemaker To Run Household Errands, Schedule A Test Drive Today! Viewings Are Strictly On Appointment Basis.

Carro

Posted: 20-Jun-2018 Tags: 2016 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda



☐ Honda Vezel 1.5A X

\$77,800

\$9,570 /yr

03-Feb-2016

1,496 cc

25,600 /mo

SUV

Available

Up To 90% Loan, Flexible Bank/In House Loan Available, Subject To Approval! Superb Well Maintained, Spacious Interior, Roomy Boot Space With A Peace Of Mind, Trade In Welcome, Come View And Test Drive T...

AL Autocar Pte Ltd

Posted: 23-Jun-2018 Tags: 2016 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda



☐ Honda Vezel Hybrid 1.5A X

\$76,888

\$9,770 /yr

04-Feb-2016

1,496 cc

41,000 /mo

SUV

Available

Fuel Type: Petrol-Electric

More Than 5k Accessories 7" Pioneer 8750 HU With Bluetooth, Apple And Android CarPlay Under Seat Active Subwoofer 8 Speakers 2018 Cover All Doors Double Layer Sound Proofing Rubble Seal Sound Pro...

Posted: 14-Jun-2018 Tags: 2016 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda



☐ Honda Vezel Hybrid 1.5A X
Honda Sensing

\$80,800

\$10,280 /yr

04-Feb-2016

1,496 cc

18,000 /mo

SUV

Available

Fuel Type: Petrol-Electric

100% Accident Free, Fuel Efficient Family Car, Excellent Unit, Regularly Maintained, Both Bank And In House Loan Is Available, Road Tax Rate, Cheapest In The Market.High Trade In Is Available

Posted: 09-Jun-2018 Tags: 2016 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda



☐ Honda Vezel 1.5A X

\$73,800

\$9,100 /yr

05-Feb-2016

1,496 cc

-

SUV

Available

1 Owner Unit, Flexibility In House Loan Up To 90%, Excellent Condition, Regularly Maintained, Low Fuel Consumption, Price As Low As Your Family, Spacious And Reliable.

Posted: 24-Jun-2018 Tags: 2016 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda



☐ Honda Vezel 1.5A X

\$69,800

\$8,490 /yr

22-Feb-2016

1,496 cc

40,000 /mo

SUV

Available

Cheapest In The Market, Down Payment Only \$3,500, Low Mileage Done, Lowest Depreciation Vezel With Premium Dealer, Excellent Condition, View To Believe, High Trade In Welcome. In House, Bank Loan, Ca...

Heritage Auto Enterprise Pte Ltd

Posted: 24-Jun-2018 Tags: 2016 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda



☐ Honda Vezel 1.5A X

\$73,800

\$9,000 /yr

25-Feb-2016

1,496 cc

30,000 /mo

SUV

Available

Full Bodykit, Excellent Condition, Accident Free, No Repair Needed, Bank Loan In House Loan Available, Trade In Welcome, Appointment Only.

Posted: 23-Jun-2018 Tags: 2016 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda



☐ Honda Vezel 1.5A X

\$73,800

\$8,980 /yr

26-Feb-2016

1,496 cc

30,000 /mo

SUV

Available

100% Loan Available, 1 Owner, Full Serviced Histories With Optima, Warranty Till Feb 2019, Flexible Loan Interest And Free Personal Accident Benefit Of \$10,000 And Accident...

Finster Auto Trading

Posted: 07-Jun-2018 Tags: 2016 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda

SHOW FLAT ON MAP

Compare [3]



Honda Vezel 1.5A X

\$77,800

\$9,530 /yr

02-Mar-2016

1,496 cc

40.7 km

SUV

Available

Best Condition Unit Need No Compare, Just Arrived Yet Only 1 Owner For Your Peace Of Mind As It Is Non Rental Unit, Low Mileage, And Fuel Economy. Flexible Loan, High Trade In, Please Cont...

AL Autocar Pte Ltd



Posted: 23-Jun-2018

Tags: 2016 Honda Vezel, Honda Vezel, Honda, Used Honda

EXTRA MILEAGE



Honda Vezel 1.5A X

\$76,800

\$9,330 /yr

16-Mar-2016

1,496 cc

40.7 km

SUV

Available

1 Owner, 3 Years Warranty Till March 2019, Warranty Mileage Up To 100k, Full Servicing Record, Consignment Unit, Yearly Service, And Good Driving Dynamics, While Its Fuel Efficiency Will...

Accendore Autolution Pte Ltd



Posted: 23-Jun-2018

Tags: 2016 Honda Vezel, Honda Vezel, Honda, Used Honda

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make **▼**

Model **▼**

Price **▼**

Depreciation **▼**

Reg Date **▼**

Eng Cap **▼**

mi

mi

mi

mi

mi

mi

Status **▼**

For old advertisements, view Expired ads

« Back (1 2 3 4 5 6) Next »

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forums](#) | [Resources](#)

sgCarMart is the number one car classified for popular import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from cars or station wagons, SUV, MPV, hatchback, to CDD cars & OPC cars. For cars also buy from a car auction, look up car finds, low mileage cars, buy used Vezel, Vezel Singapore, used Vezel Singapore, used Vezel, used vehicles Singapore or even buy used Vezel Singapore. We have car authorized car dealers, and used car dealers on our site. Find new car price lists, new car location and new car promotions. Visit our performance cars, properties for sale, motor, car performance parts, car discussion, Honda discussion, commercial vehicle leasing & more.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or for any loss or damage.

Follow **sgCarMart.com**



[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

SHOW FILTERS | SORT BY

Compare (3)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/06/2018 13:45
Date Of Accident	22/06/2018 17:05
Exact Location Of Accident	NICOLL DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB1822K
Insured/Policyholder	
Name Of Registered Owner	LOUISE KAM CHIA HUI(GAN JIAHUI)
NRIC No	S8116642J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96251215
Alternative Phone No	OTHERS-96251215

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL 1.5X CVT
Exact Purpose for which vehicle was being used at time of accident	PTE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1618321802
Cover Note Number	

Driver

Name of Driver	KOH SHOU REN, DENIS(XU SHOUREN,DENIS)
NRIC No	S8243111Z
Date Of Birth	19/12/1982
Occupation	INDOOR
Date Of Driving Pass	15/03/2004
Driving Experience	14 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97977836
Fax Number	
Contact Number	
Email Address	DENISKOHSHOUREN@GMAIL.COM

Address BLOCK 669B EDGEFIELD PLAINS #03-676
 Postcode 822669
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 3
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I TRAVELLED ALONG NICOLL DRIVE TOWARDS CHANGI COAST ROAD. SUDDENLY VEHICLE B, GBA7118U HIT ONTO MY VEHICLE FRONT PORTION FROM THE OTHER SIDE OF THE ROAD. UPON CHECKING, IT WAS VEHICLE C, XD9230M THAT HIT ONTO VEHICLE B AND CAUSED IT TO HIT ONTO MY VEHICLE.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBA7118U
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver) 1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number XD9230M



**SINGAPORE
POLICE FORCE**



T/20180623/2047

2 of 3

Report No. T/20180623/2047

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

CONTINUATION OF REPORT

Brief Details.

On 22/06/2018 at about 1703hrs, I was driving my vehicle SLB1822K along Nicoll Drive towards Changi Coast Road at the extreme right lane.

Suddenly, a vehicle GBA7118U from the opposite lane came into my lane and I could not stop in time and hit against the said vehicle. I quickly stationary stop my vehicle and went out to make a check. I discovered that I had got into an accident with two other vehicles.

I then called for police. I made a check with the driver of GBA7118U and I was informed that the lorry behind bearing the vehicle plate of XD9230M had hit him which resulted him to protrude forward and came into my lane. I also made a check with the driver of XD9230M and I was informed by the driver that he was trying to evade a cyclist and hit on the van GBA7118U. There were damages found at the front and right portion of my vehicle.

I took photo of my vehicle and the van. I managed to exchange particulars with the van GBA7118U. After a while, traffic police came and took our particulars and took photos of the scene. Traffic police then asked us to drive our vehicle to the right road shoulder. The traffic police then ask us to engage our own tow truck as such I complied. Ambulance came and convey the driver of GBA7118U to hospital. The traffic police gave me a police case card and advise me to lodge a police report.

After a while, my tow truck came and tow my vehicle away. I follow the tow truck to the workshop located at Kaki Bukit. After that I went back home. However, after the accident I felt pain at shoulder, neck, knee cap area and some scratches on my hand area. I went to Prohealth Medical Group @Punggol spectra to make a check and I am entitled with a total of 3 days of medical leave from 22/06/2018 to 24/06/2018.

When I viewed back my vehicle in-build car camera and the footage captured that the van GBA7118U which is at the opposite lane was about to turn right into my lane. Suddenly, a lorry bearing the vehicle plate of XD9230M which is behind the van had hit at the rear and the van protruded to my lane and I could not stop in time and hit against his vehicle.

Sheet1

SW WERKZ PTE LTD

BLOCK 25 KAKI BUKIT ROAD 4 #03-65/67/68 SYNERGY @ KB Singapore 417800

HP: 92712214 Fax: (65) 69664526

Email : chris_chanbebe@hotmail.com

LOUISE KAM CHIA HUI
Bk 25 Kaki Bukit Rd 4
05-26 SYNERGY @KB
Singapore 417800

TP MS16

Xiao Chen

'25th JUNE 2018Accident date: 22th JUNE 2018

Estimated repair cost for vehicle no: SLB1822K HONDA VEZEL 1.5X A '15

S/n	Qty	Items	U/price	Amount
1	1	Front bonnet Distorted		\$950.40 ✓
2	1	Front bonnet lock Damaged		\$188.10 ✓
3	1	bonnet inner insulator crumpled		\$225.20 ✓
4	1	front bonnet inner rubber lt		\$86.20 ✓
5	2	Front head lamp -led crumpled	\$1,784.50	\$3,569.00 ✓
6	2	head lamp lower bracket crumpled	\$68.00	\$136.00 ✓
7	2	log lamp chrome cover. R.H. Distorted	\$118.20	\$236.40 118.20
8	1	Front bumper Distorted		\$936.70 781.50 ✓
9	2	Front bumper side bracket nr	\$68.20	\$136.40 ✓
10	10	Front bumper clips nr	\$5.00	\$50.00 30
11	1	Front bumper number plate Nol New		\$0.00 x
12	1	Front bumper reinforcement Bent		\$484.00 321
13	1	Front Bumper Lower Grille Detached		\$280.20 105
14	1	front centre garnish moulding nr		\$138.00 x
15	1	Front bumper center lower cover nr		\$295.10 x
16	1	Front Bumper Towing Cover nr		\$68.00 x
17	1	front windscreen moulding New		\$158.00 ✓
18	1	front windscreen cracked		\$1,090.00 ✓
19	1	ERP bracket New		\$30.00 20/20
20	1	Front Grille- upper Chrome lt		\$225.00 75
21	1	front grille -lower crumpled		\$385.00 ✓
22	1	Front Grille emble logo New		\$58.00 ✓
23	10	Front Grille clips nr	\$5.00	\$50.00 10
24	1	Front support panel Distorted		\$989.00 576.20
25	2	Front support panel side bracket nr	\$55.80	\$111.60
26	2	Front support panel side cover Detached	\$187.25	\$374.50
27	8	Front support panel side cover clips nr	\$12.90	\$103.20 20

28	1	Front water tank	Crushed		\$225.00 160.20
29	1	Front radiator	Distorted		\$960.00 ✓
30	1	radiator fan blade	Caulking crushed		\$169.70 ✓
31	1	radiator fan motor	Not Rec		\$850.00 x
32	1	Front air-con condenser	Distorted		\$1,020.10 ✓
33	1	Front air-con condenser section pipe	Bent		\$281.80 ✓
34	1	Front air-con condenser fan motor assy	Distorted		\$381.72 ✓
35	1	Front air-con compressor	Not Rec		\$1,179.20 x
36	1	Front manifold	Crushed		\$850.00 ✓
37	1	Front alternator	Crushed		\$1,580.40 ✓
38	1	Front horn	Not Rec		\$185.00 x
39	1	Front engine mounting - RH	Damaged		\$280.40 ✓
40	1	Front engine mounting - LH			\$214.90 x
41	1	Front engine mounting - Front			\$102.80 ✓
42	1	Front engine mounting - Rear			\$95.80 x
43	1	Front wheel housing -RH	Repair		\$480.00 ✓
44	1	Front chassis -RH	Repair		\$680.00 x
45	1	Front dashboard	Torn		\$964.00 ✓
46	1	Front dashboard panel	Not Rec		\$469.00 x
47	1	Front steering column camping	Not Rec		\$591.40 x
48	1	Front airbag - RH	Activated		\$2,068.60 ✓
49	1	Front airbag - LH			\$2,790.70 ✓
50	1	ABS pump	Not Rec		\$4,938.30 x
51	2	Front safety belt	Activated	\$722.30 640	\$1,444.60 1360
52	1	Front Wiper Panel	Repair		\$386.00 x
53	1	Front wiper garnish	Crushed		\$561.40 345
54	1	Front wiper garnish rubber	Not Rec		\$131.75 x
55	1	front wiper	Not Rec		\$98.00 x
56	6	Front wiper garnish clips	Rec	\$12.90	\$77.40 30
57	1	Front R/H fender	Distorted		\$705.00 ✓
58	1	Front R/H fender cowling	Torn		\$107.40 ✓
59	10	Front R/H fender cowling clips	New	\$5.00	\$50.00 30
60	1	Front R/H lower arm			\$226.50 x
61	1	Front R/H knuckle arm			\$318.00 x
62	1	Front R/H knuckle arm bearing			\$147.70 x
63	1	Front R/H shock absorber			\$469.70 x
64	1	Front drive shaft	Not Rec		\$899.80 x
65	1	Front steering rack			\$1,885.00 x
66	1	front R/H Tyre			\$450.00 x
67	1	front R/H rim			\$650.00 x
68	1	front Door-RH	Repair		\$1,008.10 x

Air Duct. Crushed

152.30

Subtotal :- \$42,329.17

Bonnet Hinge x2 Bent

61.5 x 2 = 123

24855.12

Front Support Panel Top Garnish Crushed 98.20

15884.09

Fusebox Crushed

793.10

Front Grille Bracket Crushed 98.20

Labour charges

To Remove & refix cushion	\$120.00	x
To Remove & refix front windscreen	\$120.00	✓
Gum	\$50.00	✓
Remove & refix front dashboard	\$380.00	220
Remove & refix front airbag and reset	\$380.00	300
To remove & refix front seat	\$350.00	x
Tuff kote	\$120.00	50
To remove & re-fix air-con condenser & radiator fan Motor & top up gas	\$280.00	120
To Remove & refix air-cond compressor, alternator, manifold cover.	\$380.00	250
WHeel alignment (computer)	\$150.00	x
to remove & install front RH undercarriage & steering rack	\$380.00	x
to Remove & install front chassis & wheel housing	\$350.00	x
Towing charges	\$150.00	60
To Check Wiring System	\$80.00	30
Panel beating	\$1,600.00	1400
Spray painting	\$1,600.00	1200

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Subtotal :- \$6,490.00

Total:- \$48,819.17

total 23684.09

h/s: 18.9K ✓

14 Days.

5083.12

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Jun 2018		25 Jun 2018 16:33 Edit Adj Rpt	S\$18,900.00 Edit Estimates	S\$18,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Indeco Engineers (Pte) Ltd, Co. Reg. No.: 198304130G								
Main Claimant:	LOUISE KAM CHIA HUI (GAN JIAHUI), ID: S8116642J								
Vehicle Reg. No.:	SLB1822K	Date of Loss:	22/06/2018 17:00 - :59 [26 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 562141	Policy/Cover Note No.:	28809641MKF (Third Party Only) Coverage: 01/09/2017 - 31/08/2018						
Vehicle Reg. No. (Insured):	GBA7118U	Policy No. (Claimant):							
		Excess:							
Repairer:	Sw Werkz Pte Ltd (HQ) BLK 25 KAKI BUKIT ROAD 4, #03-67/68 SYNERGY @ KAKI BUKIT, 417800 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 25/07/2018]								
Adj Asg. Remarks:	on WP. SJE Agree Please appoint LKK and contact Chris Chan Pick Yuen @ 92712214 Liability (Non-reporting)								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLB1822K (562141)

[GBA7118U]

TP

LOUISE KAM CHIA HUI (GAN JIAHUI)

Jun 22 2018 5:00PM

[Indeco Engineers (Pte) Ltd]

Sw Werkz Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Video							1 per page		☒	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print		
1	26/06/18 08:09	3P video						Load AVI		
Letters/Correspondences							1 per page		☒	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print		
1	25/06/18 14:16	Non Reporting Letter to OI						Load HTM		
Assessment Reports							1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print		
1	17/10/18 10:35	Adjuster Immediate Advice						Load HTM		
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print		
1	17/10/18 09:41	General View						Load JPG	☒	
2	17/10/18 09:41	General View						Load JPG	☒	
3	17/10/18 09:41	General View						Load JPG	☒	
4	17/10/18 09:41	General View						Load JPG	☒	
5	17/10/18 09:41	General View						Load JPG	☒	
6	17/10/18 09:41	General View						Load JPG	☒	
7	17/10/18 09:41	General View						Load JPG	☒	
8	17/10/18 09:41	General View						Load JPG	☒	
9	17/10/18 09:41	General View						Load JPG	☒	
10	17/10/18 09:41	General View						Load JPG	☒	
11	17/10/18 09:41	General View						Load JPG	☒	
12	17/10/18 09:41	General View						Load JPG	☒	
13	17/10/18 09:41	General View						Load JPG	☒	
14	17/10/18 09:41	General View						Load JPG	☒	
15	17/10/18 09:41	General View						Load JPG	☒	
16	17/10/18 09:41	General View						Load JPG	☒	
17	17/10/18 09:41	General View						Load JPG	☒	
18	17/10/18 09:41	General View						Load JPG	☒	
19	17/10/18 09:41	General View						Load JPG	☒	
20	17/10/18 09:41	General View						Load JPG	☒	
21	17/10/18 09:41	General View						Load JPG	☒	
22	17/10/18 09:41	General View						Load JPG	☒	
23	17/10/18 09:41	General View						Load JPG	☒	
24	17/10/18 09:41	General View						Load JPG	☒	
25	17/10/18 09:41	General View						Load JPG	☒	
26	17/10/18 09:41	General View						Load JPG	☒	
27	17/10/18 09:41	General View						Load JPG	☒	

Video			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
28	17/10/18 09:41	General View	 Load JPG	☒
29	17/10/18 09:41	General View	 Load JPG	☒
30	17/10/18 09:41	General View	 Load JPG	☒
31	17/10/18 09:41	General View	 Load JPG	☒
32	17/10/18 09:41	General View	 Load JPG	☒
33	17/10/18 09:41	General View	 Load JPG	☒
34	17/10/18 09:41	General View	 Load JPG	☒
35	17/10/18 09:41	General View	 Load JPG	☒
36	17/10/18 09:41	General View	 Load JPG	☒
37	17/10/18 09:41	General View	 Load JPG	☒
38	17/10/18 09:41	General View	 Load JPG	☒
39	17/10/18 09:41	General View	 Load JPG	☒
40	17/10/18 09:41	General View	 Load JPG	☒
41	17/10/18 09:41	General View	 Load JPG	☒
42	17/10/18 09:41	General View	 Load JPG	☒
43	17/10/18 09:41	General View	 Load JPG	☒
44	17/10/18 09:41	General View	 Load JPG	☒
45	17/10/18 09:41	General View	 Load JPG	☒
46	17/10/18 09:41	General View	 Load JPG	☒
47	17/10/18 09:41	General View	 Load JPG	☒
48	17/10/18 09:41	General View	 Load JPG	☒
49	17/10/18 09:41	General View	 Load JPG	☒
50	17/10/18 09:41	General View	 Load JPG	☒
51	17/10/18 09:41	General View	 Load JPG	☒
52	17/10/18 09:41	General View	 Load JPG	☒
53	17/10/18 09:41	General View	 Load JPG	☒
54	17/10/18 09:41	General View	 Load JPG	☒
55	17/10/18 09:41	General View	 Load JPG	☒
56	17/10/18 09:41	General View	 Load JPG	☒
57	17/10/18 09:41	General View	 Load JPG	☒
58	17/10/18 09:41	General View	 Load JPG	☒
59	17/10/18 09:41	General View	 Load JPG	☒
60	17/10/18 09:41	General View	 Load JPG	☒
61	17/10/18 09:41	General View	 Load JPG	☒
62	17/10/18 09:41	General View	 Load JPG	☒
63	17/10/18 09:41	General View	 Load JPG	☒
64	17/10/18 09:41	General View	 Load JPG	☒
65	17/10/18 09:41	General View	 Load JPG	☒
66	17/10/18 09:41	General View	 Load JPG	☒
67	17/10/18 09:41	General View	 Load JPG	☒
68	17/10/18 09:41	General View	 Load JPG	☒
69	17/10/18 09:41	General View	 Load JPG	☒
70	17/10/18 09:41	General View	 Load JPG	☒
71	17/10/18 09:41	General View	 Load JPG	☒
72	17/10/18 09:41	General View	 Load JPG	☒
73	17/10/18 09:41	General View	 Load JPG	☒
74	17/10/18 09:41	General View	 Load JPG	☒
75	17/10/18 09:41	General View	 Load JPG	☒
76	17/10/18 09:41	General View	 Load JPG	☒
77	17/10/18 09:41	General View	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
78	17/10/18 09:41	General View	 Load JPG	☒
79	17/10/18 09:41	General View	 Load JPG	☒
80	17/10/18 09:41	General View	 Load JPG	☒
81	17/10/18 09:41	General View	 Load JPG	☒
82	17/10/18 09:41	General View	 Load JPG	☒
83	17/10/18 09:41	General View	 Load JPG	☒
84	17/10/18 09:41	General View	 Load JPG	☒
85	17/10/18 09:41	General View	 Load JPG	☒
86	17/10/18 09:41	General View	 Load JPG	☒
87	17/10/18 09:41	General View	 Load JPG	☒
88	17/10/18 09:41	General View	 Load JPG	☒
89	17/10/18 09:41	General View	 Load JPG	☒
90	17/10/18 09:41	General View	 Load JPG	☒
91	17/10/18 09:41	General View	 Load JPG	☒
92	17/10/18 09:41	General View	 Load JPG	☒
93	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
94	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
95	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
96	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
97	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
98	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
99	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
100	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
101	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
102	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
103	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
104	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
105	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
106	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
107	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
108	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
109	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
110	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
111	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
112	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
113	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
114	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
115	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
116	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
117	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
118	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
119	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
120	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
121	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
122	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
123	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
124	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
125	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
126	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
127	17/10/18 09:42	Reinspection Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
128	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
129	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
130	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
131	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
132	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
133	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
134	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
135	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
136	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
137	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
138	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
139	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
140	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
141	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
142	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
143	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
144	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
145	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
146	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
147	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
148	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
149	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
150	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
151	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
152	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
153	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
154	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
155	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
156	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
157	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
158	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
159	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
160	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
161	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
162	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
163	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
164	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
165	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
166	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
167	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
168	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
169	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
170	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
171	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
172	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
173	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
174	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
175	17/10/18 09:42	Reinspection Photo	 Load JPG	☒
176	17/10/18 09:42	Reinspection Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/06/18 14:13	PRI	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18011525/QD3Q2

Date: 23/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28809641MKF

Claimant Vehicle No: SLB1822K

Insured Vehicle No: GBA7118U

Date of Loss: 22/06/2018

Nature of Claim: TP

Claim No: 562141

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLB1822K

Make & Model: HONDA VEZEL, 1.5 (A)

Engine No: L15B4030997

Reg. Date: 30/03/2016 (Man. Year: 2015)

Chassis No: RU11110993

Colour: Blue

Odometer: 37133 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	43,593.97	19,904.10	23,689.87	54.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,490.00	3,800.00	2,690.00	41.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	50,083.97	23,704.10	26,379.87	52.67
Approved Total (Overridden) (S\$)		18,900.00		
Nett Amount (S\$)	50,083.97	18,900.00	31,183.97	62.26

INSPECTION

Date of Assignment: 25/06/2018

Date Inspected: 25/06/2018 Inspected At:

Sw Werkz Pte Ltd (HQ)
BLK 25 KAKI BUKIT ROAD 4, #03-67/68
SYNERGY @ KAKI BUKIT
Singapore 417800

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Oct 2018)

Parts: M1-SUV HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLB1822K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Distorted	950.40 F	*950.40 FL
2	1		*FRONT BONNET LOCK	Damaged	188.10 F	*188.10 FL
3	1		*BONNET INNER INSULATOR	Crumpled	225.20 F	*225.20 FL
4	1		*FRONT BONNET INNER RUBBER	Cut	86.20 F	*86.20 FL
5	2		*FRONT HEAD LAMP -LED	Cracked	3,569.00 F	*3,569.00 FL
6	2		*HEAD LAMP LOWER BRACKET	Cracked	136.00 F	*136.00 FL
7	1		*FOG LAMP COVER	O/S Distorted	236.40 F	*118.20 FL
8	1		*FRONT BUMPER	Distorted	936.70 F	*781.50 FL
9	2		*FRONT BUMPER SIDE BRACKET	Necessary	136.40 F	*136.40 FL
10	10		*FRONT BUMPER CLIPS	Necessary	50.00 F	*30.00 FL
11	1		*FRONT BUMPER NUMBER PLATE (NPA)	Not Necessary	0.00 F	*- FL
12	1		*FRONT BUMPER REINFORCEMENT	Bent	484.00 F	*321.00 FL
13	1		*FRONT BUMPER LOWER GRILLE	Deformed	280.20 F	*105.00 FL
14	1		*FRONT CENTRE GARNISH MOULDING	Not Necessary	138.00 F	*- FL
15	1		*FRONT BUMPER CENTER LOWER COVER	Not Necessary	295.10 F	*- FL
16	1		*FRONT BUMPER TOWING COVER	Not Necessary	68.00 F	*- FL
17	1		*FRONT WINDSCREEN MOULDING	Necessary	158.00 F	*158.00 FL
18	1		*FRONT WINDSCREEN	Cracked	1,090.00 F	*1,090.00 FL
19	1		*ERP BRACKET	Necessary	30.00 FS	*20.00 FS
20	1		*FRONT GRILLE CHROME	Cut	225.00 F	*75.00 FL
21	1		*FRONT GRILLE	Cracked	385.00 F	*385.00 FL
22	1		*FRONT GRILLE EMBLE LOGO	Necessary	58.00 F	*58.00 FL
23	10		*FRONT GRILLE CLIPS	Necessary	50.00 F	*10.00 FL
24	1		*FRONT SUPPORT PANEL	Distorted	989.00 F	*576.20 FL
25	2		*FRONT SUPPORT PANEL SIDE BRACKET	Damaged	111.60 F	*111.60 FL
26	2		*FRONT SUPPORT PANEL SIDE COVER	Deformed	374.50 F	*374.50 FL
27	8		*FRONT SUPPORT PANEL SIDE COVER CLIPS	Necessary	103.20 F	*20.00 FL
28	1		*FRONT WATER TANK	Cracked	225.00 F	*160.20 FL
29	1		*FRONT RADIATOR	Distorted	960.00 F	*960.00 FL
30	1		*RADIATOR FAN COWLING	Cracked	169.70 F	*169.70 FL
31	1		*RADIATOR FAN MOTOR	Not Necessary	850.00 F	*- FL
32	1		*FRONT AIR-CON CONDENSER	Distorted	1,020.10 F	*1,020.10 FL
33	1		*FRONT AIR-CON CONDENSER SECTION PIPE	Bent	281.80 F	*281.80 FL
34	1		*FRONT AIR-CON CONDENSER FAN MOTOR ASSY	Distorted	381.72 F	*381.72 FL
35	1		*FRONT AIR-CON COMPRESSOR	Not Necessary	1,179.20 F	*- FL
36	1		*FRONT MANIFOLD	Cracked	850.00 F	*850.00 FL
37	1		*FRONT ALTERNATOR	Cracked	1,580.40 F	*1,580.40 FL
38	1		*FRONT HORN	Not Necessary	185.00 F	*- FL
39	1		*FRONT ENGINE MOUNTING -RH	Damaged	280.40 F	*280.40 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*FRONT ENGINE MOUNTING -LH	Not Necessary	214.90 F	*- FL
41	1		*FRONT ENGINE MOUNTING -FRONT	Not Necessary	102.80 F	*- FL
42	1		*FRONT ENGINE MOUNTING -REAR	Not Necessary	95.80 F	*- FL
43	1		*FRONT WHEEL HOUSING -RH	Repair	480.00 F	*- FL
44	1		*FRONT CHASSIS -RH	Repair	680.00 F	*- FL
45	1		*FRONT DASHBOARD	Torn	964.00 F	*964.00 FL
46	1		*FRONT DASHBOARD PANEL	Not Necessary	469.00 F	*- FL
47	1		*FRONT STEERING COLUMN CAMPING	Not Necessary	591.40 F	*- FL
48	1		*FRONT AIRBAG-RH	Activated	2,068.60 F	*2,068.60 FL
49	1		*FRONT AIRBAG-LH	Activated	2,790.70 F	*2,790.70 FL
50	1		*ABS PUMP	Not Necessary	4,938.30 F	*- FL
51	2		*FRONT SAFETY BELT	Activated	1,444.60 F	*1,360.00 FL
52	1		*FRONT WIPER PANEL	Repair	386.00 F	*- FL
53	1		*FRONT WIPER GARNISH	Cracked	561.40 F	*345.00 FL
54	1		*FRONT WIPER GARNISH RUBBER	Not Necessary	131.75 F	*- FL
55	1		*FRONT WIPER	Not Necessary	98.00 F	*- FL
56	6		*FRONT WIPER GARNISH CLIPS	Necessary	77.40 F	*30.00 FL
57	1		*FRONT R/H FENDER	Distorted	705.00 F	*705.00 FL
58	1		*FRONT R/H FENDER COWLING	Torn	107.40 F	*107.40 FL
59	10		*FRONT R/H FENDER COWLING CLIPS	Necessary	50.00 F	*30.00 FL
60	1		*FRONT R/H LOWER ARM	Not Necessary	226.50 F	*- FL
61	1		*FRONT R/H KNUCKLE ARM	Not Necessary	318.00 F	*- FL
62	1		*FRONT R/H KNUCKLE ARM BEARING	Not Necessary	147.70 F	*- FL
63	1		*FRONT R/H SHOCK ABSORBER	Not Necessary	469.70 F	*- FL
64	1		*FRONT DRIVE SHAFT	Not Necessary	899.80 F	*- FL
65	1		*FRONT STEERING RACK	Not Necessary	1,885.00 F	*- FL
66	1		*FRONT R/H TYRE	Not Necessary	450.00 F	*- FL
67	1		*FRONT R/H RIM	Not Necessary	650.00 F	*- FL
68	1		*FRONT DOOR -RH	Repair	1,008.10 F	*- FL
69	1		*AIR DUCT	Deformed	152.30 F	*152.30 FL
70	2		*BONNET HINGE	Bent	123.00 F	*123.00 FL
71	1		*FRONT SUPPORT PANEL TOP GARNISH	Deformed	98.20 F	*98.20 FL
72	1		*FUSEBOX	Cracked	793.10 F	*793.10 FL
73	1		*FRONT GRILLE BRACKET	Cracked	98.20 F	*98.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **43,593.97** **24,875.12**
 - List Item Discount on L Items 0.00/20.00% (\$\$) **0.00** **4,971.02**

Total Parts (\$\$) **43,593.97** **19,904.10**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX CUSHION	New	120.00	0.00
2	TO REMOVE & REFIX FRONT WINDSCREEN	New	120.00	120.00
3	GUM	New	50.00	50.00
4	REMOVE & REFIX FRONT DASHBOARD	New	380.00	220.00
5	REMOVE & REFIX FRONT AIRBAG AND RESET	New	380.00	300.00
6	TO REMOVE & REFIX FRONT SEAT	New	350.00	0.00
7	TUFF KOTE	New	120.00	50.00
8	TO REMOVE & REFIX AIRCON CONDENSER & RADIATOR FAN MOTOR & TOP UP GAS	New	280.00	120.00
9	TO REMOVE & REFIX AIR-COND COMPRESSOR ,ALTERNATOR,MANIFOLD COVER	New	380.00	250.00
10	WHEEL ALIGNMENT (COMPUTER)	New	150.00	0.00
11	TO REMOVE & INSTALL FRONT RH UNDERCARRIAGE & STEERING RACK	New	380.00	0.00
12	TO REMOVE & INSTALL FRONT CHASSIS & WHEEL HOUSING	New	350.00	0.00
13	TOWING CHARGES	New	150.00	60.00
14	TO CHECK WIRING SYSTEM	New	80.00	30.00
15	PANEL BEATING	New	1,600.00	1,400.00
16	SPRAY PAINTING	New	1,600.00	1,200.00
Gross Labour Cost (S\$)			6,490.00	3,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >